



UNIVERSAL ROBOTS

C-API

Functional Specification





UNIVERSAL ROBOTS

UR White Paper C-API, 2014

Motion Control Commands



1) **void** robotinterface_command_position_velocity_acceleration

```
(  
    const double *q,  
    const double *qd,  
    const double *qdd  
)
```

Purpose : *Send a set of joint angle values(q) to the controller along with speed(qd) and acceleration(qdd) values on how to get to said configuration.*

Parameters:

q - list of 6 joint angle values [$j_0, j_1, j_2, j_3, j_4, j_5$] in radians

qd - list of 6 joint speed values in radians/sec

qdd - list of 6 joint accel values in radians/sec/sec

Return:

No return value

2) **void** robotinterface_command_velocity_acceleration

```
(  
    const double *q,  
    const double *qd,  
    const double *qdd  
)
```

Purpose : *Send a set of joint speeds(qd) and accels(qdd) to the controller to have the joints accelerate to and achieve said speed.*

Parameters:

q - returns list of 6 joint angle values [$j_0, j_1, j_2, j_3, j_4, j_5$] in radians, configuration

qd - list of 6 joint speed values in radians/sec

qdd - list of 6 joint accel values in radians/sec/sec

Return:

No return value



3) **void** robotinterface_command_velocity

```
(  
                                const double *qd,  
                                )
```

Purpose : *Send a set of joint speeds(qd) to the controller to have the joints move with set speeds. Sent every 8ms to maintain set speed.*

Parameters:

qd – list of 6 joint speed values [j0, j1, j2, j3, j4, j5] in radians/sec

Return:

No return value

4) **void** robotinterface_command_joint_position_velocity_acceleration(

```
int joint,  
double q,  
double qd,  
double qdd  
)
```

Purpose : *Send joint ID(joint), position(q), speed(qd) and accel(qdd) to the controller to have the specified joint move with set speed and accel.*

Parameters:

*joint – joint ID [0-5 => base to wrist3]
q - joint angle value in radians
qd –joint speed value in radians/sec
qdd –joint accel value in radians/sec/sec*

Return:

No return value



5) **void** robotinterface_command_velocity_security_torque_control_torque
(
 const double *qd,
 const double *security_torque,
 const double *control_torque,
 const double *softness
)

Purpose : *Send set(6 values for each joint) of speeds(qd), security torques, control torques and softness factors to the controller to have all the joints move with set speed and torque values.*

Parameters:

qd – joint speed values in radians/sec [j0, j1, j2, j3, j4, j5]
security torque – reference torques for safety limits
control_torque – target torques
softness – [0 to 1] gain values (stiff to soft)

Return:

No return value



UNIVERSAL ROBOTS

UR White Paper C-API, 2014

I/O interface commands



6) **void** robotinterface_command_digital_out_port(int port, int value)

Purpose : *Set any digital output between 0 and 9 to high or low*

Parameters:

port – 0 - 9

value – 0(low) or 1(high)

Return:

No return value

7) **void** robotinterface_command_digital_out_bits(unsigned short bits)

Purpose : *Set multiple digital outputs together using bit masks*

Parameters:

bits – value between 0 and 1023

e.g 1 => digital_output[0] is high.

1023 => outputs 0 through 9 are high

Return:

No return value

8) **void** robotinterface_command_analog_output_domain (int port, int type)

Purpose : *Set output for any of the 2 analog outs to current or voltage output*

Parameters:

port – 0 or 1

type – 0 => current,

1=> voltage

Return:

No return value



9) **void** robotinterface_command_analog_out_port(int port, double value)

Purpose : *Set output for any of the 2 analog outs to a value*

Parameters:

port – 0 or 1

value – current (4-20mA) or voltage(0-10v)

Return:

No return value

10) **void** robotinterface_command_analog_input_range_port(int port, int range);

Purpose : *Set analog input and input range for selected input*

Parameters:

port – 0 - 3

range– 0 => 0 to 5v

1=> 0 to 10v

2=> -5 to 5v

3=> -10 to 10v

Return:

No return value

11) **void** robotinterface_command_tool_output_voltage(unsigned char value)

Purpose : *Set output voltage at tool connector to 0,12 or 24v*

Parameters:

value – 0, 12 or 24v

Return:

No return value



UNIVERSAL ROBOTS

UR White Paper C-API, 2014

Robot state commands



12) **void** robotinterface_set_tcp(const double *tcp_pose)

Purpose : *Set TCP pose*

Parameters:

tcp_pose – list of 6 values => [x, y, z, Rx, Ry, Rz] w.r.t base

Return:

No return value

13) **void** robotinterface_set_tcp_payload_cog(const double *tcp_payload_cog)

Purpose : *Set center of gravity of payload*

Parameters:

tcp_payload_cog – list of 3 values => [x, y, z] w.r.t tool frame

Return:

No return value

14) **void** robotinterface_set_tcp_payload(double tcp_payload)

Purpose : *Set actual payload at load end of robot*

Parameters:

tcp_payload – payload in kilograms

Return:

No return value

15) **void** robotinterface_get_tcp (double *tcp_pose)

Purpose : *Retrieve current TCP pose*

Parameters:

tcp_pose – returns TCP pose as a list of 6 values

Return:

No return value



- 16) **void** robotinterface_get_tcp_payload_cog(double *tcp_pose)
Purpose : *Retrieve current settings for center of gravity co-ordinates*
Parameters:
tcp_pose – returns a list of 3 points [x, y, z]
Return:
No return value
- 17) **double** robotinterface_get_tcp_payload()
Purpose : *Retrieve current settings for robot payload*
Parameters:
No parameters to be passed
Return:
Current payload settings in kilograms
- 18) **void** robotinterface_set_tcp_wrench(
 const double *new_tcp_wrench
 const int in_base_coord
)
Purpose : *set required TCP wrench settings*
Parameters:
*new_tcp_wrench –list of 6 points force along x, y, z
 and twist about x,y and z*
in_base_coord – specifies reference frame as base
Return:
No return value



19) **void** robotinterface_get_tcp_wrench(
double *gotten_tcp_wrench
)

Purpose : *get current TCP wrench settings*

Parameters:

*gotten_tcp_wrench – returns list of 6 points, force along x, y, z
and twist about x,y and z*

Return:

No return value

20) **void** robotinterface_get_actual_position(
double *q
)

Purpose : *get current joint angles*

Parameters:

q – returns list of 6 joint angles

Return:

No return value

21) **void** robotinterface_get_actual_velocity(
double *qd
)

Purpose : *get current joint speeds*

Parameters:

qd – returns list of 6 joint speeds

Return:

No return value



22) **void** robotinterface_get_actual_current(
double *I
)

Purpose : *get joint current drawn*

Parameters:

I – returns list of 6 joint current

Return:

No return value

23) **void** robotinterface_get_tool_accelerometer_readings(
double *ax,
double *ay,
double *az,
)

Purpose : *get TCP acceleration along x y and z axes*

Parameters:

ax – acceleration along x axes

ay – acceleration along y axes

az – acceleration along z axes

Return:

No return value



UNIVERSAL ROBOTS

UR White Paper C-API, 2014



UNIVERSAL ROBOTS

UR White Paper C-API, 2014

Interface Handshake Commands



24) **int** robotinterface_open(
int open_simulated
)

Purpose : *open C-API interface*

Parameters:

open_simulated = communicate with real(0) or simulated robot

Return:

Result = 1(if simulation) else Ethernet connection message

25) **void** robotinterface_send()
Purpose : *after every control command*

Parameters:

n/a

Return:

n/a

26) **void** robotinterface_security_stop(
char joint_code
int error_state
int error_argument
)

Purpose : *to trigger a security stop*

Parameters:

joint_code – [0 to 6] base to tool

error_state – definition of error (string)

error_argument – [-1 to 10] set robotmode

Return:

n/a



RobotModes

-1	NO_CONTROLLER_MODE
0	ROBOT_RUNNING_MODE (normal state)
1	ROBOT_FREEDRIVE_MODE
2	ROBOT_READY_MODE
3	ROBOT_INITIALIZING_MODE
4	ROBOT_SECURITY_STOPPED_MODE
5	ROBOT_EMERGENCY_STOPPED_MODE
6	ROBOT_FAULT_MODE
7	ROBOT_NO_POWER_MODE
8	ROBOT_NOT_CONNECTED_MODE
9	ROBOT_SHUTDOWN_MODE
10	ROBOT_SAFEGUARD_STOP_MODE



Miscellaneous

<code>uint8_t robotinterface_get_joint_mode(int joint);</code>	pass joint ID to get joint mode as return value
<code>void robotinterface_get_motor_temperature(float *T);</code>	returns a list of 6 motor temperatures
<code>float robotinterface_get_master_temperature();</code>	returns temperature of MASTERBOARD
<code>void robotinterface_get_actual(double *q, double *qd);</code>	returns list of current joint position and joint speed
<code>void robotinterface_get_actual_current(double *I);</code>	returns list of current joint currents
<code>uint64_t robotinterface_get_step();</code>	returns step size for motor in radians (same for all motors)
<code>double robotinterface_get_time();</code>	returns current timestamp
<code>double robotinterface_get_time_per_step();</code>	returns time taken for each step (changes with speed)
<code>uint8_t robotinterface_get_robot_mode();</code>	returns current robot mode [-1 to 10 in previous page]
<code>uint8_t robotinterface_get_tool_mode();</code>	returns current tool state
<code>int robotinterface_is_power_on_robot();</code>	returns 1 if power is on
<code>int robotinterface_is_security_stopped();</code>	returns 1 if robot is security stopped
<code>int robotinterface_is_emergency_stopped();</code>	returns 1 if robot is e-stopped
<code>int robotinterface_is_power_button_pressed();</code>	returns 1 if power button is pressed on pendant
<code>void robotinterface_get_tcp_force(double *F);</code>	returns current force along x,y,z and twist about x,y,z (list of 6 values)
<code>void robotinterface_get_tcp_speed(double *V);</code>	returns linear and angular velocities at TCP (list of 6 values)
<code>float robotinterface_get_robot_voltage_48V();</code>	returns voltage on the powerbus of the robot
<code>float robotinterface_get_robot_current();</code>	returns current being drawn by the robot
<code>float robotinterface_get_master_io_current();</code>	returns current drawn by the I/Os on the MASTERBOARD
<code>unsigned char robotinterface_get_master_safety_state();</code>	returns state of the safety inputs on the MASTERBOARD



UR White Paper C-API, 2014

<code>unsigned char robotinterface_get_master_on_off_state();</code>	returns the ON/OFF state off the MASTERBOARD
<code>void robotinterface_get_micro_temperature(float *T);</code>	returns processor temperature on all joints (list of 6)
<code>void robotinterface_get_joint_voltage(float *V);</code>	returns joint voltages (list of 6)
<code>float robotinterface_get_tool_temperature();</code>	returns temperature of tool PCB
<code>float robotinterface_get_tool_voltage_48V();</code>	returns voltage across tool PCB
<code>unsigned char robotinterface_get_tool_output_voltage();</code>	returns voltage at tool output
<code>float robotinterface_get_tool_current();</code>	returns current drawn at tool