



Worstead Laboratories (Reg. Office)
North Walsham, Norfolk NR28 9SA
Tel: (0692) 405189
Telex: 97360 SHARET G
MAPCON approved consultants

oct
1 JUNE 1984

Dear Customer,

Enclosed you will find a set of bug patches for your copy of PL/9 version 3.XX.

We are about to release version 4.XX of PL/9. Details of the enhancements are enclosed.

You may purchase the upgrade for \$25.00 (if outside of the U.K.) or 18.00 pounds (plus VAT) if you are within the U.K. Further details can be found on the enclosed order form.

If you wish to purchase the upgrade follow this procedure:

1. Locate the original disk we supplied with your copy of PL/9. Make a copy of it for your archives.
2. Complete the enclosed order form. This is very important as it will be the document U.K. customs will look for if they open the parcel for inspection. The order form substantiates the fact that the software is of U.K. origin so that it will clear customs without duties or delay.
3. If you are outside of the U.K. complete the 'GREEN CUSTOMS DECLARATION', which is enclosed, as follows:

"COMPUTER SOFTWARE OF U.K. ORIGIN BEING RETURNED FOR UPGRADE"

Declare the value of the goods as: \$198.00

4. Insure the parcel for \$198.00 (the cost of replacement).
5. Post the parcel with your remittance and the enclosed order form.

NOTES

- A. YOU MUST RETURN THE ORIGINAL DISK SUPPLIED WITH YOUR COPY OF PL/9. WE WILL NOT ACCEPT ANY ORDERS FOR UPGRADES UNLESS THEY ARE ACCOMPANIED BY THE ORIGINAL DISK.
- B. If you fail to fix the customs declaration to the parcel OR complete it incorrectly OR fail to complete and enclose the order form supplied the parcel may be siezed by U.K. customs. It will then take about two to three weeks to clear it.
- C. If you fail to insure the parcel and we don't receive it you are out of luck! You will have to purchase the latest version at the full price. WE WILL NOT BE HELD RESPONSIBLE FOR THE PARCEL UNTIL IT IS IN OUR POSSESSION!
- D. The parcel MUST be accompanied with payment for the upgrade. We will NOT supply upgrades against purchase orders on an open account basis.

CHANGES TO PL/9 FOR VERSION 4.XX

1. The STACK keyword

The STACK keyword has been enhanced, while maintaining compatibility with the old version. STACK can be used either outside or inside a procedure. In the former case, its purpose is to initialise the stack pointer at the start of a program. The operand may be Immediate (as before), Program Counter Relative (also as before) and now Extended, as follows:

Immediate:

```
STACK = $BFFF;  
STACK = VALUE; (following CONSTANT VALUE = <NUMBER>)
```

These generate LDS #\$XXXX

Program Counter Relative:

```
STACK = *;      generating      LEAS *,PCR
```

Extended:

```
STACK = MEMEND; (following AT $CC2B: INTEGER MEMEND;)
```

generating LDS \$XXXX

Inside a procedure, the STACK keyword may be used on either the left or right of an expression. Its effect is to access or assign the 6809 CPU's Stack Pointer register, as in the following:

```
STACK = <Expression>;      giving      <get expression in ACCD>  
                                         TFR D,S  
  
<Variable> = STACK;      giving      TFR S,D  
                                         STD <Variable>
```

Please note that the stack is not assigned or read directly; the former statement causes <Expression> to be evaluated in the D accumulator, regardless of complexity, and copied into the Stack Pointer, while the second copies the Stack Pointer into the D accumulator before using it in an expression. The effect is that in each case the accumulator is modified. This is important in the sort of programs that need to load or save the stack pointer!

2. Code improvements

The code generated by PL/9 has been improved for INTEGER vectors, such as the previously poor

```
VECTOR(INDEX) = VECTOR(INDEX) + .....
```

Any program that uses INTEGER vectors much will see a worthwhile decrease in size, with some improvement in speed (depending if the code is in a critical area).

3. Compiler options

The compile options T, P and L can now be used in combination, e.g. printout with output to screen. The listing output is now slightly different, in that lines now end with carriage return and line feed instead of just the former. This is to help some print spoolers do their job properly.

There is now an 'R' option which forces the compiler to use the MC6809 interrupt vectors at \$FFF2 - \$FFFF in lieu of those defined by SETPL9. This enables you to use SETPL9 to configure the copy of PL/9 for your system interrupt RAM vectors. Any compilation without the 'R' option (A:0, etc) will produce overlays for the RAM vectors. If you include the 'R' option (A:0,R) the MC6809 hardware vectors will be substituted. This was previously only possible if you created two versions of the compiler using SETPL9.

The result of these changes, together with fixes for all the bugs reported for the earlier version, was to take the size of the compiler to over 16k bytes. This limit is self-imposed in order to keep as much space as possible for source and object. The solution was to remove the error messages from the body of the compiler and put them into their own file. PL9.ERR has the same structure as ERRORS.SYS and is substituted for that file by the compiler when required, a facility thoughtfully included in FLEX by TSC. The effect is to slow down error reporting by an amount depending upon the efficiency of your disc drivers. If you find this a problem you'd better not make so many errors!

This version is also accompanied by a new manual which is essentially a reorganised version of the one supplied with version 3.XX. The main changes are that the manual is now supplied in two sections, a REFERENCE manual and a USERS GUIDE. It was felt that the existing manual was simply too bulky for most peoples tastes.

Along with the reorganisation we have taken the opportunity to correct several typographical errors. We have also expanded the sections covering:

- a. POINTERS.
- b. ASMPROCS.
- c. ROM based programs.

As a result the manual now pushes 400 pages and hence the need to split it in two.

Please allow 6 weeks for delivery. Thats 3 weeks to us and 3 weeks back!

PL/9 VERSION 2.XX ... 3.XX UPGRADE ENHANCEMENTS

15 October 1983

Dear Registered PL/9 user,

Your copy of PL/9 may be upgraded to the current release. The main enhancements in the product are outlined below. Some of the enhancements will require slight modifications to the source files written for the older versions of the compiler. The main area where there are syntax differences that require modification are in the use of unsigned BYTES and INTEGERS.

VERSION 3.XX ENHANCEMENT SUMMARY

- A. The manual has been revised to 300+ pages. A complete re-organization of the manual has taken place and a massive 'USERS GUIDE' with plenty of examples is the focus of the new document. The manual has been expanded to provide a full tutorial on programming in PL/9 and now includes a full description of all of the library routines provided.
- B. Source files may now be written in upper or lower case. The compiler does not make any distinction between the case of letters however. Thus 'TEST', 'test' and 'TeSt' are all the same as far as the compiler is concerned.
- C. You now have direct access to the 'X' register in the same way as you previously had access to 'A', 'B' and 'D'. This is provided primarily to improve communication with assembly language routines.
- D. Several new forms of the 'Pointer' structure are provided:
 - .POINTER = .BUFFER(18); Compute the address of the 18th element of BUFFER and place it in the memory location reserved for pointer.
 - POINTER = BUFFER(18); Take the 18th element of BUFFER and place it in the memory location pointed to by POINTER.
 - .POINTER = .POINTER + 1; Take the value contained in the memory location reserved for pointer and increment it by one.
 - .POINTER = .POINTER(1); Step POINTER to the next element of the data it is pointing to. In the case of BYTE size data this is the same as the previous example. If the data is INTEGER then it is the same as '.POINTER = .POINTER + 2'. If the data is REAL it is the same as '.POINTER = .POINTER + 4'.
 - POINTER(5) = BUFFER(3); Take the element of data at BUFFER(3) and copy it to POINTER(5).
- E. SWI, SWI2, SWI3, and RESET procedure names (with the associated function) are now provided.
- F. The previous restrictions involving the use of 'BREAK' have been removed.

- G. The speeds of the REAL and INTEGER mathematics routines have been substantially improved.
- H. The handling of unsigned BYTE and INTEGER variables has been improved with the use of HEX notation in evaluation or assignment being taken as a desire to have the operation performed as unsigned. (no minor trick in a compiler designed to work with signed numbers!)
- I. The tracer now resides in the FLEX transient command area thus enabling many extra features to be added to it.
- J. The compiler may now be called directly from the FLEX command line to compile a program. A typical call looks like this:


```
+++PL9,1.SOURCE.PL9,0=1.OBJECT.BIN,P,C
```

Compile the program called SOURCE.PL9 to a disk object file called OBJECT.BIN make a printed listing of the compiled source with object code.
- K. A:N option produces a symbol table only. Symbol table now includes GLOBALS and their offset from the 'Y' register to assist assembly language programmers wishing to access the GLOBAL variables on the stack.

UPGRADE PROCEDURE

If you wish to take advantage of our upgrade service follow the procedure outlined below:

1. Locate the ORIGINAL disk we supplied with the product. We will only accept the original disk (with our label on it) for upgrade. This is an unbreakable company policy and has been adopted to prevent 'kloning' of the original package without introducing massive overheads into our internal procedures. The only way we can offer this service at the price is to rigidly enforce this basic rule.
2. Make a working master of the original disk and put it in a safe place. This is just in case you crash your work disk while we have the original or in case you want to continue using the old version for a while.
3. For customers outside of the U.K. the upgrade fee is \$25.00. For customers within the U.K. the upgrade fee is 18.98 pounds (15.00 + 1.50 PP + 2.48 VAT). Payment by bankers draft or international money order is preferred. Personal cheques are acceptable but they can take up to four weeks to clear. VISA/ACCESS/MASTER/EURO credit cards are all acceptable.

ALL UPGRADES MUST BE PRE-PAID. NO OPEN ACCOUNT FACILITIES ARE AVAILABLE.

3. Forward the ORIGINAL disk to us via REGISTERED post insuring it for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us. Mark the customs declaration: GOODS OF U.K. ORIGIN BEING RETURNED FOR REPAIR.
4. Unless otherwise specified the upgrade disk will be returned in the same format as the disk returned to us. If you wish to swap it for another disk size or track density PLEASE STATE YOUR REQUIREMENTS as we are not clairvoyant!
5. We will forward you the upgrade package via REGISTERED AIR MAIL within one working week of clearing your payment.

PL/9 COMPILER, VERSION 3.01 AND 3.02 BUG FIXES as at 15 OCTOBER 1983

The following patches cure all known problems with the above versions of the compiler and upgrade it to the current version; 3.03.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-301.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

The green customs declaration should state: GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR.

1. The first part of the document is a list of names and addresses.

2. The second part of the document is a list of names and addresses.

3. The third part of the document is a list of names and addresses.

4. The fourth part of the document is a list of names and addresses.

5. The fifth part of the document is a list of names and addresses.

6. The sixth part of the document is a list of names and addresses.

7. The seventh part of the document is a list of names and addresses.

8. The eighth part of the document is a list of names and addresses.

9. The ninth part of the document is a list of names and addresses.

SOFTWARE BUG REPORT

PRODUCT _____ REVISION _____ SERIAL NUMBER _____

NAME OF DEALER _____

DATE _____

NAME _____

ADDRESS _____


DESCRIBE YOUR SYSTEM HARDWARE AND ANY MODIFICATIONS YOU MAY HAVE MADE.

Describe, in detail, the problem you are having. Include examples which we can run that clearly and REPEATEDLY demonstrates the problem. The simpler the example the quicker we will be able to locate the cause of it.

Attach extra sheets or send us a SS/SD disk with upper case file names.

SEND THIS FORM AND ANY ASSOCIATED DOCUMENTATION TO:

Windrush Micro Systems, Worstead Labs., N. Walsham, Norfolk, NR28 9SA, England



TROUBLE WITH THE 'INCHNE' VECTOR?

We have encountered a lot of problems with our use of this FLEX vector located at \$D3E5. It is supposed to point to the 'INPUT CHARACTER, NEVER ECHO ROUTINE', which, like 'INCH' is supposed to strip parity.

One of the enclosed patches (Patch 8) does not need to be performed if your version of FLEX has the INCHNE vector at \$D3E5 implemented correctly. Most of the problems with our software involve SWTP versions of FLEX. Either this vector has not been implemented at all or, if it is implemented, it does not strip the parity bit out of the incoming code.

Either of these situations will result in PL/9, SETPL9, MACE, XMACE, SETMACE, and SETXMACE either locking up or crashing the system.

The root cause of the problem appears to be a revision in the FLEX I/O routine vector table that was made around 1980 by TSC. Earlier versions of FLEX started the vector table at \$D3E7 and did not have an INCHNE vector whilst the current versions start the vector table at \$D3E5 and have the INCHNE vector at this location. In most of the SWTP versions we have encountered problems with \$D3E5 points to the MC6850 ACIA location.

The best solution to the problem is to upgrade your version of FLEX to the latest version which has the INCHNE vector at \$D3E5 installed correctly. Alternatively you can build an INCHNE routine into PL/9 as described in Patch 8.

Since SETPL9 also uses the INCHNE routine (it is part of the 'IOSUBS.LIB' file) it must be recompiled once you have patched PL/9 itself. If you call PL/9 from the FLEX command line you will be able to recompile the SETPL9 program AFTER you have modified the 'GETCHAR_NOECHO' routine in the IOSUBS library as required by your system configuration. The FLEX call looks like this:

```
+++PL9,0.SETPL9.PL9,0=0.SETPL9.CMD <RETURN>
```

If your system uses 'SBUG-E', 'GMX-BUG', 'CHIEFBUG' or 'GT-BUG' or any other system monitor that has the following vector table located at \$F800 the modifications required will be quite simple.

\$F800	RESET	COLD START
\$F802	CNTRL	WARM START
\$F804	INCHNE	INPUT CHARACTER, NEVER ECHO
\$F806	INCHAE	INPUT CHARACTER, ALWAYS ECHO
\$F808	INCHECK	TEST FOR INCOMING CHARACTER (<> 0 IF CHAR IS WAITING)
\$F80A	OUTCH	OUTPUT A CHARACTER
\$F80C	PDATA	OUTPUT STRING POINTED TO BY 'X' (\$04 TERMINATES)
\$F80E	CRLF	OUTPUT CR-LF STRING
\$F810	PSTRNG	OUTPUT CR-LF FOLLOWED BY STRING POINTED TO BY 'X' (\$04 TERM)
\$F812	LRA	LOAD REAL ADDRESS (USED MAINLY BY DMA DISK CONTROLLERS)
\$F814	JMP CONTROL (not present in some monitors)	

In the above circumstances the 'GETCHAR_NOECHO' routine in IOSUBS can be modified as follows:

```
PROCEDURE GETCHAR_NOECHO;  
  GEN $AD,$9F,$F8,$04;      /* JSR [$F804]          */  
  GEN $84,$7F;              /* ANDA #$7F (STRIPS PARITY) */  
ENDPROC ACCA;
```

If you are using another system monitor you can construct an INCHNE routine as follows:

```
PROCEDURE GETCHAR_NOECHO;
  REPEAT;
    CALL $CD4E;          /* FLEX 'STAT'          */
    UNTIL CCR AND $04 = 0; /* THERE IS A KEY WAITING! */

    GEN $B6,$E0,$05;      /* LDA $E005 (READ ACIA DATA PORT) */
    GEN $84,$7F;          /* ANDA #$7F (STRIP PARITY)          */
ENDPROC ACCA;
```

In the above example we are using the FLEX 'STAT' routine to test the status of the system console keyboard. Once we have determined that a key has been pressed we then simply read the ACIA data port, strip the parity bit, and return the code in the 'A' accumulator.

We could just as easily read the data from a PIA data port or whatever I/O device you have in the system.

Patch 1

This patch fixes the problem of the wrong code being generated for pointers with constant indices.

25D1 12

Patch 2

This patch fixes the problem of the compiler crashing on an assignment split between two lines.

1E43 16
1E44 21
1E45 6E
1E46 5F
1E47 4F
1E48 DD
1E49 6D
1E4A 35
1E4B 90

399F 16
39A0 E4
39A1 A4

Patch 3

This patch fixes the problem of symbols that contain numbers being confused with symbols containing letters in the same position.

0CD6 16
0CD7 32
0CD8 F2

Patch 4

This patch fixes (yet another) problem with multiple ORIGINS, this time where accessing DATA previously located at a higher address generates the wrong code.

279E 12
279F 17
27A0 18
27A1 37
27A2 26
27A3 11

Patch 5

This patch fixes the problem of RETURN and ENDPROC not forcing INTEGER when it is specified.

1AAC 34
1AAD 04
1AAE 16
1AAF 25
1AB0 3A

Patch 6

This patch fixes the problem of ENDPROC not always cleaning up the stack properly if the last constant encountered was hex. (How about that for cause-and-effect?)

1B0C	17
1B0D	24
1B0E	E9

Patch 7

This patch fixes the problem in some versions of FLEX that the interrupt vectors IRQ and SWI3 get altered by FLEX while it is loading the tracer.

353B	17
353C	09
353D	13

3E51	EE
3E52	9F
3E53	00
3E54	07
3E55	10
3E56	AE
3E57	9F
3E58	00
3E59	0F
3E5A	34
3E5B	60
3E5C	BD
3E5D	CD
3E5E	4B
3E5F	35
3E60	60
3E61	EF
3E62	9F
3E63	00
3E64	07
3E65	10
3E66	AF
3E67	9F
3E68	00
3E69	0F
3E6A	39

Patch 8

This patch does not need to be performed in the vast majority of systems

This patch is only required in systems that use a version of FLEX that does not have the INCHNE vector at \$D3E5 installed or in versions that have the vector installed but the routine does not strip the parity bit out of the incoming code.

Most of the systems we have had problems with in this area are early SWTP 6809 systems. Since these systems all have 'SBUG-E' this patch is organized around this system monitor. The basic principle of the patch is to 're-aim' four calls in PL/9 that use the FLEX 'INCHNE' vector at \$D3E5 to a vector at \$3E70. The vector at \$3E70 (which is installed by this patch) points to a routine at \$3E72:

```
02CD  3E    (CURRENTLY D3)
02CE  70    (CURRENTLY E5)

3A29  3E    (CURRENTLY D3)
3A2A  70    (CURRENTLY E5)

3A32  3E    (CURRENTLY D3)
3A33  70    (CURRENTLY E5)

3F57  3E    (CURRENTLY D3)
3F58  70    (CURRENTLY E5)

3E70  3E    :
3E71  72    : (NEW VECTOR IN LIEU OF $D3E5)
```

Next we instal the INCHNE routine itself. This routine can take many forms but since the majority of problems appear to be in SWTP systems we are simply going to use the INCHNE vector in 'SBUG-E' itself:

```
3E72  AD    :
3E73  9F    : ( JSR [$F804] )
3E74  F8    :
3E75  04    :

3E76  84    :
3E77  7F    : ( ANDA #$7F ... STRIP PARITY )

3E78  39    : ( RTS          )
```

If your system monitor does not have an INCHNE routine that you can use you can construct one in the 14 bytes available between \$3E72 and \$3E7F as indicated in the following example:

```
3E72  BD    :
3E73  CD    : (JSR $CD4E ... 'STAT' IN FLEX)
3E74  4E    :

3E75  27    :
3E76  FB    : (BEQ $3E72 ... LOOP IF NO KEY PENDING)

3E77  B6    : (LDA DATAPORT ... IN THIS CASE AN MC6850 ACIA AT $E004      )
3E78  E0    : (Note: This could have just as easily been a PIA at $E040 by)
3E79  05    : (      using: B6, E0, 40.                                     )

3E7A  84    :
3E7B  7F    : ( ANDA #$7F ... STRIP PARITY )

3E7C  39    : ( RTS          )
```

Patch 9

This is the extra code needed for patches one (1) through seven (7). It is located at the end of the code for PL/9.

3FB4	8C	+----->	3FD9	10
3FB5	41		3FDA	83
3FB6	B3		3FDB	FF
3FB7	10		3FDC	83
3FB8	27		3FDD	2D
3FB9	DE		3FDE	09
3FBA	E7		3FDF	10
3FBB	A6		3FE0	83
3FBC	82		3FE1	00
3FBD	81		3FE2	82
3FBE	20		3FE3	2E
3FBF	27		3FE4	03
3FC0	03		3FE5	1A
3FC1	34		3FE6	04
3FC1	02		3FE7	39
3FC3	5C		3FE8	1C
3FC4	9C		3FE9	FB
3FC5	6D		3FEA	39
3FC6	22		3FEB	17
3FC7	EC		3FEC	E1
3FC8	16		3FED	5C
3FC9	DE		3FEE	6D
3FCA	85		3FEF	E0
3FCB	17		3FF0	27
3FCC	CE		3FF1	03
3FCD	54		3FF2	17
3FCE	10		3FF3	DD
3FCF	26		3FF4	14
3FD0	CD		3FF5	16
3FD1	1C		3FF6	DA
3FD2	8B		3FF7	CE
3FD3	20		3FF8	0F
3FD4	A1		3FF9	22
3FD5	3F		3FFA	16
3FD6	16		3FFB	CE
3FD7	CD		3FFC	67
3FD8	01 >-----+			

Patch 10

These final patches change the version number to 3.03 and modify the the END of PL/9 pointer (used by 'SETPL9') to point to the new end of the PL/9 code defined by these patches.

005A 33
006E 3F
006F FC

PL/9 COMPILER, VERSION 3.03 BUG FIXES as at 15 NOVEMBER 1983

The following patches cure all known problems with the above versions of the compiler and upgrade it to the current version; 3.04.

If you have versions 3.01 or 3.02 you must incorporate all of the modifications outlined on the previous 'bug-patches' letter before incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-303.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

The green customs declaration should state: GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR.

SOFTWARE BUG REPORT

PRODUCT _____ REVISION _____ SERIAL NUMBER _____

NAME OF DEALER _____

DATE _____

NAME _____

ADDRESS _____

DESCRIBE YOUR SYSTEM HARDWARE AND ANY MODIFICATIONS YOU MAY HAVE MADE.

Describe, in detail, the problem you are having. Include examples which we can run that clearly and REPEATEDLY demonstrates the problem. The simpler the example the quicker we will be able to locate the cause of it.

Attach extra sheets or send us a SS/SD disk with upper case file names.

SEND THIS FORM AND ANY ASSOCIATED DOCUMENTATION TO:

Windrush Micro Systems - Worstead Labs. - N. Walsham - Norfolk - NP28 9SA - England

TROUBLE WITH THE 'INCHNE' VECTOR?

We have encountered a lot of problems with our use of this FLEX vector located at \$D3E5. It is supposed to point to the 'INPUT CHARACTER, NEVER ECHO ROUTINE', which, like 'INCH' is supposed to strip parity.

One of the enclosed patches (Patch 1) does not need to be performed if your version of FLEX has the INCHNE vector at \$D3E5 implemented correctly. Most of the problems with our software involve SWTP versions of FLEX. Either this vector has not been implemented at all or, if it is implemented, it does not strip the parity bit out of the incoming code.

Either of these situations will result in PL/9, SETPL9, MACE, XMACE, SETMACE, and SETXMACE either locking up or crashing the system.

The root cause of the problem appears to be a revision in the FLEX I/O routine vector table that was made around 1980 by TSC. Earlier versions of FLEX started the vector table at \$D3E7 and did not have an INCHNE vector whilst the current versions start the vector table at \$D3E5 and have the INCHNE vector at this location. In most of the SWTP versions we have encountered problems with \$D3E5 points to the MC6850 ACIA location.

The best solution to the problem is to upgrade your version of FLEX to the latest version which has the INCHNE vector at \$D3E5 installed correctly. Alternatively you can build an INCHNE routine into PL/9 as described in Patch 8.

Since SETPL9 also uses the INCHNE routine (it is part of the 'IOSUBS.LIB' file) it must be recompiled once you have patched PL/9 itself. If you call PL/9 from the FLEX command line you will be able to recompile the SETPL9 program AFTER you have modified the 'GETCHAR NOECHO' routine in the IOSUBS library as required by your system configuration. The FLEX call looks like this:

```
+++PL9,0.SETPL9.PL9,0=0.SETPL9.CMD <RETURN>
```

If your system uses 'SBUG-E', 'GMX-BUG', 'CHIEFBUG' or 'GT-BUG' or any other system monitor that has the following vector table located at \$F800 the modifications required will be quite simple.

\$F800	RESET	COLD START
\$F802	CNTRL	WARM START
\$F804	INCHNE	INPUT CHARACTER, NEVER ECHO
\$F806	INCHAE	INPUT CHARACTER, ALWAYS ECHO
\$F808	INCHECK	TEST FOR INCOMING CHARACTER (<> 0 IF CHAR IS WAITING)
\$F80A	OUTCH	OUTPUT A CHARACTER
\$F80C	PDATA	OUTPUT STRING POINTED TO BY 'X' (\$04 TERMINATES)
\$F80E	CRLF	OUTPUT CR-LF STRING
\$F810	PSTRNG	OUTPUT CR-LF FOLLOWED BY STRING POINTED TO BY 'X' (\$04 TERM)
\$F812	LRA	LOAD REAL ADDRESS (USED MAINLY BY DMA DISK CONTROLLERS)

\$F814 JMP CONTROL (not present in some monitors)

In the above circumstances the 'GETCHAR_NOECHO' routine in IOSUBS can be modified as follows:

```
PROCEDURE GETCHAR NOECHO;  
  GEN $AD,$9F,$F8,$04;      /* JSR [$F804]          */  
  GEN $84,$7F;              /* ANDA #$7F (STRIPS PARITY) */  
ENDPROC ACCA;
```

If you are using another system monitor you can construct an INCHNE routine as follows:

```
PROCEDURE GETCHAR_NOECHO;  
  REPEAT;  
    CALL $CD4E;          /* FLEX 'STAT'          */  
    UNTIL CCR AND $04 = 0; /* THERE IS A KEY WAITING! */  
  
    GEN $B6,$E0,$05;      /* LDA $E005 (READ ACIA DATA PORT) */  
    GEN $84,$7F;          /* ANDA #$7F (STRIP PARITY)          */  
ENDPROC ACCA;
```

In the above example we are using the FLEX 'STAT' routine to test the status of the system console keyboard. Once we have determined that a key has been pressed we then simply read the ACIA data port, strip the parity bit, and return the code in the 'A' accumulator.

We could just as easily read the data from a PIA data port or whatever I/O device you have in the system.

Patch 1

This patch does not need to be performed in the vast majority of systems

This patch is only required in systems that use a version of FLEX that does not have the INCHNE vector at \$D3E5 installed or in versions that have the vector installed but the routine does not strip the parity bit out of the incoming code.

Most of the systems we have had problems with in this area are early SWTP 6809 systems. Since these systems all have 'SBUG-E' this patch is organized around this system monitor. The basic principle of the patch is to 're-aim' four calls in PL/9 that use the FLEX 'INCHNE' vector at \$D3E5 to a vector at \$3E70. The vector at \$3E70 (which is installed by this patch) points to a routine at \$3E72:

```
02CD  3E    (CURRENTLY D3)
02CE  70    (CURRENTLY E5)

3A29  3E    (CURRENTLY D3)
3A2A  70    (CURRENTLY E5)

3A32  3E    (CURRENTLY D3)
3A33  70    (CURRENTLY E5)

3F57  3E    (CURRENTLY D3)
3F58  70    (CURRENTLY E5)

3E70  3E    :
3E71  72    : (NEW VECTOR IN LIEU OF $D3E5)
```

Next we instal the INCHNE routine itself. This routine can take many forms but since the majority of problems appear to be in SWTP systems we are simply going to use the INCHNE vector in 'SBUG-E' itself:

```
3E72  AD    :
3E73  9F    : ( JSR [$F804] )
3E74  F8    :
3E75  04    :

3E76  84    :
3E77  7F    : ( ANDA #$7F ... STRIP PARITY )

3E78  39    : ( RTS          )
```

If your system monitor does not have an INCHNE routine that you can use you can construct one in the 14 bytes available between \$3E72 and \$3E7F as indicated in the following example:

```
3E72  BD    :
3E73  CD    : (JSR $CD4E ... 'STAT' IN FLEX)
3E74  4E    :

3E75  27    :
3E76  FB    : (BEQ $3E72 ... LOOP IF NO KEY PENDING)

3E77  B6    : (LDA DATAPORT ... IN THIS CASE AN MC6850 ACIA AT $E004      )
3E78  E0    : (Note: This could have just as easily been a PIA at $E040 by)
3E79  05    : (      using: B6, E0, 40.                                     )

3E7A  84    :
3E7B  7F    : ( ANDA #$7F ... STRIP PARITY )

3E7C  39    : ( RTS          )
```

Patch 2

This patch fixes the problem of the compiler crashing when it encounters an error in a call to a procedure using a subscripted pointer.

1657	16
1658	00
1659	5B

Patch 3

This patch fixes the problem of F!/string or C!/string either not working or crashing the compiler.

0409	CC
040A	FF
040B	FF
040C	DD
040D	0C
040E	30
040F	01
0410	39

Patch 4

This final patch changes the version number to 3.04.

005A	34
------	----

PL/9 COMPILER, VERSION 3.04 BUG FIXES as at 1 DECEMBER 1983

The following patches cure all known problems with the above versions of the compiler and upgrade it to the current version; 3.05.

If you have versions 3.01, 3.02 or 3.03 you must incorporate all of the modifications outlined on the previous 'bug-patches' letters before incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-304.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

The green customs declaration should state: GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR.

TROUBLE WITH THE 'INCHNE' VECTOR?

We have encountered a lot of problems with our use of this FLEX vector located at \$D3E5. It is supposed to point to the 'INPUT CHARACTER, NEVER ECHO ROUTINE', which, like 'INCH' is supposed to strip parity.

One of the enclosed patches (Patch 1) does not need to be performed if your version of FLEX has the INCHNE vector at \$D3E5 implemented correctly. Most of the problems with our software involve SWTP versions of FLEX. Either this vector has not been implemented at all or, if it is implemented, it does not strip the parity bit out of the incoming code.

Either of these situations will result in PL/9, SETPL9, MACE, XMACE, SETMACE, and SETXMACE either locking up or crashing the system.

The root cause of the problem appears to be a revision in the FLEX I/O routine vector table that was made around 1980 by TSC. Earlier versions of FLEX started the vector table at \$D3E7 and did not have an INCHNE vector whilst the current versions start the vector table at \$D3E5 and have the INCHNE vector at this location. In most of the SWTP versions we have encountered problems with \$D3E5 points to the MC6850 ACIA location.

The best solution to the problem is to upgrade your version of FLEX to the latest version which has the INCHNE vector at \$D3E5 installed correctly. Alternatively you can build an INCHNE routine into PL/9 as described in Patch 8.

Since SETPL9 also uses the INCHNE routine (it is part of the 'IOSUBS.LIB' file) it must be recompiled once you have patched PL/9 itself. If you call PL/9 from the FLEX command line you will be able to recompile the SETPL9 program AFTER you have modified the 'GETCHAR NOECHO' routine in the IOSUBS library as required by your system configuration. The FLEX call looks like this:

```
+++PL9,0.SETPL9.PL9,0=0.SETPL9.CMD <RETURN>
```

If your system uses 'SBUG-E', 'GMX-BUG', 'CHIEFBUG' or 'GT-BUG' or any other system monitor that has the following vector table located at \$F800 the modifications required will be quite simple.

\$F800	RESET	COLD START
\$F802	CNTRL	WARM START
\$F804	INCHNE	INPUT CHARACTER, NEVER ECHO
\$F806	INCHAE	INPUT CHARACTER, ALWAYS ECHO
\$F808	INCHECK	TEST FOR INCOMING CHARACTER (<> 0 IF CHAR IS WAITING)
\$F80A	OUTCH	OUTPUT A CHARACTER
\$F80C	PDATA	OUTPUT STRING POINTED TO BY 'X' (\$04 TERMINATES)
\$F80E	CRLF	OUTPUT CR-LF STRING
\$F810	PSTRNG	OUTPUT CR-LF FOLLOWED BY STRING POINTED TO BY 'X' (\$04 TERM)
\$F812	LRA	LOAD REAL ADDRESS (USED MAINLY BY DMA DISK CONTROLLERS)
\$F814	JMP CONTROL	(not present in some monitors)

In the above circumstances the 'GETCHAR_NOECHO' routine in IOSUBS can be modified as follows:

```
PROCEDURE GETCHAR NOECHO;  
  GEN $AD,$9F,$F8,$04;          /* JSR [$F804]          */  
  GEN $84,$7F;                  /* ANDA #$7F (STRIPS PARITY) */  
ENDPROC ACCA;
```

If you are using another system monitor you can construct an INCHNE routine as follows:

```
PROCEDURE GETCHAR _NOECHO;  
  REPEAT;  
    CALL $CD4E;          /* FLEX 'STAT' */  
    UNTIL CCR AND $04 = 0; /* THERE IS A KEY WAITING! */  
  
    GEN $B6,$E0,$05;      /* LDA $E005 (READ ACIA DATA PORT) */  
    GEN $84,$7F;          /* ANDA #$7F (STRIP PARITY) */  
ENDPROC ACCA;
```

In the above example we are using the FLEX 'STAT' routine to test the status of the system console keyboard. Once we have determined that a key has been pressed we then simply read the ACIA data port, strip the parity bit, and return the code in the 'A' accumulator.

We could just as easily read the data from a PIA data port or whatever I/O device you have in the system.

Patch 1

This patch does not need to be performed in the vast majority of systems

This patch is only required in systems that use a version of FLEX that does not have the INCHNE vector at \$D3E5 installed or in versions that have the vector installed but the routine does not strip the parity bit out of the incoming code.

Most of the systems we have had problems with in this area are early SWTP 6809 systems. Since these systems all have 'SBUG-E' this patch is organized around this system monitor. The basic principle of the patch is to 're-aim' four calls in PL/9 that use the FLEX 'INCHNE' vector at \$D3E5 to a vector at \$3E70. The vector at \$3E70 (which is installed by this patch) points to a routine at \$3E72:

```
02CD  3E    (CURRENTLY D3)
02CE  70    (CURRENTLY E5)

3A29  3E    (CURRENTLY D3)
3A2A  70    (CURRENTLY E5)

3A32  3E    (CURRENTLY D3)
3A33  70    (CURRENTLY E5)

3F57  3E    (CURRENTLY D3)
3F58  70    (CURRENTLY E5)

3E70  3E    :
3E71  72    : (NEW VECTOR IN LIEU OF $D3E5)
```

Next we instal the INCHNE routine itself. This routine can take many forms but since the majority of problems appear to be in SWTP systems we are simply going to use the INCHNE vector in 'SBUG-E' itself:

```
3E72  AD    :
3E73  9F    : ( JSR [$F804] )
3E74  F8    :
3E75  04    :

3E76  84    :
3E77  7F    : ( ANDA #$7F ... STRIP PARITY )

3E78  39    : ( RTS          )
```

If your system monitor does not have an INCHNE routine that you can use you can construct one in the 14 bytes available between \$3E72 and \$3E7F as indicated in the following example:

```
3E72  BD    :
3E73  CD    : (JSR $CD4E ... 'STAT' IN FLEX)
3E74  4E    :

3E75  27    :
3E76  FB    : (BEQ $3E72 ... LOOP IF NO KEY PENDING)

3E77  B6    : (LDA DATAPORT ... IN THIS CASE AN MC6850 ACIA AT $E004      )
3E78  E0    : (Note: This could have just as easily been a PIA at $E040 by)
3E79  05    : (      using: B6, E0, 40.                                     )

3E7A  84    :
3E7B  7F    : ( ANDA #$7F ... STRIP PARITY )

3E7C  39    : ( RTS          )
```

Patch 2

This patch fixes the problem with ENDPROC END not adjusting the stack properly if local variables have been used in the procedure.

1A74	17
1A75	23
1A76	F4
1A77	27
1A78	08
1A79	8D
1A7A	74

3E6B	DC
3E6C	12
3E6D	D3
3E6E	10
3E6F	39

Patch 3

This final patch changes the version number to 3.04.

005A	35
------	----

PL/9 COMPILER, VERSION 3.05 BUG FIXES as at 1 JANUARY 1983

The following patches cure all known problems with the above versions of the compiler and upgrade it to the current version; 3.06.

If you have versions 3.01, 3.02, 3.03 or 3.04 you must incorporate all of the modifications outlined on the previous 'bug-patches' letters (which will bring your copy of PL/9 up to version 3.05) BEFORE incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-305.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

CUSTOMERS OUTSIDE OF THE U.K. PLEASE NOTE

You must affix a customs declaration to the parcel/envelope containing the disk. The description of contents should state:

GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR.

If you fail to do this we have to process additional paperwork to clear the disk through customs and as a duty exempt import. This process usually takes two to three weeks!

SOFTWARE BUG REPORT

PRODUCT _____ REVISION _____ SERIAL NUMBER _____

NAME OF DEALER _____

DATE _____

NAME _____

ADDRESS _____

DESCRIBE YOUR SYSTEM HARDWARE AND ANY MODIFICATIONS YOU MAY HAVE MADE.

Describe, in detail, the problem you are having. Include examples which we can run that clearly and REPEATEDLY demonstrates the problem. The simpler the example the quicker we will be able to locate the cause of it.

Attach extra sheets or send us a SS/SD disk with upper case file names.

SEND THIS FORM AND ANY ASSOCIATED DOCUMENTATION TO:

Windrush Micro Systems, Worstead Labs., N. Walsham, Norfolk, NR28 9SA, England

TROUBLE WITH THE 'INCHNE' VECTOR?

We have encountered a lot of problems with our use of this FLEX vector located at \$D3E5. It is supposed to point to the 'INPUT CHARACTER, NEVER ECHO ROUTINE', which, like 'INCH' is supposed to strip parity.

One of the enclosed patches (Patch 1) does not need to be performed if your version of FLEX has the INCHNE vector at \$D3E5 implemented correctly. Most of the problems with our software involve SWTP versions of FLEX. Either this vector has not been implemented at all or, if it is implemented, it does not strip the parity bit out of the incoming code.

Either of these situations will result in PL/9, SETPL9, MACE, XMACE, SETMACE, and SETXMACE either locking up or crashing the system.

The root cause of the problem appears to be a revision in the FLEX I/O routine vector table that was made around 1980 by TSC. Earlier versions of FLEX started the vector table at \$D3E7 and did not have an INCHNE vector whilst the current versions start the vector table at \$D3E5 and have the INCHNE vector at this location. In most of the SWTP versions we have encountered problems with \$D3E5 points to the MC6850 ACIA location.

The best solution to the problem is to upgrade your version of FLEX to the latest version which has the INCHNE vector at \$D3E5 installed correctly. Alternatively you can build an INCHNE routine into PL/9 as described in Patch 8.

Since SETPL9 also uses the INCHNE routine (it is part of the 'IOSUBS.LIB' file) it must be recompiled once you have patched PL/9 itself. If you call PL/9 from the FLEX command line you will be able to recompile the SETPL9 program AFTER you have modified the 'GETCHAR_NOECHO' routine in the IOSUBS library as required by your system configuration. The FLEX call looks like this:

```
+++PL9,0.SETPL9.PL9,0=0.SETPL9.CMD <RETURN>
```

If your system uses 'SBUG-E', 'GMX-BUG', 'CHIEFBUG' or 'GT-BUG' or any other system monitor that has the following vector table located at \$F800 the modifications required will be quite simple.

\$F800	RESET	COLD START
\$F802	CNTRL	WARM START
\$F804	INCHNE	INPUT CHARACTER, NEVER ECHO
\$F806	INCHAE	INPUT CHARACTER, ALWAYS ECHO
\$F808	INCHECK	TEST FOR INCOMING CHARACTER (<> 0 IF CHAR IS WAITING)
\$F80A	OUTCH	OUTPUT A CHARACTER
\$F80C	PDATA	OUTPUT STRING POINTED TO BY 'X' (\$04 TERMINATES)
\$F80E	CRLF	OUTPUT CR-LF STRING
\$F810	PSTRNG	OUTPUT CR-LF FOLLOWED BY STRING POINTED TO BY 'X' (\$04 TERM)
\$F812	LRA	LOAD REAL ADDRESS (USED MAINLY BY DMA DISK CONTROLLERS)
\$F814	JMP CONTROL	(not present in some monitors)

In the above circumstances the 'GETCHAR_NOECHO' routine in IOSUBS can be modified as follows:

```
PROCEDURE GETCHAR_NOECHO;  
  GEN $AD,$9F,$F8,$04;      /* JSR [$F804]          */  
  GEN $84,$7F;              /* ANDA #$7F (STRIPS PARITY) */  
ENDPROC ACCA;
```

If you are using another system monitor you can construct an INCHNE routine as follows:

PROCEDURE GETCHAR_NOECHO;

REPEAT;

CALL \$CD4E;

/* FLEX 'STAT' */

*/

UNTIL CCR AND \$04 = 0;

/* THERE IS A KEY WAITING! */

*/

GEN \$B6,\$E0,\$05;

/* LDA \$E005 (READ ACIA DATA PORT) */

*/

GEN \$84,\$7F;

/* ANDA #\$7F (STRIP PARITY) */

*/

ENDPROC ACCA;

In the above example we are using the FLEX 'STAT' routine to test the status of the system console keyboard. Once we have determined that a key has been pressed we then simply read the ACIA data port, strip the parity bit, and return the code in the 'A' accumulator.

We could just as easily read the data from a PIA data port or whatever I/O device you have in the system.

Patch 1

This patch does not need to be performed in the vast majority of systems

This patch is only required in systems that use a version of FLEX that does not have the INCHNE vector at \$D3E5 installed or in versions that have the vector installed but the routine does not strip the parity bit out of the incoming code.

Most of the systems we have had problems with in this area are early SWTP 6809 systems. Since these systems all have 'SBUG-E' this patch is organized around this system monitor. The basic principle of the patch is to 're-aim' four calls in PL/9 that use the FLEX 'INCHNE' vector at \$D3E5 to a vector at \$3E70. The vector at \$3E70 (which is installed by this patch) points to a routine at \$3E72:

```
02CD  3E    (CURRENTLY D3)
02CE  70    (CURRENTLY E5)

3A29  3E    (CURRENTLY D3)
3A2A  70    (CURRENTLY E5)

3A32  3E    (CURRENTLY D3)
3A33  70    (CURRENTLY E5)

3F57  3E    (CURRENTLY D3)
3F58  70    (CURRENTLY E5)

3E70  3E    :
3E71  72    : (NEW VECTOR IN LIEU OF $D3E5)
```

Next we instal the INCHNE routine itself. This routine can take many forms but since the majority of problems appear to be in SWTP systems we are simply going to use the INCHNE vector in 'SBUG-E' itself:

```
3E72  AD    :
3E73  9F    : ( JSR [$F804] )
3E74  F8    :
3E75  04    :

3E76  84    :
3E77  7F    : ( ANDA #$7F ... STRIP PARITY )

3E78  39    : ( RTS          )
```

If your system monitor does not have an INCHNE routine that you can use you can construct one in the 14 bytes available between \$3E72 and \$3E7F as indicated in the following example:

```
3E72  BD    :
3E73  CD    : (JSR $CD4E ... 'STAT' IN FLEX)
3E74  4E    :

3E75  27    :
3E76  FB    : (BEQ $3E72 ... LOOP IF NO KEY PENDING)

3E77  B6    : (LDA DATAPORT ... IN THIS CASE AN MC6850 ACIA AT $E004      )
3E78  E0    : (Note: This could have just as easily been a PIA at $E040 by)
3E79  05    : (      using: B6, E0, 40.                                     )

3E7A  84    :
3E7B  7F    : ( ANDA #$7F ... STRIP PARITY )

3E7C  39    : ( RTS          )
```

Patch 2

This patch fixes problems associated with comparisons of unsigned integers.

1FFD 16
1FFE 14
1FFF 08

349E 59	+	----->	34D0 33
349F 4F			34D1 20
34A0 55		34D2 2A	
34A1 27		34D3 2A	
34A2 52		34D4 2A	
34A3 45		34D5 0D	
34A4 20		34D6 0A	
34A5 4F		34D7 04	
34A6 4E		34D8 0D	
34A7 20		34D9 1C	
34A8 59		34DA 27	
34A9 4F		34DB 09	
34AA 55		34DC 30	
34AB 52		34DD 8C	
34AC 20		34DE 0C	
34AD 4F		34DF 17	
34AE 57		34E0 EE	
34AF 4E		34E1 83	
34B0 20		34E2 16	
34B1 4E		34E3 EE	
34B2 4F		34E4 36	
34B3 57		34E5 17	
34B4 21		34E6 EE	
34B5 0D		34E7 3F	
34B6 0A		34E8 16	
34B7 2A		34E9 EB	
34B8 2A		34EA 15	
34B9 2A		34EB 02	
34BA 20		34EC 34	
34BB 52		34ED 06	
34BC 45		34EE 02	
34BD 2D		34EF EC	
34BE 45		34F0 62	
34BF 4E		34F1 02	
34C0 54		34F2 A3	
34C1 45	34F3 E4		
34C2 52	34F4 02		
34C3 20	34F5 32		
34C4 50	34F6 64		
34C5 4C	34F7 00		
34C6 2F			
34C7 39			
34C8 20			
34C9 41			
34CA 54			
34CB 20			
34CC 24			
34CD 30			
34CE 30			
34CF 30			

(most of this 'code' is used to shorten the banner printed by PL/9 when entering the system monitor to make room for the additional program code required for this bug-fix which starts at \$34D8)

Patch 3

This final patch changes the version number to 3.06.

PL/9 COMPILER, VERSION 3.06 BUG FIXES as at 20 FEBRUARY 1983

The following patches cure all known problems with the above version of the compiler and upgrade it to the current version; 3.07.

If you have versions 3.01, 3.02, 3.03, 3.04 or 3.04 you must incorporate all of the modifications outlined on the previous 'bug-patches' letters (which will bring your copy of PL/9 up to version 3.06) BEFORE incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-306.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

CUSTOMERS OUTSIDE OF THE U.K. PLEASE NOTE

You must affix a customs declaration to the parcel/envelope containing the disk. The description of contents should state:

GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR.

If you fail to do this we have to process additional paperwork to clear the disk through customs and as a duty exempt import. This process usually takes two to three weeks!

Patch 1

This patch fixes a bug in the compiler routine which scans the source line for a number or a constant. The symptoms of this bug are generally as obscure as the above description.

0D76	26
0D77	1F

0D92	32
0D93	61
0D94	10
0D95	9E
0D96	6B
0D97	16
0D98	27
0D99	5E

34F8	A6
34F9	A4
34FA	81
34FB	27
34FC	10
34FD	26
34FE	D8
34FF	9F
3500	31
3501	21
3502	16
3503	D8
3504	95

Patch 2

This patch prevents PL/9 from appending a control-Z to the output file when (S)aving or (W)riting.

35A3	20
35A4	31

Patch 3

This final patch changes the version number to 3.07.

005A	37
------	----

The following patches cure all known problems with the above version of the compiler and upgrade it to the current version; 3.08.

If you have versions 3.01, 3.02, 3.03, 3.04, 3.05 or 3.06 you must incorporate all of the modifications outlined on the previous 'bug-patches' letters (which will bring your copy of PL/9 up to version 3.07) BEFORE incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the enclosed 'BUG REPORT' and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-307.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

CUSTOMERS OUTSIDE OF THE U.K. PLEASE NOTE

You must affix a customs declaration to the parcel/envelope containing the disk. The description of contents should state:

GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR

If you fail to do this we have to process additional paperwork to clear the disk through customs and as a duty exempt import. This process usually takes two to three weeks!

IF YOU DEVELOP YOUR PROGRAMS IN A SEPERATE EDITOR

If you prepare text for PL/9 in an editor other than the resident editor you must ensure that the line length never exceeds 127 characters. If you exceed this line length the compiler will crash as only 127 characters have been reserved on the stack for the line buffer during program compilation. The resident editor it will not allow you to enter a line longer than 127 characters and hence the reason why the compiler does not check line length.

Patch 1

This patch fixes a bug reported by Brutech of Holland. If a forward branch fixup (indicated on the A:C,T listing by a parenthesised entry) occurs at the point that a block of binary is about to be written to disc, the data in the binary file may be incorrect. The patch is fairly lengthy - our apologies!

3BB8	34	+----->	3BE2	5D
3BB9	36		3BE3	26
3BBA	DC		3BE4	06
3BBB	14		3BE5	DC
3BBC	93		3BE6	14
3BBD	B8		3BE7	D3
3BBE	25		3BE8	54
3BBF	19		3BE9	ED
3BC0	10		3BEA	1D
3BC1	83		3BEB	6C
3BC2	01		3BEC	1F
3BC3	FE		3BED	D6
3BC4	24		3BEE	74
3BC5	0E		3BEF	C1
3BC6	8E		3BF0	01
3BC7	43		3BF1	26
3BC8	F0		3BF2	16
3BC9	30		3BF3	E6
3BCA	8B		3BF4	1F
3BCB	A6		3BF5	27
3BCC	E4		3BF6	12
3BCD	A7		3BF7	31
3BCE	84		3BF8	1D
3BCF	8E		3BF9	86
3BD0	45		3BFA	02
3BD1	F1		3BFB	17
3BD2	20		3BFC	00
3BD3	1F		3BFD	95
3BD4	17		3BFE	CB
3BD5	00		3BFF	03
3BD6	CB		3C00	17
3BD7	20		3C01	00
3BD8	E1		3C02	8E
3BD9	8E		3C03	5A
3BDA	45		3C04	26
3BDB	F1		3C05	FA
3BDC	E6		3C06	7F
3BDD	1F		3C07	45
3BDE	A6		3C08	F0
3BDF	E4		3C09	35
3BE0	A7		3COA	B6
3BE1	85	----->+		

Patch 2

This final patch changes the version number to 3.08.

The following patches cure all known problems with the above version of the compiler and upgrade it to the current version; 3.09.

If you have versions 3.01, 3.02, 3.03, 3.04, 3.05, 3.06 or 3.07 you must incorporate all of the modifications outlined on the previous 'bug-patches' letters (which will bring your copy of PL/9 up to version 3.08) BEFORE incorporating these patches.

If you are aware of any other problems we would be most obliged if you would complete the 'BUG REPORT' form supplied with your copy of PL/9 and return it to us. We will endeavor to fix any reported bug that we can verify within three weeks.

To implement the patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 object code into memory:

```
+++GET,0.PL9.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9.CMD as follows:

```
+++RENAME,0.PL9.CMD,0.PL9-30S.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE' command as follows:

```
+++SAVE,0.PL9.CMD,0000,3FFC,0000 <RETURN>
```

NOTE TO NON-ASSEMBLY LANGUAGE PROGRAMMERS

If you do not feel competent to perform these patches (not everybody is comfortable at machine code level) you are welcome to return your original disk to us and we will perform them for you free of charge. We will turn the disk around within five working days.

The original disk must be returned via REGISTERED post and insured for the full purchase price of the product. We will not accept any responsibility for disks that fail to reach us.

CUSTOMERS OUTSIDE OF THE U.K. PLEASE NOTE

You must affix a customs declaration to the parcel/envelope containing the disk. The description of contents should state:

GOODS OF U.K. ORIGIN BEING RETURNED FOR WARRANTY REPAIR

If you fail to do this we have to process additional paperwork to clear the disk through customs and as a duty exempt import. This process usually takes two to three weeks!

Patch 1

This patch changes the version number of PL/9 to 3.09. There are no actual bugs in the compiler itself. The bug lies in the TRACER but we keep track of revision levels in any part of the compiler in the compilers version number, hence the need for this patch. To implement this patch follow the instructions on the first sheet.

005A 39

Patch 2

NOTE: This patch applies to the file 'PL9_TD.CMD' NOT the file 'PL9.CMD'.

This patch fixes the problem of breakpoints not working when the R command is used.

C23E	0D
C23F	BE
C240	27
C241	0B
C242	0D
C243	BC
C244	27
C245	42
C246	DC
C247	C2
C248	26
C249	03

C167 31

To implement the above patches follow this procedure:

1. Use the FLEX 'GET' command to load the PL/9 TRACER object code into memory:

```
+++GET,0.PL9_TD.CMD <RETURN>
```

2. Use the FLEX 'RENAME' command to change the name of the old PL9_TD.CMD as follows:

```
+++RENAME,0.PL9_TD.CMD,0.PL9_TD8.CMD <RETURN>
```

3. Use your system monitor memory examine and change command to implement the patches by altering the contents of the various memory locations as indicated.

4. Once all of the patches have been made (make sure you get it right!) save the binary out to disk using the FLEX 'SAVE.LOW' command as follows:

```
+++SAVE.LOW,0.PL9_TD.CMD,C100,C556,CD03 <RETURN>
```

COPYRIGHT NOTICE

The entire contents of this manual and the accompanying software have been copyrighted by Windrush Micro Systems Limited and its author. The reproduction of this material by any means, for any reason, is strictly prohibited.

SERIAL NUMBER NOTICE

This product has been assigned a unique serial number at the time of manufacture. This serial number is encrypted into the body of the product. This product is therefore traceable to the original purchaser in the event of plagiarized copies being discovered.

This product is sold on the basis of being used on a SINGLE microcomputer system by a SINGLE user.

We shall consider it to be an attempt to criminally plagiarize us if duplicate copies of this manual or the accompanying disk are made available for use by other parties, or on other microcomputers. This consideration also applies to, but is not limited to, duplicate copies being produced for use within the original purchasers organisation, establishment, or home for anything other than archival purposes.

WARNING

We at Windrush Micro Systems Limited and the author consider the recognition we receive as a result of the sale of our programs and manuals to be of vital importance in remaining in business.

Unless written arrangements to the contrary have been made between authorized agents of Windrush Micro Systems Limited and the purchaser of this manual and the accompanying computer program we shall consider it to be an attempt to criminally plagiarize us if our company name, the program name, or the authors name is altered, changed or removed on or from any of the materials purchased from us regardless of the means by which accomplished. This consideration shall include, but not be limited to, the re-writing of this manual, or its reproduction for distribution under another company, program or trade name, or any like modification of the accompanying computer program.

WARRANTY NOTICE

Although every effort has been made to insure the accuracy of this material, it is sold AS IS and without warranty. No claim as to the suitability or workability of this material for any particular application or on any particular computer is made. This statement is in lieu of any other statement whether expressed or implied.

W A R N I N G

We at Windrush Micro Systems Limited are in the business of selling and supporting software NOT rebuilding disks crashed by carelessness.

The first thing you should do with the disk(s) we supply is to make a working copy of it on a system known to be performing properly. Once this has been done the original disks should be stored in a safe place.

You should NEVER use the original disk in a system that you suspect has hardware problems ... it can prove to be very expensive if you do!

If you accidentally wipe out the disk we supply we will REQUIRE that you return the disk(s) supplied with this product; disks other than those bearing our labels WILL NOT BE ACCEPTED. The disk(s) MUST be returned via REGISTERED mail with a cheque or money order for \$25.00 (15.00 Pounds Sterling + VAT in U.K.). This is to cover our costs in rebuilding the disk and the return postage. This will prove to be a time consuming exercise at the best of times.

THERE ARE NO EXCEPTIONS TO THIS POLICY

```
* * * * *
*
*   DON'T EVER USE THE DISK WE SUPPLY FOR ANYTHING OTHER THAN
*   MAKING A WORKING COPY OF ITSELF ON A KNOWN GOOD MACHINE!!
*
* * * * *
```

A N O T H E R W A R N I N G

Whenever you wish to return a disk to us for a product enhancement upgrade you MUST return the original disk we supplied with this product via REGISTERED mail insured for the full value of the new product. If the disk fails to reach us you then can make a claim and recover the cost of the product and purchase a new one. If you send the disk to us by any other means and it fails to reach us you will have to purchase the product all over again. We cannot, and will not, be held responsible for losses outside of our control.

We will not accept any reason for your inability to return the original disk. Therefore take whatever steps you consider necessary to protect the disk from theft, flood, fire, your cat/dog/budgie, mother-in-law, etc. The only way we can keep the cost of our upgrade service down to \$25.00 is to eliminate administrative overheads. We do this by ONLY upgrading original disks.

```
* * * * *
*
*   THERE ARE NO EXCEPTIONS TO THIS POLICY EITHER
*
* * * * *
```

If you purchase this product through a dealer and he has had to copy it from our original disk onto another disk for compatibility with your hardware ENSURE that you get our original disk from the dealer.

We apologize for the harshness of the wording in these warnings. From our past experience in these areas it seems that abruptness is the only way we can drive home the fact that we must follow rigid procedures that prevent unauthorized copies of disks from being produced. In this way we can provide better after-sales support and an upgrade service that is unique in the industry.