


The old CPU09GPP card seems to use the wrong bus signals.


The SIG30 is not connected with AC64 pin A30 and C30 but on A29 and C29!

Just cut the trace on the part site and connect it to C30 add the bottom connect C30 to A30.

New patch



^ Old patch



Connect C30 to A30.

The CPU09GPP REV: 1.0, CPU09GPD REV: 0.5 and CPU09FLX REV: 0.8 are correct.