

## UNIT TRIPPING REPORT

UNIT No: 2

STATION: NTPL, TUTICORIN.

OUTAGE NO: 88

REPORT NO: 88

- |   |  |
|---|--|
| 1. Date of tripping                     | : 01-06-2024                                 |
| 2. Time of tripping                     | : 18:41:40 Hrs                               |
| 3. Status before tripping               |  |
| a) Unit load                            | : 297MW                                      |
| b) Mills in service                     | : C, D, F, G & H                             |
| c) Oil guns in service                  | : Nil  |
| d) Boiler feed pumps in service         | : TDBFP A & B                                |
| e) CEPs in service                      | : A & B                                      |
| f) ID fans in service                   | : A & B                                      |
| g) FD fans in service                   | : A & B                                      |
| h) PA fans in service                   | : A & B                                      |
| i) CWP in service                       | : A & B                                      |
| 4. First Up protection acted            | : Boiler tripped on flame failure protection |
| 5. Other relays/protection acted        | : Turbine & Generator tripped on MFT.        |
| 6. Supporting documents attached        | : S.O.E & Trends                             |
| 7. Any operation done prior to tripping | : Mill change over and WB operation          |

8. Analysis of tripping :

Unit was running at 297 MW in CMC with a coal flow 240tph and 1200tph air flow. At 18:10:00 hrs Wall blower operation started. At 18:31:00 hrs mill-D started to stop import coal mill-B. On 18:39:00 hrs feeder-B stopped after loading feeder-D to 30tph. On 18:41:40 hrs unit tripped on MFT from Flame Failure Protection.

9. Root cause :

To conserve imported coal -mill B feed rate was reduced to minimum after reaching technical minimum, mill D taken into service and feed rate was gradually raised to 30 tph with O/L temp 60 degC & feeder B stopped. Mill-D further loaded to 40tph, but the mill D- current and mill DP were found fluctuating. Due to fluctuating coal feed to the boiler from mill-D and wall blower operation the flame in

furnace got disturbed which is captured by flame scanner and flame failure protection acted.

10. Remedial measures taken/to be taken:

It's advised to stop wall blower operation if any during mill change over and to check mill loading condition before stopping the mill.

11. Time/Date of boiler light up and sync:

Light Up: : 19:41 Hrs on 01/06/2024

Sync'd: : 21:21 Hrs on 01/06/2024

12. Delay for light up : nil

13. Recommendation / Action plan :

- i) Wall blower operation to be suspended during mill change over at part load (Technical Minimum).
- ii) Before stopping the feeder, the stability of loaded mill to be confirmed with parameters.

14. Any specific learning / feedback : nil



EE/EEMG



EE / OS



DCE / C&I



ACM / OS



CM/OS

Copy submitted to CEO / NTPL

Copy submitted to GM/O&M