

**BOILER TUBE FAILURE REPORT (C-2 FORM)**  
(C-2 FORM SHOULD BE SENT WITHIN 12 HOURS OF SYNCHRONISATION)

|   |      |             |    |                     |        |  |        |
|---|------|-------------|----|---------------------|--------|--|--------|
| 1) STATION:                                       | NTPL | 2) UNIT No. | II | 3) LAST UNIT OUTAGE | Aug-22 | 4) LAST UNIT O/H                         | Nov-21 |
| 5) UNIT SHUTDOWN FROM                             | 13   | 12          | 22 | 15                  | 28     | 9) OUTAGE HOURS                          | 63     |
| 6) WATER FILLING CLEARANCE                        | 16   | 12          | 22 | 04                  | 00     | (ONLY DUE TO BTF)                        | 00     |
| 7) CLEARANCE FOR LIGHTUP<br>(AFTER REPAIR OF BTF) | 16   | 12          | 22 | 06                  | 30     | 10) GENERATION LOSS<br>(ONLY DUE TO BTF) | hh mm  |
| 8) UNIT SYNCHRONISED AT                           | dd   | mm          | yy | hh                  | mm     |  | MUS    |
| 11) BTF INSPECTED BY                              | 16   | 12          | 22 | 14                  | 55     |  |        |
|   | dd   | mm          | yy | hh                  | mm     |  |        |
| BTF COMMITTEE HEAD                                |      |             |    | MTP                 |        | FQA                                      |        |
| CHEMISTRY   |      |             |    | OPERATION           |        | O&C                                      |        |

**BOILER TUBE FAILURE LOCATION**

12) FAILED TUBE LOCATION MARKED ON UNIT MATERIAL DIAGRAM AND BOILER GENERAL ARRANGEMENT DRAWING  
(CLEARLY IDENTIFYING TUBE NO., COIL NO., TUBE DIMENSION, TUBE MATERIAL AND X,Y,Z COORDINATES)  
Tube Dimension D51x6mm; SA210 Gr.C, RHS Waterwall (52 ML), S-Panel (10 ML), Corner 4 Transition tubes (52 ML)

**DESCRIPTION OF BOILER FAILED TUBES**

13) PHOTOGRAPHS OF LOCATION OF FAILURE BEFORE START OF REPAIR WORK



14) PHOTOGRAPHS OF PRIMARY FAILED TUBE



15) PHOTOGRAPHS OF REPAIRED LOCATION AFTER RESTORATION WORK



16) DETAILS OF REPAIR WORK (SPECIFY JOINT DETAILS, COIL NO./ TUBE NO. & RESTORATION WORK)  
Waterwall Tubes

Replacement of Spool Pieces  
No of Spools Replaced - 11; No. of pinholes attended - 1

17) DETAILS OF INSPECTION OF ADJACENT AND IDENTICAL LOCATIONS

Physical inspection of adjacent coils for signs of erosion/steam impingement. No abnormalities observed.

18) HISTORY OF WORK IN FAILED TUBE/COIL/LOCATION IN PAST FIVE YEARS

| YEAR | HISTORY OF WORK (DETAILS OF WORK DONE IN THE AREA/COIL) |               |                       |                          |
|------|---|---------------|-----------------------|--------------------------|
|      | LOCATION  | Tube/Coil No. | No. OF TUBES REPLACED | NATURE OF FAILURE & WORK |
|      | NIL   |               |                       |                          |

19) REMARKS

20) STATION OBSERVATION W.R.T. CAUSE OF TUBE FAILURE

Attachment weld failure in 10 ML of Tube 3 (From RHS WW) in Front WW resulting in Fish mouth opening at 52 ML of Corner 4 Transition tubes.

COPY TO:  
1) DISPLAY IN UCB  
2) GM/O&M  
3) HOD (OS-BOILER)

(SIGNATURE OF BTF HEAD)

NAME:  
DESIGNATION:  
DATE: