

TRIP ANALYSIS REPORT

TRIP ANALYSIS REPORT /TAR-012/ UNIT 1 / 14.07.2017

Dt. 17-07-17

Ref: 1. TRIP ANALYSIS REPORT /TAR-010/ UNIT 1 / 14.07.2017 Dated 17-07-17

OCCURRENCE:

- (a) **Condition:** Unit-1 was in service with 435 MW in LP mode and coal flow 208 tph at 23:25 hrs. on 14.07.2017.
- (b) **Incident:** Turbine tripped on protection IPT Fr DT high at 23:26:36.7 and Boiler tripped at 23:27:59 hrs on MFT (RH Protection). Unit was light up at 00:30 hrs after getting clearance from concerned authority from C&I division and synchronized at 01:43 hrs on 15.07.2017.

SOE OF DDCMIS ALARM PAGES:

| TIME | DESCRIPTION | STATUS |
|--------------|---------------------------------------|---------------|
| 23:26:36.275 | IP Casing Fr Diff Temp (11MYA01EZ175) | Operated |
| 23:26:36.354 | TP CHNL 1.1 On | True |
| 23:26:36.496 | IP Casing Fr Diff Temp (12MYA01EZ175) | Operated |
| 23:26:36.764 | Turb. Trip Ch1.1 CMD | On |
| 23:26:36.764 | Turb. Trip Ch1.2 CMD | On |
| 23:26:36.986 | Turb. Trip Ch2.2 CMD | On |
| 23:26:37.285 | Turb. Trip Ch1.1 Operated | |
| 23:26:37.642 | Main Trip VLV-1 | Tripped |
| 23:26:37.669 | Main Trip VLV-2 | Tripped |
| 23:26:38.714 | All ESVs Closed | |
| 23:26:40.062 | Turbine Tripped | |
| 23:26:40.425 | HPBP Valve Fast Open Acted | |
| 23:26:40.825 | BP 1 Valve Fast Open | True |
| 23:26:40.825 | BP 2 Valve Fast Open | True |
| 23:26:41.334 | MDBFP Auto Start | True |
| 23:26:41.814 | BP1 VLV > 2% Open | True |
| 23:26:41.814 | BP2 VLV > 2% Open | True |
| 23:26:42.004 | Gen Breaker Opened | |
| 23:26:42.939 | Run Back 3 Mill Acted | |
| 23:26:43.824 | BP 1 Valve Fast Open | False |
| 23:26:43.824 | BP 2 Valve Fast Open | False |
| 23:26:46.076 | Pulv Motor F Tripped on Run Back | |
| 23:26:47.911 | MDBFP On | |
| 23:26:51.555 | Pulv Motor E Tripped on Run Back | |
| 23:26:56 | Pulv Motor D Tripped on Run Back | |
| 23:26:57 | BP1 VLV < 2% Open | |
| 23:27:26 | BPE2 Downstream Temp V High | |
| 23:27:31.795 | BP2 Priority Close | |
| 23:27:47 | BP2 VLV < 2% Open | |
| 23:27:48.420 | Both HPBP Closed | |
| 23:27:58.559 | Loss of RH Protection Acted | |
| 23:27:59 | MFT CH 2 Operated | |

23:27:59 MFT CH 3 Operated
23:27:59 MFT CH 1 Operated

ANALYSIS from SOE and Trend:

Trip analysis from SOE and trend is made as below:

1. Unit was in service at 435 MW and 6 mills in service with a total coal flow of 208 tph.
2. At 23:26:36.275 IPT Casing Front DT protection acted (False Pick up) and Turbine tripped on this protection at 23:26:36.764.
3. On tripping of turbine, HPBP Fast open command acted 23:26:40.425 and BPV 1 & 2 opened from 0% to 100% (Trend Data: 23:26:40 to 23:26:45). MDBFP auto start command processed at 23:26:41.334. Generator CB opened at 23:26:42.004 and Runback to 3 Mill Condition acted at 23:26:42.939.
4. After completion of period for BPV Fast open command, BPV 1 closed to 0% (Trend data: 23:26:45 to 23:26:55) and BPV 2 was maintaining the MS Pressure in auto based on pressure controller set point. (Trend data: 23:26:45 to 23:27:45).
5. Downstream temperature of BPV2 increased from 259 °C at 23:26:45 to 377 259 °C at 23:27:30 (Trend Data) leading to Priority close of BPV2 at 23:27:31.795 (SOE).
6. Due to Closing of both BPV1&2, Both HPBP Closed alarm appeared at 23:27:48.420 and lead to MFT on loss of RH Protection at 23:27:58.559.
7. MFT acted at 23:27:59 and tripped the boiler.

CONCLUSION:

Following points were concluded:

1. False Pick up in IPT FR Diff Temperature protection was due to failure in milli Amp converter. It was replaced by C&I Division and clearance was given for light up.
2. The milli Amp converter failure was due to no AC in the control room suspected. The cabin temp was 51 deg cent.
3. BPV1 didn't operate after fast open is servo valve problem.
4. As per logic when any one BP Valves open more than 2 %, BD valve will open in auto. But in this case, even though BPV2 & BPE 2 were open > 2%, BD Valve didn't open, as the corresponding logic was bypassed. Even after spray valve BPE2 opening increased from 0% to 32% (Trend Data), BPV2 downstream temperature increased to more than 370 °C and priority close acted on BPV2. It lead to closing of BPV2 and subsequently Loss of RH Protection acted due closing of all BPVs.

RECOMMENDATIONS:

1. To avoid unit tripping/Equipment tripping due to spurious action of instrument parameters, certain protection parameters for boiler and turbine were modified with acceptance of concerned department HOD and those may be implemented. (Annexure attached)

2. Whenever open or close auto operation for equipments was bypassed due to operational requirement, it shall be normalized within the shift. Foolproof system shall be evolved for this simulation.
3. Trip Committee recommendations provided in trip analysis report point no. 2 & 4 in reference-1 shall be adopted.
4. Control room AC shall always be maintained

CM/OS(T)

ADGM/C&I

DGM/Elec

DGM/O&C