

## 171 Instruction Break Point On VMRUN Instruction Leads To Unpredictable System Behavior

### Description

VMRUN can be interrupted using a hardware instruction breakpoint using one of the debug registers, DR[0-3]. When the debug handler executes IRET, the processor is expected to execute the VMRUN instruction. However, in the failing case, the processor incorrectly re-enters the breakpoint handler with mixed guest and host state. This in turn causes erroneous execution and leads to unpredictable system behavior.

### Potential Effect on System

Hypervisor developers will not be able to use hardware instruction break point on VMRUN instruction.

### Suggested Workaround

Set the breakpoint on the instruction prior to VMRUN, then single step through VMRUN.

### Fix Planned

No