

503 APIC Task-Priority Register May Be Incorrect

Description

An APIC task priority register (TPR) write may use an incorrect internal buffer for the data.

Potential Effect on System

Incorrect interrupt prioritization.

Suggested Workaround

BIOS should set MSRC001_102A[11] to 1b.

Fix Planned

No fix planned