

*Engineers like to solve problems. If there are no problems handily available, they will create their own problems.* - Scott Adams

Topics on Electrical Engineering



## Questions



1. We have seen a three-phase rotating magnetic field (RMF) and how it was generated. For this exercise, here is a six-phase current waveform input. Please calculate the generated magnetic flux density ( $\mathbf{B}_{\text{net}}$ ). The currents flowing through each phases (A, B, C, D, E, F) are as follows:

$$\begin{aligned} i_{AA'} &= I_{\max} \sin(\omega t), & i_{BB'} &= I_{\max} \sin(\omega t - 60^\circ), \\ i_{CC'} &= I_{\max} \sin(\omega t - 120^\circ), & i_{DD'} &= I_{\max} \sin(\omega t - 180^\circ), \\ i_{EE'} &= I_{\max} \sin(\omega t - 240^\circ), & i_{FF'} &= I_{\max} \sin(\omega t - 300^\circ). \end{aligned}$$




Figure 1: A graphic representation of a six-phase current waveform.

2. As an engineering consultant on electric machine design, you have been contacted to design a 10-phase rotating magnetic field for use in high power applications. For this exercise, show the diagram of how it should be wound.
3. An induction machine has the following parameters:

$$R_r = 0.183 \quad \Omega, \quad R_s = 0.277 \quad \Omega, \quad \text{Y-connected}, \quad V_{\text{in}} = 200 \quad \text{V}, \quad 2p = 4$$

$$L_r = 0.056 \quad \text{H}, \quad L_s = 0.0553 \quad \text{H}, \quad 3\text{-phase}, \quad f_{\text{in}} = 60 \quad \text{Hz} \quad a = 3.$$

where  $a$  is the effective stator to rotor turns ratio and  $p$  is the number of pole pairs. The motor is supplied with its rated and balanced voltages. Find the  $\mathbf{q}$  and  $\mathbf{d}$  axes steady-state voltages and currents and phase currents ( $I_{qr}, I_{dr}, I_\alpha, I_\beta$ ) when the rotor is locked, Use the stator reference from model of the induction machine.

4. A three-phase wye (Y)-connected 220-V, 7.5-kW 60Hz six-pole induction motor has the following parameter values in  $\Omega$ /phase referred to the stator:

$$R_1 = 0.294 \quad \Omega, \quad R_2 = 0.294 \quad \Omega,$$

$$X_1 = 0.503 \quad \Omega, \quad X_2 = 0.209 \quad \Omega, \quad X_m = 13.25 \quad \Omega.$$

The total friction, windage, and core losses are assumed to be constant at 403 W, independent of the load. For a slip of 2 percent, compute the speed, output torque and power, stator current, power factor, and efficiency when the motor is operated at rated voltage and frequency.

5. The three-phase, 230 V, 60 Hz, 12 kW, four-pole IM is to be driven by a field-oriented speed-control system at a speed of  $1740 \text{ min}^{-1}$  with following properties:

$$R_1 = 0.095 \text{ } \Omega, \quad R_2 = 0.200 \text{ } \Omega,$$

$$X_1 = 0.680 \text{ } \Omega, \quad X_2 = 0.672 \text{ } \Omega, \quad X_m = 18.7 \text{ } \Omega.$$

Assuming the controller is programmed to set the rotor flux linkages ( $\lambda_{dr}$ ) to the machine rated peak value, find the RMS<sup>1</sup> amplitude of the input current ( $I_{in}$ ), the applied electrical frequency ( $f_e$ ), and the RMS terminal voltage, if the electromagnetic power is 9.7 kW and the motor is operating at a speed of  $1680 \text{ min}^{-1}$ .


---

<sup>1</sup>Root-Mean Square



## Answers





**Figure 2:** Polar coordinate form of the acting magnetic flux densities for the six phases at the electrical angle of  $\theta_e = 30^\circ$ .

1. Let us first consider, what happens at the time instant of the voltage waveforms. Unlike a three-phase system, at the instant  $\theta = 90^\circ$ , the voltage in phase **A** is positive maximum (1.0), phases **B** and **F** are half amplitude (0.5), **E** and **C** are also half amplitude but opposite sign (-0.5) and phase **D** is negative maximum (-1.0).

These six (6) waveforms are represented by the following equations:

$$v_{AA'} = V_{\max} \sin(\omega t), \quad v_{BB'} = V_{\max} \sin(\omega t - 60^\circ), \quad (1a)$$

$$v_{CC'} = V_{\max} \sin(\omega t - 120^\circ), \quad v_{DD'} = V_{\max} \sin(\omega t - 180^\circ), \quad (1b)$$

$$v_{EE'} = V_{\max} \sin(\omega t - 240^\circ), \quad v_{FF'} = V_{\max} \sin(\omega t - 300^\circ). \quad (1c)$$

where  $\omega = 2\pi \text{ rad} \cdot \text{s}^{-1}$ ,  $V_{\max}$  is the maximum value of the voltage or induced EMF in each phase and  $f$  is the supply frequency (Hz). If the flux densities (or fluxes  $\phi$ ) as both are valid approaches) are added to find the resultant magnetic flux density in phasor form the magnitude is found as;

$$\begin{aligned}
\mathbf{B}_{\text{net}} &= B_{\text{AA}'} \sin(\omega t) \angle 0^\circ + B_{\text{BB}'} \sin(\omega t - 60^\circ) \angle 60^\circ \\
&+ B_{\text{CC}'} \sin(\omega t - 120^\circ) \angle 120^\circ + B_{\text{DD}'} \sin(\omega t - 180^\circ) \angle 180^\circ \\
&+ B_{\text{EE}'} \sin(\omega t - 240^\circ) \angle 240^\circ + B_{\text{FF}'} \sin(\omega t - 300^\circ) \angle 300^\circ,
\end{aligned} \tag{2a}$$

$$\begin{aligned}
\mathbf{B}_{\text{net}} &= B_{\text{max}} \sin(\omega t) [\hat{\mathbf{x}} \cos(0^\circ) + \hat{\mathbf{y}} \sin(0^\circ)] \\
&+ B_{\text{max}} \sin(\omega t - 60^\circ) [\hat{\mathbf{x}} \cos(60^\circ) + \hat{\mathbf{y}} \sin(60^\circ)] \\
&+ B_{\text{max}} \sin(\omega t - 120^\circ) [\hat{\mathbf{x}} \cos(120^\circ) + \hat{\mathbf{y}} \sin(120^\circ)] \\
&+ B_{\text{max}} \sin(\omega t - 180^\circ) [\hat{\mathbf{x}} \cos(180^\circ) + \hat{\mathbf{y}} \sin(180^\circ)] \\
&+ B_{\text{max}} \sin(\omega t - 240^\circ) [\hat{\mathbf{x}} \cos(240^\circ) + \hat{\mathbf{y}} \sin(240^\circ)] \\
&+ B_{\text{max}} \sin(\omega t - 300^\circ) [\hat{\mathbf{x}} \cos(300^\circ) + \hat{\mathbf{y}} \sin(300^\circ)]
\end{aligned} \tag{2b}$$

$$\begin{aligned}
\mathbf{B}_{\text{net}} &= B_{\text{max}} \times \sin(\omega t) \times [1 \hat{\mathbf{x}} + 0 \hat{\mathbf{y}}] \\
&+ B_{\text{max}} \times \sin(\omega t - 60^\circ) \times \left[ \frac{1}{2} \hat{\mathbf{x}} + \frac{\sqrt{3}}{2} \hat{\mathbf{y}} \right] \\
&+ B_{\text{max}} \times \sin(\omega t - 120^\circ) \times \left[ -\frac{1}{2} \hat{\mathbf{x}} + \frac{\sqrt{3}}{2} \hat{\mathbf{y}} \right] \\
&+ B_{\text{max}} \times \sin(\omega t - 180^\circ) \times [-1 \hat{\mathbf{x}} + 0 \hat{\mathbf{y}}] \\
&+ B_{\text{max}} \times \sin(\omega t - 240^\circ) \times \left[ -\frac{1}{2} \hat{\mathbf{x}} - \frac{\sqrt{3}}{2} \hat{\mathbf{y}} \right] \\
&+ B_{\text{max}} \times \sin(\omega t - 300^\circ) \times \left[ \frac{1}{2} \hat{\mathbf{x}} - \frac{\sqrt{3}}{2} \hat{\mathbf{y}} \right]
\end{aligned} \tag{2c}$$

Let's rearrange the equation by their **cardinal components**, namely  $\hat{\mathbf{x}}$  and  $\hat{\mathbf{y}}$ .

$$\begin{aligned}
\mathbf{B}_{\text{net}} &= \left[ B_{\text{max}} \sin(\omega t) + \frac{1}{2} B_{\text{max}} \sin(\omega t - 60^\circ) \right. \\
&- \frac{1}{2} B_{\text{max}} \sin(\omega t - 120^\circ) - B_{\text{max}} \sin(\omega t - 180^\circ) \\
&- \left. \frac{1}{2} B_{\text{max}} \sin(\omega t - 240^\circ) + \frac{1}{2} B_{\text{max}} \sin(\omega t - 300^\circ) \right] \hat{\mathbf{x}} \\
&+ \left[ \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 60^\circ) + \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 120^\circ) \right. \\
&- \left. \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 240^\circ) - \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 300^\circ) \right] \hat{\mathbf{y}}
\end{aligned} \tag{3}$$

We need to do the following trigonometric conversions if we want to simplify the aforementioned equation of a mess

These conversions are based on the following trigonometric identities:

$$\sin(x + 180^\circ) = -\sin(x), \quad (4a)$$

$$\sin(x + 360^\circ) = +\sin(x). \quad (4b)$$

$$\sin(\omega t + 300^\circ + 360^\circ) = +\sin(\omega t + 60^\circ), \quad (5a)$$

$$\sin(\omega t - 240^\circ + 360^\circ) = +\sin(\omega t + 120^\circ), \quad (5b)$$

$$\sin(\omega t - 180^\circ + 180^\circ) = -\sin(\omega t). \quad (5c)$$

Inserting these equations to Eq. (3),

$$\begin{aligned} \mathbf{B}_{\text{net}} = & \left[ B_{\text{max}} \sin(\omega t) + \frac{1}{2} B_{\text{max}} \sin(\omega t - 60^\circ) \right. \\ & - \frac{1}{2} B_{\text{max}} \sin(\omega t - 120^\circ) + B_{\text{max}} \sin(\omega t) \\ & \left. - \frac{1}{2} B_{\text{max}} \sin(\omega t + 120^\circ) + \frac{1}{2} B_{\text{max}} \sin(\omega t + 60^\circ) \right] \hat{\mathbf{x}} \\ & + \left[ \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 60^\circ) + \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t - 120^\circ) \right. \\ & \left. - \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t + 120^\circ) - \frac{\sqrt{3}}{2} B_{\text{max}} \sin(\omega t + 60^\circ) \right] \hat{\mathbf{y}} \end{aligned} \quad (6)$$

Now we can do some tidying up and do some arrangements of these sine values;

$$\begin{aligned} \mathbf{B}_{\text{net}} = & \left[ 2B_{\text{max}} \sin(\omega t) + \frac{1}{2} B_{\text{max}} \left( \sin(\omega t - 60^\circ) + \sin(\omega t + 60^\circ) \right) \right. \\ & \left. - \frac{1}{2} B_{\text{max}} \left( \sin(\omega t - 120^\circ) + \sin(\omega t + 120^\circ) \right) \right] \hat{\mathbf{x}} \\ & + \left[ -\frac{\sqrt{3}}{2} B_{\text{max}} \left( \sin(\omega t - 60^\circ) - \sin(\omega t + 60^\circ) \right) \right. \\ & \left. - \frac{\sqrt{3}}{2} B_{\text{max}} \left( \sin(\omega t + 120^\circ) - \sin(\omega t - 120^\circ) \right) \right] \hat{\mathbf{y}} \end{aligned} \quad (7)$$

Now it is time to do some trigonometric manipulation

These conversions are based on the following trigonometric identities:

$$\sin(A + B) + \sin(A - B) = 2 \sin(A) \cos(B), \quad (8)$$

$$\sin(A + B) - \sin(A - B) = 2 \cos(A) \sin(B). \quad (9)$$

and come up with our final equation to explain this rotating magnetic field for a six-phase system.



$$\begin{aligned}\mathbf{B}_{\text{net}} = & \left[ 2B_{\text{max}} \sin(\omega t) + \frac{1}{2}B_{\text{max}} \left( 2 \sin(\omega t) \cos(60^\circ) \right) \right. \\ & \left. - \frac{1}{2}B_{\text{max}} \left( 2 \sin(\omega t) \cos(120^\circ) \right) \right] \hat{\mathbf{x}} \\ & + \left[ -\frac{\sqrt{3}}{2}B_{\text{max}} \left( 2 \cos(\omega t) \sin(60^\circ) \right) \right. \\ & \left. - \frac{\sqrt{3}}{2}B_{\text{max}} \left( 2 \sin(\omega t) \cos(120^\circ) \right) \right] \hat{\mathbf{y}}\end{aligned}\quad (10a)$$

$$\begin{aligned}\mathbf{B}_{\text{net}} = & B_{\text{max}} \left[ 2B_{\text{max}} \sin(\omega t) + 0.5 \sin(\omega t) + 0.5 \sin(\omega t) \right] \hat{\mathbf{x}} \\ & + B_{\text{max}} \left[ -\frac{3}{2} \cos(\omega t) - \frac{3}{2} \cos(\omega t) \right] \hat{\mathbf{y}}\end{aligned}\quad (10b)$$

$$\mathbf{B}_{\text{net}} = 3B_{\text{max}} \sin(\omega t) \hat{\mathbf{x}} - 3B_{\text{max}} \cos(\omega t) \hat{\mathbf{y}}, \quad (11)$$

$$\mathbf{B}_{\text{net}} = \left( \frac{6}{2} \right) B_{\text{max}} [\sin(\omega t) \hat{\mathbf{x}} - \cos(\omega t) \hat{\mathbf{y}}] \quad \blacksquare \quad (12)$$

- (i) In addition to saving on wiring, three-phase systems have notable performance advantages over a single-phase system.
- (ii) For a given power rating, three-phase drives have superior efficiency than single-phase drives.
- (iii) Three-phase drives also have a higher power factor, which means they draw less volt-amperes for a given load and efficiency. Some electricity tariffs include charges for deficient power factor, and three-phase drives can help reduce them.
- (iv) Since single-phase systems deliver pulsating power, drives tend to experience more vibration, while the constant supply of three-phase systems results in a more stable operation.
- (v) Single-phase drives cannot start by themselves, requiring external devices. On the other hand, a three-phase drives can start with the power supply alone, and it can even reverse direction if you switch two conductors with each other.
- (vi) A three-phase system is also **more versatile** than a single-phase installation. If you need to run a single-phase device with a three-phase power supply, you can use only one of the three conductors.

However, there opposite does not apply: three-phase appliances cannot be operated with single-phase power. Motors are an exception: you can run a three-phase drive with a single-phase power supply, but the drive's mechanical power is drastically reduced and its service life is shortened drastically.

-From NY Engineers

2. We first begin by analysing the current waveforms: The applied phase voltages are as follows:




Figure 3: A graphic representation of a ten-phase current waveform.

As can be seen, the **base** phase (i.e, with a shift of 0) reaches maximum after the 10<sup>th</sup> phase.

1 2 3 4 5 6 7 8 9 10

And these phases are electrically 36° degrees apart ( $\theta_e$ ). The connection between the electrical and mechanical angle are as follows:

$$\theta_m = \frac{3}{2}\theta_e,$$

where based on this we can calculate the mechanical angle as  $\theta_m = 54^\circ$ . Based on this we can draw the following diagram.




Figure 4: A graphic representation of a ten-phase current waveform.

3. The applied phase voltages are as follows:

$$v_{as} = \frac{200}{\sqrt{3}} \times \sqrt{2} \sin(\omega t) = 163.3 \sin(\omega t) \quad \text{V},$$

$$v_{bs} = 163.3 \sin(\omega t) [-120^\circ] \quad \text{V},$$

$$v_{cs} = 163.3 \sin(\omega t) [+120^\circ] \quad \text{V}.$$

The **d** and **q** axes voltages are:

$$\begin{bmatrix} v_{qs} \\ v_{ds} \\ v_0 \end{bmatrix} = T_{abc}^s \begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix} \quad \text{V}.$$

where,

$$T_{abc}^s = \frac{2}{3} \begin{bmatrix} \cos \theta_s & \cos \left( \theta_s - \frac{2\pi}{3} \right) & \cos \left( \theta_s + \frac{2\pi}{3} \right) \\ \sin \theta_s & \sin \left( \theta_s - \frac{2\pi}{3} \right) & \sin \left( \theta_s + \frac{2\pi}{3} \right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \quad \text{where } \theta_s = 0.$$

We can deduce the following statements based on the matrix multiplication.

$$v_{qs} = \frac{2}{3} \left[ v_{as} - \frac{1}{2} (v_{bs} + v_{cs}) \right] \quad \text{V}.$$

For a balanced input the following statement is **true**:

$$v_{as} + v_{bs} + v_{cs} = 0 \quad \text{V}.$$

Substituting for  $v_{bs}$  and  $v_{cs}$  in terms of  $v_{as}$  presents the following:

$$v_{qs} = \frac{2}{3} \left[ \frac{3}{2} v_{as} \right] = v_{as} \quad \text{V}.$$

Similarly:

$$v_{ds} = \frac{1}{\sqrt{3}} (v_{cs} - v_{bs}) \quad \text{V}.$$

and  $v_{ds} = 0$ ,

$$v_{qs} = v_{as} = 163 \sin(\omega t) = 163.3 \underline{0} = 163.3 \quad \text{V},$$

$$v_{ds} = \frac{1}{\sqrt{3}} (v_{cs} - v_{bs}) = 163.3 \cos(\omega_s t) = 163.3 \underline{90} = j163.3 \quad \text{V}.$$

The rotor is locked and therefore we can see:

$$\dot{\theta}_r = 0 \quad \text{rad} \cdot \text{s}^{-1}$$

For steady-state evaluation:

$$p_t = j\omega_s = j2\pi f_s = j2\pi 60 = j377 \quad \text{rad} \cdot \text{s}^{-1}$$

$$\begin{bmatrix} v_{qs} \\ v_{ds} \\ 0 \\ 0 \end{bmatrix} = \begin{bmatrix} R_s + L_s p_t & 0 & L_{sr} p_t & 0 \\ 0 & R_s + L_s p_t & 0 & L_{sr} p_t \\ L_{sr} p_t & 0 & R_r + L_r p_t & 0 \\ 0 & L_{sr} p_t & 0 & R_r + L_r p_t \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{qr} \\ i_{dr} \end{bmatrix}$$

The rotor windings are short-circuited, and hence rotor voltages are zero.

Now we can put the numerical values for the parameters and solve the currents.

$$i_{qs} = 35.37 - j108.8 = 113.81 \angle -71.9^\circ \text{ A},$$

$$i_{ds} = 108.8 + j35.37 = 113.81 \angle 18.1^\circ \text{ A},$$

$$i_{qr} = -34.88 + j103.63 = 109.34 \angle 108.6^\circ \text{ A},$$

$$i_{dr} = -103.63 + j34.88 = 109.34 \angle -161.4^\circ \text{ A}.$$

The stator and rotor currents are displaced by 90 degrees among themselves as expected in a two-phase machine.

The zero-sequence currents are zero as it is non-existent with balanced supply voltages.

The phase currents are:

$$\begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} = \begin{bmatrix} 1 & 0 & 1 \\ -1/2 & -\sqrt{3}/2 & 1 \\ -1/2 & \sqrt{3}/2 & 1 \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \end{bmatrix} = \begin{bmatrix} 113.9 \angle -71.9^\circ \\ 113.9 \angle 168.1^\circ \\ 113.9 \angle 48.1^\circ \end{bmatrix} \text{ A}.$$

The various rotor currents are:

$$i_{qrr} = a i_{qr} = 328.02 \angle 108.6^\circ \text{ A},$$

$$i_{drr} = a i_{dr} = 328.02 \angle -161.4^\circ \text{ A}.$$

The  $\alpha$  and  $\beta$  currents, assuming  $\theta_r = 0$  are:

$$\begin{bmatrix} i_\alpha \\ i_\beta \end{bmatrix} = \begin{bmatrix} \cos \theta_r & \sin \theta_r \\ \sin \theta_r & -\cos \theta_r \end{bmatrix} \begin{bmatrix} i_{drr} \\ i_{qrr} \end{bmatrix} = \begin{bmatrix} 1 & 0 \\ 0 & -1 \end{bmatrix} \begin{bmatrix} i_{drr} \\ i_{qrr} \end{bmatrix} = \begin{bmatrix} 328.02 \angle -161.4^\circ \\ -328.02 \angle 108.6^\circ \end{bmatrix} \text{ A} \quad \blacksquare$$




Figure 5: The steady-state equivalence circuit of an induction drive.

4. Let the impedance  $Z_{eq}$  define the per phase impedance presented to the stator by the magnetising reactance and the rotor. But first let's calculate the rotor impedance:

$$Z_r = \frac{R_r}{s} + jX_r \quad \Omega,$$

We know to calculate the  $Z_{eq}$  we treat  $Z_m$  and  $Z_r$  as **parallel** impedances.

$$Z_m = jX_m \quad \text{and} \quad Z_{meq} = \frac{Z_m \times Z_{eq}}{Z_m + Z_{eq}}.$$

Knowing these values, we can add the stator values to calculate the input impedance:

$$Z_{in} = R_s + jX_s + Z_{meq} = 5.70 + j3.61 = 6.75/\underline{32.3^\circ} \quad \Omega$$

Therefore, the input current can be calculate as:

$$V_{ph} = \frac{22}{\sqrt{3}} = 127 \quad V.$$

$$I_{in} = \frac{V_{in}}{Z_{in}} = \frac{127}{6.75/\underline{32.3^\circ}} = 18.8/\underline{-32.3^\circ} \quad A$$

The stator current is 18.8 A, therefore the power factor is equal to  $\cos(-32.3^\circ) = 0.845$  **lagging**. Let us take our attention to speed calculations. To calculate the synchronous speed in  $\text{min}^{-1}$ :

$$n_s = \left( \frac{120}{\text{poles}} \right) f_s = \left( \frac{120}{6} \right) 60 = 1200 \quad \text{min}^{-1}.$$

And of course in  $\text{rad} \cdot \text{s}^{-1}$ , the speed is:

$$\omega_s = \frac{4\pi f_s}{\text{poles}} = 125.7 \quad \text{rad} \cdot \text{s}^{-1}.$$

The rotor speed is:

$$n_r = (1 - s) n_s = (0.98) 1200 = 1176 \quad \text{min}^{-1},$$

$$\omega_r = (1 - s) \omega_s = (0.98) 125.7 = 123.2 \quad \text{rad} \cdot \text{s}^{-1}.$$

For the power calculations, we start with the air-gap power:

$$P_{gap} = n_{ph} I_r^2 \left( \frac{R_2}{s} \right) \quad W$$

Note however that because the only resistance included in  $Z_{\text{meq}}$  is  $R_2/s$  the power dissipated in  $Z_{\text{meq}}$  is equal to the power dissipated in  $R_2/s$  and therefore we can write:

$$P_{\text{gap}} = n_{\text{ph}} I_s^2 R_{\text{meq}} = 3 (18.8)^2 (5.41) = 5740 \text{ W.}$$

From here, we can calculate the mechanical power and the shaft output power:

$$\begin{aligned} P_{\text{shaft}} &= P_{\text{mech}} - P_{\text{rot}} = (1 - s) P_{\text{gap}} - P_{\text{rot}} \\ &= (0.98) 5740 - 403 = 5220 \text{ W.} \end{aligned}$$

The shaft output torque can be calculated as:

$$T_{\text{shaft}} = \frac{P_{\text{shaft}}}{\omega_m} = \frac{5220}{123.2} = 42.4 \text{ N} \cdot \text{m.}$$

The efficiency is calculated as the ratio of shaft output power to stator input power. The input power is given by:

$$\begin{aligned} P_{\text{in}} &= n_{\text{ph}} \text{Re}[V_{\text{in}} I_{\text{in}}] = 3 \text{Re}[127 (18.8/\underline{32.3^\circ})] \\ &= 3 \times 127 \times 18.8 \cos(32.2^\circ) = 6060 \text{ W.} \end{aligned}$$

Therefore, the efficiency ( $\eta$ ) is equal to:

$$\eta = \frac{P_{\text{shaft}}}{P_{\text{in}}} = 0.861 = 86.1 \% \quad \blacksquare$$

5. We must first determine the parameters for this machine:

$$L_m = \frac{X_{m0}}{\omega_{e0}} = \frac{18.7}{120\pi} = 49.6 \text{ mH},$$

$$L_s = L_m + \frac{X_{s0}}{\omega_{e0}} = 49.6 + \frac{0.680}{120\pi} = 51.41 \text{ mH},$$

$$L_r = L_m + \frac{X_{r0}}{\omega_{e0}} = 49.6 + \frac{0.672}{120\pi} = 51.39 \text{ mH}.$$

The rated rms line-to-neutral terminal voltage for this machine is  $230/\sqrt{3} = 132.8$  and therefore the peak rated flux for this machine is:

$$(\lambda_{\text{rated}})_{\text{peak}} = \frac{\sqrt{2} (V_{\text{in}})_{\text{rated}}}{\omega_e} = \frac{\sqrt{2} \times 132.8}{120\pi} = 0.498 \text{ Wb}.$$

For the specified operating condition:

$$\omega_r = n_r \left( \frac{\pi}{30} \right) = 1680 \left( \frac{\pi}{30} \right) = 176 \text{ rad} \cdot \text{s}^{-1},$$

and the mechanical torque is:

$$T_{\text{mech}} = \frac{P_{\text{mech}}}{\omega_s} = \frac{9.7 \times 10^3}{176} = 55.1 \text{ N} \cdot \text{m}^{-1}.$$

We can re-use the torque equation to isolate the quadrature current:

$$\begin{aligned} T_{\text{mech}} &= \frac{3}{2} \left( \frac{p}{2} \right) \left( \frac{L_m}{L_r} \right) (\lambda_{\text{dr}} i_q - \lambda_{\text{qr}} i_d), \\ i_q &= \frac{2}{3} \left( \frac{2}{p} \right) \left( \frac{L_r}{L_m} \right) \left( \frac{T_{\text{mech}}}{\lambda_{\text{dr}}} \right), \\ &= \frac{2}{3} \left( \frac{2}{4} \right) \left( \frac{51.39 \times 10^{-3}}{49.6 \times 10^{-3}} \right) \left( \frac{55.1}{0.498} \right) = 38.2 \text{ A}. \end{aligned}$$

Using  $\lambda_{\text{dr}} = L_m i_d$ , we can deduce:

$$i_d = \frac{\lambda_{\text{dr}}}{L_m} = \frac{0.498}{49.6 \times 10^{-3}} = 10.0 \text{ A}$$

The rms input current is:

$$I_{\text{in}} = \sqrt{\frac{i_d^2 + i_q^2}{2}} = \sqrt{\frac{10.0^2 + 38.2^2}{2}} = 27.9 \text{ A}$$

The electrical frequency can be found from:

$$\omega_e = \omega_{\text{me}} + \frac{R_r}{L_r} \left( \frac{i_q}{i_d} \right)$$

With:

$$\omega_{\text{me}} = (p/2) \omega_m = 2 \times 176 = 352 \text{ rad} \cdot \text{s}^{-1},$$

$$\omega_e = 352 + \left( \frac{0.2}{51.39 \times 10^{-3}} \right) \left( \frac{38.2}{10.0} \right) = 367 \text{ rad} \cdot \text{s}^{-1}$$

and  $f_e = \omega_e / (2\pi) = 58.4$  Hz. Finally we can calculate the rms line-to-neutral terminal voltage as:

$$V_a = \sqrt{\frac{(R_s i_d - \omega_e (L_s - L_m^2/L_r) i_q)^2 + (R_s i_q + \omega_e L_s i_d)^2}{2}},$$

$$= 140.6 \text{ V line-to-neutral} = 243.6 \text{ V line-to-line} \quad \blacksquare$$