



Medtronic

Errata Sheet for the Model 9995 Software for the Medtronic 2090 CareLink Programmer and CareLink Encore Programmer

The following table lists certain conditions that may occur during use of the software and the resolution of these conditions.

Condition	Observed Behavior	Suggested Corrective Action
Advise SR MRI devices are interrogated with Model 9995 Software version 8.3 or earlier.	<p>The following behavior could be observed:</p> <ul style="list-style-type: none">■ MRI SureScan screen is not available for enabling or disabling MRI SureScan mode.■ Nominal values for Lower Rate, VT Monitor Interval, Pacing Mode, and EGM1 Source are not consistent with the values in the manuals for Advise SR MRI.■ Atrial EGM selections are available for EGM1 Source and EGM3 Source even though they are not applicable for Advise SR MRI. If the Atrial values are programmed then a flat line EGM will be displayed.■ Displayed and printed labels may contain information not applicable to Advise SR MRI.	Interrogate Advise SR MRI device using Model 9995 Software version 8.4 or greater.

The following list includes trademarks or registered trademarks of Medtronic in the United States and possibly in other countries. All other trademarks are the property of their respective owners.

Advise SR MRI, CareLink, CareLink Encore, Medtronic, SureScan

Caution: Federal law (USA) restricts this device to sale by or on the order of a physician.

