

Turbine No./Id: 235
Service Order: 6269

PAD No.
LIMALONGES LIM5

Turbine Type: V110
Start Date: 30.04.2024
End Date: 30.04.2024

Customer's Ref./P.O.No.:
Date & Time of Receipt: 11.12.2023 02:43:46

Vestas Ref.:
IP10202

Customer's Address:

ENERGIE LIMALO
29 Rue

Site's Address:

F-

Reason for Call Out: Check ICPE Torque

Check ICPE Torque

Work Performed

Fait le 30/03/2024Pause à 12h56Run à 15:46Checks ICPE torque

Specification of Item Consumption

Item	Description	Serial Number	Quantity	UoM
------	-------------	---------------	----------	-----

Specification of Time Consumption

Person Name	Date	Start	End	Hours	Activity type
S	30.04.2024	16:45:00	17:00:00	0.25	MOB / DE-MOB

Total Time Consumption: 0.25

Turbine No./Id:
235

Service order
6269

Service Inspection Form

0010 Check ICPE Torque V90-V110 2MW MK10

0 eSIF

0.01 0. DMS: 0093-0083 V03

1 Safety

- | | | |
|------|--|----|
| 1.01 | Two persons present. | OK |
| 1.02 | Trained in and aware of the contents of the Vestas Corporate OH and S OK
Manual including 'Working with Hazardous Materials' and Safety
Regulations for Operators and Technicians. | |
| 1.03 | Be sure to know the general recommendations regarding the following OK
points: For safety reasons, note the location of the emergency stop
buttons. Please refer to documentation 'Safety Regulations for
Operators and Technicians' of the corresponding turbine platform. | |
| 1.04 | Locking of rotor/blades. | OK |
| 1.05 | Hearing protection. | OK |
| 1.06 | Hydraulic tools. | OK |

2 Article 16 (6-monthly)

- | | | |
|------|---|--|
| 2.01 | Check that wind turbine is clean. Check that no combustible or OK
inflammable material is stored inside the wind turbine. | |
| 2.02 | L'intérieur de l'aérogénérateur est maintenu propre. L'entreposage à OK
l'intérieur de l'aérogénérateur de matériaux combustibles ou
inflammables est interdit. | |
| 2.03 | Remarks: (as a comment) | |

Not Applicable

3 Article 18 I

- | | | |
|------|--|--|
| 3.01 | Control of all mechanical connections between blade and blade bearing OK | |
|------|--|--|

Turbine No./Id:
235

Service order
6269

based on relevant platform SII, SIF, SWI.

3.02 Contrôle de l'ensemble des brides de fixations et de la fixation des pales: Contrôle de l'ensemble des brides de fixations entre la pale et le roulement de pale. OK

3.03 Control of all mechanical connections between blade bearing and hub based on relevant platform SII, SIF, SWI. OK

3.04 Contrôle de l'ensemble des brides de fixations entre le moyeu et le roulement de pale. OK

3.05 Control of all mechanical connections between hub and Main shaft based on relevant platform SII, SIF, SWI.

Not Applicable

3.06 Contrôle de l'ensemble des brides de fixations entre l'arbre principal et le moyeu OK

3.07 Control of all mechanical connections between Yaw ring and Tower top based on relevant platform SII, SIF, SWI. OK

3.08 Contrôle de l'ensemble des brides de fixations entre la couronne d'orientation et le mât OK

3.09 Remarks: (as a comment)

Not Applicable

4 Article 18 I

4.01 Visual Control of Tower. OK

4.02 Contrôle visuel du mât et Contrôle de l'ensemble des brides du mât: Contrôle visuel du mât de l'aérogénérateur OK

4.03 Control of all Tower flanges and Foundation mechanical connections based on relevant platform SII, SIF, SWI. OK

4.04 Contrôle de l'ensemble des brides du mât OK

Turbine No./Id:
235**Service order**
6269

4.05 Remarks: (as a comment)

Not Applicable

5 Article 18 II - Contrôle visuel (6-month)5.01 If under Vestas scope, visual control of blades and external elements OK
for damages like thunder impact.5.02 L'exploitant procède à un contrôle visuel des pales et des éléments OK
susceptibles d'être endommagés, notamment par des impacts de
foudre.5.03 Remarks, precise who made the vestas control (Vestas or another
company): (as a comment)

Not Applicable