

# AXC F 2152 – CHANGE NOTES

## Change notes for the AXC F 2152 controller

### Application note

108427\_en\_24

© PHOENIX CONTACT 2021-05-06

## 1 General information

This document contains all changes made between firmware version 1.0.0 and the current firmware version of the AXC F 2152 controller (Order No. 2404267).

Current firmware version: 2021.0.5 LTS



### Recommended:

To be able to use all new functions of a firmware version, always use all elements of the toolchain in the same version. The toolchain includes, for example, PLCnext Engineer, SDK and PLCnext CLI.



### NOTE: Material damage due to a freezing of the outputs

With firmware versions 2019.6, 2019.3, or 2019.0 LTS, a high CPU load in conjunction with frequent PROFINET disconnections may cause the outputs of the Axioline local bus to freeze.

- Make sure to perform an update to firmware version **2019.0.4 LTS**, **2019.6.3** or **2019.9** or higher.

### 1.1 Maritime approvals

The following firmware versions are certified for use in maritime applications:

- 2021.0.3 LTS
- 2020.0.1 LTS
- 2020.0 LTS
- 2019.0.4 LTS
- 2019.0 LTS



Make sure you always use the latest documentation. It can be downloaded at [phoenixcontact.net/product/2404267](https://phoenixcontact.net/product/2404267).

## 2 Table of contents

1	General information .....	1
2	Table of contents .....	1
3	Changes in firmware version 2021.0.5 LTS .....	2
4	Changes in firmware version 2021.0.3 LTS .....	3
5	Changes in firmware version 2021.0.2 LTS .....	4
6	Changes in firmware version 2021.0 LTS .....	6
7	Changes in firmware version 2020.6.1 .....	11
8	Changes in firmware version 2020.3.1 .....	15
9	Changes in firmware version 2020.0.1 LTS .....	18
10	Changes in firmware version 2020.0 LTS .....	18
11	Changes in firmware version 2019.9 .....	21
12	Changes in firmware version 2019.0.4 LTS .....	23
13	Changes in firmware version 2019.6.3 .....	23
14	Changes in firmware version 2019.6 .....	24
15	Changes in firmware version 2019.3 .....	27
16	Changes in firmware version 2019.0 LTS .....	28
17	Changes in firmware version 1.2.0 .....	30
18	Changes in firmware version 1.1.0 .....	31
19	Changes in firmware version 1.0.2 .....	32
20	Changes in firmware version 1.0.1 .....	33

### 3 Changes in firmware version 2021.0.5 LTS



To be able to use all new functions of the firmware, you need PLCnext Engineer version 2021.0.2 LTS or newer.  
Select the latest template for firmware version 2021.0.0 LTS in the PLCnext Engineer project.

#### 3.1 Changes

##### System

“Paho” libraries were updated to the following versions:

- paho-mqtt-c: 1.3.8
- paho-mqtt-cpp: 1.2.0

#### 3.2 Error corrections

The following errors have been rectified:

##### System

An unusually high amount of logging entries in the log file /var/volatile/log/auth.log could cause the system to crash after some time.

##### GDS

Firmware version 2021.0 LTS rejected a GDS connection between a port variable of a C++ component and a port variable of a program instance. As a consequence the program did not start.

##### PLCnext Store

- During offline installation of licenses a reboot is recommended. If this reboot has been performed by switching off the power, the license files on the controller could be lost.
- If a controller has been updated from a firmware version older than 2020.3 to a firmware version 2020.3 or newer, the folder /opt/plcnext/config in the overlay partition sporadically got wrong access rights. As a consequence it was not possible to install licenses. In the past, a reset to “Default setting type 1” had to be performed as workaround. Firmware version 2021.0.5 LTS corrects the access rights.

##### ESM

With firmware version 2021.0 LTS the execution of tasks sporadically did not obey the task priorities, when a code worksheet was displayed in the online mode of PLCnext Engineer.

##### DataLogger

During the writing of large databases and simultaneous unexpected system restart due to a voltage interruption or a system watchdog, an invalid state of the database could occur. As a result, the system could not restart properly afterwards.

#### 3.3 Known limitations and errors

- The app “MQTT\_Client\_Library” version 2 (Build 20210205), which is available in the PLCnext Store, is not compatible with firmware version 2021.0.5 and will cause a system watchdog which reboots the controller. Please contact the contributor of the app (PLCnext Store) for any questions and potential fixes.
- In addition, the known errors and limitations from firmware version 2021.0.2 LTS also exist in this firmware version.  
See section 5.3 “Known limitations and errors” on page 4.

#### 3.4 Security updates

The following security updates have been made in this release. For more information about the specified CVE numbers, see:

- <https://nvd.nist.gov/vuln>
- <https://cert.vde.com>

Information on the Phoenix Contact “PSIRT” can be found at: <https://www.phoenixcontact.com/psirt>

##### SSL

- CVE-2021-3449
- CVE-2021-3450

##### RAUC

- CVE-2020-25860

## 4 Changes in firmware version 2021.0.3 LTS



All changes described in section 5 “Changes in firmware version 2021.0.2 LTS” on page 4 are also valid for this firmware version.

### 4.1 Error corrections

**The following errors have been rectified:**

#### **System**

The bug fixing of firmware version 2021.0.2 LTS concerning the logging of information into files located at „tmpFS“ has been reworked. As of firmware version 2021.0.3 LTS the following applies:

Logging information into files located at „tmpFS“ occupied too much RAM. Consequently the System Watchdog re-started the controller. Now the following files are regularly checked:

- /var/log/debug
- /var/log/error
- /var/log/messages
- /var/log/syslog
- /var/log/auth.log
- /var/log/kern.log
- /var/log/user.log
- /var/log/cron.log
- /var/log/btmp
- /var/log/wtmp

If one of the files is too large, it will be moved to the backup. The backups are located in the same folder and „.1“ is appended to the backup file name. This will overwrite existing backups.

## 5 Changes in firmware version 2021.0.2 LTS



To be able to use all new functions of the firmware, you need PLCnext Engineer version 2021.0.2 LTS or newer.  
Select the latest template for firmware version 2021.0.0 LTS in the PLCnext Engineer project.

### 5.1 New functions

#### PROFINET

- PROFINET controller certification according to PROFINET specification version 2.4.1 and Net Load Class II.
- PROFINET device certification according to PROFINET specification version 2.4.1 and Net Load Class II.

### 5.2 Error corrections

The following errors have been rectified:

#### PROFINET

- After a restart of the device by voltage reset it could happen that the PROFINET controller could not establish a connection to all PROFINET devices. This occurred when connecting with large numbers of PROFINET devices.
- Minor problems were solved, which occurred when a superseded PROFINET controller requested to check the MRP configuration of the PROFINET device.
- Minor problems in the representation of device specific information via LLDP were solved.
- Sporadic link problems were solved that occurred with a PROFINET device which only offers 100 Mbit full-duplex/half-duplex.
- In combination with AXC F XT ETH 1 TX: If autonegotiation of remote devices is deactivated, the default speed option of the interface is 100 Mbit half-duplex. In that case an existing PROFINET connection has not been aborted.

#### System

- Logging information into files located at „tempFS“ occupied too much RAM. Consequently the System Watchdog restarted the controller. Now the following files are regularly checked:
  - /var/log/debug
  - /var/log/error
  - /var/log/messages

- /var/log/syslog
- /var/log/auth.log
- /var/log/kern.log
- /var/log/user.log

If one of the files is too large it will be moved to the backup. This will overwrite existing backups.

- With firmware version 2021.0 LTS a reset to „Default setting type 1“ was not possible when executed by pressing the reset button of the controller.

#### SDK/C++

The SDK related to firmware version 2021.0 LTS redefines the „std::make\_unique“ function, thus creating a conflict when compiling existing code. Use the SDK related to firmware version 2021.0.2 LTS instead.

#### Network

- In case the „dhcp“ option was configured in the „interfaces“ configuration file, it could happen that the manual „DHCP Gateway“ setting was overwritten.
- The Ethernet connection froze after a few minutes when the controller is connected to another port that is configured to 100 Mbit full-duplex without autonegotiation.

### 5.3 Known limitations and errors

- Firmware update  
The firmware update removes the following files so that the contents are lost:

- /opt/plcnext/projects/Default/Plc/Eclr/Default.eclr.config
- /opt/plcnext/projects/Default/Plc/Gds/Default.gds.config
- /opt/plcnext/projects/Default/Plc/Meta/Default.meta.config
- /opt/plcnext/projects/Default/Plc/Plm/Plm.config
- /opt/plcnext/projects/Default/Plc/Esm/Default.esm.config
- /opt/plcnext/projects/Default/Plc/Esm/ServiceTask.esm.config
- /opt/plcnext/projects/Default/Plc/Esm/Globals.esm.config

These files are not edited by PLCnext Engineer nor are they intended to be modified by the user.

- In addition, the known errors and limitations from firmware version 2021.0 LTS also exist in this firmware version. See section 6.3 “Known limitations and errors” on page 9.

#### 5.4 Security updates

The following security updates have been made in this release. For more information about the specified CVE numbers, see:

- <https://nvd.nist.gov/vuln>
- <https://cert.vde.com>

Information on the Phoenix Contact “PSIRT” can be found at: <https://www.phoenixcontact.com/psirt>

#### SSL

- CVE-2020-1971

#### SNMP

- The SNMP “Get” call of “OID .1.3.6.1.2.1.2.2.1.6.0” for network interface used as PROFINET controller or device caused the firmware to crash.

## 6 Changes in firmware version 2021.0 LTS



To be able to use all new functions of the firmware, you need PLCnext Engineer version 2021.0 LTS.  
Select the latest template for firmware version 2021.0 LTS in the PLCnext Engineer project.

### 6.1 New functions

#### Articles

With this firmware version the following articles are supported for the first time:

- AXC F XT EXP (Order No. 1139999)

#### IEC 61131

- Backup and restore of GDS retain variables is supported.
- The priority of the Linux thread representing an ESM task of type „IDLE“ has been increased. It is now just below the lowest ESM priority (15). This results in less jitter and faster execution of the associated program instances due to less interruptions.  
As a consequence the IDLE task can now interrupt the „Globals“ task which updates system variables and IEC 61131-3 resource global variables that are connected with I/O. To prevent this Phoenix Contact recommends to select appropriate „update tasks“ in the PLCnext Engineer project.

#### WBM

- Security related product information is available via links in the „Help“ menu in the header of the WBM and in the „Tip of the day“ section on the start page.
- IO-Link diagnostic information is available in the Axioline tree view on the „Local Bus“ page.
- The „System Use Notification“ can be edited on the „User Authentication“ page in the „Security“ area.
- The „System Use Notification“ is displayed when logging in to WBM or PLCnext Engineer.
- The HTTPS certificate can be configured on the „Web Services“ page to avoid browser security warnings.

#### PROFINET

The PROFINET controller and device can be enabled and disabled separately via configuration file.

#### Proficloud

„Proficloud V3 TSD service“ is supported and replaces the „Proficloud TSD service“. Hereby the change from „www.proficloud.net“ to „www.proficloud.io“ is necessary.

#### OPC UA

The following topics apply to projects created with PLCnext Engineer 2021.0 LTS for a controller of firmware 2021.0 LTS:

- The new security policies „AES 128 SHA256 RSA OAEP“ and „AES 256 SHA256 RSA PSS“ are supported. These policies can be selected in the OPC UA configuration.
- When the UA server checks the certificate of the connecting client, the „ApplicationURI“ from the client's „ApplicationDescription“ has to match to the „SubjectAlternateURI“ in the client's certificate. This check is performed by default for new projects as well as when an older controller is replaced by a controller of firmware 2021.0 LTS in the PLCnext Engineer project. If necessary the check can be suppressed by deactivating the „Check application URI against client certificate“ checkbox in the OPC UA configuration in PLCnext Engineer.
- When the UA server is configured to use a „self-signed“ certificate, the trust store „OpcUA-configurable“ is used. The client certificate is checked against the Trust List and the Certificate Revocation List is applied. This applies to new projects as well as when an older controller is replaced by a controller of firmware 2021.0 LTS in the PLCnext Engineer project. Previous versions used the trust store „Empty“ as default and no client authentication was applied. If necessary the former default can be applied by deactivating the „Use the truststore for client authentication“ checkbox in the OPC UA configuration in PLCnext Engineer.
- The „SubscriptionKind“ can now be selected in the OPC UA configuration in PLCnext Engineer. The options „Direct Read“, „High Performance“ and „Real Time“ are available. „Direct Read“ is set as default for new projects as when an older controller is replaced by a controller of firmware 2021.0 LTS in the PLCnext Engineer project.  
The previous default „Real Time“ can be selected if required.

#### PLCnext Store

Multiple controller types are supported in the app extension („app\_info.json“).  
During the installation of the app, the extension checks if the version of the app is suitable for the controller used.

## HMI

- Trending data services in interaction with the PLCnext Engineer HMI trending functionality are supported.
- Multiple project languages in interaction with PLCnext Engineer HMI language settings are supported.

## Docker

For Docker support a possible co-existence of „iptables“ and „nftables“ is useful. Therefore the default firewall configuration has been adjusted.

The names of the following tables and chains have been changed:

Old name	New name
FILTER	<b>plcnext_filter</b>
input	<b>plcnext_input</b>
output	<b>plcnext_output</b>
basic_filter	<b>plcnext_basic_filter</b>
user_input	<b>plcnext_user_input</b>
user_output	<b>plcnext_user_output</b>

For compatibility with existing firewall configurations, the new settings also contain the old names as „deprecated-Name“.

## IO-Link

The IO-Link system integration refers to all types of IO-Link master modules from Phoenix Contact which can be driven by the PLCnext controllers via PROFINET or Axioline:

- AXL F IOL8 2H (Order No. 1027843)
- AXL SE IOL4 (Order No. 1088132)
- AXL F IOL8 2H (Order No. 1027843)
- AXL SE IOL4 (Order No. 1088132)
- AXL E PN IOL8 DI4 M12 6M (Order No. 2701519)
- AXL E PN IOL8 DI4 M12 6P (Order No. 2701513)
- IOL MA8 PN DI8 (Order No. 1072838)

**Note:** A support by PLCnext Engineer is planned for version 2021.3.

## 6.2 Error corrections

The following errors have been rectified:

### WBM

- When displaying the network settings, an empty page could be displayed if a parameter could not be read. Now the page is displayed completely and affected parameters are shown as „N/A“.
- When adding a new user in the user administration, the entered password was not deleted if the process was cancelled with „Cancel“.
- When using the Internet Explorer for LDAP configuration, a new LDAP server entry could not be created successfully.
- Spelling mistakes in various messages of the WBM have been corrected.
- If an INTERBUS peripheral error occurred that was resolved and acknowledged by the application, the „Local Bus (Interbus)“ page was not reset and the error was still displayed.
- After downloading a PLC project, the name of the project was not immediately displayed in the WBM. The page had to be refreshed in the browser by the user.
- Conflicting error messages occurred when entering invalid characters on the „Certificate Authentication“ page.

### IEC 61131

- The system could sporadically crash during the „Write and Start Project Changes“ process if the PLCnext Engineer HMI component was reading variables at the same time. This fix has the following effects on the „Write and Start Project Changes“ process:
  - GDS: Services respond with status „CurrentlyUnavailable“
  - OPC UA: It is not possible to update values and browse variables
  - PLCnext Engineer HMI: Use replacement value „0“
- Exceptions in connection with managed C# code used in the PLC project were not handled correctly. This could cause the IEC 61131 runtime to stop responding. Now the exception is shown/listed including the call stack.
- An unexpected PLC task watchdog could occur in a low-priority task with a very long cycle time in connection with cold, warm and hot restart.
- When reading the eCLR error catalog with PLCnext Engineer, the firmware of the standard controller (SIGSEGV) could sporadically crash. This subsequently raised a software watchdog.

- After starting the PLC project, the system variables for the system time were only maintained with a delay. As a result, the value „0“ was displayed for several cycles.
- PROFINET plug alarms could not be reported via the function block „RECV\_ALARM“.
- The cyclical call of the function block „AR\_STATISTIC“ led to a very high system load up to the sporadic reduction of the PROFINET communication.
- When executing the function blocks „RDREC“ and „WRREC“ in fast succession, it could happen that the corresponding PROFINET AR was removed and the function blocks could not process any further services. Corresponding error messages were issued.

### PROFINET

- Under various project conditions, PROFINET performance could deteriorate or unexpected connection failures could occur.  
Extensive PROFINET performance optimizations have been made to eliminate this behavior.
- When reading the PROFINET device of the controller via PLCnext Engineer, it could happen that the matching module „I/O 512“ could not be determined.
- The system variable „PNIO\_CONFIG\_STATUS“ did not match the documented behavior. The corrected behavior now shows the value 3 after a successful connection setup. Bit 0 (Ready) and Bit 1 (Active) are set.
- No more DCP or DCERPC frames were sent after changing the local date or time of the controller. As a result, PROFINET could not function properly.
- The PROFINET controller performance was improved.

### RSC

The RSC service „Write DeviceSettings“ with the parameter „Rtc.Date“ had not considered leap years and had rejected corresponding settings with „OutOfRange“.

### System

- When restarting the PLCnext firmware after a software reset, an exception could occur very sporadically. This meant that the firmware could not be started properly.
- Sporadically it could happen that a remoting based communication (such as that of PLCnext Engineer) could not be established if connection requests were already sent to the controller during the boot phase.
- During the reboot of the controller a system watchdog could occur very sporadically. Especially when triggering the reboot via SSH terminal the current retain data of the PLC project could be lost.

- An SD card that was removed during operation triggered a stop of the PLC project, although the support of an external SD card was deactivated in the WBM configuration.
- The status LED on the device was blinking with the wrong frequency in case of a removed external SD card. It has been corrected according to the description.
- Reading „Status.Memory.Usage.Percent“ via RSC interface was only possible with the user role „Admin“.
- If an app with temporary data was installed but not started and then the controller was restarted, the folder previously created for the app was deleted. As a result, the app could not access the folder after starting.
- The cold start event task was no longer executed during a cold start of the PLC project if a change was previously made that caused a cold start (e.g. change of project name).
- The basic CPU usage of the system was improved.
- The default text of the „System Use Notification“ was improved. The „System Use Notification“ is displayed when logging in to the controller (e.g. WBM or PLCnext Engineer).
- The file name of the firmware update container was changed.  
Now the complete firmware version is considered.

### OPC UA

- With certain method calls the status „Bad“ of the OPC UA server could occur during download changes of the PLC project.
- Due to an unfavorable startup sequence of the OPC UA component it could happen that certain alarms could not be detected in time.
- Browsing from a node to a child node and back did not work.
- When a value which shall be written to a STRING variable exceeds the maximum length of this variable, then writing is rejected with the error code „Bad\_OutOfRange“.  
In previous versions the UA server truncated the value to the maximum length of the variable.



### 6.3 Known limitations and errors

- Retain variables
  - If a requested warm start is not possible to execute via PLCnext Engineer, an implicit cold start is automatically executed. The retain variables are set to their initialization value.
  - After a system watchdog, only a cold start can be performed when the controller is started. The retain variables are set to their respective initialization values.  
From firmware 2021.0 LTS a dedicated state of the retain values can be restored from a backup.
- Retain handling  
With extended retain handling in the context of this firmware, the retain variables are reinitialized by a cold start when downgrading to firmware 2020.3 or older. A previous saving of the retain variables by the user is not supported with firmware 2020.6 and older.
- Retain variable behavior in case of firmware downgrade  
If firmware 2020.0 LTS or later is downgraded to 2019.9 or older and then upgraded again to firmware version 2020.0 LTS or later, a cold start is performed. The retain variables are set to their initialization value.
- PLCnext CLI version  
The PLCnext CLI version used must match the current SDK for this version. Downward compatibility cannot be guaranteed.
- EthernetIP  
If the firewall is activated via WBM, the operation of EthernetIP is no longer possible.  
This can be remedied by subsequently activating the ports:
  - Incoming connections: **port 44818**
  - Outgoing connection: **port 2222**
- Firmware downgrade  
After downgrading the firmware, it is recommended to reset to „Default setting type 1“. This is not necessary when updating the firmware.
- PROFINET PRL support  
Firmware version 2021.0.0 LTS is the last version which supports PROFINET PRL (Phoenix Redundancy Layer).  
Future versions will no longer support this feature.
- Firmware startup  
If the PLCnext system firmware has not started up properly, the WBM displays the error message „Bad Gateway 502“.
- Task name  
If „Event“, „EventTask“ or „Globals“ is used as the name of a task, an error condition of the controller occurs when the project is downloaded.  
This is because „Event“, „EventTask“ and „Globals“ are already used internally as class name.
- DHCP  
DHCP can only be switched on for Ethernet adapters that are not assigned as PROFINET controllers or PROFINET devices. To make the settings effective in the network, the device must be restarted.
- Variables  
The content of the variables „ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_COUNT“ and „ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_INTERVAL“ is permanently set to 0.
- HMI pages during program downloads  
During a PLCnext Engineer program download (both total and changes), the web server returns an error 503 (busy) for requests to the HMI pages.
- Multiple DataLogger Sessions  
If two or more DataLogger sessions are configured to write to the same database, only the data of one session will be transferred to the database on the SD card at the end. The user does not receive a message that not all data can be saved.
- Retain data  
Using the maximum quantity structures of the retain data can increase the task duration of the using task. This can trigger a task watchdog for time-critical applications.
- Crash during startup phase  
The system watchdog is not yet active during the start-up phase if you start C++ extensions very early. If the user code causes a crash during this phase, this can lead to an endless boot loop.  
You can solve the problem by removing the SD card before rebooting.
- STRING variables  
Access to long STRING variables outside the application is limited to 511 bytes. This concerns reading and writing via the RSC services „IDataAccessService“ and „ISubscriptionService“. These services are used by OPC UA, PLCnext Engineer HMI and the online functions of PLCnext Engineer, among others.
- „Download Changes“  
Sporadically a PLCnext Engineer project may reject „Download changes“ without giving a reason.
- Uninstalling Solution Apps  
When a Solution App is uninstalled by the PLCnext Store, it can happen that the controller then no longer reacts to any actions by the PLCnext Store, al-

though it reports the status „online“. A system watchdog was also sporadically observed. This behavior has not been observed when using the offline deactivation in the WBM for uninstalling a solution app.

- LAN gateway settings  
AXC F 2152 in combination with AXC F XT ETH 1TX extension module: If there are several „Default Gateway“ settings, only the setting of the first network interface is applied. The settings of other LAN adapters are ignored. Only one „standard gateway“ is supported internally.
- Local time zone setting  
Setting local time zones is not fully supported.
- „DBG“ LED  
The „DBG“ LED should signal if a variable has been set via forcing in debug mode in the PLC project. This behavior is currently not supported. Despite forcing the variable, the „DBG“ LED remains off.
- „Link“ and „Active“ LEDs  
The „Link“ and „Active“ LEDs on the network interfaces „X1“ and „X2“ are not active when a „10BaseT“ connection is used.
- PROFINET cycle time  
The use of a PROFINET cycle time of 1 ms leads to a deviation of the jitter behavior required by the controller certification.  
Operation in this state is possible, but not recommended.

## 6.4 Security updates

The following security updates have been made in this release. For more information about the specified CVE numbers, see:

- <https://nvd.nist.gov/vuln>
- <https://cert.vde.com>

Information on the Phoenix Contact „PSIRT“ can be found at: <https://www.phoenixcontact.com/psirt>

### WBM

- CVE-2020-12517

### System

- CVE-2020-12518

### Shell

- CVE-2020-12519

### LLDP

- CVE-2020-12521

## 7 Changes in firmware version 2020.6.1



To be able to use all new functions of the firmware, you need PLCnext Engineer version 2020.6.  
Select the latest template for firmware version 2020.6.1 in the PLCnext Engineer project.

### 7.1 New functions

#### WBM

The connection to existing LDAP(S) servers can be configured in WBM.

#### GDS

Enhanced Retain Handling:

When changes to retain variables are transferred to the controller via „Download All“, no implicit cold start is performed. As many retain values as possible are retained. This behavior of the retain variables corresponds to the „Download Changes“ behavior, where all variables are retained even if the project is changed at runtime.

To avoid data inconsistencies with retain variables, the retain variables are always initialized by an implicit cold start after a project change (project name). In the previous firmware versions a warm start was only carried out if the retain variables were exactly the same.

#### IEC 61131

- Improvement of jitter and latency for programs with IEC 61131 or C# context..
- New system variable „USER\_PARTITION“ to display the load of the user partition with the following elements:
  - MEM\_TOTAL
  - MEM\_FREE
  - MEM\_USED
  - MEM\_USAGE

#### PROFINET

Support of Fast Startup (FSU) by the PROFINET controller (up to 16 FSU devices).

#### OPC UA

- User comments on the confirmation and acknowledgment of alarms via OPC UA are supported. The comments are also entered in the „Notification Logger“.
- Basic support for loading new user-specific information models into the OPC UA server.

#### DataLogger

New RSC-API „IDataLoggerService2“ for application of the DataLogger. The triggered logic analysis in PLCnext Engineer is based on this API.

#### Network

Support of a DHCP basic functionality for IP address allocation.

#### SDK/C++

The GCC compiler has been updated from version 8.3 to version 9.3. All newly created applications are now compiled on this basis.

#### PROFICLOUD

PROFICLOUD V3 basic support (firmware update from the cloud).

### 7.2 Error corrections

The following errors have been rectified:

#### WBM

- The call of WBM pages could sporadically lead to a PROFINET connection termination.
- When configuring new firewall rules in WBM, not all available network interfaces were displayed.
- There was no character limitation when entering user or password. After 64 or 128 bytes the input string was cut off without error message.
- A notification field of a message was displaced in the „Notifications“ menu when switching languages.
- Certain UTF-8 special characters could not be entered in the „Username“ input field in the „User Authentication“ menu.  
An empty error message was displayed.
- In the „Certificate Authentication“ menu, the key type „RSA TPM 2048“ was displayed in the „Add Identity Store“ entry by mistake.

## IEC 61131

- A „Fatal Exception“ could occur if the project was to be restarted after debugging the project while following a certain procedure.
- If a PLCnext Extension component (ACF or PLM) or a PLCnext Engineer Shared Native Library was to be linked against a non-existent „shared object library“, a crash could occur.
- From this version on, the block „RTC\_S“ returns the local time, provided a time zone with root rights has been set before.  
In previous versions, the UTC time was always returned.

## DataLogger

- The project could not be loaded if an exception was thrown due to too many configured variables in a DataLogger session.  
In this case the notification „Arp.Services.DataLogger.Error“ is now displayed. The project is loaded without starting the incorrectly configured DataLogger session.
- The firmware could not be accessed if the parameter „maxFileSize“ was too large during a DataLogger session that writes to a volatile sink.

## PROFINET

- When loading projects that were created with PLCnext Engineer 2020.3, a notification „Arp.Io.PnC.ConfigurationWarning“ with the severity „Warning“ can be triggered. The PayLoadString is „Parsed FSPParameterUUID '{}' has invalid format. Parameter will be ignored. Please check engineering and/or device description“.  
This problem has been fixed in PLCnext Engineer 2020.6 or later.
- The PROFINET connection setup could take a relatively long time if many nodes were used.
- The PROFINET controller could only process 10 RPC requests at a time. So far „nca\_server\_too\_busy“ was reported back to the PROFINET devices. Some devices did not repeat their RPC request.  
The PROFINET controller can now accept up to 45 RPC requests simultaneously.
- The controller sporadically had incorrect IP settings after a DCP factory reset was requested by the higher-level PROFINET controller.
- After switching off MRP, an AXC F 2152 was no longer accessible as a device.

## GDS

- In case of fatal error (e.g. SIGSEGV) in a C++ program, a system watchdog could be triggered cyclically. Under certain circumstances this could also be caused by a faulty GDS configuration.
- When using the Write functions of the „IDataAccessService“ RSC service, the variable could not be overwritten correctly if the data type of the overwrite value did not match the data type of the variable to be overwritten.

## RSC

When using certain RSC services simultaneously, an exception in „CommonRemoting“ or a „Protocol violation“ ERROR could occur.

## ESM

In rare cases the detected watchdog of an ESM task was not handled correctly. Thereupon the firmware was terminated.

## System

- During system startup, a system watchdog could be triggered if, for example, a higher-level PROFINET controller changed the IP settings via DCP protocol.
- With the C++ function „Directory::Clear(path)“ from the namespace „Arp.System.Commons.Io“ a directory could not be cleared as long as it was viewed with WinSCP.
- Names of NTP servers could not be set if they contained more than 2 dots.
- Under certain operating conditions cyclic error messages were entered in conjunction with LLDP. These messages are not errors and were therefore reclassified as debug information.
- When setting the IP address via DCP, an error message was erroneously entered in the „Output.log“, although the setting was successful.

## INTERBUS

With the AXC F 2152 in conjunction with the AXC F IL ADAPT extension module, the error „SYSFAIL“ could occur when working with breakpoints. If, after working with breakpoints in a project, the program continued running without entering a breakpoint again, the „SYSFAIL“ signal was not reset. Although the fieldbus continued to run, process data exchange was no longer possible.

## Docker

An issue related to calling the Docker „exec“ command to install or configure a Docker Container was fixed. So far only the Docker „run“ command could be used.

### 7.3 Known limitations and errors

- Retain variables
  - If a requested warm start is not possible to execute via PLCnext Engineer, an implicit cold start is automatically executed. The retain variables are set to their initialization value.
  - After a system watchdog, only a cold start can be performed when the controller is started. The retain variables are set to their respective initialization values.
- PLCnext CLI version
 

The PLCnext CLI version used must match the current SDK for this version. Downward compatibility cannot be guaranteed.
- EthernetIP
 

If the firewall is activated via WBM, the operation of EthernetIP is no longer possible. This can be remedied by subsequently activating the ports:

  - Incoming connections: **port 44818**
  - Outgoing connection: **port 2222**
- DHCP
 

DHCP can only be switched on for Ethernet adapters that are not assigned as PROFINET controllers or PROFINET devices. To make the settings effective in the network, the device must be restarted. In general, when DHCP is switched on, the current IP settings are not yet displayed in the WBM and on the display, but the static settings last set are displayed.
- Retain handling
 

With extended retain handling in the context of this firmware, the retain variables are reinitialized by a cold start when downgrading to firmware 2020.3 or older. A previous saving of the retain variables by the user is currently not supported.
- Variables
 

The content of the variables „ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_COUNT“ and „ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_INTERVAL“ is permanently set to 0.
- HMI pages during program downloads
 

During a PLCnext Engineer program download (both total and changes), the WebServer returns an error 503 (busy) for requests to the HMI pages.
- Multiple DataLogger Sessions
 

If two or more DataLogger sessions are configured to write to the same database, only the data of one session will be transferred to the database on the SD card at the end. The user does not receive a message that not all data can be saved.
- Internal network interface
 

Sporadically, frequent calls of PROFINET Read or Write REC may cause communication to the corresponding AR to be disturbed and a connection termination may occur.
- Retain data
 

Using the maximum quantity structures of the retain data can increase the task duration of the using task. This can trigger a task watchdog for time-critical applications.
- STRING variables
 

Access to long STRING variables outside the application is limited to 511 bytes. This concerns reading and writing via the RSC services „IDataAccessService“ and „ISubscriptionService“. These services are used by OPC UA, PLCnext Engineer HMI and the online functions of PLCnext Engineer, among others.
- SDK
 

The SDK only works with PLCnext CLI 2020.0 or later, not with older versions (both PLCnext CLI 2019.x and PC WORX Target for Simulink 2019.x).
- If the controller is rebooted using the Linux command „sudo reboot“ or the RSC service „IDeviceControlService::RestartDevice()“ (also used by the „Reboot“ button in the PLCnext Engineer cockpit), a system watchdog may occur in rare cases. This means that only a cold start is possible when the controller is subsequently booted, i.e. all retain variables are reinitialized.
 

This behavior does not occur when the operating voltage is switched off and then booted.
- Crash during startup phase
 

The system watchdog is not yet active during the start-up phase if you start C++ extensions very early. If the user code causes a crash during this phase, this can lead to an endless boot loop. You can solve the problem by removing the SD card before rebooting.
- PROFINET name
 

If firmware 2020.6 is downgraded to an older version, the PROFINET name is lost.
- Debugging of IEC 61131 code
 

When debugging IEC 61131 code with activated breakpoints, display errors may occur in the call sequence function and variable contents.
- „Download Changes“
 

Sporadically a PLCnext Engineer project may reject „Download changes“ without giving a reason.
- RTC setting
 

After setting a local time zone, unexpected results may

occur when reading out times from different contexts (RTC-S FB, OPC UA, SPNS LOG).

- Restriction for Device Info service  
The „DI - Device Info - Status.Memory.Usage.Percent“ service no longer returns a value with the following roles:
  - „Engineer“
  - „Commissioner“
  - „Service“
  - „DataViewer“
  - „DataChanger“
  - „Viewer“
  - „UserManager“
- Controller in error state  
When using „Event“ as name of a program, an error condition of the controller occurs when downloading the project. „Event“ is already used internally as class name.
- Firmware downgrade  
After downgrading the firmware, it is recommended to reset to „Default setting type 1“. This is not necessary when updating the firmware.
- Retain variable behavior with firmware downgrade  
If firmware 2020.0 or later is downgraded to 2019.9 or older and then upgraded again to firmware version 2020.0 or later, a cold start is performed. The retain variables are set to their initialization value.
- Bus behavior after power failure  
If an Axioline bus contains a power terminal and a Smart Elements module with empty slots, the bus will not restart after a power failure.
- AXC F 2152 with extension module  
AXC F XT ETH 1TX  
If both network adapters are configured with the same „Subnet Mask“, the PROFINET controller functionality will not work as desired. A proper connection setup is not possible.
- Uninstalling Solution Apps  
When a Solution App is uninstalled by the PLCnext Store, it can happen that the controller then no longer reacts to any actions by the PLCnext Store,

although it reports the status „online“. A system watchdog was also sporadically observed. This behavior has not been observed when using the offline deactivation in the WBM for uninstalling a solution app.

- Task watchdog  
A task watchdog may sporadically occur with a low-priority PLC task with a cycle time in the range of seconds if the running PLC project was stopped and immediately restarted with a cold/warm/hot start.
- After resetting the controller there is no TrustStore with the name „proficloudv3“. The TrustStore is necessary for the update via ProficloudV3.  
Workaround: Re-create the TrustStore in the WBM of the controller.
- Gateway settings LAN2  
AXC F 2152 in combination with AXC F XT ETH 1TX extension module: If there are several „Default Gateway“ settings, only the setting of LAN1 is used. The settings of other LAN adapters are ignored.

## 7.4 Security updates

The following security updates have been made in this release. For more information about the specified CVE numbers, see:

- <https://nvd.nist.gov/vuln>
- <https://cert.vde.com>

Information on the Phoenix Contact “PSIRT“ can be found at: <https://www.phoenixcontact.com/psirt>

### OpenSSL

- CVE-2020-1967

### Python

- CVE-2020-8492

### System

- Activation of security-relevant compiler flags (e.g. to prevent unauthorized introduction of executable code).
- Correction of a problem that RSC-Services of fieldbus components could be used without authentication.

### OpenSSL

- The outdated OpenSSL version 1.0.2 is no longer supported. Instead, the current OpenSSL version 1.1.1 is used.

## 8 Changes in firmware version 2020.3.1



To be able to use all new functions of the firmware, you need PLCnext Engineer version 2020.3.  
Select the latest template for firmware version 2020.3.1 in the PLCnext Engineer project.

### 8.1 New functions

#### System

You can now set the parameters for the NTP time server protocol in PLCnext Engineer.

#### DCP flashing

DCP flashing for PROFINET controllers/devices of the PLCnext Control family has been implemented.

#### PROFINET diagnostics

The PROFINET controller provides diagnostic information as function block "ARStatistik".

#### New functions in WBM

- Display and download of the notification log  
The notifications are displayed in the WBM on a separate page.
- Extended Ethernet display  
The WBM provides an extended display of information about the Ethernet configuration of all available LAN interfaces.

#### Docker

"Docker" is supported for all articles of the PLCnext family. Additionally the "Balena Engine" is supported. ("nftables" configuration, "cgroups" are mounted at boot time).

#### OPC UA server

- Configurable "subscription type"  
The component can now be configured using the configuration file "PCWE.opcua.config", e.g. using the PLCnext Engineer software.
- Support of "DateTime"  
The data type "DateTime" is supported via OPC UA in any nesting, e.g. Structs, ArraysOf ..., Simple Var, FBs etc.

#### Linux

The packages for "rsync" for file synchronization are supported.

### 8.2 Error corrections

The following errors have been rectified:

- System files  
System files modified with "root" access could prevent proper reboot after a firmware update.
- Axioline  
In conjunction with the AXC F XT IB module, the contents of the diagnostic parameter registers in the system variables were swapped.
- WBM
  - Some WBM diagnostic pages were not displayed correctly with Internet Explorer.
  - On the WBM page for network configuration, the name "Baud rate" was incorrect. This was changed to "Data rate".
  - A WBM session of a logged on user was never terminated if a page with cyclically updated data was open.
  - An eHMI user could never log out completely.
- IEC 61131  
An error could occur when restoring the retain data after a reboot.  
This behavior only occurred in the PLCnext Engineer project if program instances were moved to another ESM task.
- DataLogger  
After a firmware update, logging into the DataLogger database did not work anymore if the database design had changed.
- RSC  
Synchronous execution of RSC services without security context was not supported and could lead to an unexpected error message.

### 8.3 Known limitations and errors

- Retain variables
  - If a warm start is requested via PLCnext Engineer and this is not possible internally, an implicit cold start is automatically executed. The retain variables are set to their initialization value.
  - After a system watchdog, only a cold start can be performed when the controller is started. The retain variables are set to their initialization values.
- Special characters
 

When using UTF8 special characters (Unicode) for the user name and password, the length restriction (user name = 64 bytes, password = 128 bytes) can take effect, although the maximum character length was not used. This reason is that the number of bytes and not the number of characters is limited in the RSC service.
- OpenSSL
 

For security reasons, applications should no longer be linked against the outdated OpenSSL version 1.0.2.
- PLCnCLI version
 

The PLCnCLI version used must match the current SDK for this version. Backward compatibility cannot be guaranteed.
- GNU compiler
 

With the GNU compiler types GCC (8.3.0, 9.2.1) used, a quadratic increase in compilation time and memory consumption on the desktop PC is observed when very large structures are used.

Note this behavior if you use a large number of ports in PLCnext applications (e.g. connection of a very large number of Simulink signals).
- EthernetIP
 

If the firewall is activated via WBM, the operation of EthernetIP is no longer possible.

This can be remedied by subsequently activating the ports:

  - Incoming connections: **port 44818**
  - Outgoing connection: **port 2222**
- System variables
 

The system variables ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_COUNT and ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_INTERVAL are no longer supported.

Now, the value of the variables is always 0.
- Error during program download
 

During a program download (both complete and modifications) in PLCnext Engineer, the WebServer returns error 503 (busy) for requests to the HMI pages.
- DataLogger
 

If two or more DataLogger sessions are configured to write to the same database, only the data from one session is transferred to the database on the SD card. You will **not** receive a message that not all data can be saved.
- Debugging
 

After debugging a PLCnext Engineer project with breakpoints, the project may stop after restarting.
- PROFINET connection setup
 

The PROFINET connection setup can take a long time in combination with a very large PROFINET structure.
- PROFINET Read/Write
 

Frequent calls of PROFINET Read or Write REC may disturb the communication to the corresponding AR. A connection termination may occur.
- Increased task duration caused by retain data
 

If the maximum retain data volume is used, the duration of the task may increase. A task watchdog could be triggered in time-critical applications.
- STRING variables
 

Access to long STRING variables outside the application is limited to 511 bytes. This concerns reading and writing via the RSC services "IDataAccessService" and "ISubscriptionService".

These services are used by OPC UA, PLCnext Engineer-HMI and the online functions of PLCnext Engineer, among others.
- SDK and PLCnCLI
 

The SDK only works with PLCnCLI 2020.0 or later, not with older versions (both PLCnCLI 2019.x and PC Worx Target for Simulink 2019.x).
- Reboot via Linux shell
 

After rebooting the controller via the Linux shell, a system watchdog may occur in rare cases. When the controller is subsequently booted, only a cold start is possible. This initializes all retain variables.

This behavior only occurs when rebooting via the Linux shell. No system watchdog was observed when the controller lost power.
- OpenSSL update
 

Updating the OpenSSL version 1.0.2 to version 1.1.1 can lead to problems with existing C++ applications that are based on this and run in the same process (e.g. function extensions). Phoenix Contact recommends



paying attention to possible updates in the PLCnext Store.

In the event of incompatibility, the firmware may not start up.

- Switching off MRP  
After switching off MRP, a restart of the AXC F 2152 is required in order for it to work properly.
- Bus behavior after power failure  
If an Axioline bus contains a power terminal and a Smart Elements module with empty slots, the bus will not restart after a power failure.
- Crash during startup phase  
The system watchdog is not yet active during the start-up phase if you start C++ extensions very early. If the user code causes a crash during this phase, this can lead to an endless boot loop.  
You can solve the problem with a “factory reset”.
- PROFINET name  
If firmware 2020.3 is downgraded to an older version, the PROFINET name is lost.
- Debugging IEC 61131 code  
When debugging IEC 61131 code with activated breakpoints, display errors may occur in the call sequence function and variable contents.
- “Download Changes”  
Occasionally “Download Changes” may be rejected in a PLCnext Engineer project without stating a reason.

#### 8.4 Security updates

The following security updates have been made in this release. For more information about the specified CVE numbers, see:

- <https://nvd.nist.gov/vuln>
- <https://cert.vde.com>

Information on the Phoenix Contact “PSIRT” can be found at: <https://www.phoenixcontact.com/psirt>

##### git

- CVE-2019-19604
- CVE-2019-1387
- CVE-2019-1348

##### vim

- CVE-2019-20079

##### sqlite3

- CVE-2019-19646
- CVE-2019-19645
- CVE-2019-16168
- CVE-2019-8457

## 9 Changes in firmware version 2020.0.1 LTS



In interaction with this firmware the following points are not necessary:

- Update of PLCnext Engineer
- Update of SDK files for high-level language applications

### 9.1 Error corrections

The following problems have been fixed:

- A problem that led to cyclical connection terminations of the PROFINET application relationships (AR). This behavior occurred depending on the cycle times of the ESM tasks.
- A problem that caused an incorrect recovery of the retain data after a reboot of the controller. This behavior only occurred if program instances in the PLC project were moved to another ESM task.
- A problem that caused the controller to stop booting after resetting the controller to factory default type 2 (factory default). In this state the BOOT LED flashes red (2 Hz). The LED D is permanently yellow.
- A problem that was possible in conjunction with OPC UA. Scalar data types could be written with the wrong data type. This could lead to incorrect data in the IEC project when overwriting with larger data types. The error code "StatusCodes.BadTypeMismatch" would be expected here.

## 10 Changes in firmware version 2020.0 LTS



If you changed system files via a "root" access, the controller might not start up correctly after a firmware update.

- In this case, reset the controller to default setting type 1.

### 10.1 New functions

#### Offline installation of apps from the PLCnext Store

You can install apps downloaded from the PLCnext Store via the WBM of the controller without Internet connection and activate the corresponding licenses.

#### DataLogger improvements

- When configuring the DataLogger, you can specify the percentage of data to be deleted when the database reaches its maximum size (attribute "deleteRatio").
- You can configure the data format of time and date (attribute "tsfmt").



For more detailed information on configuring the DataLogger, please refer to the "PLCnext Technology" user manual. The user manual can be downloaded at [phoenixcontact.net/product/2404267](https://phoenixcontact.net/product/2404267).

#### Axioline Smart Elements

The controller supports Axioline Smart Elements.

#### Implementation of the "SysV IPC" Linux extension

With this extension, you can use the three IPC techniques (semaphore, message queue, and shared memory) of "SysV".

#### OpenSSL update to version 1.1.1

The OpenSSL library has been updated to version 1.1.1.



#### Recommended:

- Use version 1.1.1 of the OpenSSL library. The older version 1.0.2 of the OpenSSL library is still part of the firmware for reasons of downward compatibility.

#### Docker software support

Options for support of the Docker software have been enabled in the Linux kernel.

## 10.2 Error corrections

- Task execution  
Sporadically a task was not executed correctly in the given cycle.  
This error has been rectified.
- eHMI visualization after “Download Changes”  
After downloading program changes to the controller, the eHMI visualization could only be used after reloading the page in the browser.  
This error has been rectified.
- Data exchange with PROFICLOUD  
If variable values from an ESM1 task and from an ESM2 task were to be transferred to PROFICLOUD at the same time, the data exchange with PROFICLOUD was interrupted.  
This error has been rectified.
- Accessing an undefined element in the array  
When accessing an undefined element within a multidimensional array (“Array of Array” or “Array of Struct”) with OPC UA, the controller broke down.  
This error has been rectified.
- Length limitation of strings  
If strings with a length of more than 2993 bytes were created, access with OPC UA or RSC services of the GDS could cause the controller to break down.  
This error has been rectified. As part of the error correction, the length of a string was limited to a maximum of 511 bytes.

## 10.3 Known limitations and errors

- Mixed operation of different OpenSSL versions  
If the use of existing C++ applications (Function Extensions) results in mixed operation of the OpenSSL versions 1.0.2 and 1.1.1, the controller does not boot.  
Recommended: If you are using an app of the type “Function Extension” from the PLCnext Store, check whether an update is already available in the PLCnext Store.
- Automatic cold start  
If you initiate a warm start in PLCnext Engineer and this is not possible internally, a cold start is performed automatically, i.e., the retain variables are reinitialized.
- Cold start after system watchdog  
After a system watchdog, a cold start is performed.
- System watchdog after reboot via shell  
If you restart the controller via the shell, the system watchdog is triggered sporadically.

- Limitation of password and username  
The length of the password is limited to 64 bytes and the length of the user name is limited to 128 bytes. Note that the entered characters are UTF-8 encoded, i.e. one character can occupy up to four bytes (e.g. umlauts).
- PLCnCLI version and SDK version  
The PLCnCLI version must match the current SDK version (2020.0.0). Downward compatibility cannot be ensured.
- One database for several DataLogger sessions  
If you configure two or more DataLogger sessions to write to the same database, only the data from one session is transferred to the database on the SD card. There is no message that not all of the data can be stored.
- STOP of the controller after debugging  
After setting breakpoints in debug mode, the controller can switch to the STOP state when the project is restarted.
- PROFINET connection setup  
In the case of very large PROFINET quantity structures, the PROFINET connection setup can take several minutes.
- PROFINET connection interruptions  
Frequent calls of the “Read Record” and “Write Record” function blocks can occasionally interrupt the PROFINET connection.
- EtherNet/IP™  
If you enable the controller firewall in the WBM, EtherNet/IP™ is no longer available.  
To be able to use EtherNet/IP™ with enabled firewall, you have to activate the ports for incoming and outgoing connections subsequently (port 44818 and port 2222).
- C++ projects  
C++ projects that were created using “WorkerThread” in SDK version 2019.0 LTS have to be compiled again using an SDK version ≥ 2019.3.  
Otherwise, the “WorkerThread” is not loaded after restart of the application.
- Copying configuration files  
If you use the Linux command “scp” **without** the option “-p” to copy configuration files from a Linux PC to the directory /opt/plcnext/projects on the controller, the file permissions are partly set incorrectly.  
Remedy:  
After copying the configuration files, use the Linux command “chmod” to set the file permissions in such a way that the firmware can delete the configuration files in case of “Download Changes” (group: “plcnext”, owner: “plcnext\_firmware”).

- Large amount of retain data  
In projects with a large amount of retain data, the PLC task watchdog infrequently triggers.
- Error message on HMI display  
While a program or program changes are being downloaded to the controller, the “503 (busy)” error message is displayed on a connected HMI display.

## 11 Changes in firmware version 2019.9



If you changed system files via a “root” access, the controller might not start up correctly after a firmware update.

- In this case, reset the controller to default setting type 1.

### 11.1 New functions

#### New function in the WBM

A diagnosis for the local bus is available in the WBM.

#### PROFINET System Redundancy Layer (SRL)

In operation as PROFINET controller or PROFINET device the controller now supports PROFINET SRL.

#### Forcing GDS variables

You can now force GDS variables and thus the I/Os connected via PROFINET or Axioline F.

#### PROFINET controller: Behaviour of the BF-C LED

If you do not configure a PROFINET device or interrupt the connection using the “AR\_MGT” function block, the BF-C LED remains switched off.

### 11.2 Error corrections

- Freezing of the outputs  
A high CPU load and frequent PROFINET disconnections could cause the outputs to freeze.  
This error has been rectified.
- Delay of a variable value during the start of the controller  
If 24 V voltage was applied to a digital input of the Axioline F local bus and the signal was transmitted with a global variable or a port link into the application, there could be a delay of several cycles. The error occurred during the start of the controller.  
This error has been rectified.
- Changing the IP address via DCP  
Changing the IP address via DCP could affect the real-time of the project and trigger the PLC task watchdog.  
This error has been rectified.
- CPU load after PROFINET connection setup  
After many PROFINET connections had been established, the controller could reach 100 % CPU load and the firmware could no longer react.  
This error has been rectified.

- Resetting the IP address via DCP  
If there was a connection to at least one configured PROFINET participant, the PLC task watchdog could be triggered when the IP address was reset via DCP.  
This error has been rectified.
- Setting breakpoints in debug mode  
If a breakpoint was set in debug mode, the PLC task watchdog could be triggered.  
This error has been rectified.
- Error of the Notification Logger  
If an error occurred during a restart of the controller, the Notification Logger was not automatically configured and notifications were not displayed in PLCnext Engineer.  
This error has been rectified.

### 11.3 Known limitations and errors



#### When using SafetyBridge Technology, note the following:

To ensure reliable operation in conjunction with SafetyBridge Technology, make the following settings in PLCnext Engineer.

„/ Profinet“ editor group, „Interface List“ editor:

- Reduction ratio: 8 (or higher)
- Monitor factor: 6 (or higher)

- System variables  
The system variables ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_COUNT and ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_INTERVAL are no longer supported.  
Now, the value of the variables is always 0.
- Copying configuration files  
If you use the Linux command “scp” **without** the option “-p” to copy configuration files from a Linux PC to the directory /opt/plcnext/projects on the controller, the file permissions are partly set incorrectly.  
Remedy:  
After copying the configuration files, use the Linux command “chmod” to set the file permissions in such a way that the firmware can delete the configuration files in case of “Download Changes” (group: “plcnext”, owner: “plcnext\_firmware”).
- Deinstalling a licensed app from the PLCnext Store  
The deinstallation of a licensed app via the PLCnext Store is not possible if you manually deleted the license from the controller beforehand.
- Large amount of retain data  
In projects with a large amount of retain data, the PLC task watchdog infrequently triggers.

- Error message on HMI display  
While a program or program changes are being downloaded to the controller, the "503 (busy)" error message is displayed on a connected HMI display.
- C++ projects  
C++ projects that were created using "WorkerThread" in SDK version 2019.0 LTS have to be compiled again using an SDK version  $\geq$  2019.3.  
Otherwise, the "WorkerThread" is not loaded after re-start of the application.
- EtherNet/IP™  
If you enable the controller firewall in the WBM, EtherNet/IP™ is no longer available.  
To be able to use EtherNet/IP™ with enabled firewall, you have to activate the ports for incoming and outgoing connections subsequently (port 44818 and port 2222).

## 12 Changes in firmware version 2019.0.4 LTS



### When using SafetyBridge Technology, note the following:

To ensure reliable operation in conjunction with SafetyBridge Technology, make the following settings in PLCnext Engineer.

„/ Profinet“ editor group, „Interface List“ editor:

- Reduction ratio: 8 (or higher)
- Monitor factor: 6 (or higher)

Firmware version 2019.0.4 LTS offers the same features as firmware version 2019.0 LTS, but the error described below has been rectified.

### 12.1 Error corrections

- Freezing of the outputs  
A high CPU load and frequent PROFINET disconnections could cause the outputs to freeze.  
This error has been rectified.

## 13 Changes in firmware version 2019.6.3



### When using SafetyBridge Technology, note the following:

To ensure reliable operation in conjunction with SafetyBridge Technology, make the following settings in PLCnext Engineer.

„/ Profinet“ editor group, „Interface List“ editor:

- Reduction ratio: 8 (or higher)
- Monitor factor: 6 (or higher)

Firmware version 2019.6.3 offers the same features as firmware version 2019.6, but the error described below has been rectified.

### 13.1 Error corrections

- Freezing of the outputs  
A high CPU load and frequent PROFINET disconnections could cause the outputs to freeze.  
This error has been rectified.

## 14 Changes in firmware version 2019.6



If you changed system files via a “root” access, the controller might not start up correctly after a firmware update.

- In this case, reset the controller to default setting type 1.

### 14.1 New functions

#### PROFINET stack

The PROFINET controller/device stack was updated from version 6.2 to version 6.3:

- MRP Client function
- SRL S2 function

#### MRP (Media Redundancy Protocol)

You can use the controller as a Media Redundancy Client (MRC) in an MRP ring. The MRC is activated and configured via the higher-level controller and PDEV objects. Only the default domain 0xFFFFFFFF is supported.

#### DataLogger

The DataLogger transfers real-time data from the GDS (Global Data Space) to an SQL based database for recording and storage.

The scope of functions of the DataLogger was extended:

- New recording modes:
  - Storage in case of changes
  - Continuous
- Historical data can be called within a defined period of time.



For more detailed information on the DataLogger, please refer to the “PLCnext Technology” user manual.

#### Updating Axioline F I/O data

The behavior for updates of Axioline F I/O data was changed:

If you do not select a trigger task, the firmware automatically calculates an interval for updating the Axioline F I/O data from the interval times of all available cyclic tasks. Event or idle tasks are not taken into account for the calculation. If no cyclic task is available, the data of the Axioline F modules is updated every 500 µs.

As an alternative to a cyclic task, you can select an idle task for updating Axioline F I/O data.

#### Interval times for cyclic tasks

The interval time of a cyclic task now has to be at least 1 ms. For projects that were created using an earlier firmware version and contain cyclic tasks with interval times < 1 ms, the PLC task watchdog might trigger.

#### TON\_R\_LTIME, TP\_R\_LTIME and TOF\_R\_LTIME function blocks

The time accuracy of the TON\_R\_LTIME, TP\_R\_LTIME and TOF\_R\_LTIME function blocks was improved. Now, also times < 1 ms can be recorded.

To be able to use the improved time accuracy of the function blocks in existing projects, you have to compile the project again and transfer it to the controller.

#### New functions in the WBM

- On the “Profinet” page, the PROFINET topology is displayed in tree view.
- You can activate the support of an external SD card via the WBM.  
If you deactivate the support of an SD card, and the SD card is then inserted into the controller, the SD card is not recognized during the initialization phase of the controller. Therefore, the data from the internal parameterization memory is **not** automatically copied to the SD card.
- The name of the PLCnext Engineer project running on the controller is displayed.
- On the “License Management” page, you can view the licenses of the apps from the PLCnext Store that are installed on the controller.

#### OPC UA Historical Access (HA)

The integrated OPC UA server (eUA) supports access to historical data (OPC UA Historical Access Specification).



### PROFINET controller/device function

- Now, you can select if an application relation (AR) is to be established while the boot project is being loaded.
- The DNS names of the PROFINET controller and the PROFINET devices can now be set via the “IConfigurationService” RSC service. Via the RSC interface, the functions Read(), Write(), GetControllerName() und GetDeviceNames() are now available.



For more detailed information on RSC (Remote Service Calls), please refer to the “PLCnext Technology” user manual.

### 14.2 Error corrections

- HTTPS connection  
After 20 minutes, the connection of an HTTPS client to the HTTPS server used to be disconnected automatically.  
This error has been rectified.
- Static\_String array in C++ programs  
In an array of the type Static\_String (C++), the array size was miscalculated.  
This error has been rectified.
- Disconnection from the HMI web server  
After the DISABLE system variable of the HMI\_CONTROL data structure was set to TRUE, and this way, the connection to the HMI web server was set, the PLCnext Engineer HMI web server and the client were able to connect nevertheless.  
This error has been rectified.
- Controller breakdown in the PROFINET network  
If in a larger PROFINET network, the IP address of a PROFINET device was changed, the controller used to break down.  
This error has been rectified.
- PROFINET diagnostic state in the WBM  
If the application relation (AR) of a PROFINET device was disabled, a wrong diagnostic state was displayed on the “Profinet” page in the WBM.  
This error has been rectified.
- AXC F 2152 as a PROFINET device  
The AXC F 2152 could not be operated as a PROFINET device under PROFINET controllers from third-party manufacturers.  
This error has been rectified.
- SINT type process data elements  
Linking SINT type process data elements led to a run-time error in the application program (LED FAIL).  
This error has been rectified.
- Reading out OPC UA subscriptions  
Reading out OPC UA subscriptions via the “UA Expert” tool was not possible.  
This error has been rectified.
- OPC UA: “IecTime” data type variables  
“IecTime” data type variables were not displayed correctly.  
This error has been rectified.
- OPC UA: Index based monitoring  
Independent of the index set, all data of an array was output during index based monitoring.  
This error has been rectified.
- OPC UA: Index calculation  
Access to an array of the data type StaticString resulted in errors in index calculation.  
This error has been rectified.
- Traces in the format YYYYMMDD  
For traces in the format YYYYMMDD, sometimes the leading 0 was missing for the day.  
This error has been rectified.
- Setting breakpoints  
Setting breakpoints in extensive ST code worksheets resulted in controller freezing.  
This error has been rectified.
- Event task “Cold Start”  
In the following cases, the event task “Cold Start” was not executed:
  - After resetting the controller to default setting type 1 or 2
  - After SFTP transmission of the project and subsequent reboot of the controller
 This error has been rectified.
- Installed apps from the PLCnext store  
Resetting the controller to default setting type 1 or 2 resulted in licensing conflicts for apps from the PLCnext store that were installed on the controller.  
This error has been rectified.

### 14.3 Known limitations and errors

- System variables  
The system variables  
ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_COUNT and  
ESM\_DATA.ESM\_INFOS[\*].ESM\_TICK\_INTERVAL  
are no longer supported.  
Now, the value of the variables is always 0.
- C++ projects  
C++ projects that were created using “WorkerThread”  
in SDK version 2019.0 LTS have to be compiled again  
using an SDK version  $\geq$  2019.3.  
Otherwise, the “WorkerThread” is not loaded after re-  
start of the application.
- EtherNet/IP™  
If you enable the controller firewall in the WBM,  
EtherNet/IP™ is no longer available.  
To be able to use EtherNet/IP™ with enabled firewall,  
you have to activate the ports for incoming and outgoing  
connections subsequently (port 44818 and port 2222).
- HMI applications  
You cannot access an HMI application while a  
PLCnext Engineer project is downloaded to the control-  
ler.  
In this case, an error message is displayed in the web  
browser.
- Copying configuration files  
If you use the Linux command “scp” **without** the option  
“-p” to copy configuration files from a Linux PC to the di-  
rectory /opt/plcnext/projects on the controller, the file  
permissions are partly set incorrectly.  
Remedy:  
After copying the configuration files, use the Linux com-  
mand “chmod” to set the file permissions in such a way  
that the firmware can delete the configuration files in  
case of “Download Changes” (group: “plcnext”, owner:  
“plcnext\_firmware”).
- Deinstalling a licensed app from the PLCnext Store  
The deinstallation of a licensed app via the PLCnext  
Store is not possible if you manually deleted the license  
from the controller beforehand.
- Availability of network services  
In case of frequent and fast linkUp and linkDown in  
large PROFINET quantity structures, the controller can  
infrequently reach 100% CPU load. In this case, net-  
work services are no longer available.
- Restart of a project  
For projects with extremely long task cycle times (e.g.,  
15000 ms), the restart of the project after a project  
download can take several minutes.
- Setting network settings via DCP  
Setting network settings via DCP can affect the real-  
time of the project. For watchdog times  $< 10$  ms, this  
can infrequently result in a triggering of the PLC task  
watchdog.
- SafetyBridge Technology  
Reliable operation in conjunction with SafetyBridge  
Technology is not ensured.  
If you want to use SafetyBridge Technology, use the  
controller with firmware version 2019.3.

## 15 Changes in firmware version 2019.3

### 15.1 New functions

#### PRL (Phoenix Redundancy Layer)

The PROFINET device functionality has been extended to include the PRL function (Phoenix Redundancy Layer).

#### EtherNet/IP™ device function

You can use the controller as an EtherNet/IP™ device.

#### Dynamic bus configuration

The controller supports the dynamic bus configuration of the Axioline F local bus.

#### Left-alignable INTERBUS master


The controller now supports left-alignment of the INTERBUS AXC F XT IB master (Order No. 2403018).

#### PLCnext Store: New app types

The controller supports the execution of the app types “function extension”, “runtime”, “library”, and “solution app”.

### 15.2 Known limitations and errors

- Static\_String array in C++ programs  
The array sizes are incorrectly calculated in Static\_String-type arrays (C++), meaning that access to the second element contained in the array and to those following is incorrect.  
String arrays in IEC 61131 programs are not affected by this.
- AXC F 2152 as a PROFINET device  
The AXC F 2152 cannot be operated as a PROFINET device under PROFINET controllers from third-party manufacturers.
- Monitor time of PROFINET data  
The PROFINET data monitor time must be at least 24 ms. The monitor time is the product of „Reduction ratio“ and „Monitor factor“ (in PLCnext Engineer: „Profinet“ editor group, „Interface list“ editor).



#	Name	Function	Location	RT class	Reduction ratio	Update time	Monitor factor	Monitor time
0	192.168.1.10 / axi-fib-gp-1 / dip-1 / interface-1	RT			8	8	3	24

Reduction ratio	Update time	Monitor factor	Monitor time
8	8	3	24

Figure 1 Monitor time

- Metrics that can be transferred to the PROFICLOUD  
You can transfer up to 194 variable values as metrics into the PROFICLOUD.
- Very high CPU utilization  
The online connection to PLCnext Engineer may be interrupted when the controller CPU utilization is very high.  
The connection interruption is indicated in PLCnext Engineer without any indication of the cause.
- Setting breakpoints is not supported  
Setting breakpoints in debug mode results in the controller becoming unreachable.

## 16 Changes in firmware version 2019.0 LTS



### Please note:

Updating to firmware version 2019.0 LTS will reset the controller to factory default setting type 1. Any application-specific data and projects on the controller will be deleted.

### 16.1 New functions

#### Download changes

The controller now supports the “Download Changes” function. With the “Download Changes” function, program changes can be transferred to the controller during operation without interruption.

This is subject to the following conditions:

- You have not made any changes to the bus configuration.
- You have not changed the process data assignment.
- You have not changed the properties of the existing tasks (e.g., task type, interval, watchdog).
- You have not deleted any tasks or added any new tasks.

#### Left-alignment of Axioline F extension modules

The controller now supports left-alignment of the Axioline F AXC F XT ETH 1TX extension module (left-alignable Ethernet interface, Order No. 2403115).

#### New functions in the WBM

New functions are now available in the web-based management (WBM), e.g., PROFINET diagnostics and firewall configuration.

#### Declaring retentive data

You can now also declare variables from C++ programs as retentive data in PLCnext Engineer.

#### Updating Axioline F I/O data

You can now specify the refresh interval for Axioline F I/O data. This is done by selecting which task triggers the Axioline F I/O data update in the PLCnext Engineer project.

To do this, proceed as follows:

- Double-click on the “Axioline F (x)” node in the “PLANT” area.

The “/ Axioline F” controller editor group opens.

- Select the “Trigger task” view in the “Settings” editor.
- In the drop-down list, select the task that is to trigger the Axioline F I/O data update.




Figure 2 Select Trigger task

If you do not select a task, the update will occur by default every 50 ms.

## 16.2 Known limitations and errors

- AXC F 2152 as a PROFINET device

The AXC F 2152 cannot be operated as a PROFINET device under PROFINET controllers from third-party manufacturers.

- Downloading PC Worx Engineer projects to the controller

You can only download PLCnext Engineer projects to the controller with firmware version 2019.0 LTS that were created and compiled in PLCnext Engineer version 2019.0 LTS. Projects that you created in PC Worx Engineer must be re-created in PLCnext Engineer.

If you download a PC Worx Engineer project to the controller with firmware version 2019.0 LTS, the project will not run on the controller. However, no error message is displayed in PLCnext Engineer.



### Please note:

The PC Worx Engineer software has been renamed to PLCnext Engineer:

- Name up to Version 7.2.3:  
PC Worx Engineer
- Name starting from Version 2019.0 LTS:  
PLCnext Engineer

- Monitor time of PROFINET data

The PROFINET data monitor time must be at least 24 ms. The monitor time is the product of „Reduction ratio“ and „Monitor factor“ (in PLCnext Engineer: „Profinet“ editor group, „Interface list“ editor).

#	Name	Function	Location	RT class	Reduction ratio	Update time	Monitor factor	Monitor time
0	192.168.1.10 / plc-f348-gps-1 / ddp-1 / interface-1			RT	8	8	3	24

Reduction ratio	Update time	Monitor factor	Monitor time
8	8	3	24

Figure 3 Monitor time

- Metrics that can be transferred to the PROFICLOUD

You can transfer up to 194 variable values as metrics into the PROFICLOUD.

- Exceeding CPU system limits

Exceeding the CPU system limits for the controller may result in an interruption of the online connection to PLCnext Engineer.

The connection interruption is indicated in

PLCnext Engineer without any indication of the cause.

- Setting breakpoints is not supported

Setting breakpoints in debug mode results in the controller becoming unreachable.

## 17 Changes in firmware version 1.2.0

### 17.1 New functions

#### Design of a PLCnext Inline station

As an alternative to an Axioline F station, you can now set up a PLCnext Inline station using the controller. To do so, you need the AXC F IL ADAPT Inline adapter terminal (Order No. 1020304). You can directly install the Inline modules in series on the adapter terminal.

#### License verification

When an SD card is used, the controller now verifies if the SD card contains a Phoenix Contact license. You can only use the controller together with an appropriate Phoenix Contact SD card.

### 17.2 Notes on firmware downgrades and resetting the controller



**For performing firmware downgrades, please note the following:**

#### Downgrade to a firmware version $\leq 1.0.2$

After downgrading to a firmware version  $\leq 1.0.2$ , you can only use the controller **with** an SD card. Using it without an SD card is possible starting from firmware version 1.1.0.

- Ensure that the SD card has been inserted before switching the controller on, in order that the controller can use it.
- Only use an SD card provided by Phoenix Contact.

#### Downgrade to firmware version 1.0.0

After downgrading to firmware version 1.0.0, you can only use the reset button of the controller while an application is running. Resetting the controller to default setting type 2 is not possible.



**For resetting the controller to default setting type 2, please note the following:**

When restoring to default setting type 2, the firmware of the controller is also reset to the delivery state. Controllers with a firmware version  $\leq 1.0.2$  can only be used **with** an SD card. Using them without an SD card is possible starting from firmware version 1.1.0.

- Ensure that the SD card has been inserted before switching the controller on, in order that the controller can use it.
- Only use an SD card provided by Phoenix Contact.

### 17.3 Known limitations and errors

- Time-outs during the communication with PCP devices  
If more than eight PCP devices are connected at the same time, time-outs can occur during the communication between the controller and the PCP devices.
- Maximum permissible number of Axioline F local bus devices  
Currently, a maximum of 30 Axioline F local bus devices is supported.
- Interrupting the PROFINET communication  
When transmitting files via SFTP to the controller, the PROFINET communication is interrupted.
- Function of the reset button  
When the controller is reset to default setting type 2, all LEDs light up after approx. 30 s.  
To actually restore the controller to default setting type 2, you need to press and hold the reset button for another 2 s after all LEDs have lit up.

## 18 Changes in firmware version 1.1.0



**Please note:**

After the update to firmware version 1.1.0, the controller has to be restarted.

### 18.1 New functions

#### Use of SD card now optional

The SD card is now optional and is no longer mandatory for operating the controller.

– Operation without SD card:

All data is saved on the internal parameterization memory. If you make changes to files and directories on the internal parameterization memory, the Linux operating system generates an overlay filesystem from the changed files and directories.

– Operation with SD card:

If you use an SD card, all application-specific data (e.g. network configuration, project bus configuration, etc.) is saved to the SD card.

Two cases of SD card use can be distinguished:

- 1) There is no overlay filesystem on the SD card:  
If there is an overlay filesystem on the internal parameterization memory, it is copied to the SD card.
- 2) There already is an overlay filesystem on the SD card:  
If there is an overlay filesystem on the internal parameterization memory, it is **not** copied to the SD card.

The controller accesses the overlay filesystem on the SD card. The overlay filesystem on the internal parameterization memory is deleted.



**Please note:**

The SD card is recognized during initialization of the controller. If you insert the SD card during operation, the SD card will not be detected.

- Make sure that the SD card has been inserted before you switch on the controller.

#### Memory expanded

- The program memory of the controller has been expanded from 4 MB to 8 MB.
- The data memory of the controller has been expanded from 8 MB to 16 MB.

## 19 Changes in firmware version 1.0.2

**Please note:**

After an update from firmware version 1.0.0 to firmware version 1.0.2, high-level language programs created with the Phoenix Contact SDK version 1.0.0 will no longer be executable. In this case, proceed as follows:

- Download the latest version of the Phoenix Contact SDK from [phoenixcontact.net/products](http://phoenixcontact.net/products) and install it.
- Compile existing high-level language programs with the latest version of the Phoenix Contact SDK.

When updating from firmware version 1.0.1 to firmware version 1.0.2, this procedure is not necessary.

### 19.1 Error corrections

- PROFINET configuration  
The controller was stopped when transmitting a PC Worx Engineer project with a faulty PROFINET configuration to the controller.  
This error has been rectified.

### 19.2 Known limitations and errors

- Controller breakdown  
In some rare cases the controller may break down. In case of a controller breakdown, power is disconnected to the I/O modules contained in the bus configuration.



## 20 Changes in firmware version 1.0.1



**Please note:**

After an update from firmware version 1.0.0 to firmware version 1.0.1, high-level language programs created with the Phoenix Contact SDK version 1.0.0 will no longer be executable. In this case, proceed as follows:

- Download the latest version of the Phoenix Contact SDK from [phoenixcontact.net/products](http://phoenixcontact.net/products) and install it.
- Compile existing high-level language programs with the latest version of the Phoenix Contact SDK.

### 20.1 Error corrections

- Task processing time  
The programmed maximum task processing time was exceeded by occasional task processing time outliers. The ESM watchdog was triggered. This error has been rectified.
- User authentication  
A user authentication security vulnerability was patched.
- Requested memory  
An error occurred when memory was requested from a C++ program. The requested memory was not released again. This error has been rectified.
- Data Access Service  
An error in the Data Access Service (online view in the “Data List” editor in PC Worx Engineer) has been rectified.
- Subscription service  
During data query via OPC UA, an error occasionally occurred in the subscription service. This error has been rectified.