

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

MOP of Loss of Active/Standby Communication Link (199005122) for ZTE Site

Table of contents

Activity Description.....	2
Flow Chart.....	3
Activity Summary.....	5
Activity Details.....	6
Post Analysis	11

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Activity Description


This activity is for E2E troubleshooting and alarm clearance of Temperature sensor abnormal(198092071)

Attached is the details to be followed. As this need to be followed as guideline.


Alarm Name	Loss of Active/standby communication link(199005122)
Alarm Description	Communications Subsystem Failure(306)/Connectivity Lost
Possible Causes – arrange in logical order	The link between this board and master main control board is faulty

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Flow Chart



Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference



Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Activity Summary

1	Corrective WO of alarm is received on WFM portal
2	FME will Accept the WO
3	Put WO in travel
4	After reaching site - put WO in process
5	Login the BTS & Check alarm status in which sector its coming
8	FME will Check as per MOP
10	If cleared, then Put WO in closed state
11	Put Work order in Waiting internal if any HW Req at site
12	Raise Req of Hardware to BSS Team
13	Once Material received again put WO in Travel mode
14	After reaching site - put WO in process
15	Replace the hardware
16	Check from BTS Login that alarm cleared or not after hardware replaced
17	Once Alarm Cleared
18	FME will close the WO as resolved

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference


Activity Details

Pre requisites:


- 1) SVD WO for Temperature sensor abnormal(198092071)alarm.
- 2) Alarm on OneFM/Netnumen/WFM.

Case : Temperature sensor abnormal(198092071)alarm on 1 cell


A) Login in 2G BBU/ enodeb as per RAN MOP via ZX SDR LMT OEMS connect using LAN cable




Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference



Prepared (also subject responsible if other)		No.		
Rahul Sharma & Ankur Sharma				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	



a) Start EFMS to view alarm window



EMS View:-

No.	Ro...ACK State	Severity	NE	Location	System Type	Alarm Code	Raised Time	NE Type	A
1	Unacknowledged	Major	YMN61(906611)	Equipment Resource(M...	Platform Alarm(20420)	Board communication link interrupted(198097060)	2020-02-06 16:37:10	ME(MO SDR)	E

Prepared (also subject responsible if other)		No.		
Rahul Sharma & Ankur Sharma				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	

b) Double click on the alarm to check the alarm description.(EMS View):-

ACK State	Unacknowledged
Severity	Major
NE	YMNR61(906611)
Location	Equipment Resource(MO SDR)=1,Rack(MO SDR)=1,Shelf(MO SDR)=1,Board(MO SDR)=3
System Type	Platform Alarm(20420)
Alarm Code	Board communication link interrupted(198097060)
Raised Time	2020-02-06 16:37:10
NE Type	ME(MO SDR)
Alarm Type	Equipment Alarm
Specific Problem	The link between this board and master main control board is faulty.
Remark	U RNCId: 101; CPU link; The last three steps of the MCU startup path: 0x86-0x00, 0x88-0x00, 0xff-0x00, Switch port link normal; Board serial number: 704065700254; U nodeBId:661,G sited:661,L eNBId:906611,TDL eNBId:806611
ADMC Alarm	No
Repeated Count	
Alarm Object Type	SDR
Alarm Object DN	SubNetwork=101,MEID=906611,Equipment=1,Rack=1,SubRack=1,Slot=3,PlugInUnit=1
Board Type	CR0
Alarm Object ID	906611
Site Name(Office)	YMNR61
Site ID(Office)	906611
Alarm Object Name	YMNR61
Probable Cause	Connective establishment error(566)

c) Click on the solution tab to check the check the probable cause

Default Suggestions

Reason Detail:
The link between this board and master main control board is faulty.

Handling Suggestions:


- Based on the slot number, shelf number, and rack number in the detailed alarm information, remove the board, and then install it again.
Wait 15 minutes, and check whether the alarm is cleared.
Yes -> End.
No -> Step 2.
- Install the board in another slot.
a. Based on network planning, check whether the board can be installed in another slot.
Yes -> Substep b.

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

d) Replace hardware as per fault location/Add New hardware W.r.t Board

e) Check in EFMS/OneFM/Netnumen whether alarm cleared or not.

In Below Snapshot no any alarm visible , as its cleared.



No.	Site Name	OC	Raised Time	Alarm Code	Severity	Alarm Obj.	Product
-----	-----------	----	-------------	------------	----------	------------	---------

Prepared (also subject responsible if other) Rahul Sharma & Ankur Sharma		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Post Analysis

Step No.	Step Name/Step Type	Command	Field	Mandatory (Y/N)	Expected Value
1	FME will check at One FM/Netnumen after 30 minutes to check alarm	As per attached MOP in traffic check status step--Refer RAN MOP	RAN	Y	As per MOP
2	BSS Team will check after 24 hrs if alarm has reappeared				