

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

MOP of VSWR Alarm for Huawei Site

Table of contents

Activity Description.....	2
Flow Chart	3
Activity Details.....	4

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

Activity Description


This activity is for E2E troubleshooting and alarm clearance of VSWR of the antenna feeder abnormal.

Attached is the details to be followed. As this need to be followed as guideline.

Alarm Name	RF Unit VSWR Threshold Crossed
Alarm Description	The voltage standing wave ratio (VSWR) measures the signal power that the load actually receives from the transmission line. The VSWR at the antenna port is calculated based on the sampled forward power and reverse power.
Possible Causes	<ol style="list-style-type: none">1. The connectors of the antenna and feeder cables are substandard, are not connected tightly, are penetrated by water, or have foreign objects such as metal fragments.2. The antenna and feeder cables are squeezed or bent, or the feeder cable is damaged.3. The RRU hardware / RRU Port is faulty.4. Antenna port faulty5. Difference between logical and physical cable connectivity.

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

Flow Chart



Prepared (also subject responsible if other)		No.		
Approved	Checked	Date	Rev	Reference
		15-05-2020	Ver1.0	

Activity Details

Preparation of site visit for VSWR Alarm:-

1. Check alarm information in detail to identify problematic RRU and RRU port No.
2. Arrange same type of RRU model and Jumper.

Steps Need to follow to clear alarm: -

1. Run command DSP VSWR to identify current VSWR value for problematic port.
2. PTW need to raise in FEAT Tool.
3. Check number of jumpers between RRU and Antenna. it should be according to plan.
4. If number of physical connected jumpers are equal to configured jumper, go on step 5 else contact to SME.
5. Check all cable connectivity between RRU & Antenna, Positive should be connected with positive and Negative should be connected with Negative.
6. Check all cable connector between RRU and Antenna are tightly connected or not, if Not , open it , clear dust and water if it is there and re-connect it ,cross check, connector should be tightly connected and observe VSWR value for 1 hour.
7. Check physical cable status, it should not be band or damaged. If it is there, need to change cable immediately. Observe VSWR value for 1 Hour post correction.
8. If no issue found in step 5 ,6 & 7, need to change each cable One by One between RRU and antenna until VSWR value becomes Normal. Need to observe VSWR Value
9. If VSWR alarm still not cleared, need to replace Hardware between RRU & Antenna one by one until VSWR value becomes Normal.

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

1. Run command DSP VSWR to identify current VSWR value for problematic port.

The screenshot shows the DBS3900-GL web interface. The 'Command History' field contains 'DSP VSWR'. A red arrow points to the 'Exec' button. Below the command history, there is a 'Cabinet No.' field and a text prompt: 'Type DSP VSWR to check VSWR value'.

The screenshot shows the DBS3900-GL web interface displaying the results of the 'DSP VSWR' command. The results are shown in a table with columns for Subrack No., Slot No., TX Channel No., and VSWR. A red box highlights the result for Subrack No.=80, Slot No.=0, TX Channel No.=1, which has a VSWR of 1568. A red text annotation states: 'Subrack No.=80 Slot No.=0 TX Channel No.=1 having VSWR 1568 which is high (VSWR<150)'.

Subrack No.	Slot No.	TX Channel No.	VSWR
0	70	0	118
0	71	0	128
0	71	1	126
0	72	0	128
0	72	1	120
0	80	0	108
0	80	1	1568
0	81	0	112
0	81	1	123
0	82	0	117
0	82	1	113

(Number of results = 27)

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

2. In FEAT Raising PTW




3. Check number of jumpers between RRU and Antenna and found it is correct as per plan.

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference



4. No of cable are connected as per Plan so we are going to next step.
5. we checked all connector are tight or not and found that connectors are loose as well as band.

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date	Rev	Reference
		15-05-2020	Ver1.0	



- As cable is band and damaged, so we change cable and check VSWR value.

Prepared (also subject responsible if other)		No.		
Approved	Checked	Date 15-05-2020	Rev Ver1.0	Reference

7. RUN DSP VSWR after changes and note down VSWR Value.

The screenshot shows the DBS3900-GL web interface. The top navigation bar includes links like 'Configure Emergency OM Channel', 'Obtain Documentation List', 'FTP Tool', 'Command Group Settings', and 'Password'. The main menu has tabs for 'MML', 'Alarm/Event', 'Batch', 'Trace', 'Monitor', and 'Device Maintenance'. The 'Alarm/Event' tab is active, showing a table of maintenance records.

Common Maintenance (Alt+C)		Operation Records (Alt+R)		Help (Alt+N)
0	72	0	1	120
0	80	0	0	110
0	80	0	1	115
0	81	0	0	111
0	81	0	1	123
0	82	0	0	116
0	82	0	1	113

(Number of results = 27)

Subrack No.=80 Slot No.=0 TX Channel No.=1
VSWR 115

DSP VSWR::

Command History: DSP VSWR::

Command (F5): DSP VSWR

Cabinet No.

Buttons: Assist, Exec, Use Proxy MML

8. Now VSWR value is under threshold and alarm has cleared so our activity is completed.