

Prepared (also subject responsible if other) Sanjeev Motagi		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

## MOP of GPS Time Sync Ref Alarm for Ericsson Site

### Table of contents

Activity Description.....	2
Flow Chart .....	3
Activity Summary .....	5
Activity Details.....	6
Post Analysis .....	11

Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

## Activity Description


This activity is for E2E troubleshooting and Clearance of GPS Time Sync Reference alarms 4G cell/ site.

Attached are the details to be followed by RAN Team. As this need to be followed as guideline.

Alarm Name	TIMESYNC REFERENCE FAILED at ONE FM end
Alarm Description	TIMESYNC REFERENCE FAILED alarm due to GPS connected to Node B
Possible Causes	1. GPS Receiver 2. GPS Connector and ½" Cable damage or bend 3. GPS Antenna Position (Blocking)

Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date <b>23-01-2020</b>	Rev <b>Ver1.0</b>	Reference

## Flow Chart



Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference



Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

## Activity Summary

1	Corrective WO Time Sync Reference Failed alarm is received on WFM portal
2	FME will Accept the WO
3	Put WO in travel
4	After reaching site - put WO in process
5	Login the BTS & Check alarm status
6	Raise PTW to ZTM
7	PTW Approval done by ZTM
8	Rigger will Check GPS Connectivity from Node B to GPS
9	FME will check in BTS (Alarm cleared or not)
10	If cleared, then Put WO in closed state
11	If not cleared, then check GPS Cable /Connector / GPS Antenna/GPS Receiver /GPS Cable (1/2")
12	Put Work order in Waiting internal if any HW Req at site
13	Raise Req of Hardware to BSS Team
14	Once Material received again put WO in Travel mode
15	After reaching site - put WO in process
16	Raise PTW to ZTM
17	PTW Approval done by ZTM
18	Replace the hardware
19	Check from BTS Login that alarm cleared or not after hardware replaced
20	Once Alarm Cleared
21	FME will close the WO as resolved

Prepared (also subject responsible if other) Sanjeev Motagi		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference


## Activity Details

### Pre requisites:


- 1) SVD WO for Time Sync Reference Failed alarm.
- 2) Alarm on OneFM /WFM.

When Time Sync Reference Failed Alarms reflects, Below the activities need to be done step by step to clear the alarm

- a) Login in 4G BB/ eNodeB as per RAN MOP via LMT OEMS connect using LAN cable





### Change the Laptop IP



Prepared (also subject responsible if other)		No.		
Sanjeev Motagi				
Approved	Checked	Date	Rev	Reference
		23-01-2020	Ver1.0	

Login the NodeB



b) Verify the Alarm status :

Time Sync Reference Failed Alarm in Disabled State

```
LMDKT12> altk
200121-14:36:30 100.69.36.114 19.0h MSRBS_NODE_MODEL_18.Q2_362.27897.47_d5a3 stopfile=/tmp/15597
Collecting Alarms...

=====
Date & Time (UTC)  s  Specific Problem                                     MO (Cause/AdditionalInfo)
=====
2020-01-21 09:00:35 w  TimeSyncIO Reference Failed             Synchronization=1, RadioEquipmentClock=1, RadioEquipmentClockReference=1 (Loss of signal)
>>> Total: 1 Alarms (0 Critical, 0 Major)


LMDKT12> st time
200121-14:36:44 100.69.36.114 19.0h MSRBS_NODE_MODEL_18.Q2_362.27897.47_d5a3 stopfile=/tmp/15597

Proxy  Adm  State  Op. State  MO
=====
11484      0 (DISABLED)  Transport=1, Synchronization=1, TimeSyncIO=1
=====
Total: 1 MOS
```




Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

c) Check the GPS Connectivity from NodeB to GPS Receiver to GPS Antenna (Connectivity Diagram)



d) Steps how to make GPS Connection





Prepared (also subject responsible if other) Sanjeev Motagi		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

e) Check the ½" GPS Cable routing/ Sharp bend/Damages till GPS Antenna

f) GPS Antenna Should be installed in such a way it should be **Open to 360 Degree view without any obstruction or blocking**



**GPS Installed beside Tower Leg/ Covered by IF or feeder cable, Adjacent building or Trees will lead to Time Sync Ref Failure alarm fluctuations, affects RSSI KPI of surrounding cells**



**GPS need to be installed at proper height on Tower with clear SKY View 360 Deg without any obstructions from nearby trees, buildings, tower legs etc**

g) Check the Time Sync Reference Failed alarm status by login to NodeB

**Time Sync Reference Failed Alarm should be in Enabled State**

```

LMDKT12> altk
200121-14:38:32 100.69.36.114 19.0h MSRBS_NODE_MODEL_18.Q2_362.27897.47_d5a3 stopfile=/tmp/15597
Collecting Alarms...

=====
Date & Time (UTC)  5 Specific Problem                                MO (Cause/AdditionalInfo)
=====
2020-01-21 09:00:35 w TimesyncIO Reference Failed                    Synchronization=1, RadioEquipmentClock=1, RadioEquipmentClockReference=1 (Loss of signal)
>>> Total: 1 Alarms (0 Critical, 0 Major)

LMDKT12> st time
200121-14:38:33 100.69.36.114 19.0h MSRBS_NODE_MODEL_18.Q2_362.27897.47_d5a3 stopfile=/tmp/15597
=====
Proxy  Adm State  Op. State  MO
=====
11484  1 (ENABLED)  Transport=1, Synchronization=1, TimesyncIO=1
=====
Total: 1 MOS 0

```

Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

h) If tower work involves, perform PTW



Prepared (also subject responsible if other) <b>Sanjeev Motagi</b>		No.		
Approved	Checked	Date 23-01-2020	Rev Ver1.0	Reference

## Post Analysis

Step No.	Step Name/Step Type	Command	Field	Mandatory (Y/N)	Expected Result
1	FME will visit the site after 30 minutes to check	As per MOP and run the alarm check command to confirm its Cleared	RAN	Y	As per MOP
2	BSS Team will check after 24 hrs if alarm has reappeared	As per MOP			

### NOTE:

1. Once Time Sync Reference Failed alarm reported, Site will be in hold over mode.
2. If alarm not cleared within 5:30Hrs, Site/ ENodeB will go down.
3. Once Alarm clear, Clock status will revert to LOCK Mode
4. GPS were installed on tower leg corners/feeder cable /lower heights ...etc lead to Time Sync Ref Failed alarms affected Site down and Kpi affecting RSSI Value of site and nearby sites also.
5. Further NPI to check KPI