

Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

MOP of Optical port receiving link failure (198098319) for ZTE Site

Table of contents

Activity Description.....	2
Flow Chart	3
Activity Summary	6
Activity Details.....	7
Post Analysis	14

Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Activity Description


This activity is for E2E troubleshooting and alarm clearance of Optical port receiving link failure(198098319)

Attached is the details to be followed. As this need to be followed as guideline.


Alarm Name	Optical port receiving link failure(198098319)
Alarm Description	Link failure(517)
Possible Causes – arrange in logical order	<ol style="list-style-type: none">1. Fibers or cables are damaged.2. The surfaces of fibers or cables are dirty.3. The optical or electrical module on the local or peer end is not fully inserted into the slot.4. The optical or electrical module of the peer equipment is damaged.5. The actual fiber length is longer than the maximum length supported by the optical module.6. The optical or electrical module rate on the local or peer end does not match.7. The peer equipment is operating abnormally.

Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Flow Chart



Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference



Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

2.Step C

2. Check whether the received optical power of the optical module is normal.

a. During diagnostic tests, diagnose the board based on the information about rack No., frame No., and slot No. in alarm details. Base on the information about optical port No. in alarm details, check whether the received optical power of the optical module. The receiving sensitivities of common optical modules are described as follows:

1.25G (-19dBm)
2.5G (-17dBm)
6G (-15dBm)
10G (-13dBm)

b. Check whether the received power of the optical module is lower than the receiving sensitivity.

Yes -> Substep c.

No -> Step 3.

c. During diagnostic tests, diagnose the board based on the information about rack No., frame No., and slot No. in alarm details. Base on the information about optical port No. in alarm details, query the maximum distance supported by the optical module, and then check whether fiber length is longer than the maximum distance supported by the optical module.

Yes -> Substep d.

No -> Substep e.

d. Replace the optical module with a proper one or reduce fiber length.

Waiting for 15 minutes, Check whether the alarm disappears.

Yes -> End.

No -> Substep e.

e. Verify that optical fibers are properly connected.

Yes -> Substep f.

No -> Substep g.

f. Check whether the surfaces of fiber connectors are dirty.

Yes -> Substep h.

No -> Substep i.

g. Connect fibers.

Waiting for 15 minutes, check whether the alarm disappears.

Yes -> End.

No -> Substep i.

h. Clean the fiber connectors.

Waiting for 15 minutes, check whether the alarm disappears.

Yes -> End.

No -> Substep i.

i. Check whether fibers are in good condition.

Yes -> Step 3.

No -> Substep j.

j. Replace fibers.

Waiting for 15 minutes, check whether the alarm disappears.

Yes -> End.

No -> Step 3.

Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

Activity Summary

1	Corrective WO of alarm is received on WFM portal
2	FME will Accept the WO
3	Put WO in travel
4	After reaching site - put WO in process
5	Login the BTS & Check alarm status in which sector its coming
8	FME will check as per MOP
9	If cleared, then Put WO in closed state
10	If not cleared, then check either the hardware to replace
11	If cleared, then Put WO in closed state

Prepared (also subject responsible if other)		No.		
Abhisek De				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	


Activity Details

Pre requisites:


- 1) SVD WO for Optical port receiving link failure(198098319)
- 2) Alarm on OneFM/Netnumen/WFM.

Case : Optical port receiving link failure(198098319))alarm on 1 cell


A) Login in 2G BBU/ enodeb as per RAN MOP via ZX SDR LMT OEMS connect using LAN cable




Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference



Prepared (also subject responsible if other)		No.		
Abhisek De				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	



a) Start EFMS to view alarm window



Prepared (also subject responsible if other)		No.		
Abhisek De				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	

EMS View:-



History Alarms Within Three Days: EKOL0000BNPK_IND(4501)						
No.	Root Alarm Indicator	ACK State	Alarm Object Name	Site Name(Office)	Alarm Code	Raised T
1		Unacknowledged	EKOL0000BNPK_IND	EKOL0000BNPK_IND	Optical port receiving link failure(198098319)	2020-02-

b) Double click on the alarm to check the alarm Description. (EMS View):-


Detail		Handling Suggestions	
Alarm Code	Optical port receiving link failure(198098319)		
Board Type	FS		
Product	GSM		
Severity	Minor		
Site Name(Office)	EKOL0000SRAI_VOD		
NE	EKOL0000SRAI_VOD(1958)		
Location	Equipment Resource(MO SDR)=1,Rack(MO SDR)=1,Shelf(MO SDR)=1,Board(MO SDR)=4		
System Type	Platform Alarm(20420)		
NE Type	ME(MO SDR)		
Alarm Type	Communications Alarm		
Specific Problem	1. Fibers or cables are damaged. 2. The surfaces of fibers or cables are dirty. 3. The optical or electrical module on the local or peer end is not fully inserted into the slot. 4. The optical or electrical module of the peer equipment is damaged. 5. The actual fiber length is longer than the maximum length supported by the optical module. 6. The optical or electrical module rate on the local or peer end does not match. 7. The peer equipment is operating abnormally.		
Remark	G BSCId: 8; Optical port 3; Optical port does not receive optical signals; Board serial number: 277989800331; G sitelid:319		
ADMC Alarm	No		
Repeated Count			
Alarm Object Type	SDR		
Site ID(Office)	1958		

Prepared (also subject responsible if other)		No.		
Abhisek De				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	

c) Click on the solution tab to check the check the probable cause




Prepared (also subject responsible if other)		No.		
Abhisek De				
Approved	Checked	Date	Rev	Reference
		21-01-2020	Ver1.0	




Prepared (also subject responsible if other) Abhisek De		No.		
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference

d) Replace hardware as per fault location & troubleshooting steps mentioned.



e) Check in EFMS/OneFM/Netnumen whether alarm cleared or not.



Prepared (also subject responsible if other) Abhisek De		No.			
Approved	Checked	Date 21-01-2020	Rev Ver1.0	Reference	

Post Analysis

Step No.	Step Name/Step Type	Command	Field	Mandatory (Y/N)	Expected Value
1	FME will check at One FM/Netnumen after 30 minutes to check alarm	As per attached MOP in traffic check status step-- -Refer RAN MOP	RAN	Y	As per MOP
2	BSS Team will check after 24 hrs if alarm has reappeared				