

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	1 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



MOP For NE_COMMU_BREAK Alarm Troubleshooting

Table of contents:

A	Introduction
B	Pre-check
C	Procedure
D	Post Activity Health check
E	Fall Back Procedure

A. Introduction

This document outlines the step-by-step process involved in MOP for NE_COMMU_BREAK Alarm Troubleshooting.

B. PRECHECK

- *Need to check the node reachability status of the node on which the alarm is observed and opposite end.*
 - *Check the current alarms at both the ends for any hardware related alarms such as HARD_BAD, HARD_ERR, BD_STATUS, BD_OFFLINE, WRG_BD_TYPE etc. If the alarm exists then need to arrange field support with spare hardware such as IF board, ODU, IF cable and tested login accessories.*
 - *If both the nodes are reachable then need to proceed to the next step else need to arrange field support with spare hardware such as IF board, ODU, IF cable and tested login accessories.*
- ❖ *Please note that the method of procedure is prepared as the current scenario, available devices, and deployed software version. So, activity steps and impact can vary depending upon the scenario.*

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	2 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible) Checked		
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



Current Alarms before activity


Severity	Name	Alarm ID	Alarm Source	Location Information	First Occurred (ST)	Last Occurred (ST)	Additional Info
Critical	NE_NOT_LOGIN	2	GJGT6085-AGRICALTU...	NE GJGT6085-AGRICALTURE MARKET not login	01/16/2020 01:21:44	01/16/2020 01:21:44	
Critical	NE_COMMU_BREAK	1	GJGT6085-AGRICALTU...	Communication with common NE GJGT6085-AGRICALTURE MARK...	01/16/2020 11:52:23	01/17/2020 09:23:30	

C. Procedure:

Steps for NE COMMU BREAK Alarm Clearance:-


1. Login MSDP through below mentioned link.
<https://citrix.in.nmc.ericsson.se/>

2. Provide CITRIX username and password.




3. Click on "Xenapp6.5 >> BhartiNoida >> Transmission >> Huawei 16C/17C/18C >> Bharti INNO Trans Huawei client.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	3 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	




4. Now Huawei is launched enter the credentials and server IP of the circle must log in.




5. Click on "Main Topology" to open the Topology.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	4 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



6. Right Click on the server and click on "FIND" to find the node.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	5 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



Principle:

The NE_COMMU_BREAK alarm is generated when the communication between an NE and the U2000 is interrupted.

Traffic Impact:

The NE cannot be managed on the U2000.

Possible Causes:

Cause 1: The communication between the gateway NE that the NE connects to and the U2000 fails. Hence, the NE communication fails.

Cause 2: The SCC of the NE is faulty.

Cause 3: The fiber between the NE and the gateway NE that the NE connects to is broken.

Cause 4: The network scale is large so that the ECC communication between NEs exceeds the limit of the processing capability of the NE.

Cause 5: The NE is connected to a VRP-based PTN GNE. If the GNE connects to the U2000 over the IP protocol but cannot connect to the U2000 over the QX protocol, the NE will become unreachable to the U2000 whereas the GNE remains reachable.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	6 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



Detailed Steps:

- Cause 1: The communication between the gateway **NE** that the **NE** connects to and the U2000 fails. Hence, the **NE** communication fails.
 1. Check whether the gateway **NE** reports the GNE_CONNECT_FAIL alarm. If yes, stop the alarm. For details about stopping the alarm, see [GNE_CONNECT_FAIL](#).
 2. View the current alarms on the U2000 to check whether the alarm stops. If the alarm persists, proceed to the next step.
- Cause 2: The SCC of the **NE** is faulty.
Check the indicators on the panel of the SCC. If the indicators are abnormal, you can infer that the SCC is faulty. For details about the indicators, see [Table 1](#). Reset the SCC. If the indicators are still abnormal, replace the SCC. For details about the operations, see Replacing the SCC board in the *Parts Replacement* of the equipment.
- Cause 3: The fiber between the **NE** and the gateway **NE** that the **NE** connects to is broken.
Measure the fiber with an OTDR meter. Check whether the fiber is broken and the broken section of the fiber according to the fiber attenuation curve. Replace the fiber if the fiber is broken.



NOTE:

For the usage of the OTDR meter, see the operation guide of the OTDR.

- Cause 4: The network scale is large so that the ECC communication between **NEs** exceeds the limit of the processing capability of the **NE**.



NOTE:

Check whether the planning of the ECC routes is proper. When the number of **NEs** on a network exceeds 100, the network must be divided into ECC networks to avoid overload of the ECC communication.

1. Divide a subnet of a large scale into several subnets of small scales.



NOTE:

- Allocate adjacent networks to a subnet according to the principle of managing networks by layers and areas.
- It is recommended that the number of **NEs** in a subnet does not exceed 64.

2. Select proper common **NEs** as gateway **NEs** in a subnet.



NOTE:

When there are multiple loops and links, set the equipment that is located in sections with most loops and links as gateway **NEs**. In this manner, the situation that large

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	7 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



amount of management information is transmitted through the DCC with narrow band and broad channel is avoided so as to prevent the DCN from being congested.

3. Disable the ECC connections between redundant subnets.

- Disable the interworking between ECC subnets, which is achieved through the extended ECC (automatic or manual).
- Disable the interworking between ECC subnets, which is achieved through the STM-N electrical or optical interfaces.
- Cause 5: The NE is connected to a VRP-based PTN GNE. If the GNE connects to the U2000 over the IP protocol but cannot connect to the U2000 over the QX protocol, the NE will become unreachable to the U2000 whereas the GNE remains reachable.

The GNE can query non-gateway routes. If the GNE is using IP protocol, switch to the QX protocol.

- If the alarm persists, Please get support from BO-TXN Support.

Table 1 Indicator description of the SCC board

Indicator	Name	Status	Description
STAT	Board Hardware Indicator	On (green)	The board works normally.
		On (red)	A critical alarm occurs on the board.
		On (yellow)	A minor alarm occurs on the board.
		Off	The board is not powered on.
PROG	Board Software Indicator	On (red)	Memory check failed/loading unit software failed/the FPGA file is lost/the unit software is lost.
		Blinking (red)	100ms on and 100ms off.
			BOOTROM check failed.
		Blinking quickly (green)	100ms on and 100ms off.
			Writing FLASH.
		Blinking slowly (green)	300ms on and 300ms off.
			BIOS booting/loading FPGA/loading unit software.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	8 (8)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
ECGGJLJ Subhash Chandra	BMASJZMF [Nitin Baranwal]		
Document Number	Revision	Date	Reference
BMAS-20:001205 Uen	C	2020-01-28	



Table 1 Indicator description of the SCC board

Indicator	Name	Status	Description
		On (green)	The board software or software for FPGA is uploaded successfully, or the board software is initialized successfully.
SRV	Service Alarm Indicator	On (green)	Service is normal, no service alarm occurs.
		On (red)	A critical or major alarm occurs in the service.
		On (yellow)	A minor or remote alarm occurs in the service.
		Off	No service is configured.
ALMC	Alarm cut indicator	On (yellow)	Currently in permanent alarm cut-off status.
		Off	Give sound warning upon alarm.

D. Post Activity Health Check:

Please check alarm will be clear and services also restored after confirmation from all stakeholders.

E. Fallback Procedure:

Need to shift the board to another free slot and configure the services manually.