

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	1 (6)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
EDGHHMI Sumit Sharma H			
Document Number	Revision	Date	Reference
		2020-06-22	



MOP for RADIO_RSL_LOW alarm clearance

Table of contents:

A	Introduction
B	Pre-check
C	Procedure
D	Post Activity Health check
E	Fall Back Procedure

A. Introduction

This document outlines the step-by-step process involved in MOP for RADIO_RSL_LOW alarm clearance.

The RADIO_RSL_LOW is an alarm indicating that the radio receive power is very low. This alarm is reported if the detected receive power is equal to or lower than the lower threshold of the ODU (The upper threshold is -80 dBm for the 112 MHz channel bandwidth and -90 dBm for the other channel bandwidths).

B. PRE-CHECK

- 1. Check for the mandatory fields in Standard CR Template for if any of the mandatory fields is not duly filled, CR should not be taken for execution.*
- 2. Check the data received from authorized Transmission engineer for correctness & all essential data.*
- 3. If Circle Head/ CR form does not approve the CR is not duly filled, CR should not be taken for execution.*
- 4. Every Outage involve activity should be performed in Night Shift Only.*

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	2 (6)
Prepared By (Subject Responsible)	Approved By (Document Responsible)	Checked	
EDGHHMI Sumit Sharma H			
Document Number	Revision	Date	Reference
		2020-06-22	



5. Need backup of Node where the activity is performed before any activity.

6. If any Critical/SA alarms, Don't perform activity on the node and ask circle to clear the Alarm.

7. In case of latency, Don't perform activity on the node

❖ Please note that the method of procedure is prepared as the current scenario, available devices, and deployed software version. So activity steps and impact can vary depending upon the scenario.

Current Alarms before activity

Alarm Source	Severity	Name	Location Information	Occurrence	First Occurred (ST)
PJSB55	Critical	RADIO_RSL_LOW	21-ODU-1(RTNRF-1)-RTNRF-1	1	13/06/2020 11:20:13
MGJ170	Critical	RADIO_RSL_LOW	24-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 04:03:19
KHSD01	Critical	RADIO_RSL_LOW	22-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 07:04:09
KSRL56	Critical	RADIO_RSL_LOW	21-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 07:44:43
HSAR10	Critical	RADIO_RSL_LOW	55-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 08:43:47
PLWL30	Critical	RADIO_RSL_LOW	23-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 09:06:46
BGRH65	Critical	RADIO_RSL_LOW	22-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 09:18:47
PNP256	Critical	RADIO_RSL_LOW	22-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 09:30:09
SSOD36	Critical	RADIO_RSL_LOW	22-ODU-1(RTNRF-1)-RTNRF-1	1	22/06/2020 09:36:28

Details Location Information: 22-ODU-1(RTNRF-1)-RTNRF-1 Additional Information: Remarks:	Troubleshooting K8888: (1) Certain other alarms occur at the opposite station; (2) The transmit or receive power of the RF unit at the local station does not match the transmit or receive power of the opposite station; (3) The transmit power of the opposite station is low; (4) The local RF unit is faulty; (5) Signal fading on the radio link is heavy.
--	---

C. Procedure:

Possible Causes

- Cause 1: Other alarms occur at the opposite station.
- Cause 2: The transmit power of the opposite station is very low.
- Cause 3: The local ODU is faulty.
- Cause 4: Signal attenuation on the radio link is very heavy.

Procedure

1. Cause 1: Other alarms occur at the opposite station.

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	3 (6)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
EDGHHMI Sumit Sharma H			
Document Number	Revision	Date	Reference
		2020-06-22	



Check whether any of the following alarms is generated in the equipment of the opposite station. If yes, take priority to clear the alarm.

- *RADIO_MUTE*
- *CONFIG_NOSUPPORT*
- *RADIO_TSL_LOW*
- *BD_STATUS*


2. Cause 2: The transmit power of the opposite station is very low.

Check whether the transmit power of the opposite station is normal. If not, replace the ODU of the opposite station.

3. Cause 3: The local ODU is faulty.

Procedure to check the ODU and IF board perform the ODU/IF loopback and same can be carried out at both the ends using the below mentioned guidelines:

Interference check: firstly check the if MW link have interference, if have, try to change the frequency to avoid the interference; if does not have, please go to the next step




Note: loopback will interrupt service

before inloop, should mute all other ODUs in same link, except the one will inloop

Select the NE, do inloop;

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	4 (6)
Prepared By (Subject Responsible)	Approved By (Document Responsible)	Checked	
EDGHHMI Sumit Sharma H			
Document Number	Revision	Date	Reference
		2020-06-22	



Then check the MSE(Or SNR) current; if the MSE is lower than 32dB (if your U2000 shows MSE, the value should be negative), go to the step 3; if the MSE is bigger than 32dB, means these side does not have problem, need check the other side;

Monitored Object Filter Criteria: All

Monitor Period: 15 Minute

Measure: Performance Event Type

Count: ☐ Transmitted Optical Power ☐ Radio Transmitted Signal Level ☐ Cooling Current ☐ Received Optical Power ☐ Radio Received Signal Level ☐ Bias Current ☒ Working Temperature ☐ CPU Memory Usage ☒ Others

Select All Select None

Monitored Object	Performance Event	Monitor Period	Start Time	Value MAX	Value CUR	Value MIN	Validity
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	FEC_UNCOR_BLOCK_CNT	15 Minute	03/23/2014 06:15:00	-	234	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	FEC_BEF_COR_ER	15 Minute	03/23/2014 06:15:00	-	0	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	IF_UAS(s)	15 Minute	03/23/2014 06:15:00	-	381	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	QPSK(S/s)	15 Minute	03/23/2014 06:15:00	-	392	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPC_XPD_VALUE(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPD_MAX(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPD_MIN(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SNR_MAX(dB)	15 Minute	03/23/2014 06:15:00	-	40.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SNR_MIN(dB)	15 Minute	03/23/2014 06:15:00	-	37.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SNR_AVG(dB)	15 Minute	03/23/2014 06:15:00	-	39.00	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SERV1_0E-10	15 Minute	03/23/2014 06:15:00	-	700	-	Valid
NE(9-6)-3-ISV3-1(RTNIF-1)-RTNIF-1	BDTEMP(C)	15 Minute	03/23/2014 06:15:00	44.10	44.10	44.00	Valid

Then do the IF board port inloop, if the MSE is big than 37dB (if your U2000 shows MSE, the value should be negative), means the ODU has problem, need replace the ODU; if the MSE is less than 37dB, means the IF board has problem, need replace the IF board



Local Radio Terminal: NE(150-176) - 1-ISV3-1(RTNIF-1)
NE ID: 150-176

Diagram: 1-ISV3-1(RTNIF-1) Inloop ↔ RF ↔

PORT	Inloop	Outloop
1-ISV3-1(RTNIF-1)(IF Loopback)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21-ODU-1(ODU-1)(RF Loopback)	<input type="checkbox"/>	<input type="checkbox"/>

Buttons: Get Links, Query, Apply

Monitored Object Filter Criteria: All
Monitor Period: 15 Minute

Performance Event Type: ☒ Working Temperature

Monitored Object	Performance Event	Monitor Period	Start Time	Value MAX	Value CUR	Value MIN	Validity
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	FEC_UNCOR_BLOCK_CNT	15 Minute	03/23/2014 06:15:00	-	234	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	FEC_BEF_COR_ER	15 Minute	03/23/2014 06:15:00	-	0	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	IF_UAS(s)	15 Minute	03/23/2014 06:15:00	-	381	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	QPSK(s)	15 Minute	03/23/2014 06:15:00	-	382	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPIC_XPD_VALUE(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPD_MAX(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	XPD_MIN(dB)	15 Minute	03/23/2014 06:15:00	-	0.00	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SHR_MAX(dB)	15 Minute	03/23/2014 06:15:00	-	40.00	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SHR_MIN(dB)	15 Minute	03/23/2014 06:15:00	-	40.00	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	F_SHR_AVS(dB)	15 Minute	03/23/2014 06:15:00	-	39.80	-	Valid
NE(9-9)-3-ISV3-1(RTNIF-1)-RTNIF-1	IF_BER(10E-10)	15 Minute	03/23/2014 06:15:00	-	708	-	Valid
NE(9-9)-3-ISV3-FE1	BDTEMP(C)	15 Minute	03/23/2014 06:15:00	44.10	44.10	44.00	Valid

Confidentiality Class	External Confidentiality Label	Document Type	Page
Ericsson Internal		Method of Procedure	6 (6)
Prepared By (Subject Responsible)	Approved By (Document Responsible)		Checked
EDGHHMI Sumit Sharma H			
Document Number	Revision	Date	Reference
		2020-06-22	



Cause 4: Signal attenuation on the radio link is very heavy.

- a. *Browse history alarms and check whether the alarm is generated continuously.
If the alarm is generated occasionally, contact the network planning department to change the design to increase the anti-fading performance.*
- b. *Check whether the antennas at both ends are adjusted properly.
If not, align the antennas again.*
- c. *Check whether any mountain or building obstacle exists in the transmit direction.
If yes, contact the network planning department for proper modification of the planning design, hence preventing the block of the mountain or building obstacle.*
- d. *Check whether the polarization direction of the antenna, ODU, and hybrid coupler is set correctly.
If not, correct the polarization direction.*
- e. *Check whether the outdoor units such as antennas, hybrid coupler, ODU, and waveguide are wet, damp, or damaged.
If yes, replace the unit that is wet, damp, or damaged. For the operations, see Part Replacement*
- f. *Check whether the antenna gain at both the transmit and receive ends meets the requirement.
If not, replace the antenna.*

D. Post Activity Health Check:

Please check alarm will be clear and services also restored. Need to confirm the service status with all the stake holders.

E. Fall Back Procedure: -

Need to shift the link to another vacant slot and configure the link as per the requirement.