



# Aviation Investigation Final Report

<b>Location:</b>	Gregory, Michigan	<b>Accident Number:</b>	CEN23LA200
<b>Date &amp; Time:</b>	May 23, 2023, 09:46 Local	<b>Registration:</b>	N165CT
<b>Aircraft:</b>	FLIGHT DESIGN GMBH CTSW	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Hard landing	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot was landing on a grass runway with a slight right quartering tailwind. During the landing, the nose landing gear bounced after touchdown then separated from the airplane. The airplane nosed over and came to rest inverted. The fuselage and empennage sustained substantial damage.

Metallurgical examination of the nose landing gear rotation unit revealed the fracture surfaces were consistent with shear overstress. A review of the maintenance logbooks revealed that the nose landing gear had been replaced two previous times due to hard landing events. No anomalies were noted with the airplane that would have precluded normal operation.

It is likely that the landing was harder than the pilot perceived, which resulted in the shear overstress of the nose landing gear.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare that resulted in a hard, bounced landing and subsequent overstress failure of the nose landing gear.

## Findings

<b>Aircraft</b>	Landing flare - Not attained/maintained
<b>Personnel issues</b>	Incorrect action performance - Pilot
<b>Aircraft</b>	(general) - Capability exceeded
<b>Personnel issues</b>	Decision making/judgment - Pilot
<b>Environmental issues</b>	(general) - Response/compensation

# Factual Information

## History of Flight

Landing-flare/touchdown	Hard landing (Defining event)
-------------------------	-------------------------------

On May 23, 2023, about 0946 eastern daylight time, a Flight Design GMBH CTSW, N165CT, was substantially damaged when it was involved in an accident at Richmond Field Airport (69G), Gregory, Michigan. The pilot was not injured. The flight was conducted under the provisions of Title 14 *Code of Federal Regulations* Part 91 as a personal flight.

The pilot reported that after a 40-minute flight he overflew 69G to familiarize himself with the area and the condition of the turf runway before he entered a left traffic pattern for runway 36. The automated weather observing system reported the wind was nearly calm. He flew the final approach at the “appropriate speed with 40 degrees of flaps” extended. During the landing, the nose landing gear gently bounced after touchdown then the nose collapsed, and the airplane nosed over.

The responding Federal Aviation Administration inspector stated that the nose landing gear strut was found separated at the fork. A flight control continuity check was completed, and no anomalies were found. Photos of the airplane revealed the fuselage and empennage sustained substantial damage.

Metallurgical examination of the nose landing gear rotation unit revealed the fracture surfaces were consistent with shear overstress. A review of the maintenance logbooks revealed that the nose landing gear had been replaced two previous times due to hard landing events. No anomalies were noted with the airplane that would have precluded normal operation.

Recorded wind at the time of the accident was from 140° at 4 knots.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	72, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Glider	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Unknown Unknown	<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	May 5, 2023
<b>Flight Time:</b>	(Estimated) 220 hours (Total, all aircraft), 84 hours (Total, this make and model)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	FLIGHT DESIGN GMBH	<b>Registration:</b>	N165CT
<b>Model/Series:</b>	CTSW	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2006	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Experimental (Special); Experimental light sport (Special)	<b>Serial Number:</b>	06-03-09
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	April 8, 2023 Condition	<b>Certified Max Gross Wt.:</b>	1320 lbs
<b>Time Since Last Inspection:</b>	5 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	600 Hrs at time of accident	<b>Engine Manufacturer:</b>	Rotax
<b>ELT:</b>	Installed	<b>Engine Model/Series:</b>	912ULS
<b>Registered Owner:</b>	CAMERON MICHAEL F	<b>Rated Power:</b>	100 Horsepower
<b>Operator:</b>	CAMERON MICHAEL F	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KOZW,944 ft msl	<b>Distance from Accident Site:</b>	12 Nautical Miles
<b>Observation Time:</b>	10:15 Local	<b>Direction from Accident Site:</b>	18°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	140°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.2 inches Hg	<b>Temperature/Dew Point:</b>	18°C / 11°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Grosse Ile Township, MI (KONZ)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Gregory, MI (69G)	<b>Type of Clearance:</b>	Unknown
<b>Departure Time:</b>	09:00 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Richmond Field Airport 69G	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	921 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	36	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	2471 ft / 100 ft	<b>VFR Approach/Landing:</b>	Full stop;Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	42.441702,-84.064361(est)

## Administrative Information

**Investigator In Charge (IIC):** Galbraith, Damian

**Additional Participating Persons:** Dennis Heinze; FAA; Belleville, MI  
Roger Knoll; BFU

**Original Publish Date:** May 14, 2024

**Last Revision Date:**

**Investigation Class:** [Class 3](#)

**Note:** The NTSB did not travel to the scene of this accident.

**Investigation Docket:** <https://data.nts.gov/Docket?ProjectID=192230>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).