



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | Fallston, Maryland | Accident Number: | ERA23LA195 |
| Date & Time: | April 13, 2023, 15:12 Local | Registration: | N412RS |
| Aircraft: | RICHARD SPATZ RV-14A | Aircraft Damage: | Substantial |
| Defining Event: | Aerodynamic stall/spin | Injuries: | 1 Serious |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

After flying two visual approaches to southwest runway, the pilot initiated a left, 270° turn to enter a right base for the northeast-oriented runway. He turned onto final approach about ¼-nautical mile (nm) from the approach end threshold and about 200 ft above ground level (agl). Although the pilot did not recall the final approach due to his injuries, recorded GPS and engine data indicated that the airplane's vertical rate of descent increased greatly during the last few seconds of flight, and the engine speed increased, as if the pilot were performing a go-around. Also, the airplane was in a steep right bank just before impact. The airplane impacted an open field about 50 feet short of the runway, resulting in substantial damage to the airplane and serious injuries to the pilot.

The postaccident examination of the wreckage, including the flight controls, fuel system, and engine, did not reveal evidence of a malfunction or anomaly that would have precluded normal operation of the airplane. The pilot also reported that there were no mechanical failures or anomalies with the airplane during the flight.

Given the available information, it is likely that the pilot initiated the base-to-final turn too close to the runway and tried to salvage an unstable approach. The airplane entered a steep right turning descent while at a low altitude, most likely while in an aerodynamic stall, from which the pilot was unable to recover from before impact with the terrain.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to discontinue an unstabilized approach, resulting in an aerodynamic stall and collision with terrain.

Findings

| | |
|-------------------------|--|
| Aircraft | Descent rate - Not attained/maintained |
| Personnel issues | Aircraft control - Pilot |

Factual Information

History of Flight

| | |
|----------------------------|---|
| Approach-VFR pattern final | Aerodynamic stall/spin (Defining event) |
| Uncontrolled descent | Collision with terr/obj (non-CFIT) |

On April 13, 2023, about 1512 eastern daylight time, an experimental amateur-built Spatz RV-14A airplane, N412RS, was substantially damaged when it was involved in an accident near Fallston, Maryland. The private pilot was seriously injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The airplane impacted a corn field about 50 ft from the approach end of runway 4 (2,200-ft-long) at the Fallston Airport (W42), Fallston, Maryland. There were no known witnesses to the accident.

The wreckage came to rest upright and there was no fire. The right wing separated during the impact sequence and was located adjacent to the main wreckage. The forward fuselage was twisted and buckled. The engine remained attached to the fuselage and the propeller remained attached to the engine. The empennage exhibited minor damage. The landing gear were buckled under the fuselage.

The pilot reported that, due to his injuries, he did not recall the final approach. He reported on his NTSB Form 6120.1 (Pilot/Operator Aircraft Accident Report) that there were no mechanical malfunctions or failures associated with the accident.

The wreckage was recovered to an aircraft salvage facility where further examination was performed. The examination of the wreckage, including the flight controls, fuel system, and engine, did not reveal evidence of a malfunction or anomaly that would have precluded normal operation of the airplane.

The airplane was equipped with a Garmin G3Xi flight display system. Flight, engine, and systems information was recorded in non-volatile memory and downloaded by the investigation team. The data indicated that the airplane took off from Harford County Airport (0W3), Churchville, Maryland at 1456. The pilot initiated a left, climbing turn to the southwest toward W42, which was about 10 nm away. The pilot appeared to circle the field at W42 and then flew two approaches to runway 22. After the second approach, he commenced a climbing, left 270° turn to a right base leg for runway 4. He turned onto final approach about 1/4 nm south-southeast of the runway threshold at about 200 ft agl.

The G3Xi data showed that the engine speed increased during the final phase of flight, peaking at 2,580 rpm about one second before ground impact. The airplane heading and roll parameters indicated a right turn in the 5 seconds before impact, with the roll angle increasing from about 18 degrees right to 54 degrees right 2 seconds before impact, before decreasing to

8 degrees right 1 second before impact. The vertical speed decreased from a 166 ft/min descent about 5 seconds before impact to a 1,017 ft/min descent 1 second before impact. Additionally, the device was capable of recording a parameter for angle of attack, but no data for that parameter were recorded. Additionally, the parameter "CAS Alert" recorded the value "AOA UNCAL" for the entire duration of the accident flight.

Pilot Information

| | | | |
|----------------------------------|---|--|-------------------|
| Certificate: | Private | Age: | 75, Male |
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | |
| Medical Certification: | BasicMed | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | September 6, 2021 |
| Flight Time: | (Estimated) 576 hours (Total, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | RICHARD SPATZ | Registration: | N412RS |
| Model/Series: | RV-14A | Aircraft Category: | Airplane |
| Year of Manufacture: | 2019 | Amateur Built: | Yes |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 140253 |
| Landing Gear Type: | Tricycle | Seats: | 2 |
| Date/Type of Last Inspection: | September 23, 2022 Condition | Certified Max Gross Wt.: | 2050 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 83 Hrs as of last inspection | Engine Manufacturer: | Lycoming |
| ELT: | C126 installed | Engine Model/Series: | Y10-390-EXP98 |
| Registered Owner: | On file | Rated Power: | 210 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | KMTN, 21 ft msl | Distance from Accident Site: | 10 Nautical Miles |
| Observation Time: | 13:57 Local | Direction from Accident Site: | 181° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 13 knots / | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | 140° | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 29.92 inches Hg | Temperature/Dew Point: | 27°C / 8°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Churchville, MD (0W3) | Type of Flight Plan Filed: | None |
| Destination: | Fallston, MD | Type of Clearance: | None |
| Departure Time: | 14:56 Local | Type of Airspace: | Class G |

Airport Information

| | | | |
|-----------------------------|----------------------|----------------------------------|-----------------|
| Airport: | Fallston Airport W42 | Runway Surface Type: | Asphalt |
| Airport Elevation: | 460 ft msl | Runway Surface Condition: | Unknown |
| Runway Used: | 4 | IFR Approach: | None |
| Runway Length/Width: | 2200 ft / 50 ft | VFR Approach/Landing: | Traffic pattern |

Wreckage and Impact Information

| | | | |
|----------------------------|-----------|-----------------------------|---------------------------|
| Crew Injuries: | 1 Serious | Aircraft Damage: | Substantial |
| Passenger Injuries: | N/A | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Serious | Latitude, Longitude: | 39.498425,-76.413377(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Hicks, Ralph |
| Additional Participating Persons: | Dedrick P. Richard; FAA/FSDO; Baltimore, MD Ryan Enders; Lycoming Engines; Williamsport, PA |
| Original Publish Date: | June 5, 2024 |
| Last Revision Date: | |
| Investigation Class: | Class 3 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=107065 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).