



Aviation Investigation Final Report

Location:	Sturgis, South Dakota	Accident Number:	CEN23LA244
Date & Time:	June 18, 2023, 13:30 Local	Registration:	N290LA
Aircraft:	AIR TRACTOR INC AT-502	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

Analysis

The pilot reported he departed in the airplane with about 660 lbs of fuel and about 3,500 lbs of liquid chemical for application to a pasture. After arriving at the pasture, the chemical dispersal system was malfunctioning, and the pilot decided to return to the airport. During the landing to the first quarter of the runway, the airplane was about 125 mph, with “half flap” applied, and the tailwheel was locked. As the tailwheel touched down on the dry concrete runway, the pilot initiated beta mode with the propeller, and the airplane “started veering to the right.” The pilot assessed that he “reversed the propeller too aggressively and too soon.” The airplane departed the runway to the right, the left main landing gear separated after impacting a ditch, and the airplane came to rest upright on a grass field. The pilot was able to egress from the airplane without further incident. The airplane sustained substantial damage to the fuselage and the left wing.

The operator reported there were no preimpact mechanical malfunctions or failures with the airframe or the engine that would have precluded normal operation. A postaccident examination of the chemical dispersal system found foreign object debris that was likely blocking the flow of the chemical. Title 14 *Code of Federal Regulations* Part 137 Agricultural Aircraft Operations does not contain full load landing training and recurrency requirements. The pilot reported the last time he performed a full load landing was about 2 years prior. The estimated density altitude for the airport was 6,101 ft.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper timing to initiate beta mode with the propeller and his failure to maintain directional during the full load landing that resulted in a runway excursion. Contributing to the accident was the pilot's lack of recent experience with performing a full load landing and the high-density altitude that likely affected aircraft performance during the landing.

Findings

Personnel issues	Incorrect action sequence - Pilot
Personnel issues	Aircraft control - Pilot
Personnel issues	Decision making/judgment - Pilot
Personnel issues	Recent experience w/ equipment - Pilot
Aircraft	Directional control - Not attained/maintained
Environmental issues	High density altitude - Effect on equipment

Factual Information

History of Flight

Landing-flare/touchdown	Miscellaneous/other
Landing-flare/touchdown	Loss of control on ground (Defining event)
Landing-flare/touchdown	Attempted remediation/recovery
Landing-flare/touchdown	Runway excursion
Landing-flare/touchdown	Collision during takeoff/land
Post-impact	Landing gear collapse
Post-impact	Evacuation

Pilot Information

Certificate:	Commercial	Age:	35,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	April 18, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 22, 2022
Flight Time:	(Estimated) 1927 hours (Total, all aircraft), 690 hours (Total, this make and model), 1927 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	AIR TRACTOR INC	Registration:	N290LA
Model/Series:	AT-502 A	Aircraft Category:	Airplane
Year of Manufacture:	2018	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	502A-3137
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	January 15, 2023 Annual	Certified Max Gross Wt.:	10480 lbs
Time Since Last Inspection:	27 Hrs	Engines:	1 Turbo prop
Airframe Total Time:	487 Hrs at time of accident	Engine Manufacturer:	Pratt & Whitney Canada
ELT:	Not installed	Engine Model/Series:	PT6A-140AG
Registered Owner:	ASCEND AG INC	Rated Power:	867 Horsepower
Operator:	ASCEND AG INC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	ASCEND AG INC	Operator Designator Code:	3PJG

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KRCA, 3278 ft msl	Distance from Accident Site:	20 Nautical Miles
Observation Time:	12:55 Local	Direction from Accident Site:	144°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	17 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.6 inches Hg	Temperature/Dew Point:	29°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Sturgis, SD	Type of Flight Plan Filed:	VFR
Destination:	Sturgis, SD	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	STURGIS MUNI 49B	Runway Surface Type:	Concrete
Airport Elevation:	3254 ft msl	Runway Surface Condition:	Dry
Runway Used:	11	IFR Approach:	None
Runway Length/Width:	5100 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.41817,-103.37577(est)

Administrative Information

Investigator In Charge (IIC):	Hodges, Michael
Additional Participating Persons:	Brandon Caneva; FAA Rapid City FSDO; Rapid City, SD
Original Publish Date:	July 27, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=192396

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).