



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Clyde, Ohio	<b>Accident Number:</b>	ERA23LA224
<b>Date &amp; Time:</b>	May 6, 2023, 13:07 Local	<b>Registration:</b>	N678FL
<b>Aircraft:</b>	Piper PA-28-140	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel starvation	<b>Injuries:</b>	1 Serious
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot was performing a touch-and-go landing at an airport near his home base. During the initial climb after an uneventful landing, the engine lost all power. He was unable to return to the airport, so he performed a forced landing in a nearby farm field. The pilot sustained serious injuries and the airframe was substantially damaged.

The postaccident examination of the airplane revealed that the right wing was severed during the forced landing and the right wing fuel tank was compromised; however, 7 gallons of fuel were recovered from it. The left wing was intact and undamaged. About 1 quart of fuel was recovered from the left tank, and the cockpit fuel selector handle was found in the left tank position. Subsequent examination of the engine and fuel system revealed no evidence of a preexisting mechanical malfunction or failure. Fuel records indicated that the airplane was operated about 4 hours since the previous refueling. The pilot would later state that he did not know why the engine lost power but that it may have been the result of a failure to switch fuel tanks. Based on this information, it is likely that the pilots inadequate fuel management resulted in fuel starvation and the subsequent total loss of engine power.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inadequate fuel management, which resulted in fuel starvation and a forced landing.

## Findings

<b>Aircraft</b>	Fuel - Fluid management
<b>Personnel issues</b>	Use of equip/system - Pilot

# Factual Information

## History of Flight

Initial climb	Fuel starvation (Defining event)
Emergency descent	Off-field or emergency landing

On May 6, 2023, about 1307 eastern daylight time, a Piper PA-28-140, N678FL, was substantially damaged when it was involved in an accident near Clyde, Ohio. The private pilot was seriously injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that he departed from Fremont Airport (14G), Fremont, Ohio at 1150. He performed a touch-and-go landing at Fostoria Metro Airport (FZI), Fostoria, Ohio, and was planning a touch-and-go landing at Sandusky County Regional Airport (S24) before returning to 14G, his home airport. After an uneventful touch-and-go landing at S24, during the initial climb, the engine lost all power. He performed a forced landing into a cornfield about ½ mile northeast of S24. The pilot was met by first responders and was taken to a nearby hospital for treatment of his injuries. The pilot later reported that he was unsure why the engine stopped, but stated, "...could be a failure to switch tanks."

Inspectors with the Federal Aviation Administration (FAA) responded to the accident site and examined the wreckage. The fuselage came to rest upright, and there was no fire. The right wing separated from the fuselage during the impact sequence and was found inverted and adjacent to the main wreckage, with the right main landing gear still attached. The fuselage was buckled. The engine remained attached to the fuselage, and the propeller remained attached to the engine. The left wing was undamaged.

Although the right wing fuel tank was ruptured from impact, about 7 gallons of fuel were recovered from that tank. The left wing fuel tank was intact and undamaged. The left tank was drained at the accident site by the inspectors and about 1 quart of fuel was recovered. The cockpit fuel tank selector was in the left tank position.

The wreckage was recovered to a hangar where an additional examination of the engine and fuel system was performed. The engine contained about 4 quarts of clean oil. There was no visible damage to the engine case. Internal engine continuity was confirmed and valve action was correct.

The fuel gascolator was removed and examined. It was dry and contained some small, black particulates. The engine-driven fuel pump was actuated by hand; a few drops of fuel were expelled. The interior of the pump was normal in appearance. The carburetor air box was unobstructed. The carburetor was disassembled. The bowl was free of contaminants and contained about 1 tablespoon of fuel. The brass floats were uncompromised. The electric fuel

boost pump was energized with aircraft battery power; it pumped normally. The fuel tank selector valve was disassembled and operated normally.

The FAA inspectors reported that the airplane was last fueled with 18.8 gallons on March 30, 2023. According to aircraft and pilot records, the airplane was operated about 3.97 hours since the last refueling.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	69, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	February 23, 2022
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	February 11, 2023
<b>Flight Time:</b>	320 hours (Total, all aircraft), 167 hours (Total, this make and model), 8 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Piper	<b>Registration:</b>	N678FL
<b>Model/Series:</b>	PA-28-140	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1971	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	28-7125608
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	April 2, 2023 Annual	<b>Certified Max Gross Wt.:</b>	2550 lbs
<b>Time Since Last Inspection:</b>	4 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2617 Hrs at time of accident	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	C91A installed	<b>Engine Model/Series:</b>	O-320-E3D
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	150 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KPCW, 590 ft msl	<b>Distance from Accident Site:</b>	16 Nautical Miles
<b>Observation Time:</b>	12:55 Local	<b>Direction from Accident Site:</b>	49°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>	50°	<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.21 inches Hg	<b>Temperature/Dew Point:</b>	17°C / 11°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Fremont, OH (14G)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Fremont, OH (14G)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	11:50 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	Sandusky County Regional S24	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	664 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	6	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	5500 ft / 100 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious	<b>Latitude, Longitude:</b>	41.33854, -83.14562(est)

## Administrative Information

Investigator In Charge (IIC):	Hicks, Ralph
Additional Participating Persons:	John Gombar; FAA/FSDO; Cleveland, OH
Original Publish Date:	June 5, 2024
Last Revision Date:	
Investigation Class:	<a href="#">Class 3</a>
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	<a href="https://data.nts.gov/Docket?ProjectID=130452">https://data.nts.gov/Docket?ProjectID=130452</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).