



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Cortez, Colorado	<b>Accident Number:</b>	CEN23LA208
<b>Date &amp; Time:</b>	May 18, 2023, 18:00 Local	<b>Registration:</b>	N2515K
<b>Aircraft:</b>	Luscombe 8E	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Landing gear collapse	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Instructional		

## Analysis

The conventional geared airplane's right main landing gear collapsed during landing and the airplane's left wing sustained substantial damage. The pilot reported that the flight instructor performed the final landing and that the landing was very hard. The flight instructor reported that he landed on centerline and as the airplane was rolling out the right main landing gear collapsed. He noted that there were no brakes in the right seat pilot station where he was located.

Metallurgical examination of the failed landing gear revealed corrosion on the inside of the main landing gear tube in the area where it was welded to the wheel axle. The corrosion progressively thinned the leg tube walls over time and caused pitting and microcracking on the tube interior. The combination of missing material, pitting, and microcracks led to an overstress fracture of the leg at this location on the final landing, which led to two other subsequent overstress fractures.

The Federal Aviation Administration issued a special airworthiness information bulletin (SAIB), CE-17-14, to alert operators of this and other similar model airplanes of the need to inspect and address corrosion issues on main landing gear. The SAIB recommended following the procedures of the Don Luscombe Aviation History Foundation Service Recommendation No. 4, dated Jan. 22, 1996, which provided instructions for installing a drain hole in the lower portion of the leg, performing repetitive inspections of the gear legs for corrosion, and cleaning and sealing the gear legs' internal surfaces. Compliance with the SAIB is not mandatory.

Limited maintenance records were available during the investigation; however, the most recent annual inspection entry did not indicate that the landing gear were inspected for corrosion. The

fractured main landing gear did not have drain holes as noted in the service recommendation, indicating that that procedures in the service recommendation had not been performed.

Based on the available evidence the accident was the result of failure of the right main landing gear leg due to weakening from prolonged internal corrosion of the landing gear tube, which weakened the leg.

**Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Failure of the right main landing gear due to prolonged corrosion of the landing gear tube, which weakened the gear.

Findings	
Aircraft	Main landing gear - Fatigue/wear/corrosion
Aircraft	Main landing gear - Failure

# Factual Information

## History of Flight

Landing-flare/touchdown	Landing gear collapse (Defining event)
-------------------------	--

On May 18, 2023, about 1800 mountain daylight time, a Luscombe 8E, N2515K, was substantially damaged when it was involved in an accident at the Cortez Municipal Airport (CEZ), Cortez, Colorado. The pilot and the flight instructor were not injured. The airplane was operated as a Title 14 *Code of Federal Regulations (CFR)* Part 91 personal flight.

The airplane was recently purchased by the pilot and delivered to CEZ by the flight instructor. After delivery, the pilot and flight instructor conducted flights over several days to familiarize the pilot with the airplane.

According to the pilot, during the accident flight he conducted several landings without incident. The final takeoff and landing were conducted with the flight instructor manipulating the airplane’s flight controls. He said that the final landing was “very hard.”

The flight instructor reported that he landed on the runway centerline and as the airplane was rolling out, the right main landing gear collapsed. He noted that the right seat position, where he was seated, did not have brakes installed. During the landing, the right main landing gear collapsed. The airplane’s left wing was substantially damaged during the landing.

The failed right main landing gear was examined by the National Transportation Safety Board Materials Laboratory. Examination of the failed landing gear revealed corrosion on the inside of the main landing gear tube in the area where it was welded to the wheel axle. The corrosion progressively thinned the leg tube walls over time and caused pitting and microcracking on the tube interior. The combination of missing material, pitting, and microcracks led to an overstress fracture of the leg at this location on the final landing, which led to two other subsequent overstress fractures. The tube thickness near the fracture had thinned from 0.040 inches to 0.025 inches.

On June 5, 2017, the Federal Aviation Administration (FAA) issued a special airworthiness information bulletin (SAIB), CE-17-14, to alert operators of several models of JGS Properties LLC and Luscombe airplanes, including the model 8E, of a need for inspection to detect and correct corrosion inside the main landing gear legs. According to the bulletin, internal surface treatment and regular inspection of the lower legs may help mitigate the corrosion related gear failures. Compliance with a FAA SAIB is not mandatory for 14 *CFR* Part 91 operations.

The FAA recommended that owners and operators of the affected airplanes follow the inspection procedures outlined in The Don Luscombe Aviation History Foundation Service

Recommendation No. 4, dated Jan. 22, 1996, which provided instructions for installing a drain hole in the lower portion of the leg, performing repetitive inspections of the gear legs for corrosion, and cleaning and sealing the gear legs' internal surfaces. The accident airplane did not appear to have a drain hole in this portion of the lower leg. The FAA also urged using X ray or ultrasound inspection methods on the leg-to-axle joint to detect internal rust during initial or follow-on inspections of the gear leg.

Limited maintenance records were available during the investigation; however, the most recent annual inspection entry did not indicate that the landing gear were inspected for corrosion. The fractured main landing gear did not have drain holes as noted in the service recommendation.

### Flight instructor Information

<b>Certificate:</b>	Airline transport; Commercial	<b>Age:</b>	Male
<b>Airplane Rating(s):</b>	Single-engine land; Single-engine sea; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Glider	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	November 16, 2022
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	24064 hours (Total, all aircraft), 1402 hours (Total, this make and model), 38 hours (Last 90 days, all aircraft), 26 hours (Last 30 days, all aircraft)		

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	86,Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Glider	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	BasicMed	<b>Last FAA Medical Exam:</b>	January 1, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	5000 hours (Total, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Luscombe	<b>Registration:</b>	N2515K
<b>Model/Series:</b>	8E	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1947	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	5242
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	Unknown	<b>Certified Max Gross Wt.:</b>	1400 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Continental
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	C85
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	85 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KCEZ, 5903 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	17:53 Local	<b>Direction from Accident Site:</b>	22°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	360°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	23°C / 2°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Cortez, CO	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Cortez, CO	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>		<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	CORTEZ MUNI CEZ	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	5917 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	21	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	7205 ft / 100 ft	<b>VFR Approach/Landing:</b>	Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	37.303002,-108.62804

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Brannen, John
<b>Additional Participating Persons:</b>	Wesley Dollahite; FAA - Denver FSDO; Denver, CO
<b>Original Publish Date:</b>	March 28, 2024
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=192255">https://data.nts.gov/Docket?ProjectID=192255</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).