



School of Mechanical and Manufacturing Engineering

MMAN2130 Design and Manufacturing

Term 3 – 2019

Week 6

| Process Planning |

Very important content for assessments 1 & 3:
Manufacturability Review
& Final Report



Quick Quiz



1TB HDD



Nominal size?
or
Basic size?





Q2) What type of tolerance is this?

Limit of size
Bilateral
Unilateral



Limits of size.

Q3) What is the hole basis system, and why does it exist?




H8f7
Hole-basis


- Hole-basis (tables 4.1a & b)

- Hole is standard with zero deviation
 - is commonly used
 - easier to produce standard holes
 - easier to turn the shaft to suit


Q4) What is this symbol and what does it mean?



Object in 1st quadrant : FIRST ANGLE PROJECTION
Object in 3rd quadrant : THIRD ANGLE PROJECTION



3rd (third) angle projection





Q5) What is the difference between a Dimension, Tolerance & Limit


Dimension: Numerical value that defines the size, location, orientation, form or other geometric location.

Tolerance: The total amount a specific dimension is permitted to vary. The tolerance is the difference between the max and min limits.

Limits: The maximum and minimum value the specific dimension can be.




What type of fit is H7p6?



Interference!

What dim is the MML for the hole?



The diagram shows a 3D perspective of a rectangular block with a circular hole. To the left of the block is a separate cylinder representing the hole. A blue arrow points from the hole's center to a handwritten dimension label. The label consists of three parts: $\phi 1.01$ with an arrow pointing left, $\phi 1.00 \pm .01$ in the middle, and $\phi .99$ with an arrow pointing right. A blue oval encircles the $\phi 1.00 \pm .01$ and $\phi .99$ parts.

- **Maximum Material Limit (MML)**
 - The maximum (upper) limit of size for an external feature (shaft)
 - The minimum (lower) limit of size for an internal feature (hole)


0.99

Q9) Why are tolerances important 4 points ?

1. Saves money
2. Ensures inter-changeability of mating parts
3. Maximises quality
4. Uniform interpretation of specification
 - No guess work for the manufacturer
 - Clear who is at fault if there is an issue

Process Planning

Where does this fit in?




Slide adapted from Prof S Kara (UNSW, 2017)

Learning outcomes

At the end of this lecture, you should be able to:

1. Understand what a **Process Plan** is.
2. Understand the importance of the **Exploded View** and **Bill Of Materials (BOM)**.
3. Be able to create an **Assembly Chart**, **Work Method Sheet** and **Routing Sheet**.

80% of cost is during design phase




Barton, Love, Taylor 2001.

Process Plans

Set of documents that detail the **manufacturing specifications**.

- *Designed to address a number of the key issues identified on the previous slide!*
- Engineering Drawings/Blue print
- A Bill Of Materials
- An Assembly Diagram (Exploded Assembly)
- An Assembly Chart
- A Work Method Sheet
- A Routing Chart




Bill of Materials (BoM)

&

Exploded Assembly

Bill of Materials External



Bill of Materials Internal

Q'ty	Part Type	Designator	Footprint (Package type)	Description	Manufacturer	Supplier	Order Status (30/5/2018)	R = Rework W = Wave Solder H = Hand Solder N = Non	Cost per unit Ex GST	Total Cost Ex GST	Notes
1	22K	R43	0805(ACTUAL)	Res 10k	Open PHYCOMP 232273462203	Open FEC: 9237799	Ordered Fanell (RECEIVED) Sent to C.M. Entech		0.09	0.09	
1	28K	R44	0805(ACTUAL)	Res 10k	Open PHYCOMP 232273463903	Open FEC: 9237929	Ordered Fanell (RECEIVED) Sent to C.M. Entech		0.09	0.09	
1	74HC14 HEX SCHMITT	U7	SOIC8	HEX NON Inverting Schmitt Trigger	Open e.g. NXP Semiconductors: 74HC140ND	Open e.g. Digkey: 568-1469-5-ND	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	1.15	1.15	
4	JMP2 JP4 JP3 JP1	JUMPER_3PIN		COR, JUMPER, Through Hole 0.1"	Open e.g. FEC: 5217817 & 989894		Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	1.71	6.84	
1	39K	R45	0805(ACTUAL)	Res 10k	Open MULTICOMP MC 0.1V 0805 1% 39K	Open FEC: 9333649	Ordered Fanell (RECEIVED) Sent to C.M. Entech		0.06	0.06	
11	100K	R6 R12 R13 R46 R47 R18 R19 R18 R10 R4	0805(ACTUAL)	Res 10k	Open PHYCOMP 232273461004	Open FEC: 9237979	Ordered Fanell (RECEIVED)		0.09	0.99	
22	100K	C16 C8 C15 C14 C24 C17 C17 C4 C3 C3 C5 C2 C12 C13 C10 C21 C18 C1 C13 C20 C18	0805(ACTUAL)	Cap. 50V, 5%, NPO	Open AVX 0805C104KAZ2A	Open FEC: 1210805	Ordered Fanell (RECEIVED)		0.93	19.28	
1	200R	R15	0805(ACTUAL)	Res 10k	Open MULTICOMP MC 0.1V 0805 1% 200R	Open FEC: 9332798	Ordered Fanell (RECEIVED)		0.06	0.06	
2	220u	C18 C15	0805(ACTUAL)	Electrolytic 220u 50V -20%	Open e.g. PANASONIC: EEEF1E422R	Open e.g. FEC: 9639386	Ordered Fanell (RECEIVED)	RoHS	2.92	4.04	
14	500R	R12 R13 R17 R12 R13 R12 R12 R10 R13 R19 R15 R16 R24 R23	0805(ACTUAL)	Res 10k	Open MULTICOMP MC 0.1V 0805 1% 500R	Open FEC: 9333332	Ordered Fanell (RECEIVED)		0.06	0.84	
2	U2	U2 U10		2381-RELAY-DRIVER High Side Driver, Ima5 (Source) 500mA, Vma5 50V	ALLEGRO MICROSYSTEMS A282SLV-T	Open e.g. Fanell: 1236230	Ordered Fanell 12/4/8 (RECEIVED) At BCS	RoHS	4.03	0.06	
1	ADM1232 BROWNOUT/FREEDOUT		SOIC8	Adj. Voltage monitor 4.5V or 4.75V, Adj. strobe monitor with 50ms, 600ms, 1/2s options	ANALOG DEVICES: ADM1232ARNZ	Open e.g. FEC: 1438912	Ordered Fanell (RECEIVED) Sent to C.M. Entech		3.9	3.9	
2	BSS109	G2 G1	SO123_M05	Diode	Open FAPICHLD SEMICONDUCTOR BSS109...	Open FEC: 9845330	Ordered Fanell (RECEIVED) Sent to C.M. Entech		0.76	1.52	
2	DMF	C22 C23	0805(ACTUAL)	MOSFET	Open		N/A		0	0	
1	DPDT REED RELAY		0805(ACTUAL)	DPDT reed relay, Coil Voltage 5V, Pma5 50V, Picoll 150R, Ima5 0.5A	DMF		N/A		5.32	5.32	
1	Driver Connector	P1	IC2CVERT_LATCHED	Conn, Through, 26 Pin, IC Dc Keyed Board Header with Latch	Open e.g. FEC: 3166508, 1099029, 9021019, 1097099	Fanell: 4963794	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	17	17	
1	EP1M7353QC80-8N	P2	IC2PFI60	IC, PGQFP, Programmable Logic Device (PLD)	Open e.g. Digkey: 568-1469-5-ND		Ordered Austen (RECEIVED) At BCS		52.5	52.5	
1	IC_1NPN	P3	IC2IOVERT	Conn, Through, 10 Pin, IC Dc Keyed Board Header, 0.1"	Open e.g. FEC: 1099254, Electus: PP1800 (Non RoHS)		Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	0.93	0.93	
1	1238 Motor Driver	U1	L238 Motor DRIVER	Dual H bridge motor driver, Vs up to 46V, Total DC Current 2A, Over temp protection	ST Microelectronics L238	Open e.g. Digkey: 497-3624-1-ND (Prefered), RS Components: 370-6963, FEC: 402295	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	6.26	6.26	
1	LM4032	U11	SOIC8	IC SOIC8 DUAL OPAMP, Rail to Rail input, Rail to Rail output, 2.7V to 24V	NATIONAL SEMICONDUCTOR LM4032AIM	Open e.g. FEC: 9438043	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	7.07	7.07	
1	Laser Diode Driver	S1	COM-DB15-FEMALE-VERTICAL	Conn, Through, DB15 Straight, Female	TYCO ELECTRONICS / AMP: 3-834223-2	Open e.g. FEC: 5082067	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	4.14	4.14	
1	Over Temp Conn	J2	COM-MOLEX-3	Conn, Through, MOLEX KK 2.54mm, 3 Pin Straight	Molex: 227-2031	Open e.g. FEC: 9711556	Ordered Fanell (RECEIVED) Sent to C.M. Entech	RoHS	156	156	
1	PBBA-2495C	U5	PBBA-2495C	Vin 24V, Vout 5V, Iout 12A, Pma5 6V, I20 150mV ripple	Powertom: PBBA-2495C	Powertom: PBBA-2495C	Ordered Fanell (RECEIVED) Sent to C.M. Entech		55	55	

Much more detail, has every single component, order status, unit cost, supplier, manufacturer etc.

Assembly Chart

Assembly Chart


- Shows the order of assembly (Given to factory workers to assemble a product).
- Shows the grouping of parts that make up a sub-assembly.
- Don't confuse with exploded view.

Assembly Chart


BOM

No.	Part No.	Part Name
1	51292	Outlet End
2	51284	Handle
3	52043	Switch & Insulator
4	51576	Electric Cord
5	51285	Rear Housing
6	51268	Motor Mounting Plate
7	51495	Motor Assy. & Fan Spacer
8	51270	Screw & Lock Washer Assy.
9	51273	Stationary Fan
10	51488	Rotary Fan & Spacer Assy.
11	51281	Front Fan Cover
12	51272	Forward Housing
13	51286	Air Filter
14	52388	Reusable Bag
15	51288	Inlet End Assy.
16	51642	Upholstery Tool
17	52074	Crevice Tool
18	50815	Dusting Tool
19	57432	Packaging Material (not shown)

Exploded View



Assembly Chart



Work Method Sheet

- Shows in detail **how** a component is to be **manufactured**.
- List individual operations to be performed on a component.
- **Includes:**
 1. Operation times
 2. Required tools, fixtures, gauges
 3. Machine setup
 4. Risk assessment and OHS issues (Take 5)

Work method sheet


Part Name: Valve Body Part No: 302 Customer Name: Midwest Valve Co. Quantity: 15						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time	Risk Assessment
10	Inspect forging, check hardness	Rockwell tester				
20	Rough machine flanges	Lathe No. 5				
30	Check Settings & Start	Lathe No. 5				
40	Bore & counter bore holes	Boring mill No. 1				
50	Turn internal grooves	Boring mill No. 1				
60	Drill & tap holes	Drill press No. 2				
70	Grind flange end faces	Grinder No. 2				
80	Grind bore	Int. grinder No. 1				
90	Clean	Vapour degreaser				
100	Inspect	Ultrasonic tester				

What would a work method sheet look like for your part?

Part Name: Piston Part No: xxxxxx Customer Name: xxxxxx Quantity: 1						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time	Risk Assessment
1	Cut aluminium rod to length	Bandsaw	200 fpm	10 TPI fine tooth blade	3 minutes	Look out for heat build up

Routing Chart

- Graphical representation of the entire manufacturing process
- Links to the work method sheet (for more detail via the operation #)



Summary

Exploded View & BOM:

Shows all the separate parts in an easy to read fashion, doesn't show how they are assigned. Internal & External.

Assembly Chart:

Shows how the product is assembled (used by factory workers)

Work method sheet:

Shows in detail how a component is to be manufactured.

Routing Chart:

Graphical representation of the entire manufacturing process.

Manufacturability Review


(*... or, can we make it?*)

■ Manufacturability Review

- Detailed & complete 2D Engineering drawing.
- A Bill of Material and Exploded Assembly.
- An Assembly Chart.
- A Work Method Sheet for your component.
- Routing Chart for your component.
- Routing Chart for the product.

Example:

Design and make a G-clamp




Engineering Drawing



Case: Product – G Clamp

Assembly Drawing & BOM



Item	Qty	Description
1	1	Clamp body
2	1	Lower Shoe
3	1	Clamp shoe
4	2	Handle ends
5	1	Handle
6	1	Clamp screw


Case: Product – G Clamp

Work Method Sheet – for clamp body component

Part Name: Clamp Body Part No: 302 Customer Name: Midwest Valve Co. Qty: 100						
Op. #	Process Description	Machine/Tools	Speed /Feed	Tooling	Time (min)	Risk Assessment
10	Inspect casting, check hardness	Rockwell tester			1	
25	Drill 10mm hole for clamp screw	Drill press No.2	500 rpm	10 mm twist drill bit	3	
30	Tap M10 for the clamp screw hole	Drill press No.2	500 rpm	M10 tapping bit	2	
40	Drill 5 mm hole for lower shoe	Drill press No.2	500 rpm	5mm twist drill bit	3	
50	Tap M5 for the lower shoe hole hole	Drill press No.2	500 rpm	M5 tapping bit	2	
60	Inspect	Calipper			1	

Case: Product – G Clamp

Routing chart



Suggested approach

1. Finalise Engineering Drawing / Blue Print
2. Evaluate appropriate raw materials.
3. List component features E.g. Face, Hole, Slot etc.
4. List available resources E.g. Lathe, Mill, Bench Drill, Grinder etc.
5. Compare and match each component feature to available resources.
6. Determine machine requirements such as tooling and process parameters.
7. Calculate time requirements.
8. Create individual work method sheet and routing chart from this information.
9. Combine individual routing charts into product routing chart.

Some general workshop suggestions

1. Reduce component movement between machines and between work-holding devices
2. Perform delicate operations such as polishing last to avoid subsequent damage.
3. Include frequent inspections to avoid rework and scrap.

Consult with your TAFE teachers