

# Experion PKS System Alarms Reference

EPDOC-X140-en-431A  
February 2015

**Release 431**

Document	Release	Issue	Date
EPDOC-X140-en-431A	431	0	February 2015

## Disclaimer

This document contains Honeywell proprietary information. Information contained herein is to be used solely for the purpose submitted, and no part of this document or its contents shall be reproduced, published, or disclosed to a third party without the express permission of Honeywell International Sàrl.

While this information is presented in good faith and believed to be accurate, Honeywell disclaims the implied warranties of merchantability and fitness for a purpose and makes no express warranties except as may be stated in its written agreement with and for its customer.

In no event is Honeywell liable to anyone for any direct, special, or consequential damages. The information and specifications in this document are subject to change without notice.

Copyright 2015 - Honeywell International Sàrl

# Contents

<b>About this reference .....</b>	<b>13</b>
<b>Archive system alarms .....</b>	<b>15</b>
Archive - Archive Failed: Low Disk Space .....	16
Archive - Failed To Archive History .....	17
<b>COMMS system alarms .....</b>	<b>19</b>
COMMS - Backup: Not Synchronized .....	21
COMMS - Backup Server .....	22
COMMS - CHANNEL <channel number> .....	23
COMMS - CONTROLLER <controller number> .....	24
COMMS - CStnxx: Data connection to <server name> is blocked. Remote server is busy .....	25
COMMS - CStnxx: Notification Server on <server name> OVERLOADED .....	26
COMMS - CStn<nn>: Not Synchronized .....	27
COMMS - <CStnxx/Server>: Data connection to <system interface name> failed. Access denied to remote server .....	28
COMMS - <CStnxx/Server>: Data connection to <system interface name> is blocked. Remote server is busy ...	29
COMMS - <CStnxx/Server>: Data connection to TPS failed. Remote server version is incompatible .....	30
COMMS - <CStnxx/Server>: Notifications from <system interface name> .....	31
COMMS - <CStnxx/Server>: Notifications from <system interface name> failed. Access denied to remote server .....	32
COMMS - Data Srv on <server name> OVERLOADED .....	33
COMMS - Door Open .....	34
COMMS - Failed - Cannot Access .....	35
COMMS - Failed - Could Not Print .....	36
COMMS - Failed - Printer Not Found .....	37
COMMS - Link 0 (LNK00) .....	38
COMMS - Link 1 (LNK01) .....	39
COMMS - Low On Toner .....	40
COMMS - No Links Available .....	41
COMMS - Offline .....	42
COMMS - Out of Paper .....	43
COMMS - Out Of Service .....	44
COMMS - Out Of Toner .....	45
COMMS - Output Bin Full .....	46
COMMS - Paper Jam .....	47
COMMS - Paper Problem .....	48
COMMS - Paused .....	49
COMMS - Peer Version Match .....	50
COMMS - Primary: Unknown Status .....	51
COMMS - Printer Error .....	52
COMMS - SAM connection failed .....	53
COMMS - Server: Data connection to <server name> .....	54
COMMS - Server: Data connection to <server name> failed. Access denied to remote server .....	55
COMMS - Server: Data connection to <server name> is blocked. Remote server is busy .....	56
COMMS - Server: Failed - Access Is Denied .....	57
COMMS - Server: Link to <server name> .....	58

COMMS - Server: Link to <system interface name> .....	59
COMMS - Server: Notifications from <server name> .....	60
COMMS - Server: Notifications from <server name> failed. Access denied to remote server .....	61
COMMS - Station Failure .....	62
COMMS - Synchronization .....	63
COMMS - User Intervention Required .....	64
<b>DIAG system alarms .....</b>	<b>65</b>
DIAG - A/D Failure .....	70
DIAG - Activity Create Failed .....	71
DIAG - Address Overlap .....	72
DIAG - Asymmetric Response From Probe .....	73
DIAG - Backup RAM Scrub Errors .....	74
DIAG - Backup RAM Sweep Errors .....	75
DIAG - Backup State .....	76
DIAG - Bad Configuration .....	77
DIAG - Battery Not OK .....	78
DIAG - Battery Over Voltage .....	79
DIAG - Battery Under Voltage .....	80
DIAG - BOOTP Enabled .....	81
DIAG - Calibration Cleared .....	82
DIAG - Calibration Error .....	83
DIAG - CEE Cycle Overruns .....	84
DIAG - CEE Hold Breath .....	85
DIAG - Channel Hardware Fault .....	86
DIAG - Characterization Error .....	87
DIAG - Checkpoint Save Status .....	88
DIAG - CJ Failure .....	89
DIAG - Cold Junction Fault .....	90
DIAG - Communication Ceased .....	91
DIAG - Communication Error .....	92
DIAG - Communication Fault .....	93
DIAG - Communication With This Point Is Lost. Load Server Point Immediately .....	94
DIAG - Configuration Error .....	95
DIAG - Connection Error .....	96
DIAG - Connection Failed .....	97
DIAG - Connection Timeout .....	98
DIAG - CPU Free Low Alarm .....	99
DIAG - CPU Low Low Resources .....	100
DIAG - DAC Voltage Deviation .....	101
DIAG - Daughter Board Fail .....	102
DIAG - Debug Flag Enabled .....	103
DIAG - Debugger Is Running .....	104
DIAG - Device Fail .....	105
DIAG - Device/Firmware Mismatch .....	106
DIAG - Device Idle .....	107
DIAG - Device Index Setting Does Not Match Displayed Value .....	108
DIAG - Device Index Switches Changed .....	109
DIAG - Device Index Value Is Zero Upon Power Up .....	110
DIAG - Device Mismatch .....	111
DIAG - Device Not Configured .....	112
DIAG - Device Offline .....	113
DIAG - Device Registration Error .....	114
DIAG - DeviceNet IM Comm Error .....	115
DIAG - DeviceNet_IM Disabled .....	116

DIAG - DeviceNet IM Duplicate Address .....	117
DIAG - DeviceNet IM Faulted .....	118
DIAG - DeviceNet IM Idle .....	119
DIAG - DeviceNet IM Not Active .....	120
DIAG - DeviceNet IM Not Specified .....	121
DIAG - DeviceNet IM Power Fail .....	122
DIAG - DI Input Fail Alert .....	123
DIAG - Different Amount of Devices .....	124
DIAG - Drive Alarm .....	125
DIAG - Drive Fault .....	126
DIAG - Duplicate Node Address On Link .....	127
DIAG - Electrode Open Circuit or LPR Mode Error .....	128
DIAG - Electrode Short Circuit .....	129
DIAG - Electronics Failure .....	130
DIAG - Excess Calibrated Range .....	131
DIAG - Excess Calibration Correction .....	132
DIAG - Excess Span Calibration .....	133
DIAG - Excess Zero Calibration .....	134
DIAG - Excessive H1 Link Communication Errors .....	135
DIAG - Factory Data Error .....	136
DIAG - Fatal FF Communication Error .....	137
DIAG - Fieldbus devices not communicating or intermittent .....	138
DIAG - FIM Cable Failure, FIM or RTP Slot .....	139
DIAG - FIM Is Not Primary Link Master .....	140
DIAG - FIM Not Responding .....	141
DIAG - FIM Lost Sync .....	142
DIAG - FIM Schedule Error, Not Executing Slot .....	143
DIAG - FIM SLOT: XX { Tag Identifier } ( Err XX ) .....	144
DIAG - Firm Ware Error1 .....	145
DIAG - Firm Ware Error2 .....	146
DIAG - FTA A Communication Error .....	147
DIAG - FTA B Communication Error .....	148
DIAG - FTE Port A Receive Fault .....	149
DIAG - FTE Port B Receive Fault .....	150
DIAG - Function Block Error .....	151
DIAG - GPS Failed .....	152
DIAG - H1 Link Communication Error Detected .....	153
DIAG - H1 Link Power Failure .....	154
DIAG - Hardware Temperature Exceeded The Threshold .....	155
DIAG - Harmonic Distortion Mode Not Possible .....	156
DIAG - Heap Memory Not Available .....	157
DIAG - HW Rev Below Acceptable Minimum — Upgrade Required .....	158
DIAG - ICP QSend Error .....	159
DIAG - ICP Unrecognized CMD .....	160
DIAG - Illegal CLear DEVADDR Attempt On Link .....	161
DIAG - Illegal Clear PD_TAG Attempt On Link .....	162
DIAG - Illegal Set DEVADDR Attempt On Link .....	163
DIAG - Illegal Set PD_TAG Attempt On Link .....	164
DIAG - Illegal Unknown SM Event On Link .....	165
DIAG - Input 1 Calibration Failure .....	166
DIAG - Input 2 Calibration Failure .....	167
DIAG - Input 3 Calibration Failure .....	168
DIAG - Input 1 Failure .....	169
DIAG - Input 2 Failure .....	170

DIAG - Input 3 Failure .....	171
DIAG - Input 1 T/C Warning .....	172
DIAG - Input 2 T/C Warning .....	173
DIAG - Input 3 T/C Warning .....	174
DIAG - Input Failure .....	175
DIAG - Intermittent Comm Failure .....	176
DIAG - Invalid Keeper .....	177
DIAG - IOLink(1) Soft Fail Error .....	178
DIAG - IOLink(2) Soft Fail Error .....	179
DIAG - JagXtreme Communication Error .....	180
DIAG - JX Instrument Alarm .....	181
DIAG - JX Instrument Fault .....	182
DIAG - KTC Failure .....	183
DIAG - Loss Of Batch Event .....	184
DIAG - Loss Of Batch Event Data .....	185
DIAG - Lost Sync .....	186
DIAG - Low Battery .....	187
DIAG - Low External Power .....	188
DIAG - Low Power .....	189
DIAG - Local Hardware Fault .....	190
DIAG - Low Redundancy .....	191
DIAG - Max Number Of Devices Exceeded .....	192
DIAG - MDM Service Is Running .....	193
DIAG - Memory Limit Exceeded .....	194
DIAG - Missing Keeper .....	195
DIAG - Module Hardware Fault .....	196
DIAG - No Field Power Detected .....	197
DIAG - No Load Detected .....	198
DIAG - No PBIM Reference .....	199
DIAG - No Sensor Board Alert .....	200
DIAG - Non-Volatile Memory Error .....	201
DIAG - Not Using Configured Time Source .....	202
DIAG - Over Range Fault .....	203
DIAG - Over Temperature Alert .....	204
DIAG - PCIC Lonely On CNet .....	205
DIAG - Partner Not Visible on FTE .....	206
DIAG - PBIM Communication Error .....	207
DIAG - PBIM Inactive .....	208
DIAG - PBIM Registration Error .....	209
DIAG - PCIC Failure .....	210
DIAG - Pressure Overload Alert .....	211
DIAG - PROFIBUS Communication Error .....	212
DIAG - PROFIBUS Not In Run .....	213
DIAG - PROFIBUS Offline .....	214
DIAG - Program Memory Fault .....	215
DIAG - PTP Time Source Failed .....	216
DIAG - QiMPACT Communication Error .....	217
DIAG - QiMPACT Instrument Alarm .....	218
DIAG - QiMPACT Instrument Fault .....	219
DIAG - Radio Interprocessor Comm Error .....	220
DIAG - Radio Status EEPROM SP1 Communication Failure .....	221
DIAG - Radio Status Radio Communication Circuitry Failure .....	222
DIAG - Radio Status Sensor Radio SP1 Communication Failure .....	223
DIAG - Radio Status WDT Reset Occurred .....	224

DIAG - RAM Error .....	225
DIAG - RAM Fault .....	226
DIAG - Reconfiguration Fail .....	227
DIAG - Redun Standby .....	228
DIAG - Redun Count Exceeded .....	229
DIAG - Remote Hardware Fault .....	230
DIAG - ROM Application Image Checksum Failure .....	231
DIAG - ROM Boot Image Checksum Failure .....	232
DIAG - ROM Error .....	233
DIAG - RSLinx Failure .....	234
DIAG - RSLinx Initialization Failure .....	235
DIAG - RTP Disconnect .....	236
DIAG - Runtime Diagnostic Failure .....	237
DIAG - Runtime Diagnostic OVERRUN .....	238
DIAG - Runtime Fail on Daughter Board .....	239
DIAG - Secondary Address Overlap .....	240
DIAG - Sensor Alert .....	241
DIAG - Short Circuit Detected .....	242
DIAG - SIOM Offline .....	243
DIAG - SIOM Offline, Communications Ceased .....	244
DIAG - SIOM Offline, Secondary Communications Ceased .....	245
DIAG - SM Dupe Node Address .....	246
DIAG - SM Node Address Clear .....	247
DIAG - SM Node Address Set .....	248
DIAG - SM Physical Device Tag Clear .....	249
DIAG - SM Physical Device Tag Set .....	250
DIAG - SM Unknown .....	251
DIAG - SNTP Failed .....	252
DIAG - Stack Limit Exceeded .....	253
DIAG - Stale Output Alert .....	254
DIAG - Sync Checksum Fail .....	255
DIAG - Sync HW Failure .....	256
DIAG - Task Health Monitoring Warning .....	257
DIAG - Time Jump Greater Than Five Minutes .....	258
DIAG - UMAX Exceeded .....	259
DIAG - Uncommanded Shutdown .....	260
DIAG - Uncomm Dev Oper Class Changed To Basic .....	261
DIAG - Under Range Fault .....	262
DIAG - Unexpected Partner on Redundancy Link .....	263
DIAG - Verify Lost .....	264
DIAG - Watchdog Timer Error .....	265
DIAG - WDT Refresh Warning .....	266
DIAG - Wire off Detected .....	267
<b>Duplicate Point system alarms .....</b>	<b>269</b>
Duplicate Point - message/alarm/alert from con <server name> is on a point which is a duplicate of an existing point from con <server name> .....	270
<b>EVTARC system alarms .....</b>	<b>271</b>
EVTARC - Event Archive Initialization Failed .....	272
EVTARC - Invalid archive directory .....	273
<b>HSTARC system alarms .....</b>	<b>275</b>
HSTARC - Disk Full Error .....	276
HSTARC - Invalid Pathname For Move .....	277
HSTARC - Permission Error .....	278

<b>LNK nn system alarms .....</b>	<b>279</b>
LNK nn - Cntrl Stream Upgraded .....	280
LNK nn - Peer Server Host Name Cannot Be Resolved .....	281
<b>No condition system alarms .....</b>	<b>283</b>
Asset Electronic Signature .....	284
CStnxx: Server Is Not Available .....	285
Disk Space Low: Deleting Old Archives .....	286
Disk Space Low: Suspending Event Collection .....	287
Event Archiving Reset Failed .....	288
Event File Error .....	289
Failed logon attempt .....	290
<b>NULL system alarms .....</b>	<b>291</b>
NULL - Console Fail .....	292
NULL - Console Marginal .....	293
NULL - Console Station Is Not Available .....	294
<b>ORPHANS system alarms .....</b>	<b>295</b>
ORPHANS - Orphan Activities Detected .....	296
<b>OTHER system alarms .....</b>	<b>297</b>
OTHER - Duplicate IOL Address .....	298
OTHER - IOL Channel A Failure .....	299
OTHER - IOL Channel B Failure .....	300
OTHER - IOL Maximum Errors Exceeded .....	301
OTHER - IOL Pre-fetch Alarm Overruns .....	302
OTHER - IOL Process Data Cycle Overruns .....	303
OTHER - IOL Processor, Diagnostic Cycle Overflow .....	304
OTHER - IOL Processor Diagnostic Exceeded Time Threshold .....	305
OTHER - IOL Processor Diagnostic Failed To Complete .....	306
OTHER - IOL Processor, Diagnostic Initiation Timeout .....	307
OTHER - IOL Processor, Resumption Of Non-Wait Task .....	308
OTHER - IOL Processor Stack Limit Overflow .....	309
OTHER - IOL Processor Unknown SF .....	310
OTHER - Not Active Supervisor .....	311
OTHER - Partner I/F Mismatch on IOL .....	312
OTHER - Partner I/F Not Visible On IOL .....	313
<b>Replication system alarms .....</b>	<b>315</b>
Replication - Events Database Replication Failed .....	316
Replication <replication number> failed .....	317
<b>Scripting system alarms .....</b>	<b>319</b>
Scripting - Script Engine Error .....	320
<b>Series C and Process Manager I/O System Alarms .....</b>	<b>321</b>
A/D Conversion Data Overflow - 5v Supply to Application board failure .....	324
A/D Conversion Data Overflow - A/D Conversion Data Overflow .....	325
A/D Conversion Incomplete - A/D Conversion Incomplete .....	326
ADC Register Write Failure - ADC Register Write Failure .....	327
ADC Supply Voltage Failure - ADC Supply Voltage failure .....	328
ADOUTUDF_042 - ADC VALUE UNDERFLOW(APPLY TO DATA I/P'S) .....	329
ADPCOMFL_027 - NO COM TO ADP OR OTHER MICRO PROCSR AM .....	330
ADRAMADR_01 - ADP PRIVATE RAM ADDRESSING FAILURE .....	331
ADRAMCNT_011 - ADP PRIVATE RAM CONTENTS FAILURE .....	332
ADROMERR_016 - ADP EPROM CHECKSUM FAILURE .....	333



ADSTRUP_018 - ADP START UP FAILURE .....	334
AI Channel Not Calibrated - AI IOM is out of calibration .....	335
AO Channel Not Calibrated - AO IOM is out of calibration .....	336
AO Channel Not Calibrated - SVP-IOM/SP-IOM AO channels not calibrated .....	337
BADADPER_017 - BAD ERROR CODE DETECTED IN ADP .....	338
BADADPJP_034 - BAD BRANCH TAKEN IN ADP ROM EXECUTION .....	339
BADCALRF_039 - CALIBRATION REFERENCE OUTSIDE LIMITS .....	340
BADFLREG_044 - AO FAILURE SELECTION REGISTER IS BAD .....	341
BADPLUGM_029 - BAD PLUG-IN MODULE IN FTA .....	342
BADRESUM_003 - RESUME OF NON-WAITING TASK .....	343
BADRJVAL_033 - REFERENCE JUNCTION VALUE BAD .....	344
BADSECRG_022 - SECONDARY REGULATOR NOT OK .....	345
BDOUTBFR_046 - Bad Output Buffer .....	346
BDSNDLTC_045 - Bad Secondary Latch .....	347
CABLE DISCONNECT, RTP - No RTP connection .....	348
CALBABRT_038 - CALIBRATION SEQUENCE ABORTED .....	349
Channel Not Field Calibrated - SVP-IOM/SP-IOM Channel not field calibrated .....	350
Cold Start - Device Cold Start .....	351
COMMS - No IOLP access to shared RAM .....	352
Configuration Changed - Device Configuration Changed .....	353
Device Malfunction - Field Device Malfunction .....	354
DIAGCTFL_026 - AI Input-Output loopback failure .....	355
DIAGCTFL_026 - DI Input-Output loopback failure .....	356
DIAGCTFL_026 - IOM diagnostic circuit failure .....	357
DIAGOFLO_005 - ENTIRE DIAG CYCLE OVERFLOW .....	358
DIAGTMOT_004 - ONE DIAG INITIATION TIMED OUT .....	359
DO Relay Extn Board Missing - Relay Extension Board Missing .....	360
DTPATHFL_069 - DATA PATH FAILURE .....	361
DTPATHTO_070 - DATA PATH TIME OUT .....	362
EECKSMER_007 - EEPROM CHKSUM ERROR .....	363
EECNTERR_008 - EEPROM counter error - too many writes .....	364
EEFAILED_040- EEPROM UPDATE FAILED DUE TO EEPROM BUSY .....	365
EEFLAGER_009 - EEPROM INCOMPLETION ERROR .....	366
Feedback Inputs failure - Resolver Feedback Inputs Failure .....	367
FTA 1 Calibration Failure - FTA 1 CALIBRATION FAIL .....	368
FTA1 Comm Failure - FTA 1 COMMUNICATION FAIL .....	369
FTA 1 Fail - LLMUX FTA1 HAS A FAILURE .....	370
FTA 1 Identification Error - FTA 1 IDENT ERROR .....	371
FTA1 Not Calibrated - FTA 1 IS NOT CALIBRATED .....	372
FTA 1 Ref Voltage Failure - FTA 2 VREF FAIL .....	373
FTA 2 Calibration Failure - FTA 3 CALIBRATION FAIL .....	374
FTA 2 Comm Failure - FTA 2 COMMUNICATION FAIL .....	375
FTA2 Fail - LLMUX FTA2 HAS A FAILURE .....	376
FTA 2 Identification Error - FTA 2 IDENT ERROR .....	377
FTA 2 Not Calibrated - FTA 2 IS NOT CALIBRATED .....	378
FTA 2 Ref Voltage Failure - FTA 2 VREF FAIL .....	379
FTA 3 Calibration Failure - FTA 3 CALIBRATION FAIL .....	380
FTA 3 Comm Failure - FTA 3 communication failure .....	381
FTA 3 Fail - AI-MUX FTA3 HAS A FAILURE .....	382
FTA 3 Identification Failure - FTA 3 identification failure .....	383
FTA 3 Not Calibrated - FTA 3 IS NOT CALIBRATED .....	384
FTA 3 Ref Voltage Failure - FTA 3 reference voltage failure .....	385
FTA 4 Calibration Failure - FTA 4 CALIBRATION FAIL .....	386
FTA 4 Comm Failure - FTA 4 communication failure .....	387

FTA4 Fail - AI-MUX FTA4 HAS A FAILURE .....	388
FTA 4 Identification Error - FTA 4 identification failure .....	389
FTA 4 Not Calibrated - FTA 4 IS NOT CALIBRATED .....	390
FTA 4 Ref Voltage Failure - FTA 4 reference voltage failure .....	391
FTA Power Failure - FTA Power Failure .....	392
FTAMISSG_006 - FTA or power adapter missing .....	393
FTASMCCH_031 - FTA type mismatch with point configuration .....	394
HART Comm Failure - HART Communication Fail .....	395
HART Diagnostic Underrun - HART PROCESSOR DIAGNOSTIC TASK UNDER-RUN .....	396
HART Modem 1 Error - HART hardware error detected against DUART channel 1 or modem 1 .....	397
HART Modem 2 Error - HART hardware error detected against DUART channel 2 or modem 2 .....	398
HART Modem 3 Error - HART hardware error detected against DUART channel 3 or modem 3 .....	399
HART Modem 4 Error - HART hardware error detected against DUART channel 4 or modem 4 .....	400
HART Stack High - HSTACKHI .....	401
HWFILOFL_064 - HARDWARE FIFO FAILURE .....	402
INPTFAIL_021 - INPUT POINT FAILURE .....	403
IOL Address Diag Failure - IOL Address Diag Failure .....	404
IOM or IOTA HART Chan Failure - IOM or IOTA HART Channel Failure .....	405
IOPSWITCHOVER - IOP Switchover Occurred .....	406
LOSTSYNC_058 - LOSTSYNC .....	407
LVDT Core Fallout - LVDT Core Fallout .....	408
MBCHKMER_015 - MBCHKMER .....	409
MBRAMADR_014 - MBRAMADR .....	410
MBRAMCNT_013 - MBRAMCNT .....	411
MLTINPFL_060 - MLTINPFL .....	412
Module Not Calibrated - ADC OUT OF CALIBRATION .....	413
More Status Available - More Status Available .....	414
No Response .....	415
NOACLINE_028 - NOACLINE .....	416
NTUSED62_062 - Data bus failure .....	417
OP Fail in Circuit/Field Wire - Failure in output circuit/field wiring detected by AO or DO .....	418
Open Wire Detected - Open wire/sensor detected .....	419
Output Short Circuit Detected - DO channel detected a short circuit or over current situation .....	420
PIFAULTY_072 - FIELDBUS - FAULTY personality image .....	421
PRVRAMFL_065 - Private RAM diagnostic failed .....	422
PV Out of Limits - Primary Variable Out Of Limits .....	423
PVVALDFL_067 - PV validation diagnostic failed .....	424
Readback Register Diag Failure - Readback Register Diagnostic Failure .....	425
REDNDIAG_061 - REDNDIAG .....	426
Redundancy Hardware Failure - Redundancy Hardware Failure .....	427
REQOFLOW_002 - IOP task request overflow - excessive IOL activity .....	428
SCANORUN_019 - SCANORUN .....	429
Servo Current Driver Shutdown - Servo Current Driver Shutdown .....	430
SOECLKFL_066 - SOECLKFL .....	431
SOECNTFL_068 - SOECNTFL .....	432
Speed Channel - No Pulse Input - Speed Channel - No Pulse Detected .....	433
Speed RCAP Ref Clock Failure - Speed RCAP Ref Clock Failure .....	434
STCKLIM_024 - STCKLIM .....	435
STCOVRUN_001 - Sample time clock overrun .....	436
STMACHFL_071 - STMACHFL .....	437
SupIna - Not Active Supervisor .....	438
Uncertain Pulse Input - Uncertain Pulse Input .....	439
Unstable Input - Resolver Unstable Input .....	440
Variable Out Of Limits - Non-Primary Variable Out Of Limits .....	441

VDT ADC Selection Failure - LVDT ADC Channel Selection Failure .....	442
VDT Critical Signal Failure - LVDT Channel Critical Signal Failure .....	443
VDT Exctn Freq Drift - LVDT Excitation Frequency Drift Greater than 100Hz .....	444
VDT Extn Volt Out of Range - LVDT Excitation Voltage out of calibrated Range .....	445
VDT Fb A Volt Out of Range - LVDT Feedback Channel A Voltage out of calibrated Range .....	446
VDT Fb B Volt Out of Range - LVDT Feedback Channel B Voltage out of calibrated Range .....	447
VREFFAIL_041 - Reference voltage out of range .....	448
VTESTFAI_030 - VTESTFAI .....	449
VZERO_FL_032 - VZERO_FL .....	450
WRITENBL_059 - WRITENBL .....	451
WRONG_HW_063 - WRONG_HW .....	452
<b>SYNC system alarms .....</b>	<b>453</b>
SYNC - Backup Point Database Larger .....	454
SYNC - Backup Inconsistency Detected .....	455
SYNC - Backup Server Error Starting .....	456
<b>Systems Management system alarms .....</b>	<b>457</b>
ACE:CDA-SP : Experion PKS CDA-SP Service stopped .....	459
CAS: Component Admin Service is not running .....	460
CAS: was unable to Checkpoint component <component name> Error = <error num>:<error string> .....	461
<Component Name>: Component state changed from <previous state> to Communication Failure .....	462
<Component name>: Component state changed from <previous state> to Failed .....	463
<Component name>: Component state changed from <previous state> to Warning .....	464
<Component Name>: Device state changed from <previous state> to Communication Failure .....	465
<Component name>: Device state changed from <previous state> to Failed. Device Info: <device info> .....	466
<Component name>: Device state changed from <previous state> to Warning. Device Info: <device info> .....	467
Control Firewall <device name> (address <Fw address>) port <port ID> excessive TX_PAUSE change. Cur:<Tx Pause Val> Last:<Last Tx Pause Val> .....	468
Control Firewall <Fw name> (address <Fw address>) has blocked ports .....	469
Control Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE .....	470
Control Firewall <Fw Name> (address <Fw Address>) port <port index> link status is Down .....	471
Control Firewall <Fw name> (address<Fw address>) uplink RX_OCTETS has stalled. Check for intermittent cable .....	472
Control Firewall <Fw name> (address<Fw address>) uplink TX_OCTETS has stalled. Check for intermittent cable .....	473
Excessive Disk Paging: memory resource issue is causing excessive disk paging .....	474
FTE device <device name> (Device Index: <device index>) has detected a duplicate .....	475
FTE device <device name> disjoined FTE community (no longer being heard) .....	476
FTE Device <device name> interface <A/B> status is SILENT .....	477
FTE/Heartbeat network packet delivery to application layer is being delayed. Node is experiencing Disk/CPU resource utilization issues .....	478
FTE STATUS: Device state changed from <previous state> to Failed. Device Info: <device information string> .....	479
FTEProvider: FTE Provider is not running .....	480
HCINS: Alias name: <component alias name> exists on two nodes in the same TPSDomain. You must remove or rename one of them to solve this problem .....	481
HCINS: Alias name: <component alias name> from the component alias file conflicts with the one in the repository - You must remove Alias name from the component alias file to solve this problem .....	482
Modbus/TCP Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down .....	483
Modbus/TCP Firewall <Fw name> (address<Fw address>) uplink RX_OCTETS has stalled. Check for intermittent cable .....	484
Modbus/TCP Firewall <Fw name> (address <Fw address>) uplink TX_OCTETS has stalled. Check for intermittent cable .....	485
Modbus/TCP <Fw Name> (address <Fw address>) is no longer being heard by FTE .....	486
One-Wireless Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE .....	487

One-Wireless Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down .....	488
One-Wireless Firewall <Fw name> (address <Fw address>) uplink RX_OCTETS has stalled. Check for intermittent cable .....	489
One-Wireless Firewall <Fw name> (address <Fw address>) uplink TX_OCTETS has stalled. Check for intermittent cable .....	490
OPC Event Source: <node name>. Proxy ARP agent found. Check router configuration .....	491
SNMP Trap: - <IP Address> Type - AuthenticationFailure .....	492
SNMP Trap: - <IP Address> Type - ColdStart .....	493
SNMP Trap: - <IP Address> Type - LinkDown; Index - <Index> .....	494
SNMP Trap: - <IP Address> Type - WarmStart .....	495
SRP(syncrep.exe): FTE Status cannot be determined. Restart FTE Status server. <error message> .....	496
SRP(syncrep.exe): SRP has not heard expected traffic for an excessive period. Reconnecting Receive socket ..	497
Synchronization requests were not answered by node(s): <node list> .....	498
SysEvtProv: System Event Provider is not running .....	499
The system detected an address conflict for IP address <IP Address> with the system having <network> hardware address <hdw address>. <Message> .....	500
<b>Notices .....</b>	<b>503</b>
Documentation feedback .....	504
How to report a security vulnerability .....	505
Support .....	506
Training classes .....	507

# About this reference

This reference describes how to respond to Experion system alarms.

**Revision history**

Revision	Date	Description
A	February 2015	Initial release of document.



# Archive system alarms

The following topics describe archive-related system alarms and how to respond to them.

## **Related topics**

“Archive - Archive Failed: Low Disk Space” on page 16

“Archive - Failed To Archive History” on page 17

---

## Archive - Archive Failed: Low Disk Space

### Potential causes

The drive where online history archives are to be stored (typically in 'data\archive') does not have enough free space.

### Consequence of inaction

Online history could be lost if not archived. If history is lost, depending on the type lost and history archiving settings, Trends may show gaps where history is missing.

### Corrective actions

1. Call up the **History Archiving** display.
2. Check that the History Archiving Disk Limit is configured appropriately.
3. Check that the 'Location to Move History Archive to' exists and has enough free space.
4. Call up the **Server Configuration** display.
5. Check that the archive folder exists and has enough free space.

For more information, see “Configuring history archives”.

### Time to respond

Immediate.



---

## Archive - Failed To Archive History

### Potential causes

1. Online history files could not be copied to the online history archive folder (typically 'data\archive').
2. Error creating online history archive files in the destination archive folder.
3. Error writing to the online history archive files in the destination archive folder.

### Consequence of inaction

Online history could be lost if not archived. If history is lost, trends may show gaps where history is missing (depending on the type lost and history archiving settings).

### Corrective actions

1. Open the **Experion PKS Server Configuration Panel**.
2. Check that the archive folder exists.
3. Check that MNGR user has permission to create files and directories and write to the archive folder.

For more information, see “Configuring history archives”.

### Time to respond

Immediate.



# COMMS system alarms

The following topics describe communication-related system alarms and how to respond to them.

## Related topics

- “COMMS - Backup: Not Synchronized” on page 21
- “COMMS - Backup Server” on page 22
- “COMMS - CHANNEL <channel number>” on page 23
- “COMMS - CONTROLLER <controller number>” on page 24
- “COMMS - CStnxx: Data connection to <server name> is blocked. Remote server is busy” on page 25
- “COMMS - CStnxx: Notification Server on <server name> OVERLOADED” on page 26
- “COMMS - CStn<nn>: Not Synchronized” on page 27
- “COMMS - <CStnxx/Server>: Data connection to <system interface name> failed. Access denied to remote server” on page 28
- “COMMS - <CStnxx/Server>: Data connection to <system interface name> is blocked. Remote server is busy” on page 29
- “COMMS - <CStnxx/Server>: Data connection to TPS failed. Remote server version is incompatible” on page 30
- “COMMS - <CStnxx/Server>: Notifications from <system interface name>” on page 31
- “COMMS - <CStnxx/Server>: Notifications from <system interface name> failed. Access denied to remote server” on page 32
- “COMMS - Data Srv on <server name> OVERLOADED” on page 33
- “COMMS - Door Open” on page 34
- “COMMS - Failed - Cannot Access” on page 35
- “COMMS - Failed - Could Not Print” on page 36
- “COMMS - Failed - Printer Not Found” on page 37
- “COMMS - Link 0 (LNK00)” on page 38
- “COMMS - Link 1 (LNK01)” on page 39
- “COMMS - Low On Toner” on page 40
- “COMMS - No Links Available” on page 41
- “COMMS - Offline” on page 42
- “COMMS - Out of Paper” on page 43
- “COMMS - Out Of Service” on page 44
- “COMMS - Out Of Toner” on page 45
- “COMMS - Output Bin Full” on page 46
- “COMMS - Paper Jam” on page 47
- “COMMS - Paper Problem” on page 48
- “COMMS - Paused” on page 49
- “COMMS - Peer Version Match” on page 50
- “COMMS - Primary: Unknown Status” on page 51
- “COMMS - Printer Error” on page 52

- “COMMS - SAM connection failed” on page 53
- “COMMS - Server: Data connection to <server name>” on page 54
- “COMMS - Server: Data connection to <server name> failed. Access denied to remote server” on page 55
- “COMMS - Server: Data connection to <server name> is blocked. Remote server is busy” on page 56
- “COMMS - Server: Failed - Access Is Denied” on page 57
- “COMMS - Server: Link to <server name>” on page 58
- “COMMS - Server: Link to <system interface name>” on page 59
- “COMMS - Server: Notifications from <server name>” on page 60
- “COMMS - Server: Notifications from <server name> failed. Access denied to remote server” on page 61
- “COMMS - Station Failure” on page 62
- “COMMS - Synchronization” on page 63
- “COMMS - User Intervention Required” on page 64

---

## COMMS - Backup: Not Synchronized

### Potential causes

The Experion PKS Server state has changed to Database Only. CDA or SR services on the primary or backup may have been stopped or failed, or the system may be experiencing network issues.

### Consequence of inaction

Server synchronization has failed. Future modifications to primary System Repository content will not be synchronized with the backup, and may be lost.

### Corrective actions

If the backup server is in Database Only state, return it to Running state. Synchronization will occur automatically.

Otherwise, go to the Server Redundancy display and check the System Repository backup status. If the status is 'Stopped,' go to the services and start the Experion PKS System Repository service. You may also need to check that the status of the Experion PKS Control Data Access Server service is running.

### Time to respond

Immediate.

---

## COMMS - Backup Server

**Potential causes**

The backup server is not running.

**Consequence of inaction**

Backup Server (and therefore server redundancy) is not available. The system will continue to run on Primary, but without redundancy.

**Corrective actions**

1. Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.
2. Set the backup server status to System Running.

**Time to respond**

Backup Server is unavailable as when alarm is raised. The time to respond will depend on assessment of process/site/operations for criticality/risk of running without backup server available.

---

## COMMS - CHANNEL <channel number>

**Potential causes**

A SCADA channel is marginal or failed.

**Consequence of inaction**

If a SCADA channel fails, process data from point parameters on that channel will not be available. It will also not be possible to initiate control.

**Corrective actions**

1. Check the SCADA controller status on the **System Status** display.
2. Check communication links to SCADA devices and the devices themselves.

**Time to respond**

The corrective actions should be initiated immediately to prevent loss of process data on the SCADA channel.

---

## COMMS - CONTROLLER <controller number>

### Potential causes

A SCADA device is marginal or failed.

### Consequence of inaction

If a SCADA controller fails, process data from point parameters on that controller will not be available. It will also not be possible to initiate control.

### Corrective actions

1. Check the SCADA controller status on the **System Status** display.
2. Check communication links to SCADA devices and the devices themselves.

### Time to respond

The corrective actions should be initiated immediately to prevent loss of process data on the SCADA controller.



---

## COMMS - CStnxx: Data connection to <server name> is blocked. Remote server is busy

### Potential causes

The numbered Console Station has notified that the server is not responding in a timely manner.

### Consequence of inaction

The Console Station will not be able to view data from the mentioned connection. If the blocked connection is the cluster server connection, the Console Station will not be able to view SCADA, DSA, or third-party OPC data, but direct data remains unaffected.

### Corrective actions

- 1 Call up the **Console Station Status Detail** display on the remote server.
- 2 Use Windows Performance Monitor on the remote server to make sure CPU load and free memory are within the Experion Specification limits. The Experion Specification is available from Honeywell.

### Time to respond

Immediately.

---

## COMMS - CStnxx: Notification Server on <server name> OVERLOADED

### Potential causes

The numbered Console Station has notified that the DSA remote server is experiencing alarm overload. The remote server may be experiencing high system load and is having trouble sending alarms to the local server fast enough.

### Consequence of inaction

There may be a delay before notifications from that server are displayed on the Console Station. If the Experion cluster server is overload, DSA, SCADA, and third-party OPC alarms will be delayed.

### Corrective actions

- 1 Call up the **Console Station Status Detail** display on the remote server.
- 2 Use Windows Performance Monitor on the remote server to make sure CPU load and free memory are within the Experion Specification limits. The Experion Specification is available from Honeywell.

### Time to respond

Immediately.

---

## COMMS - CStn<nn>: Not Synchronized

### Potential causes

CDA or SR services on the Console Station might have been stopped or failed, or the system might be experiencing network issues.

### Consequence of inaction

Server synchronization has failed. Future modifications to primary System Repository content will not be visible on the Console Station. If the CDA or SR services have failed, you might not be getting data updates from CDA. CDA data might appear in inverse video and No Tag alarms might be generated.

### Corrective actions

Go to the services and check that both the Experion PKS System Repository service and the Experion PKS Control Data Access Server service are running.

Check the connection to CDA. If the status of data or notifications is not OK and/or you are not receiving data updates from CDA, go to the services and start the Experion PKS Control Data Access Server service. You may also need to start the Experion PKS System Repository service.

### Time to respond

Synchronization is lost immediately when this alarm occurs. Time to respond will depend on assessment of process/site/operations for criticality/risk of losing synchronization.

---

## **COMMS - <CStnxx/Server>: Data connection to <system interface name> failed. Access denied to remote server**

### **Potential causes**

The Console Station or server has notified that data-channel communication with <system interface name> has failed.

### **Consequence of inaction**

Point parameter data will not be available from the system interface.

### **Corrective actions**

Call up the **System Interfaces Status Summary** display.

### **Time to respond**

Immediately.

---

## **COMMS - <CStnxx/Server>: Data connection to <system interface name> is blocked. Remote server is busy**

### **Potential causes**

There are three outstanding requests to the system interface that have not returned. Experion will not create any more requests until one of the outstanding requests is returns.

### **Consequence of inaction**

Point parameter data will not be available from the system interface.

### **Corrective actions**

Check that the server the system interface is connected to is functioning correctly.

### **Time to respond**

Immediately

---

## **COMMS - <CStnxx/Server>: Data connection to TPS failed. Remote server version is incompatible**

### **Potential causes**

The wrong version of TPN Server has been installed.

### **Consequence of inaction**

Point parameter data will not be available from TPS.

### **Corrective actions**

Install the TPN server version that matches the release of Experion being used.

### **Time to respond**

Immediately.

---

## COMMS - <CStnxx/Server>: Notifications from <system interface name>

### Potential causes

The Console Station or server has notified that notifications from the system interface are unavailable.

### Consequence of inaction

Notifications will not be available from the system interface.

### Corrective actions

1. Call up the **System Status** display.
2. Check that the network connection between the Experion server and the system interface is working correctly.

### Time to respond

Immediately.

---

## **COMMS - <CStnxx/Server>: Notifications from <system interface name> failed. Access denied to remote server**

### **Potential causes**

The local server has notified that notification-channel communication with the remote system interface has failed due to access restriction.

This is commonly caused by incorrect *mng*r password or incorrect RPC setup.

### **Consequence of inaction**

Notifications will not be available from the system interface.

### **Corrective actions**

1. Check that the *mng*r account password is same on both servers.
2. Check that there nothing preventing RPC from communicating between the Experion server and the system interface, such as a firewall or Windows settings.

### **Time to respond**

Immediately.



---

## COMMS - Data Srv on <server name> OVERLOADED

### Potential causes

Data from the DSA remote server may not be current due to overload. The remote server may be experiencing high system load and is having trouble sending data to the local server.

### Consequence of inaction

Station might display outdated parameter values from this connection.

### Corrective actions

1. Call up the **Console Station Status Detail** display.
2. Use Windows Performance Monitor on the remote server to make sure CPU load and free memory are within the Experion Specification limits. The Experion Specification is available from Honeywell.

### Time to respond

If the values are changing regularly or the Overload is intermittent, it may be acceptable to take corrective action as soon as suitable technicians are available, but not necessarily immediately.

---

## COMMS - Door Open

### **Potential causes**

Printing failed due to open printer door.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to Failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Check that all printer doors and enclosures are closed.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Failed - Cannot Access

### Potential causes

Access to the printer is denied.

### Consequence of inaction

Print of alarm events or report failed and will not be retried. Whilst the alarm is active, subsequent event and report print requests will be discarded.

### Corrective actions

Check that the printer name and Windows access rights are correct.

- If the printer is a network printer:
  1. Check that the printer name or URL (network address) is spelled correctly.
  2. Check that the current logon security level user group has access rights to the Windows printer and to the computer hosting the Windows printer.
- If the printer is an Experion system printer:
  1. Check that the printer **Name** property on the Experion server **Printer Summary** display exactly matches the Windows printer name configured on the Experion server computer.
  2. Check that the current logon security level user group for Station has access rights to the Windows printer defined as the Experion system printer.



#### Attention

For the printing of Experion reports or alarms and events, the Experion server uses the *mngt* account and password as defined on the Experion server to gain access to the system printer and computer hosting the system printer.

---

### Time to respond

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Failed - Could Not Print

### **Potential causes**

Printing failed.

### **Consequence of inaction**

Print of alarm events or report failed and will not be retried. Whilst the alarm is active, subsequent event and report print requests will be discarded.

### **Corrective actions**

Check that the printer is working correctly.

Use Windows print manager to print a test page to that printer.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Failed - Printer Not Found

### Potential causes

The printer was not found.

### Consequence of inaction

Print of alarm events or report failed and will not be retried. Whilst the alarm is active, subsequent event and report print requests will be discarded.

### Corrective actions

Check that the printer name and Windows access rights are correct.

- If the printer is a network printer:
  1. Check that the printer name or URL (network address) is spelled correctly.
  2. Check that the current logon security level user group has access rights to the Windows printer and to the computer hosting the Windows printer.
- If the printer is an Experion system printer:
  1. Check that the printer **Name** property on the Experion server **Printer Summary** display exactly matches the Windows printer name configured on the Experion server computer.
  2. Check that the current logon security level user group for Station has access rights to the Windows printer defined as the Experion system printer.



#### Attention

For the printing of Experion reports or alarms and events, the Experion server uses the *mngtr* account and password as defined on the Experion server to gain access to the system printer and computer hosting the system printer.

---

### Time to respond

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Link 0 (LNK00)

### Potential causes

Redundancy data link 0 failed.

1. The link has re-established. However, the alarm still exists because it has not been acknowledged.
2. The backup server is not operational or is not connected to the network.
3. There is an invalid or missing entry in the hosts file on one or both of the Experion servers.
4. There is a problem with the network connection between Servers A and B.

### Consequence of inaction

Redundancy of links has been lost if Link 1 is configured and remains operational on a dual link configured system. If both links have failed, the No Links Available alarm will be raised.

### Corrective actions

1. Acknowledge the alarm.
2. Investigate why the backup server is not operational. Start the backup server and make sure that it is connected to the network.
3. Correct the hosts file on both servers.
4. Verify communications between the Servers using 'ping' command or accessing network shares.
5. Verify on the **Server Redundancy Status** display that the link has been restored, and then re-synchronize the backup and primary servers. For more information, see “Synchronizing the server databases”.

### Time to respond

Time to respond will depend on availability of Link 1 (if configured) and an assessment of process/site/operations for criticality/risk of losing synchronization between servers.

---

## COMMS - Link 1 (LNK01)

### Potential causes

Redundancy data link 1 failed.

1. The link has re-established. However, the alarm still exists because it has not been acknowledged.
2. The backup server is not operational or is not connected to the network.
3. There is an invalid or missing entry in the hosts file on one or both of the Experion servers.
4. There is a problem with the network connection between Servers A and B.

### Consequence of inaction

Redundancy of links has been lost if Link 0 is configured and remains operational on a dual link configured system. If both links have failed, the No Links Available alarm will be raised.

### Corrective actions

1. Acknowledge the alarm.
2. Investigate why the backup server is not operational. Start the backup server and make sure that it is connected to the network.
3. Correct the hosts file on both servers.
4. Verify communications between the Servers using 'ping' command or accessing network shares.
5. Verify that link has been restored on **Server Redundancy Status** display, and then re-synchronize the backup and primary servers. For more information, see “Synchronizing the server databases”.

### Time to respond

Time to respond will depend on availability of Link 0 (if configured) and an assessment of process/site/operations for criticality/risk of losing synchronization between servers.

---

## COMMS - Low On Toner

### **Potential causes**

The printer is running low on toner.

### **Consequence of inaction**

Printing will continue but might not be of the expected quality.

### **Corrective actions**

Replace the toner in the printer.

### **Time to respond**

At the discretion of the users, based on the quality of printing.



---

## COMMS - No Links Available

No redundancy data links are available.

### Potential causes

1. The link has re-established. However, the alarm still exists because it has not been acknowledged.
2. The backup server is not operational or is not connected to the network.
3. There is an invalid or missing entry in the hosts file on one or both of the Experion servers.

### Consequence of inaction

It is not possible to synchronize the backup servers without an available link, so the backup server database shall not be updated with the changes on the primary (including point configuration, history, events, etc.) and some automatic failover actions will not be triggered. If the link has failed due to network connection failure between Servers A and B, then both Servers A and B may both run as primary.

### Corrective actions

1. Acknowledge the alarm.
2. Investigate why the backup server is not operational. Start the backup server and make sure that it is connected to the network.
3. Correct the hosts file on both servers.
4. Verify communications between the Servers using 'ping' command or accessing network shares.
5. Verify that link has been restored on **Server Redundancy Status** display, and then re-synchronize the backup and primary servers. For more information, see “Synchronizing the server databases”.

### Time to respond

Synchronization is lost immediately when this alarm occurs. Time to respond will depend on assessment of process/site/operations for criticality/risk of losing synchronization.

---

## COMMS - Offline

### **Potential causes**

The printer is offline.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Turn on the printer.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Out of Paper

**Potential causes**

The printer is out of paper.

**Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

**Corrective actions**

Place more paper in the printer's paper tray.

**Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Out Of Service

### **Potential causes**

The printer is out of service.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

To diagnose the problem, see the “The printer does not print anything” topic.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Out Of Toner

**Potential causes**

The printer is out of toner.

**Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

**Corrective actions**

Replace the toner in the printer.

**Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Output Bin Full

### **Potential causes**

The printer's output bin is full.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Empty the output bin (tray) on the printer.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Paper Jam

**Potential causes**

Printing failed due to paper jam.

**Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

**Corrective actions**

Clear the paper jam in the printer.

**Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Paper Problem

### **Potential causes**

Printing failed due to paper related problems.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Check the printer for paper problem.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.



---

## COMMS - Paused

**Potential causes**

The printing is paused.

**Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

**Corrective actions**

Un-pause the printing.

**Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Peer Version Match

### Potential causes

Occurs when the redundancy primary and backup database versions don't match, and again when they are matched (after having been mismatched).

### Consequence of inaction

Backup Server is not available or cannot be synchronized when database versions are mismatched (see corrective actions).

### Corrective actions

Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.

- If the backup server status is Failed:  
Check that server A and server B are the same version.
- If the backup server status is Good:  
Notification and logging purposes only. No operator interaction is required.

If the alarm occurs during an On Process Migration (OPM), capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

When this alarm is raised, backup may already be unavailable. The time to respond will depend on assessment of process/site/operations for criticality/risk of running without backup server available.

---

## COMMS - Primary: Unknown Status

### Potential causes

CDA or SR services on the primary server may have been stopped or failed, or the system may be experiencing network issues.

### Consequence of inaction

If the CDA or SR services have failed, you may not be getting data updates from CDA. CDA data may appear in inverse video and No Tag alarms may be generated.

### Corrective actions

Go to the Server Redundancy display and check the System Repository backup status. If the status is 'Stopped,' go to the services and start the Experion PKS System Repository service. You may also need to start the Experion PKS Control Data Access Server service.

Check the connection to CDA. If the status of data or notifications is not OK and/or you are not receiving data updates from CDA, go to the services and start the Experion PKS Control Data Access Server service. You may also need to start the Experion PKS System Repository service.

### Time to respond

Immediate.

---

## COMMS - Printer Error

### **Potential causes**

The printer has an error.

### **Consequence of inaction**

Event or report has been sent to printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Check the printer operation.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - SAM connection failed

### Potential causes

The Server is unable to connect to the Server Activity Manager (SAM) because the service has stopped. The resulting alarm is raised only on the server, and is replicated to Console Stations.

### Consequence of inaction

While the connection is in a failed state it is not possible to:

- Create activities through the Activity Creation interface
- Create activities programmatically through MES 3
- Edit the unit for Class Based Recipe activities

### Corrective actions

Restart the SAM service.

Acknowledge the alarm.

### Time to respond

Immediate.

---

## COMMS - Server: Data connection to <server name>

### Potential causes

The local server has notified that data-channel communication for the mentioned connection (<server name>) has failed.

### Consequence of inaction

Data from the mentioned connection (<server name>) will be unavailable. The connection may be a remote DSA server or a local data source such as CDA or TPS. If the data is historized on this server, history samples will not be collected.

### Corrective actions

- 1 Call up the **DSA Status** display for the remote server.
- 2 Check that the network connection between the two servers is working correctly.

If the mentioned connection (<server name>) is a local data source, such as CDA or TPS:

- 1 If the mentioned connection (<server name>) is CDA, call up the **Server redundancy status** display and check the System Repository backup status. If the status is “Synchronizing” or “Not synchronized”, wait until the System Repository backup status is “Synchronized” and then check if the CDA connection has been re-established.
- 2 Otherwise, fail over the server and check whether this restores the connection.
- 3 For additional assistance resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation. For more information, see the “Creating a diagnostic package for TAC” topic.

### Time to respond

The corrective action should be initiated immediately to restore view to data from the mentioned connection (<server name>).

---

## COMMS - Server: Data connection to <server name> failed. Access denied to remote server

### Potential causes

The local server has notified that DSA data-channel communication with the DSA remote server has failed due to access restriction.

### Consequence of inaction

Data from the mentioned connection will be unavailable.

### Corrective actions

- 1 Call up the **DSA Status** display for the remote server.
- 2 Check that the mngr account password is same on both servers.
- 3 Check that there isn't anything preventing RPC from communicating between the two servers, such as a firewall or Windows settings.

### Time to respond

The corrective action should be initiated immediately to restore view to data from the mentioned connection.

---

## **COMMS - Server: Data connection to <server name> is blocked. Remote server is busy**

### **Potential causes**

The local server has notified that the DSA data-channel with the DSA remote server is blocked due to the remote server not responding in a timely manner.

### **Consequence of inaction**

The local server (and all Flex Stations and Console Stations connected to it) will not be able to view data from the DSA remote server.

### **Corrective actions**

- 1 Call up the **Station Status Detail** display for the remote server.
- 2 Use Windows Performance Monitor on the remote server to make sure CPU load and free memory are within the Experion Specification limits. The Experion Specification is available from Honeywell.

### **Time to respond**

Immediately.



---

## COMMS - Server: Failed - Access Is Denied

**Potential causes**

The server has reported that access to the printer is denied.

**Consequence of inaction**

Printing of alarm events or report failed and will not be retried. Whilst the alarm is active, subsequent alarm events and report print requests will be discarded.

**Corrective actions**

Check that the *mngr* account is setup with the correct permission to access the printer.

**Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.

---

## COMMS - Server: Link to <server name>

### Potential causes

The local server has notified that DSA link-channel communication with the DSA remote server has failed.

### Consequence of inaction

Data and notifications from the mentioned connection will be unavailable and not accessible on Stations in this subscribing Experion cluster.

### Corrective actions

- 1 Call up the **DSA Status** display for the remote server.
- 2 Check that the network connection between the two servers is working correctly.

### Time to respond

The corrective action should be initiated immediately to restore view to data and notifications from the mentioned DSA remote server.

---

## COMMS - Server: Link to <system interface name>

The server has notified that communication with the system interface has failed.

### **Consequence of inaction**

Point parameter data and notifications will not be available from the system interface.

### **Corrective actions**

1. Call up the **System Status** display.
2. Check that the network connection between the Experion server and the system interface is working correctly.

### **Time to respond**

Immediately.

---

## COMMS - Server: Notifications from <server name>

### Potential causes

The local server has notified that DSA notification-channel communication with the DSA remote server has failed.

### Consequence of inaction

Notifications from the mentioned connection will be unavailable. The connection may be a remote DSA server or a local source such as CDA or TPS. Existing notifications will show in Station as 'bad quality', and no new or changed notifications will be received.

### Corrective actions

- 1 Call up the **DSA Status** display for the remote server.
- 2 Check that the network connection between the two servers is working correctly.

If the mentioned connection is a local source, such as CDA or TPS:

- 1 Fail over the server and check whether this restores the connection.
- 2 For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation. For more information, see the “Creating a diagnostic package for TAC” topic.

### Time to respond

The corrective action should be initiated immediately to restore view to notifications from the mentioned connection.

---

## COMMS - Server: Notifications from <server name> failed. Access denied to remote server

### Potential causes

The local server has notified that DSA notification-channel communication with the DSA remote server has failed due to access restriction.

This is commonly caused by incorrect *mng*r password or incorrect RPC setup.

### Consequence of inaction

Notifications from the mentioned connection will be unavailable.

### Corrective actions

- 1 Call up the **DSA Status** display for the remote server.
- 2 Check that the *mng*r account password is same on both servers.
- 3 Check that there isn't anything preventing RPC from communicating between the two servers, such as a firewall or Windows settings.

### Time to respond

The corrective action should be initiated immediately to restore view to notifications from the mentioned connection.

---

## COMMS - Station Failure

### Potential causes

Either a Flex Station or a Console Station has been disconnected from the server or Console Station because of:

- A Station being shut down
- A network failure
- A hardware failure

### Consequence of inaction

Loss of view on the Station.

### Corrective actions

1. Call up the **Station Status Detail** display or the **Console Station Status Detail** display.
2. Check that the Station or Console Station is running.
  - If a Station is shut down, reopen the Station.
  - In the case of a network failure, check that the network connection between the Flex Station or Console Station is operational.

### Time to respond

Immediate.

---

## COMMS - Synchronization

### Potential causes

Indicates that redundant server synchronization has been lost.

### Consequence of inaction

Server synchronization has failed, so the backup server database shall not be updated with the changes on the primary (including point configuration, history, events, etc.) and some automatic failover actions will not be triggered.

### Corrective actions

1. Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.
2. Re-synchronize the system. For more information, see “Synchronizing the server databases”.

If synchronization continues to fail, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

Synchronization is lost immediately when this alarm occurs. Time to respond will depend on assessment of process/site/operations for criticality/risk of losing synchronization.

---

## COMMS - User Intervention Required

### **Potential causes**

User intervention is required to continue printing.

### **Consequence of inaction**

An event or report has been sent to the printer but will not be printed until the problem is rectified. Subsequent requests will be queued on the printer until the alarm becomes Urgent and Active and the printer status changes to failed, at which time subsequent print requests will be discarded.

### **Corrective actions**

Attend to the printer. Check the printer control panel for an indication of the error. See the printer's documentation for instructions on how to resolve the problem.

### **Time to respond**

Immediate action is recommended if a paper record of all events and periodic reports is important.



# DIAG system alarms

The following topics describe diagnostic-related system alarms and how to respond to them.

## Related topics

- “DIAG - A/D Failure” on page 70
- “DIAG - Activity Create Failed” on page 71
- “DIAG - Address Overlap” on page 72
- “DIAG - Asymmetric Response From Probe” on page 73
- “DIAG - Backup RAM Scrub Errors” on page 74
- “DIAG - Backup RAM Sweep Errors” on page 75
- “DIAG - Backup State” on page 76
- “DIAG - Bad Configuration” on page 77
- “DIAG - Battery Not OK” on page 78
- “DIAG - Battery Over Voltage” on page 79
- “DIAG - Battery Under Voltage” on page 80
- “DIAG - BOOTP Enabled” on page 81
- “DIAG - Calibration Cleared” on page 82
- “DIAG - Calibration Error” on page 83
- “DIAG - CEE Cycle Overruns” on page 84
- “DIAG - CEE Hold Breath” on page 85
- “DIAG - Channel Hardware Fault” on page 86
- “DIAG - Characterization Error” on page 87
- “DIAG - Checkpoint Save Status” on page 88
- “DIAG - CJ Failure” on page 89
- “DIAG - Cold Junction Fault” on page 90
- “DIAG - Communication Ceased” on page 91
- “DIAG - Communication Error” on page 92
- “DIAG - Communication Fault” on page 93
- “DIAG - Communication With This Point Is Lost. Load Server Point Immediately” on page 94
- “DIAG - Configuration Error” on page 95
- “DIAG - Connection Error” on page 96
- “DIAG - Connection Failed” on page 97
- “DIAG - Connection Timeout” on page 98
- “DIAG - CPU Free Low Alarm” on page 99
- “DIAG - CPU Low Low Resources” on page 100
- “DIAG - DAC Voltage Deviation” on page 101
- “DIAG - Daughter Board Fail” on page 102
- “DIAG - Debug Flag Enabled” on page 103
- “DIAG - Debugger Is Running” on page 104

“DIAG - Device Fail” on page 105  
 “DIAG - Device/Firmware Mismatch” on page 106  
 “DIAG - Device Idle” on page 107  
 “DIAG - Device Index Setting Does Not Match Displayed Value” on page 108  
 “DIAG - Device Index Switches Changed” on page 109  
 “DIAG - Device Index Value Is Zero Upon Power Up” on page 110  
 “DIAG - Device Mismatch” on page 111  
 “DIAG - Device Not Configured” on page 112  
 “DIAG - Device Offline” on page 113  
 “DIAG - Device Registration Error” on page 114  
 “DIAG - DeviceNet IM Comm Error” on page 115  
 “DIAG - DeviceNet\_IM Disabled” on page 116  
 “DIAG - DeviceNet IM Duplicate Address” on page 117  
 “DIAG - DeviceNet IM Faulted” on page 118  
 “DIAG - DeviceNet IM Idle” on page 119  
 “DIAG - DeviceNet IM Not Active” on page 120  
 “DIAG - DeviceNet IM Not Specified” on page 121  
 “DIAG - DeviceNet IM Power Fail” on page 122  
 “DIAG - DI Input Fail Alert” on page 123  
 “DIAG - Different Amount of Devices” on page 124  
 “DIAG - Drive Alarm” on page 125  
 “DIAG - Drive Fault” on page 126  
 “DIAG - Duplicate Node Address On Link” on page 127  
 “DIAG - Electrode Open Circuit or LPR Mode Error” on page 128  
 “DIAG - Electrode Short Circuit” on page 129  
 “DIAG - Electronics Failure” on page 130  
 “DIAG - Excess Calibrated Range” on page 131  
 “DIAG - Excess Calibration Correction” on page 132  
 “DIAG - Excess Span Calibration” on page 133  
 “DIAG - Excess Zero Calibration” on page 134  
 “DIAG - Excessive H1 Link Communication Errors” on page 135  
 “DIAG - Factory Data Error” on page 136  
 “DIAG - Fatal FF Communication Error” on page 137  
 “DIAG - Fieldbus devices not communicating or intermittent” on page 138  
 “DIAG - FIM Cable Failure, FIM or RTP Slot” on page 139  
 “DIAG - FIM Is Not Primary Link Master” on page 140  
 “DIAG - FIM Not Responding” on page 141  
 “DIAG - FIM Lost Sync” on page 142  
 “DIAG - FIM Schedule Error, Not Executing Slot” on page 143  
 “DIAG - FIM SLOT: XX { Tag Identifier } ( Err XX ) ” on page 144  
 “DIAG - Firm Ware Error1” on page 145  
 “DIAG - Firm Ware Error2” on page 146  
 “DIAG - FTA A Communication Error” on page 147  
 “DIAG - FTA B Communication Error” on page 148  
 “DIAG - FTE Port A Receive Fault” on page 149  
 “DIAG - FTE Port B Receive Fault” on page 150  
 “DIAG - Function Block Error” on page 151  
 “DIAG - GPS Failed” on page 152

“DIAG - H1 Link Communication Error Detected” on page 153  
“DIAG - H1 Link Power Failure” on page 154  
“DIAG - Hardware Temperature Exceeded The Threshold” on page 155  
“DIAG - Harmonic Distortion Mode Not Possible” on page 156  
“DIAG - Heap Memory Not Available” on page 157  
“DIAG - HW Rev Below Acceptable Minimum — Upgrade Required” on page 158  
“DIAG - ICP QSend Error” on page 159  
“DIAG - ICP Unrecognized CMD” on page 160  
“DIAG - Illegal CLeAr DEVADDR Attempt On Link” on page 161  
“DIAG - Illegal Clear PD\_TAG Attempt On Link” on page 162  
“DIAG - Illegal Set DEVADDR Attempt On Link” on page 163  
“DIAG - Illegal Set PD\_TAG Attempt On Link” on page 164  
“DIAG - Illegal Unknown SM Event On Link” on page 165  
“DIAG - Input 1 Calibration Failure” on page 166  
“DIAG - Input 2 Calibration Failure” on page 167  
“DIAG - Input 3 Calibration Failure” on page 168  
“DIAG - Input 1 Failure” on page 169  
“DIAG - Input 2 Failure” on page 170  
“DIAG - Input 3 Failure” on page 171  
“DIAG - Input 1 T/C Warning” on page 172  
“DIAG - Input 2 T/C Warning” on page 173  
“DIAG - Input 3 T/C Warning” on page 174  
“DIAG - Input Failure” on page 175  
“DIAG - Intermittent Comm Failure” on page 176  
“DIAG - Invalid Keeper” on page 177  
“DIAG - IOLink(1) Soft Fail Error” on page 178  
“DIAG - IOLink(2) Soft Fail Error” on page 179  
“DIAG - JagXtreme Communication Error” on page 180  
“DIAG - JX Instrument Alarm” on page 181  
“DIAG - JX Instrument Fault” on page 182  
“DIAG - KTC Failure” on page 183  
“DIAG - Loss Of Batch Event” on page 184  
“DIAG - Loss Of Batch Event Data” on page 185  
“DIAG - Lost Sync” on page 186  
“DIAG - Low Battery” on page 187  
“DIAG - Low External Power” on page 188  
“DIAG - Low Power” on page 189  
“DIAG - Local Hardware Fault” on page 190  
“DIAG - Low Redundancy” on page 191  
“DIAG - Max Number Of Devices Exceeded” on page 192  
“DIAG - MDM Service Is Running” on page 193  
“DIAG - Memory Limit Exceeded” on page 194  
“DIAG - Missing Keeper” on page 195  
“DIAG - Module Hardware Fault” on page 196  
“DIAG - No Field Power Detected” on page 197  
“DIAG - No Load Detected” on page 198  
“DIAG - No PBIM Reference” on page 199  
“DIAG - No Sensor Board Alert” on page 200

“DIAG - Non-Volatile Memory Error”	on page 201
“DIAG - Not Using Configured Time Source”	on page 202
“DIAG - Over Range Fault”	on page 203
“DIAG - Over Temperature Alert”	on page 204
“DIAG - PCIC Lonely On CNet”	on page 205
“DIAG - Partner Not Visible on FTE”	on page 206
“DIAG - PBIM Communication Error”	on page 207
“DIAG - PBIM Inactive”	on page 208
“DIAG - PBIM Registration Error”	on page 209
“DIAG - PCIC Failure”	on page 210
“DIAG - Pressure Overload Alert”	on page 211
“DIAG - PROFIBUS Communication Error”	on page 212
“DIAG - PROFIBUS Not In Run”	on page 213
“DIAG - PROFIBUS Offline”	on page 214
“DIAG - Program Memory Fault”	on page 215
“DIAG - PTP Time Source Failed”	on page 216
“DIAG - QiMPACT Communication Error”	on page 217
“DIAG - QiMPACT Instrument Alarm”	on page 218
“DIAG - QiMPACT Instrument Fault”	on page 219
“DIAG - Radio Interprocessor Comm Error”	on page 220
“DIAG - Radio Status EEPROM SP1 Communication Failure”	on page 221
“DIAG - Radio Status Radio Communication Circuitry Failure”	on page 222
“DIAG - Radio Status Sensor Radio SP1 Communication Failure”	on page 223
“DIAG - Radio Status WDT Reset Occurred”	on page 224
“DIAG - RAM Error”	on page 225
“DIAG - RAM Fault”	on page 226
“DIAG - Reconfiguration Fail”	on page 227
“DIAG - Redun Standby”	on page 228
“DIAG - Redun Count Exceeded”	on page 229
“DIAG - Remote Hardware Fault”	on page 230
“DIAG - ROM Application Image Checksum Failure”	on page 231
“DIAG - ROM Boot Image Checksum Failure”	on page 232
“DIAG - ROM Error”	on page 233
“DIAG - RSLinx Failure”	on page 234
“DIAG - RSLinx Initialization Failure”	on page 235
“DIAG - RTP Disconnect”	on page 236
“DIAG - Runtime Diagnostic Failure”	on page 237
“DIAG - Runtime Diagnostic OVERRUN”	on page 238
“DIAG - Runtime Fail on Daughter Board”	on page 239
“DIAG - Secondary Address Overlap”	on page 240
“DIAG - Sensor Alert”	on page 241
“DIAG - Short Circuit Detected”	on page 242
“DIAG - SIOM Offline”	on page 243
“DIAG - SIOM Offline, Communications Ceased”	on page 244
“DIAG - SIOM Offline, Secondary Communications Ceased”	on page 245
“DIAG - SM Dupe Node Address”	on page 246
“DIAG - SM Node Address Clear”	on page 247
“DIAG - SM Node Address Set”	on page 248

“DIAG - SM Physical Device Tag Clear” on page 249  
“DIAG - SM Physical Device Tag Set” on page 250  
“DIAG - SM Unknown” on page 251  
“DIAG - SNTP Failed” on page 252  
“DIAG - Stack Limit Exceeded” on page 253  
“DIAG - Stale Output Alert” on page 254  
“DIAG - Sync Checksum Fail” on page 255  
“DIAG - Sync HW Failure” on page 256  
“DIAG - Task Health Monitoring Warning” on page 257  
“DIAG - Time Jump Greater Than Five Minutes” on page 258  
“DIAG - UMAX Exceeded” on page 259  
“DIAG - Uncommanded Shutdown” on page 260  
“DIAG - Uncomm Dev Oper Class Changed To Basic” on page 261  
“DIAG - Under Range Fault” on page 262  
“DIAG - Unexpected Partner on Redundancy Link” on page 263  
“DIAG - Verify Lost” on page 264  
“DIAG - Watchdog Timer Error” on page 265  
“DIAG - WDT Refresh Warning” on page 266  
“DIAG - Wire off Detected” on page 267

---

## DIAG - A/D Failure

### **Potential causes**

Diagnostics detected defect with Analog to Digital Converter.

### **Consequence of inaction**

Device is offline.

### **Corrective actions**

Replace sensor module.

### **Time to respond**

---

## DIAG - Activity Create Failed

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

If the creation of a new batch activity module is requested when the number of current activity modules running is equal to the number of activity modules set by a user, this alarm is raised.

### **Consequence of inaction**

The activity cannot be created.

### **Corrective actions**

Increase the NUMACT value. NUMACT cannot be 0 or greater than 500.

---

## DIAG - Address Overlap

Applies to SLINK.

### **Potential causes**

An overlap is detected when the starting address of the SIOM plus the slot configuration overlaps with the starting address of the next SIOM. The two SIOMs can be on one or different links. In this situation, only one of the SIOMs comes online and the other SIOM reports an overlap condition on its link and this is reported from primary LIOM.

### **Consequence of inaction**

One of the overlapped SIOM works, while the other SIOMs will not work.

### **Corrective actions**

Assign unique addresses for SIOMs.

### **Time to respond**

Immediate.



---

## DIAG - Asymmetric Response From Probe

**Potential causes**

Electrochemical response of the probe is not symmetrical.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Check electrodes for differential attack on electrodes, for example, crevice on one electrode.

**Time to respond**

---

## DIAG - Backup RAM Scrub Errors

Applies to C300.

### **Potential causes**

The number of bit errors detected and corrected in testing of RAM in which the C300 controller maintains control strategies is greater than the number determined acceptable. This alarm is referred as corrected RAM sweep error.

### **Consequence of inaction**

A possibility for a backup RAM Sweep Error.

### **Corrective actions**

Consider replacing the C300 controller. Call the Honeywell Technical Assistance Center (TAC) for support.

### **Time to respond**

If the alarm occurs frequently, module replacement should be considered at earliest convenience.

---

## DIAG - Backup RAM Sweep Errors

Applies to C300.

### **Potential causes**

The bit errors detected during testing of the RAM in which the C300 controller maintains control strategies are unable to be corrected. This alarm is referred to as uncorrected RAM sweep errors.

### **Consequence of inaction**

Might cause unexpected behaviors in the process controller.

### **Corrective actions**

The C300 controller needs to be replaced immediately. Call the Honeywell Technical Assistance Center (TAC) for support.

### **Time to respond**

Immediately.

---

## DIAG - Backup State

Applies to C200E, C300, CPMC200, and LIOM.

### **Potential causes**

The secondary generates the Backup State Change Event as part of event regeneration. More specifically, a transition to the Backup State only occurs as part of startup or redundancy role change. For both of these cases, any previously existing notification connection is broken, a new notification connection is reformed, and event regeneration is commanded.

### **Consequence of inaction**

None – expected.

### **Corrective actions**

Normal for backup module/chassis.

### **Time to respond**

N/A.

---

## DIAG - Bad Configuration

**Potential causes**

Active Diagnostic channel requesting data, when no diagnostic buffer has been configured at the device function block.

**Consequence of inaction**

Loss of diagnostic data.

**Corrective actions**

Reconfigure the diagnostic buffer at the device function block.

**Time to respond**

Immediate.

---

## DIAG - Battery Not OK

Applies to C200E and CPMC200.

### **Potential causes**

Defective battery or invalid battery configuration.

### **Consequence of inaction**

A power failure will result in the loss of configuration.

### **Corrective actions**

Replace the defective battery or correct the invalid battery configuration.

The Battery Extension Module or Lithium battery may be used, but not both. Both batteries have a replacement schedule.

### **Time to respond**

Next maintenance shift.

---

## DIAG - Battery Over Voltage

Applies to C300.

### **Potential causes**

If battery voltage is above 4.8V this alarm is raised. This condition indicates that the battery has been removed or has become open circuit.

### **Consequence of inaction**

This may damage the RAM in the controller and cause the controller to fail. All controllers connected to this battery supply will be affected by this condition.

### **Corrective actions**

Check that the battery is connected and that all wiring is intact. The battery may need to be replaced. Contact your Honeywell Technical Assistance Center for further support.

### **Time to respond**

Next maintenance shift.

---

## DIAG - Battery Under Voltage

Applies to C300.

### **Potential causes**

This alarm is raised if the battery voltage is below 3V. This condition indicates a discharged or defective battery. If discharged due to a system power outage, it should clear in 8-10 hours.

### **Consequence of inaction**

A discharged battery may result in memory loss within the controller. It may require a checkpoint restore and cold start of the controller. All controllers connected to this battery supply will be affected by this condition.

### **Corrective actions**

If this occurs while the system is running, the battery will need to be replaced. Contact your Honeywell Technical Assistance Center for further support.

### **Time to respond**

Before next power failure.



---

## DIAG - BOOTP Enabled

**Potential causes**

The BOOTP setting of the specified ENET module has not been disabled after updating the ENET module's IP address.

**Consequence of inaction**

Loss of Communication.

**Corrective actions**

Utilize the Network Tools application to disable the BOOTP setting of the specified ENET module.

**Time to respond**

Immediate.

---

## DIAG - Calibration Cleared

### Potential causes

User calibration cleared to factory constants. Indicates that both the upper and lower trim points as well as the zero offset has been cleared. The calibration source is none.

### Consequence of inaction

Incorrect PV.

### Corrective actions

User calibration has been cleared and reset to the factory values. Proceed with user calibration if utilizing probe cables longer than 12 ft and if the anticipated corrosion rate is greater than 200 mpy.

- Select Factory Calibration; or
- Calibrate the zero offset; or
- Calibrate using the lower and upper trim points.

### Time to respond

---

## DIAG - Calibration Error

**Potential causes**

Calibration data invalid or could not be read.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

- Reattempt user calibration.
- Use Cal Clear, Restore, or User Calibrate.

**Time to respond**

---

## DIAG - CEE Cycle Overruns

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

This alarm occurs if the CPU consumption by the loaded strategies exceeds 100%.

### **Consequence of inaction**

A watchdog timer failure might occur and controller scheduling latency will be higher, resulting in loss of real time nature.

### **Corrective actions**

Reduce the load on the CPU by reducing strategies, and fine tuning phase and order in CEE and CMs.

### **Time to respond**

As early as possible.

---

## DIAG - CEE Hold Breath

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### Potential causes

The term "Hold Breath" refers to stopping normal execution of scheduled function blocks in an ACE CEE because peer pre-fetch data is not available for execution of an ACE Control Module configured for pre-fetch. An ACE Control Module configured for pre-fetch triggers collection of peer data in anticipation that peer data will be available during execution of the ACE Control Module.

The CEE stops execution (hold's breath) of all (with and without pre-fetch) control strategies, when pre-fetch data is not available prior to scheduled execution for an ACE Control Module. Communication delays long enough to cause the CEE to Hold Breath is rare and usually associated only with either a swap or switch over of a server node.

### Consequence of inaction

When a hold breath occurs, the CEE holds execution of all its blocks regardless of whether its PEERREADOPT parameter setting is PREFETCH or PUBSUB. This means all Control Modules along with all SCM, RCM, and UCM in the control strategy will stop executing for the duration of the Hold Breath timeout time.

The CEE does not attempt to recover the scheduling time lost due to the occurrence of Hold Breath.

### Corrective actions

- Occurrence of Hold Breath when an HPM point is deleted.

When the ACE is subscribed to an HPM point that is deleted, the ACE may report Hold Breath events as long as it attempts to access the deleted point. The Hold Breath occurrence increases significantly until the HPM point is re-loaded. In such a scenario, you must remove all ACE references to the deleted point.

- Occurrence of Hold Breath during NIM/HG/AM node failover.

It is possible that the pre-fetch requests from ACE targeted to LCN data owners may get lost when LCN data owners like NIM/HG/AM failover. During this time, the responses for the pre-fetch requests are not received at the ACE. As a result, Hold Breath can occur on the ACE node. In such a scenario, Hold Breath events occur until the data arrives or until the Hold Breath timeout occurs; whichever is earlier.

### Time to respond

---

## DIAG - Channel Hardware Fault

### **Potential causes**

Hardware failure.

### **Consequence of inaction**

Process disruption.

### **Corrective actions**

1. Check the channel status on the card.
2. Replace the I/O card.

### **Time to respond**

Immediate.

---

## DIAG - Characterization Error

**Potential causes**

Either the sensor cannot access the meter body characterization, or the characterization is invalid.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Check the connection between the sensor module and the meter body. If this doesn't fix the problem, replace the sensor.

**Time to respond**

---

## DIAG - Checkpoint Save Status

### Potential causes

An error has occurred when saving a Checkpoint. Additional information about the specific error can include:

- Failed/abnormal completion; state of the last checkpoint save for that node. This is indicated by one of the following values in the Checkpoint Status (CPSTATUS):
  - Complete With Stale Data
  - Complete With Dangling Data
  - Complete With Mismatched Data
  - Failed – Other, see server err logs
- RTN - Successful completion; state of the last checkpoint save for that node. This will be indicated by the value “Complete” in CPSTATUS.

### Consequence of inaction

Inability to migrate.

### Corrective actions

See the following topics in the “Appendix F - Control Builder Checkpoint Reference” section of the *Control Building User's Guide*.

- “Checkpoint file attributes”
- “Checkpoint Alarming”
- “Fixing Common Problems”

### Time to respond

Next Checkpoint save.



---

## DIAG - CJ Failure

**Potential causes**

The Cold Junction has failed.

**Consequence of inaction**

Input failure.

**Corrective actions**

Check the connectors on the terminal board and the sensor module. If necessary, replace the terminal board.

**Time to respond**

---

## DIAG - Cold Junction Fault

### Potential causes

Broken lead or a shorted lead to the CJ compensation thermistor.

### Consequence of inaction

1. All channels are marked as bad.
2. If a broken lead is detected, 70 C is substituted for the CJC temperature in all calculations.
3. If a short-circuit is detected, 0 C is substituted for the CJC temperature in all calculations.

### Corrective actions

Check leads and correct/replace them.

### Time to respond

Immediate.

---

## DIAG - Communication Ceased

Applies to SLINK.

### Potential causes

When an SIOM goes offline on a serial link, communication on the corresponding serial link, or both serial links, cease operation depending on the serial link fault configuration.

### Consequence of inaction

### Corrective actions

Enter the command **restart Slinks** at the LIOM FB configuration form.

### Time to respond

As soon as possible.

---

## DIAG - Communication Error

### Potential causes

1. Power is disrupted to the I/O chassis.
2. The interface module (for example, CNI, Profibus Interface Module, or DeviceNet Interface Module) has been removed.
3. The controller to interface communication path is broken.
4. The I/O Module has faulted or been removed from the chassis.

### Consequence of inaction

Controller to IOM communication connection is broken and results in data loss.

### Corrective actions

1. Check the I/O Module to make sure it is not faulted or unpowered.
2. Check the I/O Rack PS and restore power supply if unpowered.
3. Check any interface module in the communication path to make sure that it is not faulted or unpowered.
4. Check the communication path.

### Time to respond

Immediate.

---

## DIAG - Communication Fault

**Potential causes**

- The associated IOM Function Block loses communication with the Communications Adapter
- The associated Communications Adapter losses communication with or detects a major fault on the drive device.

**Consequence of inaction**

Connections to the drive are lost. The drive goes into the Faulted state, drive behavior is based on the Communications Adapter configuration.

**Corrective actions**

Restore the cable connection or Communications Adapter.

**Time to respond**

Immediate.

---

## **DIAG - Communication With This Point Is Lost. Load Server Point Immediately**

### **Potential causes**

The top-level block has not been loaded.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

Check for devices with EEs that are missing a top level block. Load server point (top level block).

### **Time to respond**

Immediate.

---

## DIAG - Configuration Error

**Potential causes**

Invalid, inconsistent, corrupted, or lost static data.

**Consequence of inaction**

User cannot modify static data.

**Corrective actions**

None.

**Time to respond**

---

## DIAG - Connection Error

### **Potential causes**

The DTL connection has failed.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

If the disconnection is unexpected and unexplained, examine the alarm summary, network communication nodes, network connectors and network cabling for the source of the network fault.

### **Time to respond**

Immediate.



---

## DIAG - Connection Failed

**Potential causes**

The DTL connection has failed.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

If the disconnection is unexpected and unexplained, examine the alarm summary, network communication nodes, network connectors and network cabling for the source of the network fault.

**Time to respond**

Immediate.

---

## DIAG - Connection Timeout

### **Potential causes**

The DTL connection has failed.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

If the disconnection is unexpected and unexplained, examine the alarm summary, network communication nodes, network connectors and network cabling for the source of the network fault.

### **Time to respond**

Immediate.

---

## DIAG - CPU Free Low Alarm

Applies to C300.

### **Potential causes**

When the available CPU resource falls below the limit set in the C300 Controller FB parameter CPULOLM, this alarm is generated at Low priority.

### **Consequence of inaction**

May cause frequent overruns.

### **Corrective actions**

Reduce values for items such number of blocks, adjusting period, phase, and order of execution.

### **Time to respond**

As early as possible.

---

## DIAG - CPU Low Low Resources

Applies to C300.

### **Potential causes**

When the available CPU resource falls below 5% this diagnostic alarm is generated at High priority.

### **Consequence of inaction**

Multiple phase overruns may occur and the controller response time might be impacted. There is also the possibility of a watchdog timer crash.

### **Corrective actions**

Reduce values for items such number of blocks, adjusting period, phase, and order of execution.

### **Time to respond**

As early as possible.

---

## DIAG - DAC Voltage Deviation

**Potential causes**

The electrode driver voltage deviation is greater than 3% of measured voltage.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

- Check electrodes for conductive films.
- Check transmitter probe cable connections for a possible short at the transmitter input terminals.
- Check transmitter operation offline with a different probe to determine if the fault is caused by the probe or the transmitter.

**Time to respond**

---

## DIAG - Daughter Board Fail

### Potential causes

The FIM daughter board has failed.

### Consequence of inaction

Loss of synchronization. Potential loss of process data/loss of control.

### Corrective actions

1. Use the NDM generated Point ID (for example, Driver Name : RM0203) and the given slot number in the description to identify the FIM with the daughter board failure.
2. Restart the module.
3. If the problem persists, replace the FIM hardware.

### Time to respond

Immediate.

---

## DIAG - Debug Flag Enabled

Applies to FIM4, FIM8, C300, and PGM .

### **Potential causes**

From the EPIC Program Analyzer tool – the Debug Flag is set.

### **Consequence of inaction**

If the user performs unprivileged debug operations from the CTOOL/EPA tool, the on-process system might be disturbed.

### **Corrective actions**

When the Epic Program Analyzer tool is connected to an on-process controller, deselect the Debug Flag in the EPA tool.

### **Time to respond**

As soon as possible.

---

## DIAG - Debugger Is Running

Applies to CEEACEFB, CEEC200EFB, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

A check for Visual Studio remote debuggers is done during the transition from IDLE->RUN. This alarm is raised if debuggers are found running, and the transition is disallowed.

### **Consequence of inaction**

The CEE cannot transition from IDLE to RUN while a debugger is running.

### **Corrective actions**

Turn off the debugger (VC++).

### **Time to respond**

When possible.



---

## DIAG - Device Fail

**Potential causes**

The device has failed or is not operating correctly.

**Consequence of inaction**

DNet Interface Module will no longer be able to communicate with the failed device. Affects many device blocks.

**Corrective actions**

Replace the device.

**Time to respond**

Immediate.

---

## DIAG - Device/Firmware Mismatch

### **Potential causes**

Sensor board firmware error. The software did not pass verification tests. The sensor firmware does not match the device type.

### **Consequence of inaction**

Device offline.

### **Corrective actions**

Replace sensor module.

### **Time to respond**

---

## DIAG - Device Idle

**Potential causes**

The EXECSTATE of the device is INACTIVE.

**Consequence of inaction**

Causes a break in the communication between device blocks and the DeviceNet network.

**Corrective actions**

Set the block execution status of the DNET\_IM block to ACTIVE.

**Time to respond**

Immediate.

---

## DIAG - Device Index Setting Does Not Match Displayed Value

Applies to FIM4, FIM8, C300, and PGM .

### Potential causes

1. Someone changed the setting on the binary-coded decimal rotary switches on the IOTA.
2. The Primary or non-redundant Series C FIM is defective.
3. The redundant or non-redundant IOTA is defective.
4. There is a software problem.

### Consequence of inaction

With the next reboot, the system will take up a different IP address.

### Corrective actions

1. Change binary-coded decimal rotary switches to correct setting.
2. Replace the Primary or non-redundant Series C FIM. If the Device Index switch setting matches the Device Index number in the 4-character display upon Series C FIM power up, the removed Series C FIM is defective.
3. Replace the IOTA. If the Device Index switch setting matches the Device Index number in the 4-character display upon Series C FIM power up, the removed IOTA is defective.
4. Contact Honeywell Solution Support Center (SSC) for assistance.

### Time to respond

Immediate.

---

## DIAG - Device Index Switches Changed

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

Device address is set using jumpers before booting the controller. If this is modified during run time, this alarm is raised.

### **Consequence of inaction**

With the next reboot, the system will take up a different IP address.

### **Corrective actions**

Verify if the Device Index switch setting is correct, reset if necessary. If failure persists, the IOTA may be defective. Replace the IOTA.

### **Time to respond**

Immediate.

---

## DIAG - Device Index Value Is Zero Upon Power Up

Applies to FIM4, FIM8, C300, and PGM.

### Potential causes

1. Binary-coded decimal rotary switches are set to zero on IOTA.
2. The Primary or non-redundant Series FIM4 (or FIM8) is defective.
3. The redundant or non-redundant IOTA is defective.

### Consequence of inaction

With the next reboot, the system will not acquire the appropriate IP address and it will not boot up.

### Corrective actions

1. Change the binary-coded decimal rotary switches to the correct setting.
2. Replace the Primary or non-redundant Series C FIM. If the Device Index switch setting matches the Device Index number in the 4-character display upon Series C FIM power up, the removed Series C FIM is defective.
3. Replace the IOTA. If the Device Index switch setting matches the Device Index number in the 4-character display upon Series C FIM power up, the removed IOTA is defective.

### Time to respond

As soon as possible.

---

## DIAG - Device Mismatch

**Potential causes**

The configuration of the device in RSNetWorx is not the same as the data received by the DNet Interface.

**Consequence of inaction**

Device data split between assemblies may not match.

**Corrective actions**

1. Disable DNet interface.
2. Recheck the device configuration in the RSNetWorx and reload.

**Time to respond**

Immediate.

---

## DIAG - Device Not Configured

### **Potential causes**

PROFIBUS network is not configured with a device with the specified Station/module numbers.

### **Consequence of inaction**

Fails to identify the PBIM block that will serve its I/O data.

### **Corrective actions**

Configure the PROFIBUS device to identify the associated PBIM blocks that serve the I/O data.

### **Time to respond**

Immediately.



---

## DIAG - Device Offline

**Potential causes**

The slave device is absent or returning errors on the PROFIBUS network.

**Consequence of inaction**

The slave remains offline with the active master. The master actively updates the slave, producing a faulty message, increasing the retries count each time.

**Corrective actions**

1. Check the device and reconfigure the slave device.
2. Replace the device if required.

**Time to respond**

Immediate.

---

## DIAG - Device Registration Error

### **Potential causes**

The device block could not be registered with the appropriate DNET\_IM block.

### **Consequence of inaction**

Device load error due to failed communication between the device block and one or more than one DeviceNet IM.

### **Corrective actions**

Ensure a matching configuration between DNET\_IM table and IOM block, including device address and data offsets that correspond to the data expected by the block.

### **Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Comm Error

**Potential causes**

1. Power is disrupted to the remote chassis in which the DNB-1756 resides.
2. The DNB-1756 is removed under power.
3. The controller to DNet Interface ControlNet communication path (assuming remote I/O) is broken.

**Consequence of inaction**

Controller and the DNet Interface are no longer able to transfer data between each other resulting in incomplete/ outdated information on the Status tab.

**Corrective actions**

1. Check the I/O Module to make sure it is not faulted or unpowered.
2. Check the chassis power supply, in which the Dnet Interface module resides and restore power supply if unpowered.

**Time to respond**

Immediate.

---

## DIAG - DeviceNet\_IM Disabled

### **Potential causes**

The DNET\_IM block is DISABLED.

### **Consequence of inaction**

When in Disable mode the DNB will not make an attempt to communicate on the network. The message “Network Disabled” is displayed on the front of the DNB.

### **Corrective actions**

Rectify the system error detected by the application logic and enable the communication of the device net block on the DeviceNet network by restoring the status to RUN.

### **Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Duplicate Address

**Potential causes**

The DNet interface is attempting to go online on a DeviceNet network with the same node number as an existing device on the network.

**Consequence of inaction**

DNet device fails to operate.

**Corrective actions**

Check the DNet interface module address and ensure it matches the actual device net address. Ensure that no duplicate device addresses exist.

**Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Faulted

### **Potential causes**

The DNET\_IM is in FAULTY state.

### **Consequence of inaction**

When in Fault mode the DNB will not make an attempt to communicate on the network. The message “Network Faulted” will be displayed on the front of the DNB.

### **Corrective actions**

Rectify the system error detected by the application logic and then enable the communication by restoring the device status to RUN.

### **Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Idle

**Potential causes**

The DNET\_IM is in IDLE state.

**Consequence of inaction**

When in IDLE mode, the DNB block will not receive inputs from devices on the network, and will not send active output data to the devices.

**Corrective actions**

Rectify the system error detected by the application logic and restore the device status to RUN.

**Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Not Active

### Potential causes

DNET\_IM block is INACTIVE.

### Consequence of inaction

I/O data is not transferred between the DNET\_IM block and the DNet Interface module, i.e. it causes a break in the communication between device blocks and the DeviceNet network. Fail-safe data is returned to client input blocks.

### Corrective actions

Set the block execution status of the DNET\_IM block to Active. Any load, reload or snapshot restore initializes the block status to INACTIVE.

### Time to respond

Immediate.



---

## DIAG - DeviceNet IM Not Specified

**Potential causes**

Invalid or missing DNET\_IM reference.

**Consequence of inaction**

DNET\_IM serves the device's I/O data. Invalid reference indicates loss of I/O data and fails to detect the device location.

**Corrective actions**

Reconfigure the DNET\_IM (device net interface module) block reference and reload.

**Time to respond**

Immediate.

---

## DIAG - DeviceNet IM Power Fail

### **Potential causes**

The DNet Interface cannot detect any power on the DeviceNet most likely due to removing power from the DeviceNet Network.

### **Consequence of inaction**

DNet Device fails resulting in communication problems.

### **Corrective actions**

1. Check the power cord or the cable connection to the chassis containing the DNet Interface.
2. Alternatively check if the network connection was not terminated properly.

### **Time to respond**

Immediate.

---

## DIAG - DI Input Fail Alert

**Potential causes**

Cold junction failure.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Check the connectors on the terminal board and the sensor module. If necessary, replace the terminal board.

**Time to respond**

---

## DIAG - Different Amount of Devices

### Potential causes

Primary and secondary FIMs detect a different number of devices on the link. Possible RTP or cable failure.

### Consequence of inaction

Loss of synchronization. Potential loss of process data and/or loss of control.

### Corrective actions

1. Verify Primary FIM detects all devices on the network.
2. Check RTP and cabling.
3. Check segment signal quality.

### Time to respond

Immediate.

---

## DIAG - Drive Alarm

**Potential causes**

A alarm condition (usually a warning) occurs on the associated device .

**Consequence of inaction**

An alarm is a condition that, if left untreated, may stop the drive. Drive alarms are usually warnings. The FAULTED parameter indicates major drive faults.

**Corrective actions**

The action to be taken depends on the cause of the alarm (e.g. Analog in Loss, Bipolar conflict, Brake Slipped, power loss). For more information see the Allen-Bradley drive documentation.

**Time to respond**

Immediate.

---

## DIAG - Drive Fault

### **Potential causes**

A fault condition occurs on the associated device.

### **Consequence of inaction**

Stops the drive operating.

### **Corrective actions**

The action to be taken depends on the cause of the fault (e.g., Analog in Loss, Anlg Cal Chksum, Auto tune aborted). For more information see the Allen-Bradley drive documentation.

### **Time to respond**

Immediate.

---

## DIAG - Duplicate Node Address On Link

Applies to H1 Link.

### **Potential causes**

A second node is on the H1 Link at the same address as the FIM. Typically two FIMs are connected to the same H1 network.

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.

### **Time to respond**

Immediate.

---

## DIAG - Electrode Open Circuit or LPR Mode Error

### Potential causes

Input open or probe not in solution.

### Consequence of inaction

Incorrect PV.

### Corrective actions

Check the probe cable for a loose or defective (open) connection to the electrodes or transmitter terminals.

### Time to respond



---

## DIAG - Electrode Short Circuit

**Potential causes**

An input has shorted.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Check the probe electrodes for conductive films or a defective (shorted) cable. Check the transmitter probe cable connections for a possible short at the transmitter input terminals.

**Time to respond**

---

## DIAG - Electronics Failure

### Potential causes

An electronics failure is detected on the sensor board, as determined by any of the following diagnostic status indicators:

- NVM Fault
- RAM Fault
- Program Memory Fault
- A/D Failure

### Consequence of inaction

Device offline.

### Corrective actions

Restart both the radio and the sensor. If the condition persists, replace the sensor module.

### Time to respond

---

## DIAG - Excess Calibrated Range

**Potential causes**

The selected calibration points used for upper and lower trim are outside the characterized range of the transmitter.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Check that the upper and lower trim points are both within the characterized range of the transmitter and re-attempt upper and lower trim calibration.

**Time to respond**

---

## DIAG - Excess Calibration Correction

### **Potential causes**

User calibration trim point exceeds operational range of probe.

### **Consequence of inaction**

Incorrect PV.

### **Corrective actions**

Re-calibrate using trim points within the operational range of the probe.

### **Time to respond**

---

## DIAG - Excess Span Calibration

**Potential causes**

The calibrated upper and lower trim has produced a span that is greater than 5% of the characterized span of the transmitter.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

- Clear calibration; or
- Set factory calibration; or
- Check the applied trim points and re-attempt lower and upper (trim) calibration.

**Time to respond**

---

## DIAG - Excess Zero Calibration

### **Potential causes**

The selected zero offset or the lower calibration trim point is beyond 5% of the lower end of the characterized range of the device.

### **Consequence of inaction**

Incorrect PV.

### **Corrective actions**

Clear calibration.

### **Time to respond**

---

## DIAG - Excessive H1 Link Communication Errors

Applies to H1 Link.

### **Potential causes**

Malformed packets were detected on the H1 link, typically due to faulty wiring or hardware.

### **Consequence of inaction**

Increased latency, stale data or in extreme cases loss of Control, loss of view, loss of synchronization.

### **Corrective actions**

If persistent, verify all wiring and components on the link. Replace or correct the source of the errors.

### **Time to respond**

Immediate

---

## DIAG - Factory Data Error

Applies to FIM4, FIM8, and C300.

### **Potential causes**

Factory Data is programmed into the C300 Controller Flash memory at the time of manufacture. The C300 Controller incorporates a run-time diagnostic to check that this data block is not corrupted. If it is corrupted this alarm is raised.

### **Consequence of inaction**

Loss of control.

### **Corrective actions**

Contact the Honeywell Technical Assistance Center (TAC) to arrange for replacement of the module.

### **Time to respond**

Immediate.



---

## DIAG - Fatal FF Communication Error

Applies to H1 Link.

### **Potential causes**

Occurs on Fieldbus Interface Module (FIM)2 only. Indicates that a fatal exception has occurred on the FIM2 communication co-processor.

### **Consequence of inaction**

Loss of control if non-redundant; loss of synchronization if redundant.

### **Corrective actions**

Contact your Honeywell Technical Assistance Center to diagnose, verify installation, and replace the FIM.

### **Time to respond**

Immediate.

---

## DIAG - Fieldbus devices not communicating or intermittent

### Potential causes

Noise, voltage, power supply.

### Consequence of inaction

Loss of communication.

### Corrective actions

1. Solution 1: Route field signal cables through conduit and at a distance from power cables.
2. Solution 2: Check the power supply. Use a conditioned power supply; ordinary power supply is not suitable.

### Time to respond

Immediate.

---

## DIAG - FIM Cable Failure, FIM or RTP Slot

**Potential causes**

Disconnection or failure of RTP cable or RTP assembly.

**Consequence of inaction**

Loss of synchronization. If non-redundant, loss of process data and/or loss of control.

**Corrective actions**

1. Check RTP cabling and assembly.
2. Replace RTP or cable if problems persist.

**Time to respond**

Immediate.

---

## DIAG - FIM Is Not Primary Link Master

Applies to H1 Link.

### **Potential causes**

The Fieldbus Interface Module (FIM) is not acting as primary link master. Note that FIM is configured to be primary link master by default.

### **Consequence of inaction**

Loss of control.

### **Corrective actions**

Verify that the primary FIM has regained Link Master responsibility.

### **Time to respond**

Immediate.

---

## DIAG - FIM Not Responding

**Potential causes**

Fieldbus Interface Module (FIM) does not accept downloads. FIM does not show previous configuration.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Clear FIM memory by temporarily placing FIM on a different slot. The change will be detected and the memory reset.

**Time to respond**

Immediate.

---

## DIAG - FIM Lost Sync

### **Potential causes**

FIM loss of sync.

### **Consequence of inaction**

Loss of synchronization.

### **Corrective actions**

Review the redundancy history on the RM to determine cause of loss of sync.

### **Time to respond**

Immediate.

---

## DIAG - FIM Schedule Error, Not Executing Slot

**Potential causes**

Function block schedule not executing.

**Consequence of inaction**

Loss of process data and/or loss of control.

**Corrective actions**

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the given slot number in the description to identify the FIM with the daughter board failure.
2. Restart module.
3. If the problem persists, replace FIM hardware.

**Time to respond**

Immediate.

---

## DIAG - FIM SLOT: XX { Tag Identifier } ( Err XX )

### Potential causes

Problem with the device listed in the Tag ID.

### Consequence of inaction

Loss of synchronization. Potential loss of process data and/or loss of control.

### Corrective actions

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203), the given slot number in the description field, and the Tag ID as the starting point to begin network fault isolation.
2. Check segment health to verify signal quality is within the Foundation Fieldbus specifications.
3. Replace the device if problems persist.

### Time to respond

Immediate.



---

## DIAG - Firm Ware Error1

**Potential causes**

ControlNet cable disconnected and/or defective.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the given slot number in the description to identify the FIM with the daughter board failure.
2. Restart module.

**Time to respond**

Immediate.

---

## DIAG - Firm Ware Error2

### Potential causes

Buffers not allocated.

### Consequence of inaction

Loss of communication.

### Corrective actions

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the given slot number in the description to identify the FIM with the daughter board failure.
2. Restart module.

### Time to respond

Immediate.

---

## DIAG - FTA A Communication Error

**Potential causes**

Loss of communication with the FTA .

**Consequence of inaction**

Transaction between the IOP and FTA is interrupted.

**Corrective actions**

Reset the IOP receive buffer index.

**Time to respond**

Immediate.

---

## DIAG - FTA B Communication Error

### **Potential causes**

Loss of communication with the FTA .

### **Consequence of inaction**

Transaction between the IOP and FTA is interrupted.

### **Corrective actions**

Reset the IOP receive buffer index.

### **Time to respond**

Immediate.

---

## DIAG - FTE Port A Receive Fault

Applies to FIM4, FIM8, C300, FTEB, and PGM.

This alarm is generated specifically and only for an FTE receive path fault on the IOTA, C300, or FIM itself. Disconnection of FTE Cable A or Cable B from the C300 does NOT generate this alarm. Rather a cable disconnection is alarmed by the FTE Status Monitor when it sees no messages transmitted from the C300 on the port from which the cable has been removed.

### Potential causes

This alarm is generated specifically and only for an FTE receive path fault. Disconnection of FTE Cable A or Cable B from the C300 is alarmed by the FTE Status Monitor when it sees no messages transmitted from the C300 on the port from which the cable has been removed.

### Consequence of inaction

Loss of communication with the controller.

### Corrective actions

Unless you suspect that one of the causes described above exists and is resulting in a spurious indication, you should replace the Control module exhibiting this diagnostic as soon as possible.

### Time to respond

As soon as possible.

---

## DIAG - FTE Port B Receive Fault

Applies to FIM4, FIM8, C300, FTEB, and PGM.

This alarm is generated specifically and only for an FTE receive path fault on the IOTA, C300, or FIM itself. Disconnection of FTE Cable A or Cable B from the C300 does NOT generate this alarm. Rather a cable disconnection is alarmed by the FTE Status Monitor when it sees no messages transmitted from the C300 on the port from which the cable has been removed.

### **Potential causes**

This alarm is generated specifically and only for an FTE receive path fault. Disconnection of FTE Cable A or Cable B from the C300 is alarmed by the FTE Status Monitor when it sees no messages transmitted from the C300 on the port from which the cable has been removed.

### **Consequence of inaction**

Loss of communication with the controller.

### **Corrective actions**

Unless you suspect that one of the causes described above exists and is resulting in a spurious indication, you should replace the Control module exhibiting this diagnostic as soon as possible.

### **Time to respond**

As soon as possible.

---

## DIAG - Function Block Error

**Potential causes**

Function Block Schedule not executing.

**Consequence of inaction**

Loss of synchronization. Potential loss of process data and/or loss of control.

**Corrective actions**

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the given slot number in the description field as the starting point to begin network fault isolation.
2. Restart the FIM.
3. Replace the FIM if problems persist.

**Time to respond**

Immediate.

---

## DIAG - GPS Failed

Applies to C300.

### **Potential causes**

An external GPS-based source is the current master reference for C300 System Time. This event is generated when this GPS source fails.

### **Consequence of inaction**

N/A

### **Corrective actions**

GPS is not yet implemented. So this alarm will not be raised.

### **Time to respond**

N/A



---

## DIAG - H1 Link Communication Error Detected

Applies to H1 Link.

### **Potential causes**

A single malformed packet was detected on the H1 link, typically due to faulty wiring or hardware.

### **Consequence of inaction**

Increased latency or stale data. If not corrected, excessive H1 Link Error alarms may be reported.

### **Corrective actions**

If persistent, verify all wiring and components on the link. Replace or correct the source of the errors.

### **Time to respond**

Immediate.

---

## DIAG - H1 Link Power Failure

Applies to H1 Link.

### **Potential causes**

The Fieldbus Interface Module (FIM) detects incorrect or missing power from an integrated power conditioner. If external power conditioners are used, this diagnostic should be disabled.

### **Consequence of inaction**

Failure of H1 link operations.

### **Corrective actions**

If integrated power conditioners are used, check that the power conditioner is connected to the FIM2 RTP or FIM4/FIM8 IOTA. Integrated power conditioners typically have alarming modules that will detect and report power diagnostics. If external power conditioners are used, this diagnostic should be disabled.

### **Time to respond**

Immediate.

---

## DIAG - Hardware Temperature Exceeded The Threshold

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

The temperature of the hardware has exceeded the defined temperature limit in the OVERTEMPHLD parameter.

### **Consequence of inaction**

May damage some part of the hardware and/or reduce the life time of the controller.

### **Corrective actions**

Check if the parameter value has been lowered from the default and if so, set a more appropriate limit. Also check the cabinet temperature, and whether the cabinet fans and cooling mechanisms are working effectively.

### **Time to respond**

Will vary depending on the threshold limit configured in the OVERTEMPHLD parameter.

---

## DIAG - Harmonic Distortion Mode Not Possible

### **Potential causes**

No valid 3rd harmonic component available to calculate the B value PV.

### **Consequence of inaction**

Incorrect B value.

### **Corrective actions**

Check for formation of surface films having redox behavior, such as sulfides, which can prevent the electrode from becoming polarized. Check for a diffusion-limiting corroding system.

### **Time to respond**

---

## DIAG - Heap Memory Not Available

**Potential causes**

Heap allocation failure. Software has detected that there is a heap memory shortage.

**Consequence of inaction**

Some communication packets may have been dropped.

**Corrective actions**

Clear by warm restart of device. If the condition persists, contact the Honeywell Technical Assistance Center (TAC) for support.

**Time to respond**

---

## DIAG - HW Rev Below Acceptable Minimum — Upgrade Required

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

The CPLD version in the C300 controller module is not compatible with operations using the current C300 firmware image.

### **Consequence of inaction**

The controller might not work as intended.

### **Corrective actions**

Replace the controller module with a module that meets current hardware specifications.

### **Time to respond**

---

## DIAG - ICP QSend Error

Applies to C200E, CPMC200, LIOM, FIM, IOLIM, and FTEB.

### **Potential causes**

The ICP Driver was unable to pass a message to the next layer. This is an unexpected overload of unknown cause but could include hardware corruption or traffic overload.

### **Consequence of inaction**

Intermittent data access and control data.

### **Corrective actions**

Investigate ControlNet, FTE, I/O and peer traffic loads. Swap roles to see if the problem moves with the chassis. Replace modules one at a time, ending with the chassis itself.

### **Time to respond**

Next maintenance shift.

---

## DIAG - ICP Unrecognized CMD

Applies to C200E, CPMC200, LIOM, FIM, IOLIM, and FTEB.

### **Potential causes**

The ICP ASIC received a command from the backplane that it did not recognize. This indicates hardware corruption.

### **Consequence of inaction**

Eventual system failure.

### **Corrective actions**

Swap roles to see if the problem moves with the chassis. If non-redundant, power cycle the chassis (and reload if necessary). Replace modules one at a time, ending with the chassis itself.

### **Time to respond**

Next maintenance shift.



---

## DIAG - Illegal CLeAr DEVADDR Attempt On Link

Applies to H1 Link.

### Potential causes

An attempt was made to clear the FIM's Device Address. There should be no device or system on the H1 link capable of this action.

### Consequence of inaction

Unpredictable results including loss of control and loss of view.

### Corrective actions

Verify wiring to ensure only one Fieldbus Interface Module (FIM) or redundant FIM pair is on the same H1 link. Verify no other FF host device is on the H1 network. If the problem persists, reboot the secondary FIM.

### Time to respond

Immediate.

---

## DIAG - Illegal Clear PD\_TAG Attempt On Link

Applies to H1 Link.

### **Potential causes**

An attempt was made to clear the Fieldbus Interface Module (FIM)'s Physical Device Tag. There should be no device or system on the H1 link capable of this action.

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link. Verify no other FF host device is on the H1 network. If the problem persists, reboot the secondary FIM.

### **Time to respond**

Immediate.

---

## DIAG - Illegal Set DEVADDR Attempt On Link

Applies to H1 Link.

### Potential causes

An attempt was made to set the Fieldbus Interface Module (FIM)'s Device Address. There should be no device or system on the H1 link capable of this action.

### Consequence of inaction

Unpredictable results including loss of control and loss of view.

### Corrective actions

Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link. Verify no other FF host device is on the H1 network. If the problem persists, reboot secondary FIM.

### Time to respond

Immediate.

---

## DIAG - Illegal Set PD\_TAG Attempt On Link

Applies to H1 Link.

### **Potential causes**

An attempt was made to set the Fieldbus Interface Module (FIM)'s Physical Device Tag. There should be no device or system on the H1 link capable of this action.

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link. Verify no other FF host device is on the H1 network. If the problem persists, reboot secondary FIM.

### **Time to respond**

Immediate.

---

## DIAG - Illegal Unknown SM Event On Link

Applies to H1 Link.

### **Potential causes**

An unknown System Management indication was processed by the Fieldbus Interface Module (FIM).

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link. Verify no other FF host device is on the H1 network. If the problem persists, reboot secondary FIM.

### **Time to respond**

Immediate.

---

## DIAG - Input 1 Calibration Failure

### **Potential causes**

Input 1 calibration data invalid.

### **Consequence of inaction**

No PV.

### **Corrective actions**

User calibration required.

### **Time to respond**

---

## DIAG - Input 2 Calibration Failure

**Potential causes**

Input 2 calibration data invalid.

**Consequence of inaction**

No PV.

**Corrective actions**

User calibration required.

**Time to respond**

---

## DIAG - Input 3 Calibration Failure

### **Potential causes**

Input 3 calibration data invalid.

### **Consequence of inaction**

No PV.

### **Corrective actions**

User calibration required.

### **Time to respond**



---

## DIAG - Input 1 Failure

**Potential causes**

Input 1 error.

**Consequence of inaction**

No PV.

**Corrective actions**

- Check input 1 connection and wiring.
- Check input contacts.
- Restart the sensor.

If the condition persists, replace the sensor module.

**Time to respond**

---

## DIAG - Input 2 Failure

### Potential causes

Input 2 error.

### Consequence of inaction

No PV.

### Corrective actions

- Check input 2 connection and wiring.
- Check input contacts.
- Restart the sensor.

If the condition persists, replace the sensor module.

### Time to respond

---

## DIAG - Input 3 Failure

**Potential causes**

Input 3 error.

**Consequence of inaction**

No PV.

**Corrective actions**

- Check input 3 connection and wiring.
- Check input contacts.
- Restart the sensor.

If the condition persists, replace the sensor module.

**Time to respond**

---

## DIAG - Input 1 T/C Warning

### **Potential causes**

Input 1 thermocouple faulty, resistance is excessive.

### **Consequence of inaction**

No PV.

### **Corrective actions**

Check input 1 connection and wiring. Replace the thermocouple.

### **Time to respond**

---

## DIAG - Input 2 T/C Warning

**Potential causes**

Input 2 thermocouple faulty, resistance is excessive.

**Consequence of inaction**

No PV.

**Corrective actions**

Check input 2 connection and wiring. Replace the thermocouple.

**Time to respond**

---

## DIAG - Input 3 T/C Warning

### **Potential causes**

Input 3 thermocouple faulty, resistance is excessive.

### **Consequence of inaction**

No PV.

### **Corrective actions**

Check input 3 connection and wiring. Replace the thermocouple.

### **Time to respond**

---

## DIAG - Input Failure

**Potential causes**

Input error.

**Consequence of inaction**

No PV.

**Corrective actions**

May need to replace the meter body sensor.

**Time to respond**

---

## DIAG - Intermittent Comm Failure

**Potential causes**

The NDM cannot communicate to one or more devices because either the specified device has been removed, or there is an intermittent communication problem. The former may occur as a consequence of redundant controller chassis switchover. The latter may be due to diminished unconnected communication bandwidth somewhere in between the PC hosting the NDM and the device(s).

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Scan the Event journal for any recent Comm Failure and/or Card Removed system info events to determine which devices are not able to communicate with the NDM. Be aware that removal of a device (e.g. PCIC) required for communication with other “downstream” devices will result in the NDM reporting communication errors against the other “downstream” devices. Repair or replace any device that was unexpectedly removed, and/or use the Network Tools application to investigate communication bandwidth between the PC and the specified device(s).

**Time to respond**

Immediate.



---

## DIAG - Invalid Keeper

**Potential causes**

A Keeper-capable ControlNet resident device (for example, CNI) does not indicate the Master Keeper status or Backup Keeper status. Either there is no Master Keeper on the affected ControlNet segment, or the specified device's programmed ControlNet parameters disagree with the ControlNet parameters being asserted by the Master Keeper.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Utilize the Network Tools application to reprogram the ControlNet parameters for the entire ControlNet segment or just the specified device.

**Time to respond**

Immediately.

---

## DIAG - IOLink(1) Soft Fail Error

Applies to C300.

### Potential causes

IOLINK 1 interface is in soft fail.

### Consequence of inaction

The consequence depends on the actual soft fail reported on IO LINK configuration form. It could be any of the following:

- Duplicate IOL address
- IOL channel failure
- IOL max errors exceeded
- Not active supervisor
- IOLIM daughter card failure
- Partner not visible on IOL
- Partner mismatch on IOL
- IOL process data cycle overruns
- UM51 diagnostics exceeded time threshold
- UM51 diagnostic overrun

### Corrective actions

View the Main tab of the configuration form for the IOLINK block for soft failures specific to the IO LINK interface and corresponding cause/solution.

### Time to respond

Depends on actual alarm reported on IOLINK form.

---

## DIAG - IOLink(2) Soft Fail Error

Applies to C300.

### Potential causes

IOLINK 2 interface is in soft fail.

### Consequence of inaction

The consequence depends on the actual soft fail reported on IO LINK configuration form. It could be any of the following:

- Duplicate IOL address
- IOL channel failure
- IOL max errors exceeded
- Not active supervisor
- IOLIM daughter card failure
- Partner not visible on IOL
- Partner mismatch on IOL
- IOL process data cycle overruns
- UM51 diagnostics exceeded time threshold
- UM51 diagnostic overrun

### Corrective actions

View the Main tab of the configuration form for the IOLINK block for soft failures specific to the IO LINK interface and corresponding cause/solution.

### Time to respond

Depends on actual alarm reported on IOLINK form.

---

## DIAG - JagXtreme Communication Error

### **Potential causes**

The associated JAGXTERM function block loses communication with the JX terminal.

### **Consequence of inaction**

Communication failure alarms are generated for connected terminal I/O module blocks.

### **Corrective actions**

Check the wiring and wiring terminations.

### **Time to respond**

Immediate.

---

## DIAG - JX Instrument Alarm

**Potential causes**

A alarm condition (usually a warning) occurred on the associated instrument.

**Consequence of inaction**

An alarm is a condition that, if left untreated, may stop the drive. Drive alarms are usually warnings.

**Corrective actions**

Check the instrument.

**Time to respond**

Immediate.

---

## DIAG - JX Instrument Fault

### **Potential causes**

A fault condition occurred on the associated instrument .

### **Consequence of inaction**

Stops the drive operating.

### **Corrective actions**

Check the instrument.

### **Time to respond**

Immediate.

---

## DIAG - KTC Failure

**Potential causes**

The presence of a KTC “tombstone” event implicitly indicates KTC card failure.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Restart the RSLinx service, which indirectly resets the KTC.

**Time to respond**

Immediate.

---

## DIAG - Loss Of Batch Event

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

The Sequence Id of the event requested by server during event recovery is not available.

### **Consequence of inaction**

The loss of string data, but the process will continue as is.

### **Corrective actions**

Set the Batch Event Memory value to "Large". Make use of multiple Phase blocks to retrieve all string data needed.

### **Time to respond**

As early as possible.



---

## DIAG - Loss Of Batch Event Data

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

Occurs during generation of Formula or Report events of Datatype String more than 12 , 24 , 72, with the batch event memory configuration of “Small”, “Medium”, or “Large” respectively in a single execution cycle.

### **Consequence of inaction**

The loss of string data, but the process will continue as is.

### **Corrective actions**

Set the batch event memory to "Large". Make use of multiple Phase blocks to retrieve all string data needed.

### **Time to respond**

As early as possible.

---

## DIAG - Lost Sync

### **Potential causes**

FIMs dropped synchronization for any reason.

### **Consequence of inaction**

Loss of synchronization.

### **Corrective actions**

Review the Redundancy History on the RM to determine cause of Loss of Sync.

### **Time to respond**

Immediate.

---

## DIAG - Low Battery

**Potential causes**

The device battery voltage is below 4.15V and critically low. The batteries should be replaced within 2-4 weeks.

**Consequence of inaction**

Device will go offline.

**Corrective actions**

Replace the batteries within 2–4 weeks.

**Time to respond**

---

## DIAG - Low External Power

### **Potential causes**

External power critically low.

### **Consequence of inaction**

The device may go offline.

### **Corrective actions**

Check the external 24V power supply.

### **Time to respond**

---

## DIAG - Low Power

**Potential causes**

External power critically low.

**Consequence of inaction**

Device may go offline.

**Corrective actions**

Check external 24V power supply.

**Time to respond**

---

## DIAG - Local Hardware Fault

### **Potential causes**

Short-circuit or wire-off condition.

### **Consequence of inaction**

Break in field wiring or equipment damage.

### **Corrective actions**

1. Check the power supply and connections.
2. Check the field wiring and replace if worn.

### **Time to respond**

Immediate.

---

## DIAG - Low Redundancy

**Potential causes**

Transmitter has connected with only one Multinode or FDAP.

**Consequence of inaction**

No redundant connection to the network.

**Corrective actions**

No action required. The Transmitter will periodically look for a second Multinode or FDAP in order to form a redundant connection to the network.

**Time to respond**

---

## DIAG - Max Number Of Devices Exceeded

Applies to H1 Link.

### **Potential causes**

More than 16 devices with non-visitor addresses are connected to the H1 link.

### **Consequence of inaction**

Cannot commission new devices.

### **Corrective actions**

Disconnect non-commissioned devices from the link

### **Time to respond**

During device commissioning.



---

## DIAG - MDM Service Is Running

Applies to CEEC300.

### Potential causes

If the Machine Debug Manager (MDM) service is installed and running on a node which hosts on-process ACE, either in a cut-over scenario or inadvertently, the ACE process determines the state of the service both at startup and periodically, and prevents the CEE transition to RUN. An urgent priority system diagnostic alarm is generated.

### Consequence of inaction

If the MDM service is running and the user accidentally attaches the debugger to the ACE process then the ACE application will crash.

### Corrective actions

If you try to give the CEECOMMAND as 'RUN' when MDM service is running an error message is thrown indicating "CEE can't be activated when the MDM service is running". In this case stop the MDM service and retry the CEECOMMAND 'RUN'. If this alarm is raised when the ACE controller is in a "Run" state, stop the MDM service in the ACE Machine. This will return the alarm to normal

### Time to respond

As soon as possible.

---

## DIAG - Memory Limit Exceeded

Applies to C200E, CPMC200, LIOM, SIMC200E, CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### **Potential causes**

This alarm is generated by the CPM block when the user memory (control strategy) has been exhausted.

### **Consequence of inaction**

Migration is not possible.

### **Corrective actions**

Either disable this error flag, or delete sufficient control strategy from the user pool to make and FREEMEM parameter value a positive number.

### **Time to respond**

As soon as possible.

---

## DIAG - Missing Keeper

**Potential causes**

A ControlNet segment does not have a Master Keeper. Either {1} all Keeper capable devices are in a Keeper Status other than Master or Backup (e.g. Faulted Keeper Status) or {2} there are no Keeper capable devices present on the affected ControlNet segment.

**Consequence of inaction**

Loss of Communication.

**Corrective actions**

Either {1} utilize the Network Tools application to reprogram the ControlNet parameters for the affected ControlNet segment to appropriate values (e.g. NUT 10000, UMAX 24, and SMAX 1); or {2} add a Keeper capable device to the affected ControlNet segment.

**Time to respond**

Immediate.

---

## DIAG - Module Hardware Fault

### Potential causes

Critical module hardware failure detection due to following causes:

1. A detected fault in the I/O device hardware.
2. Opened or shorted leads to the sensor.
3. A faulted remote transmitter.

### Consequence of inaction

All channels are marked as bad. PV reports NAN and disrupts process.

### Corrective actions

1. Check the leads to the sensor.
2. Replace the device.

### Time to respond

Immediate.

---

## DIAG - No Field Power Detected

**Potential causes**

Loss of field power for a particular channel. Current flow is not present at any channel.

**Consequence of inaction**

Lack of power resulting in output state change.

**Corrective actions**

Check the power supply to each channel and associated connections.

**Time to respond**

Immediate.

---

## DIAG - No Load Detected

### **Potential causes**

The output current draw falls below the threshold or a hardware output failure occurs. Detection only works when the output is in the OFF state.

### **Consequence of inaction**

No load is detected on this channel.

### **Corrective actions**

Check the I/O device and replace hardware, if required.

### **Time to respond**

Immediate.

---

## DIAG - No PBIM Reference

**Potential causes**

Invalid or missing PBIM reference.

**Consequence of inaction**

PBIM serves the devices I/O data to each of its associated blocks. Invalid reference indicates loss of I/O data and fails to detect the device location.

**Corrective actions**

Reconfigure the PBIM block reference and reload.

**Time to respond**

Immediate

---

## DIAG - No Sensor Board Alert

### **Potential causes**

The Transducer Interface Instrument - X-Band Radar board is disconnected from SmartRadar FlexLine system.

### **Consequence of inaction**

Level detection not possible.

### **Corrective actions**

Check the TII-XR board connections.

### **Time to respond**



---

## DIAG - Non-Volatile Memory Error

**Potential causes**

Startup diagnostics have detected a defect in the Non-Volatile memory sensor.

**Consequence of inaction**

The device will go offline.

**Corrective actions**

Replace the sensor module.

**Time to respond**

---

## DIAG - Not Using Configured Time Source

Applies to FIM4, FIM8, C300 and PGM.

### **Potential causes**

If the CDA is unavailable or subsequently becomes unavailable, the C300 Controller will continue to run and execute control. In this case, it will use its internal Wall Clock Time (WCT) source (based on a precision oscillator).

### **Consequence of inaction**

The system will continue to use its internal wall clock and will also generate Time Source Changed alarm.

### **Corrective actions**

Verify whether the CDA service is running.

### **Time to respond**

---

## DIAG - Over Range Fault

**Potential causes**

Indicates the input value is above the valid hardware input range of the channel (e.g. Temp>Tmax).

**Consequence of inaction**

Disrupts the process. Loss of control.

**Corrective actions**

Check the input device/transmitter.

**Time to respond**

Immediate.

---

## DIAG - Over Temperature Alert

### **Potential causes**

The meter body has exceeded the maximum temperature as defined by the meter body characterization data.

### **Consequence of inaction**

Incorrect PV.

### **Corrective actions**

Determine and rectify the cause of the excessive temperature.

### **Time to respond**

---

## DIAG - PCIC Lonely On CNet

Applies to ACE.

### Potential causes

1. Cables not connected correctly.
2. Cables not terminated correctly.
3. MAC ID assigned to the PCIC card is incorrect.

### Consequence of inaction

When a controller node becomes lonely, it will lose its configuration file and cause errors when it regains access to other nodes.

### Corrective actions

1. Check if cables are connected properly on the A & B or just the A ControlNet Supervisory segments. Also check if the terminators of the correct value are installed on both ends of the segment.
2. Check supervisory CNI for A and B network LEDs.
3. Check the MAC ID and assign it correctly.

### Time to respond

As soon as possible.

---

## DIAG - Partner Not Visible on FTE

Applies to FIM4, FIM8, C300, and PGM.

### Potential causes

The Fault Tolerant Ethernet (FTE) communications with redundant controller partner and FTE network are lost due to one of the following reasons:

1. Secondary controller is defective.
2. Secondary IOTA is defective.
3. Primary controller is defective.
4. Primary IOTA is defective.

### Consequence of inaction

System redundancy can't be achieved.

### Corrective actions

1. Replace the Secondary controller that initiated switchover when fault was detected.
2. Replace the Secondary IOTA that initiated switchover when fault was detected.
3. Replace the Primary controller.
4. Replace the primary IOTA.

### Time to respond

As soon as possible.

---

## DIAG - PBIM Communication Error

**Potential causes**

PBIM communication errors, probably between the PBIM block and the SST-PB3-CLX-HWL (PROFIBUS interface module).

**Consequence of inaction**

Data loss.

**Corrective actions**

Investigate the PBIM block's communication status.

**Time to respond**

Immediate.

---

## DIAG - PBIM Inactive

### Potential causes

PBIM block is INACTIVE.

### Consequence of inaction

Causes a break in the communication between I/O device/module blocks and the PROFIBUS network. I/O data is not transferred between the PBIM block and the SST-PB3-CLX-HWL (PROFIBUS interface module) card. Fail-Safe data is returned to client input blocks.

### Corrective actions

Set the block execution status of the PBIM block to Active. Any adding, removing or reconfiguring one or more slave devices initializes the block status to INACTIVE.

### Time to respond

As needed.



---

## DIAG - PBIM Registration Error

**Potential causes**

Generated if the block is not registered with PBIM block.

**Consequence of inaction**

Configuration mismatch between this block and the PBIM block with regard to the Station number, Module Number, and Data Offsets that correspond to the data expected by the block.

**Corrective actions**

Ensure a matching configuration between PBIM table and IOM block, including Station number, Module Number, and Data Offsets that correspond to the data expected by the block.

**Time to respond**

Immediate.

---

## DIAG - PCIC Failure

### **Potential causes**

The presence of a PCIC “tombstone” event implicitly indicates PCIC card failure.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

Restart the RSLinx, which indirectly resets the PCIC.

### **Time to respond**

Immediate.

---

## DIAG - Pressure Overload Alert

**Potential causes**

The applied pressure has exceeded the limit defined by the meter body characterization data.

**Consequence of inaction**

Incorrect PV.

**Corrective actions**

Determine and rectify the cause of the excessive pressure.

**Time to respond**

---

## DIAG - PROFIBUS Communication Error

### Potential causes

The controller to SST-PB3-CLX-HWL communication connection is broken. Causes may be:

1. Power is disrupted to the remote chassis in which the SST-PB3-CLX-HWL resides.
2. The SST-PB3-CLX-HWL is removed under power.
3. The controller to SST-PB3-CLX-HWL.

### Consequence of inaction

Controller to PROFIBUS interface module communication connection is broken. Results in data loss.

### Corrective actions

1. Check the I/O module to make sure it is not faulted or unpowered.
2. Check the chassis PS, in which the PBIM resides and restore, if unpowered.
3. In case of a remote chassis, check the cable connections.

### Time to respond

Immediately.

---

## DIAG - PROFIBUS Not In Run

**Potential causes**

PROFIBUS Run mode is not enabled (on PBIM block).

**Consequence of inaction**

Disables the communication of output values from the CEE.

**Corrective actions**

Enable the Profibus Run Mode.

**Time to respond**

As needed.

---

## DIAG - PROFIBUS Offline

### **Potential causes**

PBIM block is not online with PROFIBUS.

### **Consequence of inaction**

Changes in the PROFIBUS network will not update in the PBIM block.

### **Corrective actions**

Restore the PBIM block status to ONLINE.

### **Time to respond**

As needed.

---

## DIAG - Program Memory Fault

**Potential causes**

Startup diagnostics detected a defect in the program memory sensor.

**Consequence of inaction**

Device will go offline.

**Corrective actions**

Replace the sensor module.

**Time to respond**

---

## DIAG - PTP Time Source Failed

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

If a PTP/NTP time source is configured and if it becomes unavailable the controller uses its internal wall clock time (WCT), and reports this alarm.

### **Consequence of inaction**

The system will continue to use the CDA time source.

### **Corrective actions**

Check that the PTP time server is running.

### **Time to respond**

Not critical.



---

## DIAG - QiMPACT Communication Error

**Potential causes**

Communication error within QiMPACT cluster. The IOM Function Block loses communication with its associated QiMPACT terminal.

**Consequence of inaction**

Communication Failure alarms are generated for connected terminal I/O module blocks.

**Corrective actions**

Restore the connection to the connected terminal.

**Time to respond**

Immediate.

---

## DIAG - QiMPACT Instrument Alarm

### **Potential causes**

A alarm condition (usually a warning) occurred on the associated instrument.

### **Consequence of inaction**

An alarm is a condition that, if left untreated, may stop the drive. Drive alarms are usually warnings.

### **Corrective actions**

Check the instrument.

### **Time to respond**

Immediate.

---

## DIAG - QiMPACT Instrument Fault

**Potential causes**

A fault condition occurred on the associated instrument.

**Consequence of inaction**

Stops the drive operating.

**Corrective actions**

Check the instrument.

**Time to respond**

Immediate.

---

## DIAG - Radio Interprocessor Comm Error

### **Potential causes**

The radio board is not accessible.

### **Consequence of inaction**

Loss of communication to the device.

### **Corrective actions**

Restart both the radio and sensor. If condition persists, replace the sensor module.

### **Time to respond**

---

## DIAG - Radio Status EEPROM SP1 Communication Failure

**Potential causes**

There has been a radio EEPROM SPI communication failure.

**Consequence of inaction**

The radio will not be able to perform firmware upgrades but will operate normally using installed code.

**Corrective actions**

Replace the sensor module.

**Time to respond**

---

## DIAG - Radio Status Radio Communication Circuitry Failure

### **Potential causes**

The radio processor detected error on internal radio circuitry.

### **Consequence of inaction**

No data acquisition from the field device.

### **Corrective actions**

Replace the sensor module.

### **Time to respond**

---

## DIAG - Radio Status Sensor Radio SP1 Communication Failure

**Potential causes**

The radio detected a loss of communication with the sensor board over the inter-processor communication link.

**Consequence of inaction**

No PV.

**Corrective actions**

Restart both the radio and sensor. If the condition persists, replace the sensor module.

**Time to respond**

---

## DIAG - Radio Status WDT Reset Occurred

### **Potential causes**

The radio detected a Watch Dog Timer (WDT) timeout.

### **Consequence of inaction**

Device reset.

### **Corrective actions**

Restart both the radio and sensor. If the condition persists, replace the sensor module.

### **Time to respond**



---

## DIAG - RAM Error

**Potential causes**

Startup diagnostics detected a defect in the sensor RAM.

**Consequence of inaction**

Device will go offline.

**Corrective actions**

Replace the sensor module.

**Time to respond**

---

## DIAG - RAM Fault

### **Potential causes**

Startup diagnostics detected a defect in the processor RAM.

### **Consequence of inaction**

Device will go offline.

### **Corrective actions**

Replace the sensor module.

### **Time to respond**

---

## DIAG - Reconfiguration Fail

**Potential causes**

IOM reconfiguration status is FAILED.

**Consequence of inaction**

The reconfiguration terminates in failure.

**Corrective actions**

1. Check the device status.
2. Restart the device and configure it again.

**Time to respond**

Immediate.

---

## DIAG - Redun Standby

Applies to C200E, CPMC200, LIOM, and C300.

### **Potential causes**

Both the primary and secondary controllers generate this notification when entering the Standby sync state due to On Process Migration; this is only generated by the C300 controller.

### **Consequence of inaction**

Expected.

### **Corrective actions**

Continue with migration.

### **Time to respond**

N/A

---

## DIAG - Redun Count Exceeded

Applies to CEEACEFB, CEEC200EFB, CEEC300, CEEFB, CEESIMC200FB, and EEFB.

### Potential causes

The Redundancy Count Exceeded alarm fires whenever the maximum number of redundancy tracking bytes generated in any CEE-C300 cycle exceeds the value of parameter RDNCNTCYCTP. The maximum is accumulated once every 2 seconds. The alarm clears when the observed maximum for all cycles falls to a value that is more than 10% below the configured trip point.

### Consequence of inaction

Possible loss of synchronization.

### Corrective actions

Use RTC instrumentation parameters to determine whether the maximum load is spread across all cycles or concentrated on a few cycles. Reset statistics while examining the instrumentation to determine if regular, steady state load produces maxima close to the limit or if, instead, a burst condition tripped the alarm.

Reduce the total configuration being run in the CEE-C300 by deleting CMs. CMs with CAB types would be specifically considered for deletion. Focus on those cycles in which heavy load appears to be concentrated.

Examine, and if needed, modify CAB types deployed within the CEE-C300. CAB types with intensive looping would be specifically considered for modification or for elimination from the configuration.

Increase the trip point of the RTC alarm if absolutely necessary, and if it is safe to do so. This might be done as a stop-gap measure to eliminate Operators having to deal with the alarm noise while an engineering solution is being worked out. It is recommended that if the RTC trip point is increased, it should be done only on a temporary basis. The trip point should be decreased back to the default value after an engineering solution is implemented. If a decision not to reduce the CEE-C300 configuration after an RTC alarm fires is made, and the increased trip point value permanently retained, then the C300 configuration should be considered sealed and complete from that point on, at least for cycles which produce RTC near the trip point. Additional RTC load should not be added to the sensitive cycles.

### Time to respond

As soon as possible.

---

## DIAG - Remote Hardware Fault

### **Potential causes**

Remote transmitter is faulted.

### **Consequence of inaction**

Process disruption.

### **Corrective actions**

Replace the transmitter.

### **Time to respond**

Immediate.

---

## DIAG - ROM Application Image Checksum Failure

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

The C300 Controller Application Image resides in Flash ROM. This alarm is raised when the C300 Controller run-time diagnostic based on checksum to verify the image fails.

### **Consequence of inaction**

The controller might not boot up in application mode subsequent reboots.

### **Corrective actions**

Try reloading the application image firmware. If this condition persists, contact the Honeywell Technical Assistance Center (TAC) for support.

### **Time to respond**

Immediate.

---

## DIAG - ROM Boot Image Checksum Failure

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

The C300 Controller boot Image resides in Flash ROM. This alarm is raised when the C300 Controller run-time diagnostic based on checksum to verify the image fails.

### **Consequence of inaction**

The controller might not boot up in the subsequent reboots.

### **Corrective actions**

Try reloading the boot and application image firmware. If this condition persists, contact the Honeywell Technical Assistance Center (TAC) for support.

### **Time to respond**

As soon as possible.



---

## DIAG - ROM Error

**Potential causes**

Startup diagnostics detected a defect in the sensor ROM.

**Consequence of inaction**

Device will go offline.

**Corrective actions**

Replace the sensor module.

**Time to respond**

---

## DIAG - RSLinx Failure

### **Potential causes**

The RSLinx service has stopped for an unknown reason.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

Restart the RSLinx service.

### **Time to respond**

Immediate.

---

## DIAG - RSLinx Initialization Failure

**Potential causes**

The NDM is unable to initialize a RSLinx session. Either {1} incompatible version of RSLinx software or {2} RSLinx not running.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Either verify that the appropriate version of RSLinx software is installed for the specific software release in use or restart the RSLinx service.

**Time to respond**

Immediate.

---

## DIAG - RTP Disconnect

### **Potential causes**

Disconnected RTP cable.

### **Consequence of inaction**

Loss of synchronization. Potential loss of process data/ loss of control.

### **Corrective actions**

Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the FIM slot number in the description field to find the FIM with the disconnected RTP cable.

### **Time to respond**

Immediate.

---

## DIAG - Runtime Diagnostic Failure

Applies to H1 Link.

### **Potential causes**

Occurs on Fieldbus Interface Module (FIM) 2 only. Indicates that the co-processor has detected a diagnostic failure.

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Contact your Honeywell Technical Assistance Center to diagnose, verify installation and replace the FIM.

### **Time to respond**

Immediate.

---

## DIAG - Runtime Diagnostic OVERRUN

Applies to H1 Link.

### **Potential causes**

Occurs on the Fieldbus Interface Module (FIM) 2 only. Indicates that the diagnostic cycle on the co-processor did not complete in the allotted time.

### **Consequence of inaction**

Unpredictable results including loss of control and loss of view.

### **Corrective actions**

Contact your Honeywell Technical Assistance Center to diagnose, verify installation and replace the FIM.

### **Time to respond**

Immediate.

---

## DIAG - Runtime Fail on Daughter Board

**Potential causes**

Run time diagnostic failure of the daughter board.

**Consequence of inaction**

Loss of synchronization. Potential loss of process data and/or loss of control.

**Corrective actions**

1. Use the NDM generated Point ID (e.g. Driver Name : RM0203) and the given slot number in the description to identify the FIM with the daughter board failure.
2. Restart the module.
3. If the problem persists, replace FIM hardware.

**Time to respond**

Immediate.

---

## DIAG - Secondary Address Overlap

Applies to LIOM SLINK.

### **Potential causes**

An overlap is detected when the starting address of the SIOM plus the slot configuration overlaps with the starting address of the next SIOM. The two SIOMs under consideration can be on one or different links. In such a scenario, only one of the SIOMs comes online and the other SIOM reports an overlap condition on its link.

### **Consequence of inaction**

Only one of the overlapped SIOMs will work; others will not.

### **Corrective actions**

Assign unique addresses for all SIOMs.

### **Time to respond**

As soon as possible.



---

## DIAG - Sensor Alert

**Potential causes**

Input failure, which can happen for several reasons:

- Wired sensor is not connected to the field device.
- Input range exceeded the limits.
- There is a wire disconnection.

**Consequence of inaction**

No PV.

**Corrective actions**

- Check the connection between the wired sensor and field device.
- Check the input signal range.

**Time to respond**

---

## DIAG - Short Circuit Detected

### **Potential causes**

Short circuit or overload condition.

### **Consequence of inaction**

1. Equipment damage.
2. Damages the device due to excess current drawn for a given channel.

### **Corrective actions**

Check the power supply and associated connections.

### **Time to respond**

Immediate.

---

## DIAG - SIOM Offline

**Potential causes**

SIOM was taken offline.

**Consequence of inaction****Corrective actions**

Command "Restart Slinks" from LIOM FB configuration form.

**Time to respond**

---

## DIAG - SIOM Offline, Communications Ceased

Applies to LIOM SLINK.

### **Potential causes**

When a SIOM goes offline on a serial link, communication on the corresponding serial link, or both serial links, ceases depending on the serial link fault configuration.

### **Consequence of inaction**

All the SIOM on that particular link will not be under control of LIOM.

### **Corrective actions**

Fix the connections or power to the affected SIOM.

### **Time to respond**

Immediately.

---

## DIAG - SIOM Offline, Secondary Communications Ceased

Applies to LIOM SLINK.

### **Potential causes**

When a SIOM goes offline on a serial link, communication on the corresponding serial link, or both serial links, ceases depending on the serial link fault configuration.

### **Consequence of inaction**

All the SIOM on that particular link will not be under control of LIOM.

### **Corrective actions**

Fix the connections or power to the affected SIOM.

### **Time to respond**

Immediately.

---

## DIAG - SM Dupe Node Address

### Potential causes

A second node is on the H1 Link at the same address as the FIM. Typically two FIMs are connected to the same H1 network.

### Consequence of inaction

Unpredictable results including loss of control and loss of view.

### Corrective actions

1. Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.
2. Verify no other FF host device is on the H1 network.
3. If persists, reboot secondary FIM.

### Time to respond

Immediate.

---

## DIAG - SM Node Address Clear

**Potential causes**

An attempt was made to clear the FIM's Device Address. There should be no device or system on the H1 link capable of this action.

**Consequence of inaction**

Unpredictable results including loss of control and loss of view.

**Corrective actions**

1. Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.
2. Verify no other FF host device is on the H1 network.
3. If persists, reboot secondary FIM.

**Time to respond**

Immediate.

---

## DIAG - SM Node Address Set

### Potential causes

An attempt was made to set the FIM's Device Address. There should be no device or system on the H1 link capable of this action.

### Consequence of inaction

Unpredictable results including loss of control and loss of view.

### Corrective actions

1. Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.
2. Verify no other FF host device is on the H1 network.
3. If persists, reboot secondary FIM.

### Time to respond

Immediate.



---

## DIAG - SM Physical Device Tag Clear

**Potential causes**

An attempt was made to clear the FIM's Physical Device Tag. There should be no device or system on the H1 link capable of this action.

**Consequence of inaction**

Unpredictable results including loss of control and loss of view.

**Corrective actions**

1. Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.
2. Verify no other FF host device is on the H1 network.
3. If persists, reboot secondary FIM.

**Time to respond**

Immediate.

---

## DIAG - SM Physical Device Tag Set

### Potential causes

An attempt was made to set the FIM's Physical Device Tag. There should be no device or system on the H1 link capable of this action.

### Consequence of inaction

Unpredictable results including loss of control and loss of view.

### Corrective actions

1. Verify wiring to ensure only one FIM or redundant FIM pair is on the same H1 link.
2. Verify no other FF host device is on the H1 network.
3. If persists, reboot secondary FIM.

### Time to respond

Immediate.

---

## DIAG - SM Unknown

**Potential causes**

Unrecoverable or unexpected condition detected in System Management.

**Consequence of inaction**

Unpredictable results including loss of control and loss of view.

**Corrective actions**

1. Check segment health for network errors, noise, or nonconforming devices.
2. Replace the FIM if problems persist.

**Time to respond**

Immediate.

---

## DIAG - SNTP Failed

Applies to FIM4, FIM8, C300, and PGM.

### Potential causes

If the connection to the configured SNTP time source is broken during normal startup operation, the C300 Controller will continue to run. The loss of connection is detected when no messages from the configured system time source are received over a 90 second interval. If the C300 Controller remains connected to the FTE network and if CDA is available and functioning, the C300 Controller will transition to the use of CDA Time, causing these alarms to be raised.

### Consequence of inaction

The system will continue to use CDA time source and will also generate "Time Source Changed" and "Not using configured time source" alarms.

### Corrective actions

Check that the SNTP time server is running.

### Time to respond

Not critical.

---

## DIAG - Stack Limit Exceeded

Applies to C200E, CPM, CPM200, LIOM, C300, and FIM4.

**Potential causes**

One or more tasks have exceeded their defined stack limit.

**Consequence of inaction**

The controller may crash.

**Corrective actions**

Contact your Honeywell Technical Assistance Center for help with diagnosis.

**Time to respond**

Immediate.

---

## DIAG - Stale Output Alert

### **Potential causes**

The number of consecutively missed publishes exceeds the stale count limit.

### **Consequence of inaction**

Incorrect output value.

### **Corrective actions**

- Determine the cause of the missed publishes; or
- Check the stale count limit.

### **Time to respond**

---

## DIAG - Sync Checksum Fail

Applies to C200E, CPM, CPM200, LIOM, C300, FIM4, and FIM8.

### Potential causes

1. Invalid writes to secondary tracked memory are essentially the same as CRC errors, since invalid writes lead to CRC errors.
2. CRC of the data copied to the Tracked memory of secondary during synchronization is validated, if it fails this alarm is raised.

### Consequence of inaction

Loss of redundancy.

### Corrective actions

Restart the CPM. If problem persists, replace the CPM.

### Time to respond

Immediate.

---

## DIAG - Sync HW Failure

Applies to C200E, CPM, CPM200, LIOM, C300, FIM4, and FIM8.

### **Potential causes**

Synchronization hardware (i.e., Tracker mechanism) failure.

### **Consequence of inaction**

Loss of redundancy.

### **Corrective actions**

- If the CPM is being used in a non-redundant configuration, replace the CPM at the user's earliest convenience.
- If the CPM is currently in the primary redundancy role, attempt switchover to better primary.
- If the CPM is currently in the secondary redundancy role, first restart the CPM. If problem persists, replace the CPM.

### **Time to respond**

Immediate.



---

## DIAG - Task Health Monitoring Warning

Applies to FIM4, FIM8, and C300.

**Potential causes**

The task being monitored doesn't execute in the monitoring time window.

**Consequence of inaction**

The controller may fault and take itself offline.

**Corrective actions**

Make sure that the CPUFREE, Redundancy load, and IOLINK bandwidth usage are within Honeywell recommended limits.

**Time to respond**

Not critical.

---

## DIAG - Time Jump Greater Than Five Minutes

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

If none of the configured time sources are available controller uses its internal WCT source. As soon as it finds a more precise time source, it will switch to that source and if the time difference greater than 5 minutes, this alarm is generated.

### **Consequence of inaction**

CAB blocks that makes decision based on DELTATIME, TIME and TOD parameters will be impacted.

### **Corrective actions**

Validate whether the time jump is justified.

### **Time to respond**

Not critical.

---

## DIAG - UMAX Exceeded

**Potential causes**

A ControlNet segment has at least one node that is attempting to send unscheduled traffic and is at a MAC address higher than expected as specified by the UMAX ControlNet network parameter. Either there is no Master Keeper on the affected ControlNet segment, or the ControlNet parameters being asserted by the Master Keeper are not valid.

**Consequence of inaction**

Loss of communication.

**Corrective actions**

Utilize the Network Tools application to reprogram the ControlNet parameters for the affected ControlNet segment to appropriate values (e.g. NUT 10000, UMAX 24, and SMAX 1).

**Time to respond**

Immediate.

---

## DIAG - Uncommanded Shutdown

### **Potential causes**

The PCM child process did not set its own exit event and therefore did not exit cleanly.

### **Consequence of inaction**

Loss of communication.

### **Corrective actions**

### **Time to respond**

Immediate.

---

## DIAG - Uncomm Dev Oper Class Changed To Basic

Applies to H1 Link.

**Potential causes**

Safe device handling has set the Boot Operational Functional Class of the device to BASIC.

**Consequence of inaction**

None.

**Corrective actions**

No action required. If configured, the uncommissioned device will be changed to link master when loaded.

**Time to respond**

During device commissioning.

---

## DIAG - Under Range Fault

### **Potential causes**

Input value is under the valid hardware input range of the channel (e.g. Temp < Tmin).

### **Consequence of inaction**

Disrupts the process. Loss of control.

### **Corrective actions**

Check the input device/transmitter.

### **Time to respond**

Immediate.

---

## DIAG - Unexpected Partner on Redundancy Link

Applies to FIM4, FIM8, and C300.

### Potential causes

Only the controller explicitly configured as non-redundant generates this notification if a partner is present on the Redundancy private path. The RDNSYNCSTATE parameter is set to either PARTNERVISBL or INCOMPATIBLE. This notification returns to normal if the controller is subsequently configured as redundant or if the partner is removed from the redundancy link.

### Consequence of inaction

No impact.

### Corrective actions

This notification returns to normal if the controller is subsequently configured as redundant or if the partner is removed from the redundancy link.

### Time to respond

As soon as possible.

---

## DIAG - Verify Lost

### **Potential causes**

Actual state of the output does not match the commanded state.

### **Consequence of inaction**

Loss of control. The commanded-output state is changed and the actual input PVstate does not change accordingly

### **Corrective actions**

Check the field device.

### **Time to respond**

Immediate.



---

## DIAG - Watchdog Timer Error

**Potential causes**

Sensor Watchdog Timeout. The processor was restarted due to unexpected operation.

**Consequence of inaction**

Device will be reset.

**Corrective actions**

Clear by warm restart of device. If condition persists contact Honeywell Technical Assistance Center for support.

**Time to respond**

---

## DIAG - WDT Refresh Warning

Applies to FIM4, FIM8, C300, and PGM.

### **Potential causes**

The watchdog timer is being refreshed at a rate that is outside acceptable limits. Or the watchdog timer is being refreshed late, but not late enough for it to expire.

### **Consequence of inaction**

Task health monitoring will be disturbed.

### **Corrective actions**

The system CPU usage needs to be reduced if the statistics show very high CPU usage or CPU Overruns. If the CPU usage is reasonable then contact the Honeywell Technical Assistance Center (TAC) for support.

### **Time to respond**

As soon as possible.

---

## DIAG - Wire off Detected

**Potential causes**

Absence of a field wire (sensor/actuator) or the break in field wiring.

**Consequence of inaction**

1. Break in field wiring.
2. Loss of data from field and hence control.

**Corrective actions**

Check the field wiring and replace field wire if worn.

**Time to respond**

Immediate.



# Duplicate Point system alarms

The following topics describe duplicate point-related system alarms and how to respond to them.

## **Related topics**

“Duplicate Point - message/alarm/alert from con <server name> is on a point which is a duplicate of an existing point from con <server name>” on page 270

---

## **Duplicate Point - message/alarm/alert from con <server name> is on a point which is a duplicate of an existing point from con <server name>**

### **Potential causes**

The local server has notified that two points on different DSA servers have the same item name. The local server has received a point alarm from a DSA server. However, a point of the same name (that references another DSA server), already exists in the system.

### **Consequence of inaction**

Notifications from the duplicate point on the DSA server will not be processed and displayed on this DSA subscriber. Notifications on the existing point will be shown as expected on this DSA subscriber.

### **Corrective actions**

- 1 Change the 'item name' of one of the duplicate points. For more information, see the "Requirements for implementing a DSA system" topic.
- 2 For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation. For more information, see the "Creating a diagnostic package for TAC" topic.

### **Time to respond**

The corrective action should be initiated immediately to allow alarms from the duplicate point to be seen on this DSA subscriber, especially if operators on this DSA subscriber are responsible for monitoring and control of this point.

# EVTARC system alarms

The following topics describe event archiving-related system alarms and how to respond to them.

## **Related topics**

“EVTARC - Event Archive Initialization Failed” on page 272

“EVTARC - Invalid archive directory” on page 273

---

## EVTARC - Event Archive Initialization Failed

### Potential causes

The event archiving task has failed to start.

### Consequence of inaction

Cannot create an event archive.

### Corrective actions

- Call up the **Event Archiving Operations** display.
- For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

Immediate.



---

## EVTARC - Invalid archive directory

### Potential causes

The event archiving task cannot write to the folder because:

- The specified folder does not exist; or
- Experion does not have permission to write to the specified folder

### Consequence of inaction

Cannot create an event archive.

### Corrective actions

- Call up the **Event Archiving Configuration** display. Ensure that a valid folder is specified in **Create archive in directory**.
- Allow the MNGR account to write to the specified folder.

### Time to respond

Immediate.



# HSTARC system alarms

The following topics describe history archiving-related system alarms and how to respond to them.

## **Related topics**

“HSTARC - Disk Full Error” on page 276

“HSTARC - Invalid Pathname For Move” on page 277

“HSTARC - Permission Error” on page 278

---

## HSTARC - Disk Full Error

**Potential causes**

The drive where history archives are to be moved to does not have enough free space or an error when copying the history archives to the Location to Move.

**Consequence of inaction**

History archive files not moved. The result is that the drive on which the Experion history archives are stored may become full.

**Corrective actions**

1. Call up the **History Archiving** display.
2. Check that the History Archiving Disk Limit is configured appropriately.
3. Check that the “Location to Move History Archive to” exists and has enough free space.

For more information, see “Configuring history archives”.

**Time to respond**

As soon as possible before next history archive management run time (default 7:43AM every day), in case disk runs out of space.

---

## HSTARC - Invalid Pathname For Move

**Potential causes**

The history archive folder could not be created.

**Consequence of inaction**

History archive files have not been moved. The drive on which the history archives are stored may fill up (reducing free space).

**Corrective actions**

1. Call up the **History Archiving** display.
2. Check that the “Location to Move History Archive to” is a valid location.

**Time to respond**

As soon as possible before next history archive management run time (default 7:43AM every day), in case disk runs out of space.

---

## HSTARC - Permission Error

### Potential causes

The history archive folder could not be created.

### Consequence of inaction

History archive files have not been moved. The drive on which the history archives are stored may fill up (reducing free space).

### Corrective actions

1. Call up the **History Archiving** display.
2. Check that the “Location to Move History Archive to” exists and has enough free space.
3. Check that the MNGR user has permission to create files and directories and write to the “Location to Move History Archive to” folder.

### Time to respond

As soon as possible before next history archive management run time (default 7:43AM every day), in case disk runs out of space.

# LNK nn system alarms

The following topics describe link-related system alarms and how to respond to them.

## **Related topics**

“LNK nn - Cntrl Stream Upgraded” on page 280

“LNK nn - Peer Server Host Name Cannot Be Resolved” on page 281

---

## LNK nn - Cntrl Stream Upgraded

**Potential causes**

Server Redundancy network link control stream has been upgraded to a data stream due to change in link availability.

**Consequence of inaction**

Servers will remain out of synchronization, so the backup server database will not be updated with the changes on the primary (including point configuration, history, events, etc.) and some automatic failover actions will not be triggered.

**Corrective actions**

Resynchronize the backup and primary servers. For more information, see “.”

**Time to respond**

The time to respond will depend on availability of other Link (if configured) and an assessment of process/site/operations for criticality/risk of losing synchronization between Servers.



---

## LNK nn - Peer Server Host Name Cannot Be Resolved

### Potential causes

Hosts File is not configured correctly on Servers. Host naming rules have not been followed for redundant servers.

### Consequence of inaction

Link will become unavailable for redundancy. If only one link configured, or both links unavailable, then it shall not be possible to synchronize the servers.

### Corrective actions

1. Acknowledge the alarm.
2. Investigate why the backup server is not operational. Start the backup server and make sure that it is connected to the network.
3. Correct the hosts file on both servers.
4. Verify communications between the Servers using 'ping' command or accessing network shares.
5. Verify that link has been restored on Redundancy Status display, and then resynchronize the backup and primary servers. For more information, see “.”

### Time to respond

The time to respond will depend on availability of other Link (if configured) and an assessment of process/site/operations for criticality/risk of losing synchronization between Servers.



# No condition system alarms

The following topics describe No condition system alarms and how to respond to them.

## **Related topics**

“Asset Electronic Signature” on page 284

“CStnxx: Server Is Not Available” on page 285

“Disk Space Low: Deleting Old Archives” on page 286

“Disk Space Low: Suspending Event Collection” on page 287

“Event Archiving Reset Failed” on page 288

“Event File Error” on page 289

“Failed logon attempt” on page 290

---

## Asset Electronic Signature

### **Potential causes**

The Electronic Signatures for an asset has been enabled or disabled.

### **Consequence of inaction**

Is an information alarm.

### **Corrective actions**

To enable or disable Electronic Signatures for an asset click the link on the **Electronic Signatures General** display.

### **Time to respond**

There is no recommended response time. However, the amount of time taken to respond varies on whether any corrective action is taken and the type of corrective action.

---

## CStnxx: Server Is Not Available

### Potential causes

The numbered Console station has notified that it has lost contact with the server.

### Consequence of inaction

At minimum, this alarm signifies the loss of view to non-direct data on the Console Station. At worst, this alarm signifies complete loss of view on the Console Station.

### Corrective actions

Check that the Console Station is powered up and connected to the Experion server.

Check the status of the Console Station on the **Console Station Status Detail** display. You can view a detailed status by clicking the down arrow next to **Show details**, and check that all components are OK.

In the case of a network failure, check that the network connection between the server and the Console Station is operational.

### Time to respond

Immediate.

## Disk Space Low: Deleting Old Archives

### Potential causes

The server event manager has notified that the server event buffer is full.

### Consequence of inaction

New events could be lost.

### Corrective actions

Move old event archives to another disk and delete them from the original disk, or increase the disk size.

- 1 Choose **View > Events > Event Archiving**.




Figure 1: Event Archiving Status Display

- 2 You can now:
  - a Archive the events by clicking the **Archive Now** button.
  - b Check for tampering of event records.
  - c Restore archived events by clicking the **Restore** button.
  - d Remove restored archives by clicking the **Remove** button. The **Remove** button appears when you have restored archives.
  - e View the status of events collection and archiving.

### Time to respond

Within 24 hours.

---

## Disk Space Low: Suspending Event Collection

**Potential causes**

The server event manager is unable to determine free disk space, or disk space is less than configured limit.

**Consequence of inaction**

New events could be lost.

**Corrective actions**

1. Call up the **Event Archiving Operations** display.
2. Check disk integrity, archive old events, or increase event disk limit.

**Time to respond**

Immediate.

---

## Event Archiving Reset Failed

### Potential causes

The event archiving reset stored procedure failed to run. Can be caused by various factors.

### Consequence of inaction

New events could be lost.

### Corrective actions

- Call up the **Event Archiving Operations** display.
- For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

Immediate.



---

## Event File Error

### Potential causes

The server event manager failed to journal an event to the SQL database.

### Consequence of inaction

New events could be lost.

### Corrective actions

- Call up the **Event Archiving Operations** display.
- For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

Approximately 2 hours.

---

## Failed logon attempt

### Potential causes

The logon failed, which could be due to one of the following causes:

1. Operator or Group not configured in Experion.
2. Operator or Group disabled in Experion.
3. Operator disabled in Windows.
4. Incorrect password.
5. Windows domain controller(s) is offline.
6. Experion Operator Management Service not running under an appropriate account.

### Consequence of inaction

Is an informational alarm.

If this alarm is received frequently, it could indicate attempted unauthorized use of the system and should be investigated.

### Corrective actions

1. Configure the Operator/Group in Experion.
2. Enable the Operator/Group in Experion.
3. Enable the Operator in Windows.
4. Use the correct password.
5. Bring the Windows domain controller(s) online.
6. Run the:
  - Operator Management Service with an account that has appropriate permissions.
  - Operator Management Service on all nodes.

### Time to respond

There is no recommended response time. However, the amount of time taken to respond varies on whether any corrective action is taken and the type of corrective action.

# NULL system alarms

The following topics describe NULL-related system alarms and how to respond to them.

## **Related topics**

“NULL - Console Fail” on page 292

“NULL - Console Marginal” on page 293

“NULL - Console Station Is Not Available” on page 294

---

## NULL - Console Fail

### **Potential causes**

The server has lost communication with every Console Station and Console Station Extension in a Console. Note that this alarm can be configured. See “Configuring system alarm priorities”.

### **Consequence of inaction**

This alarm signifies that view has been lost on every Station in the Console.

### **Corrective actions**

Check that the Console is powered up and connected to the Experion Server.

Check that Station is running on each Console Station and each Console Extension Station in the cluster, and that each of these Station instances is connected.

For more information, see “Lost contact with a Console Station”.

### **Time to respond**

Immediately.

---

## NULL - Console Marginal

**Potential causes**

The server has lost communication with one or more Console Stations or Console Station Extensions in a Console.

Note that this alarm can be configured. For more information, see “Configuring system alarm priorities”.

**Consequence of inaction**

This alarm signifies that view has been lost on at least one Station, but that view is maintained on at least one other Station. If view is subsequently lost on other Stations, it might be the case that other Stations in the cluster have also lost view, and the Console Fail alarm will be raised.

**Corrective actions**

Check that the Console or Console Station Extension is powered up and connected to the Experion Server.

Check that Station is running on each Console Station and each Console Extension Station in the cluster, and that each of these Station instances is connected.

For more information, see “Lost contact with a Console Station”.

**Time to respond**

It depends on whether a failure happens on another Station in the cluster.

---

## NULL - Console Station Is Not Available

### **Potential causes**

The server has lost communication with a Console Station.

Note that this alarm can be configured. For more information, see “Configuring system alarm priorities”.

### **Consequence of inaction**

At minimum, this alarm signifies the loss of view to non-direct data on the Console Station. At worst, this alarm signifies complete loss of view on the Console Station.

### **Corrective actions**

Check that the Console is powered up and connected to the Experion Server. For more information, see “Lost contact with a Console Station”.

### **Time to respond**

Immediate.

# ORPHANS system alarms

The following topics describe orphan activity-related system alarms and how to respond to them.

## **Related topics**

“ORPHANS - Orphan Activities Detected” on page 296

---

## ORPHANS - Orphan Activities Detected

### Potential causes

A child activity has been created on the server and the parent activity does not exist on that server, possibly due to one of the following:

1. If inter-cluster peer to peer is being used so that the parent and child activities are in different clusters, but the 2 cluster servers are not configured for DSA Alarms and Data.
2. The CEE containing the parent activity has been set to IDLE, while the CEE containing the child activity is still running.

### Consequence of inaction

The child (orphan) activity will continue to run until it has reached a terminal state. The activity will then remain in the controller until it is manually removed by an operator. This may have an impact on the overall result of an batch.

### Corrective actions

1. Investigate why the parent activity could not be resolved on the server.
2. If the parents cannot be resolved, navigate to the **Orphan Activity Summary** display by double clicking on the alarm, and then manually remove any orphan activities.

### Time to respond

Depends on the configuration of the recipe.

Note that only one alarm is raised regardless of the number of orphan activities found.



# OTHER system alarms

The following topics describe the OTHER system alarm types and how to respond to them.

## Related topics

- “OTHER - Duplicate IOL Address” on page 298
- “OTHER - IOL Channel A Failure” on page 299
- “OTHER - IOL Channel B Failure” on page 300
- “OTHER - IOL Maximum Errors Exceeded” on page 301
- “OTHER - IOL Pre-fetch Alarm Overruns” on page 302
- “OTHER - IOL Process Data Cycle Overruns” on page 303
- “OTHER - IOL Processor, Diagnostic Cycle Overflow” on page 304
- “OTHER - IOL Processor Diagnostic Exceeded Time Threshold” on page 305
- “OTHER - IOL Processor Diagnostic Failed To Complete” on page 306
- “OTHER - IOL Processor, Diagnostic Initiation Timeout” on page 307
- “OTHER - IOL Processor, Resumption Of Non-Wait Task” on page 308
- “OTHER - IOL Processor Stack Limit Overflow” on page 309
- “OTHER - IOL Processor Unknown SF” on page 310
- “OTHER - Not Active Supervisor” on page 311
- “OTHER - Partner I/F Mismatch on IOL” on page 312
- “OTHER - Partner I/F Not Visible On IOL” on page 313

---

## OTHER - Duplicate IOL Address

Applies to IOLINK.

### **Potential causes**

A duplicate IOLink address has been detected.

### **Consequence of inaction**

May result in "Not Active Supervisor" alarm, one of those module may not be recognized by controller.

### **Corrective actions**

Check the secondary IO Modules for correct physical address.

### **Time to respond**

Immediate.

---

## OTHER - IOL Channel A Failure

Applies to IOLINK.

### Potential causes

This alarm is raised when there are cable errors are present.

### Consequence of inaction

Loss of communication with IOPs.

### Corrective actions

1. Check IOLINK cable A from end to end for proper connections.
2. Check the cable connectors at the IOTAs and fix as needed.
3. Refer to the IOLINK Statistics for the error counts to zero in on the suspect link (primary IOLINK, secondary IOLINK, or IOMs) and replace if necessary.

Once a problem has been identified and a fix is applied. To verify the fix:

- a. Reset the error counts via the I/O Link Command "RESET\_ERRORS" from the Main Tab.
- b. Re-enable the Periodic Cable Swap diagnostic via the I/O Link Command "ENB\_PERSWAP" from the Main Tab.
- c. Wait about 2-3 minutes for the alarm to return to normal, otherwise, monitor the error counts and if they are still accumulating, call the Honeywell SSC for support.

### Time to respond

Immediate.

---

## OTHER - IOL Channel B Failure

Applies to IOLINK.

### Potential causes

This alarm is raised when there are cable errors are present.

### Consequence of inaction

Loss of communication with IOPs.

### Corrective actions

1. Check IOLINK cable A from end to end for proper connections.
2. Check the cable connectors at the IOTAs and fix as needed.
3. Refer to the IOLINK Statistics for the error counts to zero in on the suspect link (primary IOLINK, secondary IOLINK, or IOMs) and replace if necessary.

Once a problem has been identified and a fix is applied. To verify the fix:

- a. Reset the error counts via the I/O Link Command "RESET\_ERRORS" from the Main Tab.
- b. Re-enable the Periodic Cable Swap diagnostic via the I/O Link Command "ENB\_PERSWAP" from the Main Tab.
- c. Wait about 2-3 minutes for the alarm to return to normal, otherwise, monitor the error counts and if they are still accumulating, call the Honeywell SSC for support.

### Time to respond

Immediate.

---

## OTHER - IOL Maximum Errors Exceeded

Applies to IOLINK.

### **Potential causes**

The number of IOL Communication and Silence Errors exceeds the MAX limit.

### **Consequence of inaction**

Loss of communication with IOPs.

### **Corrective actions**

Channel A and Channel B errors need to be addressed.

### **Time to respond**

Immediate.

---

## OTHER - IOL Pre-fetch Alarm Overruns

Applies to C300 and IOLIM.

### Potential causes

IO Link reports pre-fetch overrun alarm if the C300 Controller's CPU or IOLINK is heavily loaded. This alarm indicates that the C300 Controller is not able to scan input data from the Priority IOMs in a timely manner.

### Consequence of inaction

End-to-end response times may be larger than expected.

### Corrective actions

If this diagnostic alarm is reported, perform the following actions which may allow recovery:

1. Reconfigure the CMs PHASE to balance the output writes across multiple different phases.
2. Redistribute IOMs between the two IO Links.

### Time to respond

ASAP if the alarm persists

If the alarm appears and then returns to normal as a result of a temporary condition such as a checkpoint restore, an IOM load/reload, or an IOM swap over, then it can be ignored.

---

## OTHER - IOL Process Data Cycle Overruns

Applies to IOLINK.

### **Potential causes**

PV scanning from the IOM or IOMs was not completed within the IOM scan rate timeframe.

### **Consequence of inaction**

Increase in response time.

### **Corrective actions**

Reduce the IOM's scan rate or the execution period of the Control Modules containing connections to IO Channels.

### **Time to respond**

As soon as possible.

---

## OTHER - IOL Processor, Diagnostic Cycle Overflow

Applies to C300 and IOLIM.

### **Potential causes**

Internal IOLINK Communication Daughter Card diagnostic detected an internal fault.

### **Consequence of inaction**

Possible loss of communication with the IO.

### **Corrective actions**

Call Honeywell SSC.

### **Time to respond**

As soon as possible.



---

## OTHER - IOL Processor Diagnostic Exceeded Time Threshold

Applies to IOLINK.

**Potential causes**

The time allotted for the incremental internal diagnostic has been exceeded.

**Consequence of inaction**

The UM51 diagnostic may fail.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

Immediate.

---

## OTHER - IOL Processor Diagnostic Failed To Complete

Applies to IOLINK.

### **Potential causes**

The diagnostic task failed to finish.

### **Consequence of inaction**

The hardware may function improperly as at least one of the diagnostics failed to complete.

### **Corrective actions**

Call Honeywell SSC.

### **Time to respond**

Immediate.

---

## OTHER - IOL Processor, Diagnostic Initiation Timeout

Applies to C300 and IOLIM.

**Potential causes**

Internal IOLINK Communication Daughter Card diagnostic detected an internal fault.

**Consequence of inaction**

Possible loss of communication with the IO.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

As soon as possible.

---

## OTHER - IOL Processor, Resumption Of Non-Wait Task

Applies to C300 and IOLIM.

**Potential causes**

Internal IOLINK Communication Daughter Card diagnostic detected an internal fault..

**Consequence of inaction**

Possible loss of communication with the IO.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

As soon as possible.

---

## OTHER - IOL Processor Stack Limit Overflow

Applies to C300 and IOLIM.

**Potential causes**

Internal IOLINK Communication Daughter Card diagnostic detected an internal fault.

**Consequence of inaction**

Possible loss of communication with the IO.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

As soon as possible.

---

## OTHER - IOL Processor Unknown SF

Applies to C300 and IOLIM.

**Potential causes**

Internal IOLINK Communication Daughter Card diagnostic detected an internal fault.

**Consequence of inaction**

Possible loss of communication with the IO.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

As soon as possible.

---

## OTHER - Not Active Supervisor

Applies to IOLINK.

### **Potential causes**

The IOL interface daughter card could not transition into the active supervisor role. Generally this is caused by a partner IOLINK with a conflicting IOLINK Address.

### **Consequence of inaction**

Loss of communication with the IO modules.

### **Corrective actions**

See .

### **Time to respond**

As soon as possible.

---

## OTHER - Partner I/F Mismatch on IOL

Applies to IOLIM and C300.

### **Potential causes**

Only occurs in redundant configurations. The IOLINK cables from the primary (IOLIM/C300) are not connected to the correct controller or the correct Link number (in case of C300 Only).

### **Consequence of inaction**

Loss of controller redundancy.

### **Corrective actions**

Make sure the IOLINK cables are connected to the correct pair.

In case of C300 only, make sure that the cable from IOLINK1 and IOLINK2 of the primary are connected to IOLINK1 and IOLINK2 of the secondary, respectively.

### **Time to respond**

As soon as possible.



---

## OTHER - Partner I/F Not Visible On IOL

Applies to IOLINK.

**Potential causes**

The Primary IOLINK is unable to view it's redundant partner across the I/O Link.

**Consequence of inaction**

Loss of redundancy.

**Corrective actions**

Call Honeywell SSC.

**Time to respond**

As soon as possible.



# Replication system alarms

The following topics describe replication-related system alarms and how to respond to them.

## **Related topics**

“Replication - Events Database Replication Failed” on page 316

“Replication <replication number> failed” on page 317

---

## Replication - Events Database Replication Failed

### Potential causes

Redundancy replication of the Events database has failed. Can be caused by various factors.

### Consequence of inaction

Events that are collected on the primary server are not journaled on the backup. If the primary server subsequently fails, these events will be lost.

### Corrective actions

- Call up the **Event Archiving Operations** display.
- For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

If this alarm is raised, then events will not be journaled on the backup. This should be addressed in case the primary server fails.

---

## Replication <replication number> failed

### Potential causes

File replication did not replicate to all destinations.

### Consequence of inaction

Files on some computers will not be updated.

### Corrective actions

- 1 Call up the **File Replication Settings** display.
- 2 Click **View Report**.  
The file replication report for further detail on the cause of failure.
- 3 Check that the replication destination computers are online and available.

### Time to respond

Immediately.



# Scripting system alarms

The following topics describe scripting-related system alarms and how to respond to them.

## **Related topics**

“Scripting - Script Engine Error” on page 320

---

## Scripting - Script Engine Error

### Potential causes

An undefined error has occurred with a script engine. It may be due to syntax, runtime or a timeout error.

### Consequence of inaction

This alarm can be seen under the following scenarios:

1. There is a system failure in the script engine. If this happens then no scripts will run in the failed script engine.
2. There is a run time error in a script. If this happens the erroneous script will be disabled, but other scripts in the script engine will continue to execute.

### Corrective actions

1. Call up the **Script Engines** display. This will identify which script engine is in error.
2. Examine the server log to identify which script engine is in error and what kind of error is it.
3. Debug and test the script so the problem no longer occurs.

### Time to respond

Immediate.



# Series C and Process Manager I/O System Alarms

The following topics describe the Series C Process Manager I/O system alarms and how to respond to them.

## Related topics

- “A/D Conversion Data Overflow - 5v Supply to Application board failure” on page 324
- “A/D Conversion Data Overflow - A/D Conversion Data Overflow” on page 325
- “A/D Conversion Incomplete - A/D Conversion Incomplete” on page 326
- “ADC Register Write Failure - ADC Register Write Failure” on page 327
- “ADC Supply Voltage Failure - ADC Supply Voltage failure” on page 328
- “ADOUTUDF\_042 - ADC VALUE UNDERFLOW(APPLY TO DATA I/P'S)” on page 329
- “ADPCOMFL\_027 - NO COM TO ADP OR OTHER MICRO PROCSR AM” on page 330
- “ADRAMADR\_01 - ADP PRIVATE RAM ADDRESSING FAILURE” on page 331
- “ADRAMCNT\_011 - ADP PRIVATE RAM CONTENTS FAILURE” on page 332
- “ADROMERR\_016 - ADP EPROM CHECKSUM FAILURE” on page 333
- “ADSTRUP\_018 - ADP START UP FAILURE” on page 334
- “AI Channel Not Calibrated - AI IOM is out of calibration” on page 335
- “AO Channel Not Calibrated - AO IOM is out of calibration” on page 336
- “AO Channel Not Calibrated - SVP-IOM/SP-IOM AO channels not calibrated” on page 337
- “BADADPER\_017 - BAD ERROR CODE DETECTED IN ADP” on page 338
- “BADADPJP\_034 - BAD BRANCH TAKEN IN ADP ROM EXECUTION” on page 339
- “BADCALRF\_039 - CALIBRATION REFERENCE OUTSIDE LIMITS” on page 340
- “BADFLREG\_044 - AO FAILURE SELECTION REGISTER IS BAD” on page 341
- “BADPLUGM\_029 - BAD PLUG-IN MODULE IN FTA” on page 342
- “BADRESUM\_003 - RESUME OF NON-WAITING TASK” on page 343
- “BADRJVAL\_033 - REFERENCE JUNCTION VALUE BAD” on page 344
- “BADSECRG\_022 - SECONDARY REGULATOR NOT OK” on page 345
- “BDOUTBFR\_046 - Bad Output Buffer” on page 346
- “BDSNDLTC\_045 - Bad Secondary Latch” on page 347
- “CABLE DISCONNECT, RTP - No RTP connection” on page 348
- “CALBABRT\_038 - CALIBRATION SEQUENCE ABORTED” on page 349
- “Channel Not Field Calibrated - SVP-IOM/SP-IOM Channel not field calibrated” on page 350
- “Cold Start - Device Cold Start” on page 351
- “COMMS - No IOLP access to shared RAM” on page 352
- “Configuration Changed - Device Configuration Changed” on page 353
- “Device Malfunction - Field Device Malfunction” on page 354
- “DIAGCTFL\_026 - AI Input-Output loopback failure” on page 355
- “DIAGCTFL\_026 - DI Input-Output loopback failure” on page 356
- “DIAGCTFL\_026 - IOM diagnostic circuit failure” on page 357
- “DIAGOFLO\_005 - ENTIRE DIAG CYCLE OVERFLOW” on page 358

“DIAGTMOT\_004 - ONE DIAG INITIATION TIMED OUT” on page 359  
 “DO Relay Extn Board Missing - Relay Extension Board Missing” on page 360  
 “DTPATHFL\_069 - DATA PATH FAILURE” on page 361  
 “DTPATHTO\_070 - DATA PATH TIME OUT” on page 362  
 “EECKSMER\_007 - EEPROM CHKSUM ERROR” on page 363  
 “EECNTERR\_008 - EEPROM counter error - too many writes” on page 364  
 “EEFAILED\_040- EEPROM UPDATE FAILED DUE TO EEPROM BUSY” on page 365  
 “EEFLAGER\_009 - EEPROM INCOMPLETION ERROR” on page 366  
 “Feedback Inputs failure - Resolver Feedback Inputs Failure” on page 367  
 “FTA 1 Calibration Failure - FTA 1 CALIBRATION FAIL” on page 368  
 “FTA1 Comm Failure - FTA 1 COMMUNICATION FAIL” on page 369  
 “FTA 1 Fail - LLMUX FTA1 HAS A FAILURE” on page 370  
 “FTA 1 Identification Error - FTA 1 IDENT ERROR” on page 371  
 “FTA1 Not Calibrated - FTA 1 IS NOT CALIBRATED” on page 372  
 “FTA 1 Ref Voltage Failure - FTA 2 VREF FAIL” on page 373  
 “FTA 2 Calibration Failure - FTA 3 CALIBRATION FAIL” on page 374  
 “FTA 2 Comm Failure - FTA 2 COMMUNICATION FAIL” on page 375  
 “FTA2 Fail - LLMUX FTA2 HAS A FAILURE” on page 376  
 “FTA 2 Identification Error - FTA 2 IDENT ERROR” on page 377  
 “FTA 2 Not Calibrated - FTA 2 IS NOT CALIBRATED” on page 378  
 “FTA 2 Ref Voltage Failure - FTA 2 VREF FAIL” on page 379  
 “FTA 3 Calibration Failure - FTA 3 CALIBRATION FAIL” on page 380  
 “FTA 3 Comm Failure - FTA 3 communication failure” on page 381  
 “FTA 3 Fail - AI-MUX FTA3 HAS A FAILURE” on page 382  
 “FTA 3 Identification Failure - FTA 3 identification failure” on page 383  
 “FTA 3 Not Calibrated - FTA 3 IS NOT CALIBRATED” on page 384  
 “FTA 3 Ref Voltage Failure - FTA 3 reference voltage failure” on page 385  
 “FTA 4 Calibration Failure - FTA 4 CALIBRATION FAIL” on page 386  
 “FTA 4 Comm Failure - FTA 4 communication failure” on page 387  
 “FTA4 Fail - AI-MUX FTA4 HAS A FAILURE” on page 388  
 “FTA 4 Identification Error - FTA 4 identification failure” on page 389  
 “FTA 4 Not Calibrated - FTA 4 IS NOT CALIBRATED” on page 390  
 “FTA 4 Ref Voltage Failure - FTA 4 reference voltage failure” on page 391  
 “FTA Power Failure - FTA Power Failure” on page 392  
 “FTAMISSG\_006 - FTA or power adapter missing” on page 393  
 “FTAMSMCH\_031 - FTA type mismatch with point configuration” on page 394  
 “HART Comm Failure - HART Communication Fail” on page 395  
 “HART Diagnostic Underrun - HART PROCESSOR DIAGNOSTIC TASK UNDER-RUN” on page 396  
 “HART Modem 1 Error - HART hardware error detected against DUART channel 1 or modem 1” on page 397  
 “HART Modem 2 Error - HART hardware error detected against DUART channel 2 or modem 2” on page 398  
 “HART Modem 3 Error - HART hardware error detected against DUART channel 3 or modem 3” on page 399  
 “HART Modem 4 Error - HART hardware error detected against DUART channel 4 or modem 4” on page 400  
 “HART Stack High - HSTACKHI” on page 401  
 “HWFIFOFL\_064 - HARDWARE FIFO FAILURE ” on page 402  
 “INPTFAIL\_021 - INPUT POINT FAILURE ” on page 403  
 “IOL Address Diag Failure - IOL Address Diag Failure” on page 404  
 “IOM or IOTA HART Chan Failure - IOM or IOTA HART Channel Failure” on page 405  
 “IOPSWITCHOVER - IOP Switchover Occurred” on page 406

“LOSTSYNC\_058 - LOSTSYNC” on page 407  
 “LVDT Core Fallout - LVDT Core Fallout” on page 408  
 “MBCHKMER\_015 - MBCHKMER” on page 409  
 “MBRAMADR\_014 - MBRAMADR” on page 410  
 “MBRAMCNT\_013 - MBRAMCNT” on page 411  
 “MLTINPFL\_060 - MLTINPFL” on page 412  
 “Module Not Calibrated - ADC OUT OF CALIBRATION” on page 413  
 “More Status Available - More Status Available” on page 414  
 “No Response” on page 415  
 “NOACLINE\_028 - NOACLINE” on page 416  
 “NTUSED62\_062 - Data bus failure” on page 417  
 “OP Fail in Circuit/Field Wire - Failure in output circuit/field wiring detected by AO or DO” on page 418  
 “Open Wire Detected - Open wire/sensor detected” on page 419  
 “Output Short Circuit Detected - DO channel detected a short circuit or over current situation” on page 420  
 “PIFAULTY\_072 - FIELDBUS - FAULTY personality image” on page 421  
 “PRVRAMFL\_065 - Private RAM diagnostic failed” on page 422  
 “PV Out of Limits - Primary Variable Out Of Limits” on page 423  
 “PVVALDFL\_067 - PV validation diagnostic failed” on page 424  
 “Readback Register Diag Failure - Readback Register Diagnostic Failure” on page 425  
 “REDNDIAG\_061 - REDNDIAG” on page 426  
 “Redundancy Hardware Failure - Redundancy Hardware Failure” on page 427  
 “REQOFLOW\_002 - IOP task request overflow - excessive IOL activity” on page 428  
 “SCANORUN\_019 - SCANORUN” on page 429  
 “Servo Current Driver Shutdown - Servo Current Driver Shutdown” on page 430  
 “SOECLKFL\_066 - SOECLKFL” on page 431  
 “SOECNTFL\_068 - SOECNTFL” on page 432  
 “Speed Channel - No Pulse Input - Speed Channel - No Pulse Detected” on page 433  
 “Speed RCAP Ref Clock Failure - Speed RCAP Ref Clock Failure” on page 434  
 “STCKLIM\_024 - STCKLIM” on page 435  
 “STCOVRUN\_001 - Sample time clock overrun” on page 436  
 “STMACHFL\_071 - STMACHFL” on page 437  
 “SupIna - Not Active Supervisor” on page 438  
 “Uncertain Pulse Input - Uncertain Pulse Input” on page 439  
 “Unstable Input - Resolver Unstable Input” on page 440  
 “Variable Out Of Limits - Non-Primary Variable Out Of Limits” on page 441  
 “VDT ADC Selection Failure - LVDT ADC Channel Selection Failure” on page 442  
 “VDT Critical Signal Failure - LVDT Channel Critical Signal Failure” on page 443  
 “VDT Exctn Freq Drift - LVDT Excitation Frequency Drift Greater than 100Hz” on page 444  
 “VDT Extn Volt Out of Range - LVDT Excitation Voltage out of calibrated Range” on page 445  
 “VDT Fb A Volt Out of Range - LVDT Feedback Channel A Voltage out of calibrated Range” on page 446  
 “VDT Fb B Volt Out of Range - LVDT Feedback Channel B Voltage out of calibrated Range” on page 447  
 “VREFFAIL\_041 - Reference voltage out of range” on page 448  
 “VTESTFAI\_030 - VTESTFAI” on page 449  
 “VZERO\_FL\_032 - VZERO\_FL” on page 450  
 “WRITENBL\_059 - WRITENBL” on page 451  
 “WRONG\_HW\_063 - WRONG\_HW” on page 452

---

## A/D Conversion Data Overflow - 5v Supply to Application board failure

### Potential causes

Overflow bit is ON in the received analog input channel data.

### Consequence of inaction

The PV is set to NaN for that particular Analog Input Channel.

### Corrective actions

1. In the case of non-redundant, there is a loss of view for the affected channel.
2. In the case of redundant, control goes to HEALTHY and SYNCHRONIZED PARTNER.

### Time to respond

Immediate.

---

## A/D Conversion Data Overflow - A/D Conversion Data Overflow

### **Potential causes**

Overflow bit is ON in the received analog input channel data.

### **Consequence of inaction**

The PV is set to NaN for that particular analog input channel.

### **Corrective actions**

1. If non-redundant, there is a loss of view for the affected channel.
2. If redundant, control goes to HEALTHY and SYNCHRONIZED PARTNER.

### **Time to respond**

Immediate.

---

## A/D Conversion Incomplete - A/D Conversion Incomplete

### **Potential causes**

Analog to digital conversion of the input channel is incomplete.

### **Consequence of inaction**

The PV is set to NaN for that particular analog input channel.

### **Corrective actions**

1. If non-redundant, there is a loss of view for the affected channel.
2. If redundant, control goes to HEALTHY and SYNCHRONIZED PARTNER.

### **Time to respond**

Immediate.

---

## ADC Register Write Failure - ADC Register Write Failure

### **Potential causes**

ADC register write command failed.

### **Consequence of inaction**

ADC SPI Interface is not working properly.

### **Corrective actions**

Replace the AI IOM.

### **Time to respond**

If non-redundant, replace immediately, otherwise replace within 8 to 24 hours.

---

## ADC Supply Voltage Failure - ADC Supply Voltage failure

### **Potential causes**

ADC chip is not working 100% efficiently.

### **Consequence of inaction**

Replace the AI IOM.

### **Corrective actions**

Replace the AI IOM.

### **Time to respond**

If non-redundant, replace immediately, otherwise replace within 8 to 24 hours.



---

## ADOUTUDF\_042 - ADC VALUE UNDERFLOW(APPLY TO DATA I/P'S)

### **Potential causes**

A/D slot conversion on AIM slot underflowed minimum allowed count (HLAI only).

### **Consequence of inaction**

The device connected to that slot will no longer be under Experion control.

### **Corrective actions**

Power cycle the I/O module and if the alarm persists then replace the I/O module.

### **Time to respond**

Immediate.

---

## ADPCOMFL\_027 - NO COM TO ADP OR OTHER MICRO PROCSR AM

### **Potential causes**

Communication with ADP or other microprocessor is lost.

### **Consequence of inaction**

Analog to digital conversion process by ADP processor halts.

### **Corrective actions**

Replace IOP card.

### **Time to respond**

Immediate.

---

## ADRAMADR\_01 - ADP PRIVATE RAM ADDRESSING FAILURE

### **Potential causes**

ADP private RAM addressing failed.

### **Consequence of inaction**

Analog to digital conversion process by ADP processor halts.

### **Corrective actions**

Replace IOP card.

### **Time to respond**

Immediate.

---

## ADRAMCNT\_011 - ADP PRIVATE RAM CONTENTS FAILURE

### **Potential causes**

ADP (Analog to Digital Processor) private RAM contents error.

### **Consequence of inaction**

Analog to digital conversion process by ADP processor halts.

### **Corrective actions**

Replace IOP card.

### **Time to respond**

Immediate.

---

## ADROMERR\_016 - ADP EPROM CHECKSUM FAILURE

### Potential causes

ADP EPROM checksum failure.

### Consequence of inaction

Analog to digital conversion process by ADP processor halts.

### Corrective actions

Replace IOP card.

### Time to respond

Immediate.

---

## ADSTRUP\_018 - ADP START UP FAILURE

### **Potential causes**

ADP startup failure.

### **Consequence of inaction**

Analog to digital conversion process can no longer be performed as ADP is not started.

### **Corrective actions**

Replace IOP card.

### **Time to respond**

Immediate.

---

## AI Channel Not Calibrated - AI IOM is out of calibration

### **Potential causes**

If the IOMs are out of calibration and the measured/output value of these modules will not be accurate.

### **Consequence of inaction**

Measured/output value of these IOM/IOP will not be accurate.

### **Corrective actions**

Field calibration of these IOM/IOP needs to be performed.

### **Time to respond**

Immediately.

---

## AO Channel Not Calibrated - AO IOM is out of calibration

### **Potential causes**

If the IOMs are out of calibration, the measured/output value of these modules won't be accurate.

### **Consequence of inaction**

Measured/output value of these IOMs/IOPs will not be accurate.

### **Corrective actions**

Field calibration of these IOMs/IOPs needs to be performed.

### **Time to respond**

Immediate.



---

## AO Channel Not Calibrated - SVP-IOM/SP-IOM AO channels not calibrated

### Potential causes

Calibration data is not present in the Flash device.

### Consequence of inaction

Fails to load the calibration data.

### Corrective actions

Recalibrate the AO channels

### Time to respond

Immediate.

---

## **BADADPER\_017 - BAD ERROR CODE DETECTED IN ADP**

### **Potential causes**

1. ADP has failed in communications with IOLP.
2. Application processor (LLAI or STI) has a communication failure with the high-performance I/O Link card.

### **Consequence of inaction**

ADP process cannot progress.

### **Corrective actions**

If the error persists, replace the IOP card.

### **Time to respond**

Immediate.

---

## **BADADPJP\_034 - BAD BRANCH TAKEN IN ADP ROM EXECUTION**

### **Potential causes**

Bad branch taken during ADP ROM execution.

### **Consequence of inaction**

The ADP processed values are faulty.

### **Corrective actions**

Replace the LLAI IOP card for the LLAI FTA.

### **Time to respond**

Immediate.

---

## **BADCALRF\_039 - CALIBRATION REFERENCE OUTSIDE LIMITS**

### **Potential causes**

Inaccurate reference voltage provided during field calibration.

### **Consequence of inaction**

The value measured at the ADC/DAC will be inaccurate.

### **Corrective actions**

1. If the field calibration fails, a factory calibration is needed.
2. Alternatively, replace the IOM/IOP.

### **Time to respond**

Immediate.

---

## **BADFLREG\_044 - AO FAILURE SELECTION REGISTER IS BAD**

### **Potential causes**

AO module failure selection register is bad.

### **Consequence of inaction**

AO module will not work as expected.

### **Corrective actions**

Replace IOP card.

### **Time to respond**

Immediate.

---

## **BADPLUGM\_029 - BAD PLUG-IN MODULE IN FTA**

### **Potential causes**

Bad input or bad FTA plug-in module.

### **Consequence of inaction**

The connected device using that FTA cable will no longer be under EPKS control.

### **Corrective actions**

Test that the slot is wired correctly. If it is, replace the FTA plug-in module.

### **Time to respond**

Immediate.

---

## BADRESUM\_003 - RESUME OF NON-WAITING TASK

### **Potential causes**

IOP executive resumed a non-waiting task - software bug indicated.

### **Consequence of inaction**

Unexpected behavior.

### **Corrective actions**

Contact TAC for assistance.

### **Time to respond**

Immediate.

---

## **BADRJVAL\_033 - REFERENCE JUNCTION VALUE BAD**

### **Potential causes**

AIH,LLAI reference junction value is bad.

### **Consequence of inaction**

The data received through that port is faulty, resulting in unexpected behavior.

### **Corrective actions**

Check that the reference junction wire or jumper (P1) is correctly implemented on the FTA.

### **Time to respond**

Immediate.



---

## BADSECRG\_022 - SECONDARY REGULATOR NOT OK

### Potential causes

DO IOP card secondary regulator is not functioning.

### Corrective actions

Replace the DO IOP card.

### Time to respond

Immediate.

---

## **BDOUTBFR\_046 - Bad Output Buffer**

### **Potential causes**

Output disable buffer failure.

### **Consequence of inaction**

Disrupts process.

### **Corrective actions**

Replace the IOP. Use Standby Manual device if IOP is non-redundant.

### **Time to respond**

Immediate.

---

## BDSNDLTC\_045 - Bad Secondary Latch

### **Potential causes**

Secondary latch fails or bad secondary latch.

### **Consequence of inaction**

Disrupts process.

### **Corrective actions**

Replace the IOP. Use a standby manual device if IOP is non-redundant.

### **Time to respond**

Immediate.

---

## CABLE DISCONNECT, RTP - No RTP connection

### **Potential causes**

RTP cable has been disconnected or has failed.

### **Consequence of inaction**

Communication loss between the field devices.

### **Corrective actions**

Use the NDM generated Point ID and the FIM slot number in the description field to find the FIM with the disconnected RTP cable.

### **Time to respond**

Immediate.

---

## CALBABRT\_038 - CALIBRATION SEQUENCE ABORTED

### **Potential causes**

Calibration of an IOP card has been aborted during the calibration procedure, due to a failure.

### **Consequence of inaction**

Calibration error.

### **Corrective actions**

Check the precision voltage/resistance source for accuracy. Also, make sure that the correct calibration procedure is being followed.

### **Time to respond**

Immediate.

---

## Channel Not Field Calibrated - SVP-IOM/SP-IOM Channel not field calibrated

### **Potential causes**

Valve position calibration status is not complete. Sensor type is LVDT or RVDT.

### **Consequence of inaction**

Fails to load the calibration data; disrupts the process.

### **Corrective actions**

Complete calibration.

## Cold Start - Device Cold Start

---

### Potential causes

A power failure or device reset.

### Consequence of inaction

Fails to initialize the device.

### Corrective actions

Check the power supply to the device and device status.

### Time to respond

Immediate.

---

## COMMS - No IOLP access to shared RAM

### **Potential causes**

IOLP cannot gain access to shared RAM.

### **Consequence of inaction**

Input conversion will be prohibited.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.



---

## Configuration Changed - Device Configuration Changed

### **Potential causes**

An operation was performed that changed the device's configuration.

### **Corrective actions**

No action may be required. Flag may be cleared.

---

## Device Malfunction - Field Device Malfunction

### **Potential causes**

The device detected a serious error or failure.

### **Consequence of inaction**

IOP/IOM issues a Command 48 which requests the device specific status and conditions. Depending on the type of fault, the analog value and/or the digital variables may be set to the BAD state (unusable data). The channel remains in this mode until the fault is resolved.

### **Corrective actions**

Resolve the detected fault. Replace the device.

### **Time to respond**

Immediate.

---

## DIAGCTFL\_026 - AI Input-Output loopback failure

### Potential causes

This soft failure is generated due to a hardware failure in the AI channel of the I/O module.

### Consequence of inaction

Loss of data.

### Corrective actions

Replace the faulty I/O module.

---

## DIAGCTFL\_026 - DI Input-Output loopback failure

### **Potential causes**

This soft failure is generated due to a hardware failure in the AI channel of the I/O module.

### **Consequence of inaction**

Loss of data.

### **Corrective actions**

Replace the faulty I/O module.

---

## DIAGCTFL\_026 - IOM diagnostic circuit failure

### Potential causes

This soft failure is generated due to a hardware failure in the AI channel of the I/O module.

### Consequence of inaction

Loss of data.

### Corrective actions

Replace the faulty I/O module.

---

## DIAGOFLO\_005 - ENTIRE DIAG CYCLE OVERFLOW

### Potential causes

Entire diagnostic cycle overran the 2 minute allocated time in which diagnostics have to run to completion.

### Consequence of inaction

1. IOP failure.
2. Loss of control.

### Corrective actions

1. Investigate control point mix/strategy for an excessive load.
2. Otherwise, a possible I/O Link problem exists. Check I/O Link card, the I/O Link cable, and the IOP cards.

### Time to respond

Immediate.

---

## DIAGTMOT\_004 - ONE DIAG INITIATION TIMED OUT

### Potential causes

Diagnostics not run in at least 5 seconds. Processing overload.

### Corrective actions

1. Investigate control point mix/strategy for an excessive load.
2. Otherwise, a possible I/O Link problem exists. Check the I/O Link card, the I/O Link cable, and the IOP cards.

### Time to respond

Immediate.

---

## DO Relay Extn Board Missing - Relay Extension Board Missing

### **Potential causes**

Relay extension board missing.

### **Consequence of inaction**

IOP cannot communicate to the output device. Outputs non-operational.

### **Corrective actions**

Ensure relay board is properly installed.

### **Time to respond**

Immediate.



---

## DTPATHFL\_069 - DATA PATH FAILURE

### **Potential causes**

Data path failure.

### **Corrective actions**

Replace the FTA when convenient.

---

## DTPATHTO\_070 - DATA PATH TIME OUT

### **Potential causes**

Data path time.

### **Corrective actions**

Replace the FTA when convenient.

---

## EECKSMER\_007 - EEPROM CHKSUM ERROR

**Potential causes**

EEPROM (used to hold calibration information in Analog Output IOPs) checksum failure. It usually means an Analog Output IOP is not calibrated properly.

**Consequence of inaction**

Improper AO calibration. Output operations accuracy is lost.

**Corrective actions**

1. Calibrate the Analog Output IOP card.
2. If the error persists, replace the HLAI or the AO.

**Time to respond**

Immediate.

---

## EECNTERR\_008 - EEPROM counter error - too many writes

### Potential causes

EEPROM counter error. The number of writes to EEPROM has exceeded the safe number (10,000). This could indicate the IOP has not been calibrated, because a virgin EEPROM will fail this test.

### Consequence of inaction

- Too many writes or unformatted EEPROM
- Loss of calibration data
- Less accuracy
- Process disruption.

### Corrective actions

1. Calibrate the Analog Output IOP card.
2. If the error persists, replace the HLAI or the AO IOP card, or the FTA.

### Time to respond

Immediate.

---

## EEFAILED\_040- EEPROM UPDATE FAILED DUE TO EEPROM BUSY

### Potential causes

EEPROM update failed due to EEPROM busy.

### Consequence of inaction

Calibration data may be lost.

### Corrective actions

If an HLAI or AO, replace the IOP. If a LLAI, replace the affected plug-in module.

### Time to respond

Immediately.

---

## EEFLAGER\_009 - EEPROM INCOMPLETION ERROR

### **Potential causes**

Incomplete EEPROM write resulting in uncalibrated IOM.

### **Consequence of inaction**

Uncalibrated I/O module. Process disruption.

### **Corrective actions**

1. Calibrate the AI or AO card.
2. If the error persists, replace the HLAI or the AO IOP card, or the FTA.
3. Check EEPROM.

### **Time to respond**

Immediate.

---

## Feedback Inputs failure - Resolver Feedback Inputs Failure

### Potential causes

This soft failure is generated when the Resolver is not connected to the field terminals. SVP\_AI channel reports this soft failure when it is configured as “Resolver”.

### Consequence of inaction

SVP\_AI Channel PV will not be shown properly.

### Corrective actions

Ensure that the wiring connection between the Resolver and the SVPM IOTA field terminals are correct.

### Time to respond

Immediately.

---

## FTA 1 Calibration Failure - FTA 1 CALIBRATION FAIL

**Potential causes**

FTA 1 calibration failure.

**Consequence of inaction**

Loss of process data/loss of control.

**Corrective actions**

Recalibrate the FTA.

**Time to respond**

Immediate.



---

## FTA1 Comm Failure - FTA 1 COMMUNICATION FAIL

### Potential causes

FTA 1 communication failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

1. Check the connection from the Power Adapter to FTA 1.
2. If the FTA is missing, install the FTA.
3. If the FTA is present, replace the FTA.

### Time to respond

Immediate.

---

## FTA 1 Fail - LLMUX FTA1 HAS A FAILURE

### **Potential causes**

LLMUX or RHMUX FTA 1 has a soft failure.

### **Consequence of inaction**

Loss of data from field.

### **Corrective actions**

- LLMUX or RHMUX: Check FTA 1
- SI: Correct the error condition at the device connected to FTA 1.

### **Time to respond**

Immediate.

# FTA 1 Identification Error - FTA 1 IDENT ERROR

---

## Potential causes

LLMUX FTA 1 identification failure.

## Consequence of inaction

Data mismatch.

## Corrective actions

Verify/correct the FTA pinning.

## Time to respond

Immediate.

---

## FTA1 Not Calibrated - FTA 1 IS NOT CALIBRATED

### Potential causes

- LLMUX: FTA 1 is not calibrated
- SI: FTA 1 write buffer overflow.

### Consequence of inaction

Inaccurate process values.

### Corrective actions

- LLMux or RHMUX: Calibrate FTA 1
- SI: Reduce the number of writes to the FTA.

### Time to respond

Immediate.

---

## FTA 1 Ref Voltage Failure - FTA 2 VREF FAIL

### Potential causes

FTA 1 reference voltage failure.

### Consequence of inaction

Loss of process data/loss of control

### Corrective actions

Replace the FTA.

### Time to respond

Immediate.

---

## FTA 2 Calibration Failure - FTA 3 CALIBRATION FAIL

**Potential causes**

FTA 2 calibration failure.

**Consequence of inaction**

Loss of process data/ loss of control.

**Corrective actions**

Recalibrate the FTA.

**Time to respond**

Immediate.

---

## FTA 2 Comm Failure - FTA 2 COMMUNICATION FAIL

### Potential causes

FTA 2 communication failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

1. Check the connection from the Power Adapter to FTA 2.
2. If the FTA is missing, install the FTA.
3. If the FTA is present, replace the FTA.

### Time to respond

Immediate.

---

## FTA2 Fail - LLMUX FTA2 HAS A FAILURE

### **Potential causes**

LLMUX or RHMUX FTA 2 has a soft failure.

### **Consequence of inaction**

Loss of data from field.

### **Corrective actions**

1. LLMUX or RHMUX: Check FTA 2
2. SI: Correct the error condition at the device connected to FTA 2.

### **Time to respond**

Immediate.



---

## FTA 2 Identification Error - FTA 2 IDENT ERROR

### Potential causes

LLMUX FTA 2 identification failure.

### Consequence of inaction

Data mismatch.

### Corrective actions

Verify/correct the FTA pinning.

### Time to respond

Immediate.

---

## FTA 2 Not Calibrated - FTA 2 IS NOT CALIBRATED

### Potential causes

1. LLMUX: FTA 2 is not calibrated.
2. SI: FTA 2 write buffer overflow.

### Consequence of inaction

Inaccurate process values

### Corrective actions

1. LLMux or RHMUX: Calibrate FTA 2.
2. SI: Reduce the number of writes to the FTA.

### Time to respond

Immediate.

---

## FTA 2 Ref Voltage Failure - FTA 2 VREF FAIL

### Potential causes

FTA 2 reference voltage failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

Replace the FTA.

### Time to respond

Immediate.

---

## FTA 3 Calibration Failure - FTA 3 CALIBRATION FAIL

### **Potential causes**

LLMUX FTA 3 calibration failure.

### **Consequence of inaction**

Loss of process data/loss of control.

### **Corrective actions**

1. Check FTA calibration.
2. Recalibrate the FTA.

### **Time to respond**

Immediate.

## FTA 3 Comm Failure - FTA 3 communication failure

---

### Potential causes

LLMUX FTA 3 communication failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

1. Check the connection from the Power Adapter to FTA 3.
2. If the FTA is missing, install the FTA.
3. If the FTA is present, replace the FTA.

### Time to respond

Immediate.

---

## FTA 3 Fail - AI-MUX FTA3 HAS A FAILURE

### **Potential causes**

LLMUX: FTA 3 has a soft failure. E.g. FTA cable unplugged.

### **Consequence of inaction**

Loss of data from field.

### **Corrective actions**

Check FTA 3.

### **Time to respond**

Immediate.

---

## FTA 3 Identification Failure - FTA 3 identification failure

### Potential causes

LLMUX FTA 3 identification failure.

### Consequence of inaction

Data mismatch.

### Corrective actions

Verify/correct the FTA pinning.

### Time to respond

Immediate.

---

## FTA 3 Not Calibrated - FTA 3 IS NOT CALIBRATED

### **Potential causes**

FTA reference voltage is kept to zero.

### **Consequence of inaction**

Inaccurate process values.

### **Corrective actions**

Increase the reference voltage to 100mV.

### **Time to respond**

Immediate.



---

## FTA 3 Ref Voltage Failure - FTA 3 reference voltage failure

### Potential causes

LLMUX FTA 3 reference voltage failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

Replace the FTA.

### Time to respond

Immediate.

---

## FTA 4 Calibration Failure - FTA 4 CALIBRATION FAIL

### **Potential causes**

LLMUX FTA 4 calibration failure.

### **Consequence of inaction**

Loss of process data/loss of control.

### **Corrective actions**

1. Check FTA calibration.
2. Recalibrate the FTA.

### **Time to respond**

Immediate.

---

## FTA 4 Comm Failure - FTA 4 communication failure

### Potential causes

LLMUX FTA 4 communication failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

1. Check the connection from the Power Adapter to FTA 4.
2. If the FTA is missing, install the FTA.
3. If the FTA is present, replace the FTA.

### Time to respond

Immediate.

---

## FTA4 Fail - AI-MUX FTA4 HAS A FAILURE

### **Potential causes**

LLMUX: FTA 4 has a soft failure. E.g. FTA cable unplugged.

### **Consequence of inaction**

Loss of data from field.

### **Corrective actions**

Check FTA 4.

### **Time to respond**

Immediate.

## FTA 4 Identification Error - FTA 4 identification failure

---

### Potential causes

LLMUX FTA 4 identification failure.

### Consequence of inaction

Data mismatch.

### Corrective actions

Verify/correct the FTA pinning.

### Time to respond

Immediate.

---

## FTA 4 Not Calibrated - FTA 4 IS NOT CALIBRATED

### **Potential causes**

FTA reference voltage is kept to zero.

### **Consequence of inaction**

Inaccurate process values.

### **Corrective actions**

Increase the reference voltage to 100mV.

### **Time to respond**

Immediate.

---

## FTA 4 Ref Voltage Failure - FTA 4 reference voltage failure

### Potential causes

LLMUX FTA 4 reference voltage failure.

### Consequence of inaction

Loss of process data/loss of control.

### Corrective actions

Replace the FTA.

### Time to respond

Immediate.

---

## FTA Power Failure - FTA Power Failure

### **Potential causes**

LLMUX IOM is not able to power the FTAs.

### **Consequence of inaction**

Loss of field data and process disruption.

### **Corrective actions**

Replace the IOM.

### **Time to respond**

Immediate.



---

## FTAMISSG\_006 - FTA or power adapter missing

### Potential causes

- If from an LLMUX or RHMUX IOP, the power adapter is missing
- If from a Series C DO IOM the relay extension board is missing
- If from any other IOP the FTA is missing.

### Consequence of inaction

Loss of field data and process disruption.

### Corrective actions

1. Install the FTA or relay adapter.
2. If an FTA is present, replace the FTA or check the FTA cable.

### Time to respond

Immediate.

---

## FTAMSMCH\_031 - FTA type mismatch with point configuration

### **Potential causes**

FTA type mismatch with slot configuration.

### **Consequence of inaction**

Loss of field data and process disruption.

### **Corrective actions**

Reconfigure the FTA type or replace the FTA.

### **Time to respond**

Immediate.

---

## HART Comm Failure - HART Communication Fail

### Potential causes

1. Faulty wiring
2. non-HART device on the wire
3. significant electrical noise on the wires
4. problems with the device or IOM.

### Consequence of inaction

The IOM stops communicating with the HART device.

### Corrective actions

1. Check the wiring.
2. Verify the device type.
3. If the problem persists replace the device or IOM, whichever is faulty.
4. Press RESETCOMERR button to reset HNCOMERR to zero.

### Time to respond

Immediate.

---

## **HART Diagnostic Underrun - HART PROCESSOR DIAGNOSTIC TASK UNDER-RUN**

### **Potential causes**

HART processor diagnostic task under-run.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.

---

## **HART Modem 1 Error - HART hardware error detected against DUART channel 1 or modem 1**

### **Potential causes**

HART hardware error detected against DUART channel 1 or modem 1.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.

---

## **HART Modem 2 Error - HART hardware error detected against DUART channel 2 or modem 2**

### **Potential causes**

HART hardware error detected against DUART channel 2 or modem 2.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.

---

## **HART Modem 3 Error - HART hardware error detected against DUART channel 3 or modem 3**

### **Potential causes**

HART hardware error detected against DUART channel 3 or modem 3.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.

---

## **HART Modem 4 Error - HART hardware error detected against DUART channel 4 or modem 4**

### **Potential causes**

HART hardware error detected against DUART channel 4 or modem 4.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

Replace the IOP card.

### **Time to respond**

Immediate.



# HART Stack High - HSTACKHI

---

## Potential causes

HART processor program stack above 90% usage level.

## Consequence of inaction

Loss of data.

## Corrective actions

Replace the IOP card.

## Time to respond

Immediate.

---

## HWFIFOFL\_064 - HARDWARE FIFO FAILURE

### **Potential causes**

Hardware FIFO buffer diagnostic failed.

### **Consequence of inaction**

PVs of all points are set to BAD.

### **Corrective actions**

Replace the IOP.

### **Time to respond**

Immediate.

---

## INPTFAIL\_021 - INPUT POINT FAILURE

### **Potential causes**

Input point failure.

### **Consequence of inaction**

No channel PV scanning.

### **Corrective actions**

Check which input is failing, then check the fuse on IOTA and field wiring.

### **Time to respond**

Immediate.

---

## IOL Address Diag Failure - IOL Address Diag Failure

### **Potential causes**

IOL address diagnostic failure.

### **Consequence of inaction**

Disrupts process.

### **Corrective actions**

1. Check IOM number at device index switch.
2. Ensure correct assignment.
3. If not correct, reset to correct device index number.
4. Reset IOM.

### **Time to respond**

Immediate.

---

## IOM or IOTA HART Chan Failure - IOM or IOTA HART Channel Failure

### Potential causes

IOM or IOTA HART channel failure

### Consequence of inaction

Initializes the HART live database and discontinues all HART scanning for this channel.

### Corrective actions

Replace the IOM.

### Time to respond

Immediate.

---

## IOPSWITCHOVER - IOP Switchover Occurred

### **Potential causes**

1. Synchronized redundant module failure
2. Operator Command
3. Primary module was detected fault.

### **Consequence of inaction**

Depending on the cause of switchover, consequences vary. Possible loss of redundancy.

### **Corrective actions**

Check for the failures reported by the previous primary module. If no fault it may have been forced by operator.

### **Time to respond**

Immediate.

---

## LOSTSYNC\_058 - LOSTSYNC

**Potential causes**

Secondary module lost synchronization with its primary.

**Consequence of inaction**

Loss of redundancy. Secondary fails to follow up with the primary and cannot assume the primary state on switch-over.

**Corrective actions**

1. If the primary module status is OK, re-sync with the START command.
2. If the primary module status is IDLE, re-sync with the IDLE command.

**Time to respond**

Immediately.

---

## LVDT Core Fallout - LVDT Core Fallout

### **Potential causes**

This alarm is generated if the LVDT core is out of LVDT.

### **Consequence of inaction**

Bad PV generated by AI channel that will cause loss of control.

### **Corrective actions**

Check the LVDT wiring connections.

1. Check if the LVDT core is inside the LVDT, and correct the position of the LVDT core.
2. Check the wiring to ensure that there is no open or short circuit in the LVDT cable connection.

### **Time to respond**

Immediately.



---

## MBCHKMER\_015 - MBCHKMER

### **Potential causes**

LLAI shared ROM checksum error. LLAI only - no AI conversion.

### **Consequence of inaction**

Results in IOP failure, disrupting the process.

### **Corrective actions**

Unplug IOP card and plug it back in to reset device.

### **Time to respond**

Immediate.

---

## MBRAMADR\_014 - MBRAMADR

### **Potential causes**

LLAI shared ROM address error. LLAI only - no AI conversion.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

Reset the IOP.

### **Time to respond**

Immediate.

---

## MBRAMCNT\_013 - MBRAMCNT

### Potential causes

LLAI shared ROM contents failure. LLAI only - no AI conversion.

### Consequence of inaction

Disrupts the process.

### Corrective actions

Reset the IOP

### Time to respond

Immediate.

---

## MLTINPFL\_060 - MLTINPFL

**Potential causes**

Multiple input failure detected.

**Consequence of inaction**

Disrupts the process. May result in indeterminate outputs.

**Time to respond**

Immediate.

---

## Module Not Calibrated - ADC OUT OF CALIBRATION

### Potential causes

This SF pertains to both PM HLAI and Series C AI modules. It could a result of:

1. a bad internal reference voltage
2. an internal multiplexer failure
3. the module being badly out of calibration.

### Consequence of inaction

The values read from the field device could be inaccurate or reported for the wrong channel.

### Corrective actions

Recalibrate the module. If the problem persists replace the module.

### Time to respond

Immediate.

---

## More Status Available - More Status Available

### **Potential causes**

Reading additional status information.

### **Consequence of inaction**

Generates an additional device status alarm or event.

### **Corrective actions**

The measurements may still be correct and suitable for use by the control system. This alarm merely indicates that Command 48 contains diagnostic information that is useful to the host.

---

# No Response

**Potential causes**

1. I/O module hard failure due to a fatal fault (malfunction) either in the hardware or software.
2. IOLINK failure
3. Power loss to I/O module.

**Consequence of inaction**

1. Loss of control and loss of view
2. In the event of an IOLINK failure: for output modules, depending on the fault option configuration (in channel) the O/P value will be driven.

**Corrective actions**

1. In the case of module hard fail, reset the I/O module using user reset contacts (do not do power cycle)
2. Record the last hardware failure status code, I/O firmware and hardware revisions
3. Extract controller internal logs and IO internal logs
4. Report to TAC with all of the above information.

**Time to respond**

Immediate.

---

## NOACLINE\_028 - NOACLINE

### **Potential causes**

No external AC line in the LLAI - input conversions continue.

### **Consequence of inaction**

May continue to operate but at lesser degree of accuracy.

### **Corrective actions**

1. Check optical coupler and associated fuse on the back panel.
2. Check that the primary (left-side) power supply module in the power system is installed and functional.

### **Time to respond**

Immediate.



---

## NTUSED62\_062 - Data bus failure

### **Potential causes**

Unused on I/O Link interface.

### **Consequence of inaction**

Disrupts process.

### **Corrective actions**

Replace the IOP.

### **Time to respond**

Immediate.

---

## **OP Fail in Circuit/Field Wire - Failure in output circuit/field wiring detected by AO or DO**

### **Potential causes**

1. Failure in output circuit/field wiring detected by AO or DO.
2. May also indicate failure of loopback test.

### **Consequence of inaction**

Outputs non-operational.

### **Corrective actions**

Check field wiring and the fuses on the IOTA. If it is good, try replacing the IOTA and/or the appropriate IOM card.

### **Time to respond**

Immediate.

---

## Open Wire Detected - Open wire/sensor detected

### Potential causes

Open wire/sensor detected in the field device connection.

### Consequence of inaction

The sensor data cannot be read or the data may not be written to field device.

### Corrective actions

Check the field wiring and IOTA connections.

### Time to respond

Immediate.

---

## Output Short Circuit Detected - DO channel detected a short circuit or over current situation

### Potential causes

1. DO channel detected a short circuit or over current situation.
2. Wiring faults.

### Consequence of inaction

Overcurrent or DO channel draws more current than is permitted. It may spoil the DO device.

### Corrective actions

The shorted device or shorted wiring must be corrected. Check the field wiring and IOTA connections.

### Time to respond

Immediate.

---

## PIFAULTY\_072 - FIELDBUS - FAULTY personality image

### Potential causes

Personality image in F-ROM is faulty.

### Corrective actions

1. Ensure that you have the correct revision of the personality software.
2. Reload the personality image.
3. If the error appears again, contact TAC.

### Time to respond

Immediate.

---

## PRVRAMFL\_065 - Private RAM diagnostic failed

### **Potential causes**

Private RAM diagnostic failed.

### **Consequence of inaction**

PVs of all the points are set to BAD. Disrupts the process.

### **Corrective actions**

Unplug IOP card and plug it back in to reset device.

### **Time to respond**

Immediate.

---

## PV Out of Limits - Primary Variable Out Of Limits

### **Potential causes**

The PV going beyond its operating limit.

### **Time to respond**

Immediate.

---

## PVVALDFL\_067 - PV validation diagnostic failed

### **Potential causes**

PV validation diagnostic failed. Possibly either IOM hardware failure or bad input scan circuitry.

### **Consequence of inaction**

PVs of all points are set to BAD. Disrupts the process.

### **Corrective actions**

1. Unplug IOP card and plug it in back to reset device.
2. If the same alarm persists replace IOP card.

### **Time to respond**

Immediate.



---

## Readback Register Diag Failure - Readback Register Diagnostic Failure

**Potential causes**

Value read from bank registers of CPLD at startup is compared to values at run time. If they are not the same this alarm is reported.

**Consequence of inaction**

Disrupts the process.

**Corrective actions**

Internal hardware problem. Replace the IOM.

**Time to respond**

Immediate.

---

## REDNDIAG\_061 - REDNDIAG

### **Potential causes**

If IOM is in SYNC'D state and both wiggle bits in REDDATA are set, then this alarm is posted.

### **Consequence of inaction**

Disrupts the process.

### **Corrective actions**

1. If an AO, force the IOP A to be the primary then replace the FTA's plug-in module.
2. If an HLAI, synchronize the database, then replace the IOPs one at a time.

### **Time to respond**

Immediate.

---

## Redundancy Hardware Failure - Redundancy Hardware Failure

### **Potential causes**

Inhibit output is faulted or partner not controlling the screws and asserting backup request.

### **Consequence of inaction**

Loss of redundancy and hence loss of data and control.

### **Corrective actions**

Check the redundant partner.

### **Time to respond**

Immediate.

---

## REQOFLOW\_002 - IOP task request overflow - excessive IOL activity

### Potential causes

1. Excessive IOL activity.
2. Any one task taking excessive time because of events or alarms.

### Consequence of inaction

IOL time-out errors and link fault.

### Corrective actions

1. Check IOL activity.
2. Contact TAC for assistance.

### Time to respond

Immediate.

## SCANORUN\_019 - SCANORUN

---

### Potential causes

1. Input module scan overrun. Excessive IOL activity to this IOP. Inputs have been lost.
2. Intermittently bad I/O link hardware.

### Consequence of inaction

Faulty input values. Affects process.

### Corrective actions

1. Check for a chattering DI point.
2. Investigate the faulty I/O link hardware.

### Time to respond

Immediate.

---

## Servo Current Driver Shutdown - Servo Current Driver Shutdown

### **Potential causes**

This soft failure is generated due to a hardware failure on the servo driver interface.

### **Corrective actions**

Replace the faulty I/O module.

### **Time to respond**

Immediate.

---

## SOECLKFL\_066 - SOECLKFL

### **Potential causes**

The SOE clock failed.

### **Consequence of inaction**

PVs of all the points are set to BAD. Disrupts the process.

### **Corrective actions**

Replace the IOP.

### **Time to respond**

Immediate.

---

## SOECNTFL\_068 - SOECNTFL

### **Potential causes**

SOE counter diagnostic failed.

### **Consequence of inaction**

PVs of all the points are set to BAD. Disrupts the process.

### **Corrective actions**

Replace the IOP.

### **Time to respond**

Immediate.



---

## Speed Channel - No Pulse Input - Speed Channel - No Pulse Detected

### **Potential causes**

No speed probe is connected to the Speed channel terminals or there is a field open wire condition for the speed probe. This soft failure can also be generated when there is a zero speed condition in the field.

### **Consequence of inaction**

Speed Channel PV will not be shown properly.

### **Corrective actions**

Check the field wiring and correct if there are any improper connections to the Speed channel.

### **Time to respond**

Immediately.

---

## Speed RCAP Ref Clock Failure - Speed RCAP Ref Clock Failure

### **Potential causes**

This soft failure is generated if there is a hardware failure in the Speed channel hardware.

### **Consequence of inaction**

Speed Channel PV will not show correctly.

### **Corrective actions**

Replace the faulty IO module.

### **Time to respond**

Immediately.

---

## STCKLIM\_024 - STCKLIM

### Potential causes

IOM stack usage is dangerously close to its limit.

### Consequence of inaction

Module shutdown.

### Corrective actions

1. Reduce activity on this IOM.
2. Reduce scan rate or move points to a different IOP.
3. Contact TAC for assistance.

### Time to respond

Immediate.

---

## STCOVRUN\_001 - Sample time clock overrun

### Potential causes

Sample time clock overrun greater than 2 x period.

### Consequence of inaction

Affects the process.

### Corrective actions

1. Investigate a possible I/O link problem or excessive IOL activity.
2. Check C300 IOL cards, cables, IOMs and IOL budgets.
3. Contact TAC if the alarm persists or repeatedly occurs.

### Time to respond

Immediate.

---

## STMACHFL\_071 - STMACHFL

### **Potential causes**

State machine diagnostic indicates a failure in the SOE hardware engine on a DISOE IOP.

### **Consequence of inaction**

PVs of all points are set to BAD. Disrupts the process.

### **Corrective actions**

Replace the IOP.

### **Time to respond**

Immediate.

---

## Suplna - Not Active Supervisor

### **Potential causes**

The IOL interface daughter card could not transition into the active supervisor role. Generally this is caused by a partner IOLINK with a conflicting IOLINK Address.

### **Consequence of inaction**

The real time data transmission is lost.

### **Corrective actions**

Check for duplicate IOL Address.

### **Time to respond**

Immediate.

## Uncertain Pulse Input - Uncertain Pulse Input

---

### Potential causes

This soft failure is generated in the following conditions:

1. Issues in field wiring of speed probes.
2. Excessive frequency variation in the pulse input.

### Corrective actions

Check the field wiring and correct any improper connections to the speed channel.

### Time to respond

Immediate.

---

## Unstable Input - Resolver Unstable Input

### **Potential causes**

This soft failure is generated when a Resolver angle cannot be determined due to excessive variation in the Resolver signal.

### **Consequence of inaction**

PV will be fluctuating and there will be no stable PV.

### **Corrective actions**

Ensure that the Resolver connection with the SVPM IOTA is correct.

### **Time to respond**

Immediately.



---

## Variable Out Of Limits - Non-Primary Variable Out Of Limits

### Potential causes

A device variable not mapped to the PV going beyond its operating limits.

---

## VDT ADC Selection Failure - LVDT ADC Channel Selection Failure

**Potential causes**

LVDT ADC channel selection failure.

**Consequence of inaction**

Field diagnosis fails resulting in process disruption.

**Time to respond**

Immediate.

---

## VDT Critical Signal Failure - LVDT Channel Critical Signal Failure

### **Potential causes**

LVDT channel critical control signal failure i.e. ADC critical signals failures.

### **Consequence of inaction**

Field diagnosis fails resulting in process disruption.

### **Corrective actions**

Check if LVDT is enabled for diagnostics to run.

### **Time to respond**

Immediate.

---

## VDT Exctn Freq Drift - LVDT Excitation Frequency Drift Greater than 100Hz

### Potential causes

LVDT Excitation Frequency Drift Greater than 100Hz. This soft fail can be generated due to one of the following:

1. Wiring fault in the excitation voltage terminals (for instance, L1X+ / L1X- on the IOTA).
2. Excitation frequency generated by the external source is not within limits of the calibrated frequency.

### Consequence of inaction

Field diagnosis fails resulting in process disruption.

### Corrective actions

1. Verify and correct any wiring problems at the excitation terminals.
2. Check if the excitation frequency supplied by the external source is correct.

### Time to respond

Immediate.

---

## VDT Extn Volt Out of Range - LVDT Excitation Voltage out of calibrated Range

### Potential causes

LVDT Excitation Voltage out of calibrated Range. This soft failure is generated due to one of the following:

1. Wiring fault in the excitation voltage terminals (for LVDT channel, L1X+ / L1X- on the IOTA).
2. Excitation voltage generated by the external source is not within limits of the calibrated voltage.

### Consequence of inaction

Field diagnosis fails resulting in process disruption.

### Corrective actions

1. Verify and correct any wiring problems at the excitation terminals.
2. Check if the excitation voltage supplied by the external source is correct.

### Time to respond

Immediate.

---

## VDT Fb A Volt Out of Range - LVDT Feedback Channel A Voltage out of calibrated Range

### **Potential causes**

LVDT Feedback Channel A Voltage out of calibrated range. This soft failure can be generated due to faulty wiring in the feedback A voltage terminals. (For LVDT channel 1 it is L1A+ / L1A- on the IOTA).

### **Consequence of inaction**

Field diagnosis fails resulting in process disruption.

### **Corrective actions**

Check if there is any faulty wiring at the feedback A voltage terminals and correct the faulty wiring.

### **Time to respond**

Immediate.

---

## VDT Fb B Volt Out of Range - LVDT Feedback Channel B Voltage out of calibrated Range

### Potential causes

LVDT Feedback Channel B Voltage out of calibrated range. This soft failure can be generated due to faulty wiring in the feedback B voltage terminals. (For LVDT channel 1 it is L1B+ / L1B- on the IOTA).

### Consequence of inaction

Field diagnosis fails resulting in process disruption.

### Corrective actions

Check if there is any faulty wiring at the feedback B voltage terminals and correct the faulty wiring.

### Time to respond

Immediately.

---

## VREFFAIL\_041 - Reference voltage out of range

### Potential causes

In AI, the internal 5V reference is out of range. This SF pertains to both PM HLAI and Series C AI modules. This could be caused by:

1. A bad internal reference voltage.
2. An internal multiplexer failure.
3. The module being out of calibration.

### Consequence of inaction

The values read from the field device could be inaccurate or reported for the wrong channel.

### Corrective actions

Recalibrate the module. If the problem persists replace the module

### Time to respond

Immediately.



---

## VTESTFAI\_030 - VTESTFAI

### Potential causes

Test voltage reference >5% out of range - PVAUTO to NAN.

### Consequence of inaction

The PV is set to NAN by the IOP.

### Corrective actions

Replace the IOP card.

### Time to respond

Immediate.

---

## VZERO\_FL\_032 - VZERO\_FL

### **Potential causes**

Zero Reference voltage out of range in AI and AO IOMs. Zero reference failure.

### **Consequence of inaction**

The PV is set to NAN, by the IOP for AI.

### **Corrective actions**

Replace the PMIO.

### **Time to respond**

Immediate.

---

## WRITENBL\_059 - WRITENBL

### **Potential causes**

AO or DO write enable protection failure.

### **Consequence of inaction**

IOP failure can result in indeterminate outputs.

### **Corrective actions**

Replace the IOP at the earliest convenience.

### **Time to respond**

Immediate.

---

## WRONG\_HW\_063 - WRONG\_HW

### **Potential causes**

I/O redundancy configured on non-supported hardware revision.

### **Consequence of inaction**

I/O redundancy is lost.

### **Corrective actions**

Replace the IOP with an IOP that supports redundancy (proper hardware revision).

### **Time to respond**

Immediate.

# SYNC system alarms

The following topics describe synchronization-related system alarms and how to respond to them.

## **Related topics**

“SYNC - Backup Point Database Larger” on page 454

“SYNC - Backup Inconsistency Detected” on page 455

“SYNC - Backup Server Error Starting” on page 456

---

## SYNC - Backup Point Database Larger

**Potential causes**

The synchronization of the primary and backup server cannot be completed as the backup point database is larger than the primary point database.

**Consequence of inaction****Corrective actions**

Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.

For assistance in resolving the problem, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

**Time to respond**

Synchronization is lost immediately when this alarm occurs. Time to respond will depend on assessment of process/site/operations for criticality/risk of losing synchronization.

---

## SYNC - Backup Inconsistency Detected

### Potential causes

The backup server has detected a request that if processed, would corrupt its database.

### Consequence of inaction

Server synchronization has failed, so the backup server database will not be updated with the changes from the primary server (including point configuration, history, events, etc.), and some automatic failover actions will not be triggered.

### Corrective actions

Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.

Repeat synchronization attempt. If repeated attempts fail, capture a diagnostic package and send it to your Honeywell Technical Assistance Center (TAC) for investigation.

### Time to respond

Synchronization is lost immediately when this alarm occurs. Time to respond will depend on assessment of process/site/operations for criticality/risk of losing synchronization.

---

## SYNC - Backup Server Error Starting

### Potential causes

The backup server failed to restart correctly after synchronizing with the primary server.

### Consequence of inaction

Backup Server (and therefore server redundancy) is not available. The system shall continue to run on Primary, but without redundancy.

### Corrective actions

Check the backup server status on the **System Status** display. For more information, see “Checking the status of redundant servers”.

1. Set the backup server status to Database Only.
2. Set the backup server status to System Running.
3. Resynchronize the backup and primary servers. For more information, see “Synchronizing the server databases”.

### Time to respond

When the alarm is raised, Backup is already unavailable. The time to respond will depend on assessment of process/site/operations for criticality running without the backup server being available.



# Systems Management system alarms

The following topics describe Systems Management-related system alarms and how to respond to them.

## Related topics

“ACE:CDA-SP : Experion PKS CDA-SP Service stopped” on page 459

“CAS: Component Admin Service is not running” on page 460

“CAS: was unable to Checkpoint component <component name> Error = <error num>:<error string>” on page 461

“<Component Name>: Component state changed from <previous state> to Communication Failure” on page 462

“<Component name>: Component state changed from <previous state> to Failed” on page 463

“<Component name>: Component state changed from <previous state> to Warning” on page 464

“<Component Name>: Device state changed from <previous state> to Communication Failure” on page 465

“<Component name>: Device state changed from <previous state> to Failed. Device Info: <device info>” on page 466

“<Component name>: Device state changed from <previous state> to Warning. Device Info: <device info>” on page 467

“Control Firewall <device name> (address <Fw address>) port <port ID> excessive TX\_PAUSE change. Cur:<Tx Pause Val> Last:<Last Tx Pause Val>” on page 468

“Control Firewall <Fw name> (address <Fw address>) has blocked ports” on page 469

“Control Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE” on page 470

“Control Firewall <Fw Name> (address <Fw Address>) port <port index> link status is Down” on page 471

“Control Firewall <Fw name> (address<Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable” on page 472

“Control Firewall <Fw name> (address<Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable” on page 473

“Excessive Disk Paging: memory resource issue is causing excessive disk paging” on page 474

“FTE device <device name> (Device Index: <device index>) has detected a duplicate” on page 475

“FTE device <device name> disjoined FTE community (no longer being heard)” on page 476

“FTE Device <device name> interface <A/B> status is SILENT” on page 477

“FTE/Heartbeat network packet delivery to application layer is being delayed. Node is experiencing Disk/CPU resource utilization issues” on page 478

“FTE STATUS: Device state changed from <previous state> to Failed. Device Info: <device information string>” on page 479

“FTEProvider: FTE Provider is not running” on page 480

“HCINS: Alias name: <component alias name> exists on two nodes in the same TPSSDomain. You must remove or rename one of them to solve this problem” on page 481

“HCINS: Alias name: <component alias name> from the component alias file conflicts with the one in the repository - You must remove Alias name from the component alias file to solve this problem” on page 482

“Modbus/TCP Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down” on page 483

“Modbus/TCP Firewall <Fw name> (address<Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable” on page 484

“Modbus/TCP Firewall <Fw name> (address <Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable” on page 485

“Modbus/TCP <Fw Name> (address <Fw address>) is no longer being heard by FTE” on page 486

“One-Wireless Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE” on page 487

“One-Wireless Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down” on page 488

“One-Wireless Firewall <Fw name> (address <Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable” on page 489

“One-Wireless Firewall <Fw name> (address <Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable” on page 490

“OPC Event Source: <node name>. Proxy ARP agent found. Check router configuration” on page 491

“SNMP Trap: - <IP Address> Type - AuthenticationFailure” on page 492

“SNMP Trap: - <IP Address> Type - ColdStart” on page 493

“SNMP Trap: - <IP Address> Type - LinkDown; Index - <Index>” on page 494

“SNMP Trap: - <IP Address> Type - WarmStart” on page 495

“SRP(syncrep.exe): FTE Status cannot be determined. Restart FTE Status server. <error message>” on page 496

“SRP(syncrep.exe): SRP has not heard expected traffic for an excessive period. Reconnecting Receive socket” on page 497

“Synchronization requests were not answered by node(s): <node list>” on page 498

“SysEvtProv: System Event Provider is not running” on page 499

“The system detected an address conflict for IP address <IP Address> with the system having <network> hardware address <hdw address>. <Message>” on page 500

---

## ACE:CDA-SP : Experion PKS CDA-SP Service stopped

The System Health Monitor has detected that a crucial service is not running. The CDA-SP service allows OPC communication from the Control Data Access – to - supervisory platform (CDA-sp).

### Potential causes

1. The service failed to auto-start after a reboot due to a configuration error.
2. A user manually stopped the service.
3. The running service failed.

### Consequence of inaction

Potential loss of view.

### Corrective actions

From the services panel, start the “Experion PKS CDA-SP Service” service.

If the service does not start, note the failure condition cited in the error message, correct the condition, and try again to start the service.

### Time to respond

The condition should be addressed immediately.

---

## CAS: Component Admin Service is not running

The System Health Monitor has detected that a crucial service is not running. The system management Component Admin Service manages HCI Servers that choose to be managed. It provides event notifications to WMI clients like the System Management Display and Redirection Manager.

### Potential causes

1. The service failed to auto-start after a reboot due to a configuration error.
2. A user manually stopped the service.
3. The running service failed.

### Consequence of inaction

Without the CAS service, the status of components is unknown.

### Corrective actions

From the services panel, start the service “sm-Component Admin Service”.

If the service does not start, note the failure condition cited in the error message, correct the condition, and try again to start the service.

### Time to respond

The condition should be addressed immediately.

---

## **CAS: was unable to Checkpoint component <component name> Error = <error num>:<error string>**

### **Potential causes**

The various causes of this alarm are described in the alarm <error num> and <error string>.

### **Consequence of inaction**

The checkpoint file for the component is not current. If the component were to be reloaded at this time it would be loaded with data from the last successful checkpoint. If that checkpoint file is current (that is, no component configuration changes were made since the file was created) there would be little or no consequence should the component need to be reloaded. However, if that checkpoint is obsolete (that is, component configuration changes have occurred since the checkpoint file was created) the configuration data will be lost if the component is reloaded. For example, if the component should fail at a time when the checkpoint file is obsolete, and then get reloaded from the obsolete file, all configuration changes made since the last successful checkpoint would be lost.

### **Corrective actions**

The solution varies for each cause. For known causes, the error string will likely provide enough information to correct the problem. If the error string does not provide sufficient information (and for unknown causes) the component log file must be examined. The alarm comes from CAS, but CAS is just reporting the error returned from the component so further investigation must be done on the specific component. The solution may require enabling logging on the component, initiating a checkpoint again, and then examining the log file for the cause.

### **Time to respond**

Current checkpoints should be maintained so that components can be reliably restarted at any time. Correct the problem and create a checkpoint as soon as possible.

---

## <Component Name>: Component state changed from <previous state> to Communication Failure

Component cannot communicate with underlying device. This is comparable to “component failed”.

### Potential causes

1. The state of the component's underlying device (or devices) has changed from a running state to a state that renders the component failed.
2. Unknown.

### Consequence of inaction

Loss of redundancy. This component has essentially failed and redundancy has been lost.

Potential loss of view. If the redundant partner is not running or should stop, view will be lost.

### Corrective actions

1. Restart any failed devices. Search proximate alarms for indication of the cause of the device failure.
2. Attempt to restart the component. Note the failure time and look in the event viewer application log for an entry pertaining to the failure. Look also in the event viewer system event log.

### Time to respond

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## **<Component name>: Component state changed from <previous state> to Failed**

Component failed.

### **Potential causes**

1. The state of the component's underlying device (or devices) has changed from a running state to a state that renders the component failed.
2. Unknown.

### **Consequence of inaction**

Loss of view. The component has failed and view to the device is lost.

### **Corrective actions**

1. Restart any failed devices. Search proximate alarms for indication of the cause of the device failure.
2. Attempt to restart the component. Note the failure time and look in the event viewer application log for an entry pertaining to the failure. Look also in the event viewer system event log.

### **Time to respond**

The condition should be addressed immediately.

---

## <Component name>: Component state changed from <previous state> to Warning

Component state changed to warning.

### Potential causes

1. The state of the component's underlying device (or devices) has changed from a running "OK" state to a state less than OK.
2. The component is starting up and the warning state is just a step in the progression from "Stopped", "Failed", or "Off".

### Consequence of inaction

Potential loss of redundancy. An underlying device may be failed or partially failed.

Potential loss of view. If the redundant device is not running, or should stop, view will be lost.

### Corrective actions

1. Restart any failed devices. Search proximate alarms for indication of the cause of the device failure.
2. Monitor state to ensure that it proceeds to "OK" or "Running".

### Time to respond

For loss of redundancy, the condition should be addressed as soon as possible.

For loss of view, the condition should be addressed immediately.



---

## <Component Name>: Device state changed from <previous state> to Communication Failure

Some devices communicate with “sub-devices”. Failure in that communication is comparable to “device failed”, which has the description “There is an error in the device or in the communications channel to the device”.

For example, TPNServer\_Boiler1: Device state changed from Running to Communication Failure

### Potential causes

1. Device failed.
2. Watchdog timeout. The device has not reported status or data to the component for some time.
3. The device is starting up and the warning state is just a step in the progression from “Stopped”, “Failed”, or “Off”.

### Consequence of inaction

Loss of redundancy. This device has essentially failed and redundancy has been lost.

Potential loss of view. If the redundant device is off or should fail, loss of view will occur.

### Corrective actions

1. Attempt to re-start the device. Use device specific information in the message to troubleshoot the device.
2. Look at performance indicators for the device and the opponent-to-device network status. For some devices and channels, this information is available on the component's auxiliary status display. Double-click the alarm in System Status Display to get to the detail page of the node. Use the components tab to navigate to the component and then select the aux. display button. Note that not all component types have an auxiliary display.
3. Monitor state to ensure that it proceeds to “OK” or “Running”.

### Time to respond

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

**<Component name>: Device state changed from <previous state> to Failed. Device Info: <device info>**

There is an error in the device or in the communications channel to the device.

**Potential causes**

1. Device failed.
2. Watchdog timeout. The device has not reported status or data to the component for some time.
3. The device is starting up and the warning state is just a step in the progression from “Stopped”, “Failed”, or “Off”.

**Consequence of inaction**

Loss of redundancy. This device has failed and redundancy has been lost.

Potential loss of view. If the redundant device is off or should fail, loss of view will occur.

**Corrective actions**

1. Attempt to restart the device. Use device specific information in the message to troubleshoot the device.
2. Look at performance indicators for the device and the opponent-to-device network status. For some devices and channels, this information is available on the component's auxiliary status display. Double-click the alarm in System Status Display to get to the detail page of the node. Use the components tab to navigate to the component and then select the aux. display button. Note that not all component types have an auxiliary display.
3. Monitor state to ensure that it proceeds to “OK” or “Running”.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## **<Component name>: Device state changed from <previous state> to Warning. Device Info: <device info>**

There is an error in the device or in the communications channel to the device.

### **Potential causes**

1. Device error.
2. Watchdog timeout. The device has not reported status or data to the component for some time.
3. The device is starting up and the warning state is just a step in the progression from “Stopped”, “Failed”, or “Off”.

### **Consequence of inaction**

Potential loss of redundancy. Depending on the device and the warning information, loss of redundancy may occur.

Potential loss of view. Depending on the state of the redundant device, loss of view may occur.

### **Corrective actions**

1. Attempt to re-start the device. Use device specific information in the message to troubleshoot the device.
2. Look at performance indicators for the device and the component-to-device network status. For some devices and channels, this information is available on the component's auxiliary status display. Double-click the alarm in System Status Display to get to the detail page of the node. Use the components tab to navigate to the component and then select the aux. display button. Note that not all component types have an auxiliary display.
3. Monitor state to ensure that it proceeds to “OK” or “Running”.

### **Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

**Control Firewall <device name> (address <Fw address>) port <port ID>  
excessive TX\_PAUSE change. Cur:<Tx Pause Val> Last:<Last Tx Pause  
Val>**

The Control Firewall detected a possible network loop in the system. Typically, a loop is created by having extra crossover cables between switches or CF9s resulting in an infinite path for multicast traffic.

**Potential causes**

This is caused by a network loop in the system.

**Consequence of inaction**

Potential loss of redundancy. A loop may cause devices to block.

If both channels become blocked, loss of view will occur.

**Corrective actions**

Evaluate the network for misplaced cables or possibly dual homed nodes. If unable to immediately identify the loop, contact TAC/Network Services to have a network survey done.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## Control Firewall <Fw name> (address <Fw address>) has blocked ports

The Control Firewall is blocking the ports due to a possible network loop in the system. If the Control Firewall sees messages from multiple MACs on a downlink port, it will enter the blocking mode. Typically, a loop is created by having extra crossover cables between switches or CF9s resulting in an infinite path for multicast traffic.

**Attention**

This event is generated only in Control Firewall.

---

**Potential causes**

This is caused by a network loop in the system.

**Consequence of inaction**

For non-redundant devices, a loss of view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss of view will occur.

**Corrective actions**

Evaluate the network for misplaced cables or possibly dual homed nodes. If unable to immediately identify the loop, contact TAC/Network Services to have a network survey done.

**Time to respond**

The condition should be addressed as soon as possible.

---

## Control Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE

A WMI instance deletion event was received for the firewall.

### Potential causes

1. The Control Firewall uplink cable has failed or has been disconnected.
2. The Control Firewall has been powered down or otherwise lost power.

### Consequence of inaction

For non-redundant devices, a loss-of-view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss-of-view will occur.

### Corrective actions

1. Re-connect or replace the uplink cable.
2. Power up the Control Firewall.

### Time to respond

The condition should be addressed as soon as possible.

---

## Control Firewall <Fw Name> (address <Fw Address>) port <port index> link status is Down

The Polling Timer detected a link status change and the link is down.

### Potential causes

This alarm indicates that the device connected to the port has failed (or been powered down) or that the connection from the port to the device has failed (cable failure or disconnect). Double-click on the alarm to see the Detail Display and navigate to the ports tab for additional information.

1. The device connected to the port has failed or been powered down.
2. The cable from the port to the device has failed or been disconnected.

### Consequence of inaction

For non-redundant devices, a loss-of-view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss-of-view will occur.

### Corrective actions

1. Check and correct the power and status of the device. Replace the device if necessary.
2. Check and correct the cables from the port to the device. Replace the cable if necessary.

### Time to respond

The condition should be addressed as soon as possible.

---

## Control Firewall <Fw name> (address<Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable

The Control Firewall (CF) has not acknowledged receiving a status request within the timeout period.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

---

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

Potential loss of redundancy.

The paths to the devices (through this CF) may no longer be functional. If redundancy is lost and other paths to the devices are unavailable, loss of view will occur.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.



---

## Control Firewall <Fw name> (address<Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable

The switch (Control Firewall) has not reported a status request within the timeout period.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

Potential loss of redundancy.

The paths to the devices (through this Control Firewall) may no longer be functional. If redundancy is lost and other paths to the devices are unavailable, loss of view will occur.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## Excessive Disk Paging: memory resource issue is causing excessive disk paging

### Potential causes

Paging is the process of moving fixed size blocks of code and data from RAM to disk using units called pages in order to free memory for other uses. Although some paging is acceptable because it enables the use of more memory than actually exists, constant paging is a drain on system performance. Reducing paging will significantly improve system responsiveness.

### Consequence of inaction

Insufficient resources can compromise the entire node.

### Corrective actions

1. Make sure the node meets Honeywell's minimum memory requirements for the node type.
2. Use the task manager to identify any non-Honeywell processes that are using large amounts of memory. Stop those processes if reasonable to do so.
3. If only Honeywell processes are running and excessive paging persists, call TAC. There are a number of Microsoft recommendations to alleviate excessive disk paging (setting page file size, splitting page file onto multiple disks, and so on) but these should be supervised by TAC.

### Time to respond

The condition should be addressed immediately.

---

## FTE device <device name> (Device Index: <device index>) has detected a duplicate

The device index is used more than once within the multicast group.

### Potential causes

Configuration error when assigning FTE device names.

### Consequence of inaction

Potential loss of view, potential alarm inconsistencies. Duplicate indexes cause indeterminate problems.

### Corrective actions

Use the FTE event log to identify the duplicate index. Follow the steps in the “Verify duplicate device indexes were not assigned” topic in the “Troubleshooting FTE” section of the *Fault Tolerant Ethernet Installation and Service Guide*. The duplicate status can also be seen in the FTE Heartbeat Node Status Display.

In the Honeywell FTE Mux-IM Protocol Driver Properties page, resolve any duplicates. Follow the steps in the “Modify FTE settings” topic in the “Operating and servicing FTE” section of the *Fault Tolerant Ethernet Installation and Service Guide*.

### Time to respond

The condition should be addressed immediately.

---

## **FTE device <device name> disjoined FTE community (no longer being heard)**

The FTE driver is no longer receiving messages from the device.

The device is no longer being heard on either the A or the B interface. This could be due to a problem in the device itself or in the loss of redundant communication paths (redundant cable failures or redundant switch failures). In this state the device will not appear in the FTE Status Display.

### **Potential causes**

1. The FTE device failed or was powered down.
2. Look in the System Status for numerous, proximate alarms, for other devices disjoining. If there is NO indication of numerous other devices that have disjoined simultaneously, and if it is known that the device is powered up, it is likely that both cables have failed.
3. Look in the System Status for numerous, proximate alarms, for other devices disjoining. If there are numerous devices that have disjoined simultaneously, it may indicate a common point of failure such as a switch.
4. In the case of duplicate device index, FTE effectively turns off, but the node may still be able to communicate if there are no faults in the network (since redundancy is lost).

### **Consequence of inaction**

Loss of view. View to the device has been lost.

### **Corrective actions**

1. Power up the device.
2. Check and correct all cables in the path from the device.
3. Check and correct all switches in the path from the device.
4. Correct device index.

### **Time to respond**

The condition should be addressed immediately.

## FTE Device <device name> interface <A/B> status is SILENT

The 1-second status monitor detected a change. For the current cycle, no status update was received from the device on the stated interface.

For more information about monitoring FTE devices, see the “Monitoring nodes in an FTE network” topic, in the “Operating and Servicing FTE” section of the *Fault Tolerant Ethernet Installation and Service Guide*.

### Potential causes

1. DISJOIN: Look for a proximate event stating the device has “disjoined FTE community (no longer being heard)”. If the DISJOIN event exists, address that event first because when the device is no longer being heard, it will not appear in the FTE Status Display that is used to diagnose the “SILENT” event.
2. Cable fault: Open the FTE Status Display and locate the device in the PDTag column. If there are relatively few devices that are SILENT, it is likely that each SILENT represents a cable fault.

The cause is that a cable has failed (or been disconnected) in the path that connects the device to the system.

3. Switch Failure: Open the FTE Status Display. If there are numerous devices that are SILENT, it may indicate a common point of failure such as a switch.

The cause is that a switch that connects the device to the system has failed or has been powered down.

4. Link speed/duplex: Open the FTE Status Display. If the device is toggling between “OK” and “SILENT” it may indicate a configuration error in the “Link speed / Duplex” setting of a network adapter or switch port. This may also manifest as appearing/disappearing in the FTE Status Display when both adapters or both ports, are in error.

The cause is a link speed/duplex configuration error.

5. Switch Uplink Error: Open the FTE Status Display. If there are numerous devices disconnected on either A or B, it may indicate a switch uplink cable error.

The cause is an uplink cable, on a lower level switch, has failed or been disconnected.

### Consequence of inaction

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss-of-view will occur.

### Corrective actions

1. Look for a proximate event stating the device has a “disjoined FTE community (no longer being heard)”. If the DISJOIN event exists, address that event first, as the device is no longer being heard and it will not appear in the FTE Status Display to be able to diagnose the “SILENT” event.
2. Check and correct all of the cables from the device to the system by observing LED status at each connection.
3. Check and correct the power and status of all switches in the path that connects the device to the system.
4. Check “Link speed / Duplex” setting of the device’s network adapters and their connected switch ports. It is advisable to check the link speed and duplex settings of all network adapters and switch ports.
5. Check and correct the uplink cables of all switches in the path that connects the device to the system.

### Time to respond

The condition should be addressed as soon as possible.

---

## **FTE/Heartbeat network packet delivery to application layer is being delayed. Node is experiencing Disk/CPU resource utilization issues**

### **Potential causes**

1. High CPU usage.
2. High disk access: This could be low RAM causing page faults, a misbehaving app, or even a virus scan.

### **Consequence of inaction**

Potential loss of view. Insufficient resources can compromise the entire node.

### **Corrective actions**

1. Use task manager to locate applications that are using excessive CPU. Use application-specific troubleshooting guidelines to reduce the amount of CPU used by those applications. Restart those applications if necessary.
2. Close any non-critical applications and attempt to identify applications that are using excessive resources. Track page faults in performance monitor. Assistance from TAC is recommended for this.

### **Time to respond**

The condition should be addressed immediately.

---

## **FTE STATUS: Device state changed from <previous state> to Failed.**

### **Device Info: <device information string>**

#### **Potential causes**

The cause of the failure is included in the “Device Info”, the device information string of the alarm.

#### **Consequence of inaction**

Loss of redundancy. This device has failed and redundancy has been lost.

Potential loss of view. If the redundant device is off or should fail, loss of view will occur.

#### **Corrective actions**

1. If the <device information string> is “This FTE Node has a Crosslink Failure”, check and correct the crosslink cables in the path from the device to the system.
2. If the <device information string> is “This device info heartbeat provider has stopped. FTE status cannot be determined”, check the SM-Heartbeat Provider service and start it if it is not running. Ensure that the service starts. The executable for this service is named *fteprovider.exe*.

#### **Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## FTEProvider: FTE Provider is not running

The System Health Monitor has detected that a crucial service is not running. The system management FTE Provider service relays information from the FTE driver to the various applications that use FTE for system communications and it provides an “I’m alive” heartbeat.

### Potential causes

1. The service failed to auto-start after a reboot due to a configuration error,
2. A user manually stopped the service,
3. The running service failed.

### Consequence of inaction

FTE Provider is a crucial link in both FTE and non-FTE node communication.

### Corrective actions

From the services panel, start the service “sm-Component Admin Service”.

If the service does not start, note the failure condition cited in the error message, correct the condition, and try again to start the service.

### Time to respond

The condition should be addressed immediately.



---

## **HCINS: Alias name: <component alias name> exists on two nodes in the same TPSDomain. You must remove or rename one of them to solve this problem**

Two components exist that have the same alias name but different definitions. That is, either the PROGID or the ACCESS (component type) of one component is different from that of the other component.

### **Potential causes**

This can be caused by configuring or adding a component while some node in the system is down (For example, adding or configuring “AliasNameX” while “Node1” is down). When Node1 restarts, it replicates the names in its repository. If AliasNameX was already in Node1’s repository, and if that definition is different from the new definition, then the duplicate condition exists and the event is logged.

### **Consequence of inaction**

Potential alarm and data inconsistencies.

### **Corrective actions**

You must remove or rename one of the components to solve this problem. Local components can be deleted using the “Name Service Configuration” tool in the System Management Display. Domain components can only be deleted (or renamed) using the “HCI Component Configuration” tool which is also accessed through System Management Display.

### **Time to respond**

The condition should be addressed immediately.

---

## **HCINS: Alias name: <component alias name> from the component alias file conflicts with the one in the repository - You must remove Alias name from the component alias file to solve this problem**

A component alias file is being imported and it contains a definition that conflicts with a component already in the repository.

### **Potential causes**

This occurs during the import of a component alias file which contains a component by the same name (but different definition) as a component already in the repository. Allowing the import would result in a duplicate alias name condition so the import is blocked.

### **Consequence of inaction**

Inability to configure the system.

### **Corrective actions**

Remove the alias definition from the file or remove the alias name from the repository.

### **Time to respond**

The condition must be addressed before configuration can proceed.

## Modbus/TCP Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down

The Polling Timer detected a link status change and the link is down.

For more information, see the “Modbus TCP Firewall faceplate and detail displays” topic in the “Monitoring Modbus TCP Firewall” section of the *Honeywell Modbus TCP Firewall User Guide*.

### Potential causes

The MODBUS/TCP Firewall (MBTCP) has two ports, secure and unsecure. The secure port connects to the FTE network. The unsecure port connects to a Modbus device network switch or, less commonly, directly to a Modbus device.

If the unsecure connection goes down there is a proximate alarm noting this event. If the secure connection goes down, or if the firewall fails, there is a proximate alarm noting the firewall is “no longer heard”. That alarm does not distinguish between interface, device, switch, or cable failure.

Possible causes for this event are these:

1. The MBTCP has been powered off or otherwise failed.
2. The cable that connects to the port has been disconnected or has otherwise failed.
3. The switch to which the port connects has been powered down or otherwise failed.



### Attention

The MBTCP uses a generic 9 port faceplate but statistics are only available for the Uplink port and Port 1. Port 2 through Port 8 display bad-quality data.

### Consequence of inaction

For non-redundant devices, a loss-of-view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss-of-view will occur.

### Corrective actions

1. Check and correct the power and status of the MODBUS/TCP Firewall.
2. Check and correct the power and status of the Modbus device network switch that connects to the unsecure port.
3. Check and correct the power and status of the switch that is connected to the secure port.

### Time to respond

The condition should be addressed as soon as possible.

---

## Modbus/TCP Firewall <Fw name> (address<Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable

The switch (Modbus/TCP Firewall) has not acknowledged receiving a status request within the timeout period. The paths to the devices (through this FW) may no longer be functional.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

For non-redundant devices, a loss of view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss of view will occur.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## Modbus/TCP Firewall <Fw name> (address <Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable

The switch (Modbus/TCP Firewall) has not reported a status request within the timeout period. The paths to the devices (through this firewall) may no longer be functional.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

---

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

For non-redundant devices, a loss of view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss of view will occur.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## **Modbus/TCP <Fw Name> (address <Fw address>) is no longer being heard by FTE**

A WMI instance deletion event was received for the switch.

### **Potential causes**

When this alarm is reported, it does not distinguish between interface, device, switch, or cable failure.

Possible causes for this event are:

1. The Modbus/TCP Firewall has failed or been powered down.
2. The cable, that connects to the secure port, has failed or been disconnected.
3. The switch, connected to the secure port, has failed or been powered down.

### **Consequence of inaction**

For non-redundant devices, a loss of view has occurred.

For redundant devices, redundancy is lost. If the other path to the device is unavailable, a loss of view will occur.

### **Corrective actions**

1. Power up the Modbus/TCP Firewall.
2. Check and correct the cable that connects the secure port to the switch.
3. Power up the switch.

### **Time to respond**

The condition should be addressed as soon as possible.

---

## One-Wireless Firewall <Fw Name> (address <Fw address>) is no longer being heard by FTE

A WMI instance deletion event was received for the switch.

### Potential causes

When this alarm is reported, it does not distinguish between interface, device, switch, or cable failure.

Possible causes for this event are as follows:

1. The OneWireless Firewall has failed or been powered down.
2. The cable, that connects to the secure port, has failed or been disconnected.
3. The switch, connected to the secure port, has failed or been powered down.

### Consequence of inaction

Loss of view has occurred.

### Corrective actions

1. Power up the OneWireless Firewall.
2. Check and correct the cable that connects the secure port to the switch.
3. Power up the switch.

### Time to respond

The condition should be addressed immediately.

---

## One-Wireless Firewall <Fw Name>(address <Fw Address>) port <port index> link status is Down

The Polling Timer detected a link status change and the link is down.

### Potential causes

The OneWireless Firewall (OWFW) has two ports, secure and unsecure. The secure port connects to the FTE network. The unsecure port connects to the wireless network.

If the unsecure connection goes down there is a proximate alarm noting this event. If the secure connection goes down, or if the firewall fails, there is a proximate alarm noting the firewall is “no longer heard”. That alarm does not distinguish between interface, device, switch, or cable failure.

Possible causes for this event are these:

1. The OWFW has been powered off or has otherwise failed.
2. The cable that connects to the port has been disconnected or has otherwise failed.
3. The switch to which the port connects has been powered down or has otherwise failed.

### Consequence of inaction

A loss-of-view has occurred.

### Corrective actions

1. Check and correct the power and status of the OWFW.
2. Check and correct the power and status of the wireless network that connects to the unsecure port.
3. Check and correct the power and status of the switch that is connected to the secure port.

### Time to respond

The condition should be addressed as soon as possible.



---

## One-Wireless Firewall <Fw name> (address <Fw address>) uplink RX\_OCTETS has stalled. Check for intermittent cable

The switch (OneWireless Firewall) has not acknowledged receiving a status request within the timeout period. The paths to the devices (through this firewall) may no longer be functional.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

---

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

Loss of view has occurred.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

The condition should be addressed immediately.

---

## One-Wireless Firewall <Fw name> (address <Fw address>) uplink TX\_OCTETS has stalled. Check for intermittent cable

The switch (OneWireless Firewall) has not reported a status request within the timeout period. The paths to the devices (through this firewall) may no longer be functional.

**Attention**

Intermittent cables include partially failed cables where the link may still be active, but TX or RX wire pairs have failed.

---

**Potential causes**

The path from the uplink port to the system, which had previously passed data, has failed.

**Consequence of inaction**

Loss of view has occurred.

**Corrective actions**

Check and correct the uplink cable and connections. Check and correct all cables and connections in the upstream from the uplink cable.

**Time to respond**

The condition should be addressed immediately.

---

## OPC Event Source: <node name>. Proxy ARP agent found. Check router configuration

### Potential causes

By default router interfaces run a proxy ARP agent. In cases where devices are not on the same subnet as the routed interface (common with controllers under best practices) the router will respond to ARP requests for the controllers MAC address with its own MAC address, potentially causing loss of view to the controller. This can be intermittent depending on which ARPs from the controller and the router for the controller IP address reach the other nodes. The AddRoute service periodically checks to see if the router is performing the proxy ARP function and logs this event if the router responds with a proxy ARP.

### Consequence of inaction

See “Potential causes” above.

### Corrective actions

Add the “no ip proxy-arp” command to the routed interfaces connected to an FTE network.

### Time to respond

The condition should be addressed immediately.

---

## SNMP Trap: - <IP Address> Type - AuthenticationFailure

Generated when the sending device receives a message that is not properly authenticated. For example, an incorrect login attempt. An AuthenticationFailure trap signifies that the sending protocol entity is the addressee of a protocol message that does not have proper authentication.

### Potential causes

This trap occurs when a network management system (NMS) polls the device with the wrong community string.

### Consequence of inaction

Potential loss of redundancy. The device reporting path (through this switch) may be lost.

If both reporting paths (through both switches) is lost, loss of view will occur.

Potential no-impact. This could be a configuration issue that does not impact view.

### Corrective actions

The IP address in the trap indicates the origin of the message. Investigate there for authentication errors.

### Time to respond

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## SNMP Trap: - <IP Address> Type - ColdStart

Trap signifies that the sending device is re-initializing itself and may have been altered.

**Potential causes**

Switch is powered up.

**Consequence of inaction**

Not applicable.

**Corrective actions**

No action required.

**Time to respond**

Not applicable.

---

## SNMP Trap: - <IP Address> Type - LinkDown; Index - <Index>

The sending device recognizes the failure of a communication link.

### Potential causes

1. Switch is powered down or failed.
2. Cable is disconnected or failed. This includes the cross cable.
3. Device is powered down or fails.
4. Control Firewall is powered down or fails.
5. Control Firewall uplink port is disconnected or fails.

### Consequence of inaction

Loss of redundancy. The device reporting path (through this switch) has been lost.

If the device reporting path (through the other switch) is lost, loss of view will occur.

### Corrective actions

1. Power up the switch. Replace or repair switch if necessary.
2. Examine physical path to device and connect all cables. Replace or repair cables if necessary.
3. Power up the device. Replace or repair device if necessary.
4. Power up the Control Firewall. Replace or repair the Control Firewall.
5. Reconnect Control Firewall uplink port. Replace or repair Control Firewall if necessary.

### Time to respond

For loss of view, the condition should be addressed immediately.

For loss of redundancy, the condition should be addressed as soon as possible.

---

## SNMP Trap: - <IP Address> Type - WarmStart

Trap signifies that the sending device is re-initializing itself and has not been altered.

**Potential causes**

Switch reset.

**Consequence of inaction**

Not applicable.

**Corrective actions**

No action required.

**Time to respond**

Not applicable.

---

## **SRP(syncrep.exe): FTE Status cannot be determined. Restart FTE Status server. <error message>**

Various errors are funneled into this event.

### **Potential causes**

FTESStatus got an error while executing a WMI query.

### **Consequence of inaction**

Device reporting state cannot be determined.

### **Corrective actions**

From the System Status Display, restart the FTESStatus server.

### **Time to respond**

The condition should be addressed immediately.



---

## **SRP(syncrep.exe): SRP has not heard expected traffic for an excessive period. Reconnecting Receive socket**

The SRP multicast receive message handler timed out (2 minutes) while waiting for an input message. This means that the node has not even received its own message that is sent periodically from the SRP multicast send message handler. This can indicate an error in the configuration or network adapter binding order, or it can indicate an error in the configuration of network adapter link speed/duplex.

### **Potential causes**

1. Typically this does not occur in FTE nodes because the FTE installation sets the binding order automatically. For non-FTE nodes, the user must configure this manually.
2. Typically this does not occur in FTE nodes because the FTE installation sets the binding order automatically. For non-FTE nodes, the user must configure this manually.

### **Consequence of inaction**

Loss of alarms on this node.

### **Corrective actions**

1. Make sure the primary and secondary adapters are at the top of the preference order under network adapter advanced settings.
2. Make sure the link-speed duplex settings are correct so that the network card does not lose connection. Typically this needs to be set to 100MB/Full duplex, but check the release-specific specifications.

### **Time to respond**

The condition should be addressed immediately.

---

## Synchronization requests were not answered by node(s): <node list>

### Potential causes

1. Network configuration is preventing Synchronized Repository Provider (SRP) communication between nodes.
2. Synchronized Repository Provider (SRP) configuration is preventing SRP communication between nodes.

### Consequence of inaction

Nodes are out of sync with respect to the state of the various system alarms and events within the multicast scope - an accurate view of system events is not available. Failure to receive and display an alarm could make an operator unaware of a critical event.

### Corrective actions

1. Verify that adapters and corresponding switch ports are set to 100MB/Full duplex. Verify network interfaces are configured correctly with respect to IP configuration.
2. Verify that SRP multicast addresses are correct adapters and corresponding switch ports are set to 100MB/Full duplex.

### Time to respond

This should be addressed immediately.

---

## SysEvtProv: System Event Provider is not running

The System Health Monitor has detected that a crucial service is not running. The system management System Event Provider service captures windows events into a common synchronized repository of events. A filter file is used to identify window events to be produced into the synchronized repository.

### Potential causes

1. The service failed to auto-start after a reboot due to a configuration error.
2. A user manually stopped the service.
3. The running service failed.

### Consequence of inaction

Potential loss of alarms and potential loss of events. Without this service, system events and alarms are not maintained.

### Corrective actions

From the services panel, start the “sm-System Event Provider” service.

If the service does not start, note the failure condition cited in the error message, correct the condition, and try again to start the service.

### Time to respond

The condition should be addressed immediately.

## The system detected an address conflict for IP address <IP Address> with the system having <network> hardware address <hdw address>.

### <Message>

Where:

- for Event ID 4198, <Message> is “The local interface is being disabled.”
- for Event ID 4199, <Message> is “Network operations on this system may be disrupted as a result.”

#### Potential causes

The assigned Static IP displays 0.0.0.0 (for event ID 4198).

Windows detected a duplicate media access control (MAC) address on the network. The system detected an address conflict for the <IP address> with the system having the <hdw address>. The local interface has been disabled. Both the adapter and the other device are using the hardware address specified. Each device should have a unique address.

Media access control addresses are pre-assigned and permanently burned into the network interface card (NIC). These addresses under normal circumstances are always unique, however, rare errors made during the manufacturing process can cause duplicate media access control addresses to be used and cause this problem. Another source of duplicate media access control addresses can occur if you are assigning locally administered media access control addresses (LAA), in which case you are overriding the burned-in address in favor of the locally assigned media access control address. With some drivers, LAA media access control addresses are possible, usually Token Ring adapter drivers.

#### Consequence of inaction

Potential loss of view. All network connectivity over TCP/IP to this computer has ceased until the conflict is resolved and the system is restarted.

#### Corrective actions

To troubleshoot this problem, you have to determine which other computer on the network is using the same media access control address. Several tools that ship with the Microsoft TCP/IP stack can be used to locate the duplicate addressed computer. To isolate the duplicate media access control address, perform the following steps:

The example below uses IP address 129.0.0.1, and hardware address 02:A0:8C:DE:00:FD. For your troubleshooting, use the addresses from the alarm message.

From a working TPC/IP based client:

- 1 Ping the TCP/IP address found in the event log entry from a command prompt by typing the following:  
PING 129.0.0.1

You should get replies back similar to these from the duplicate addressed computer:

```
Pinging 129.0.0.1 with 32 bytes of data
Reply from 129.0.0.1: bytes=32 time=10ms ttl=128
Reply from 129.0.0.1: bytes=32 time=<10ms ttl=128
Reply from 129.0.0.1: bytes=32 time=<10ms ttl=128
Reply from 129.0.0.1: bytes=32 time=<10ms ttl=128
```

- 2 To verify the computer's media access control address is the duplicate, type the following at a command prompt:

```
ARP -a 129.0.0.1
```

You should get a reply back as follows:

```
Internet Address Physical Address
129.0.0.1 02:A0:8C:DE:00:FD <-- matches the event log entry
```

- 3 We can now use NBTSTAT to get the NetBIOS (friendly) name of the duplicate computer by typing the following at a command prompt:

```
NBTSTAT -A 129.0.0.1
```

You should get a reply back with the NetBIOS name of the computer. Use this NetBIOS name to determine who the owner of the computer is so you can locate it on your network.

NAME	TYPE	STATUS
NTSERVER1	<00>	Unique
DOMAN-NAME	<00>	GROUP
NTSERVER1	<03>	Unique

```
Media access control address = 02-A0-8C-DE-00-FD
```

If you get a message:

HOST NOT FOUND.

This would indicate that the duplicate computer is not a NetBIOS enabled computer, like a Novell server, Unix server, Router, or perhaps a Jet Direct Printer.

- 4 Once you find the duplicate addressed computer, you can either replace its network card, or if a locally administered media access control address (LAA), change it to be unique on the network.

Change the LAA:

- 1 In the Windows Control Panel, double-click the Network icon.
- 2 While displaying the properties of the installed network adapter, change the properties or configuration of the installed Network Adapters LAA to use a unique LAA.

#### Time to respond

The condition should be addressed immediately.



# Notices

## **Trademarks**

Experion®, PlantScape®, SafeBrowse®, TotalPlant®, and TDC 3000® are registered trademarks of Honeywell International, Inc.

OneWireless™ is a trademark of Honeywell International, Inc.

## **Other trademarks**

Microsoft and SQL Server are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Trademarks that appear in this document are used only to the benefit of the trademark owner, with no intention of trademark infringement.

## **Third-party licenses**

This product may contain or be derived from materials, including software, of third parties. The third party materials may be subject to licenses, notices, restrictions and obligations imposed by the licensor. The licenses, notices, restrictions and obligations, if any, may be found in the materials accompanying the product, in the documents or files accompanying such third party materials, in a file named third\_party\_licenses on the media containing the product, or at <http://www.honeywell.com/ps/thirdpartylicenses>.

---

## Documentation feedback

You can find the most up-to-date documents on the Honeywell Process Solutions support website at:

<http://www.honeywellprocess.com/support>

If you have comments about Honeywell Process Solutions documentation, send your feedback to:

[hpsdocs@honeywell.com](mailto:hpsdocs@honeywell.com)

Use this email address to provide feedback, or to report errors and omissions in the documentation. For immediate help with a technical problem, contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC) listed in the “Support and other contacts” section of this document.



---

## How to report a security vulnerability

For the purpose of submission, a security vulnerability is defined as a software defect or weakness that can be exploited to reduce the operational or security capabilities of the software.

Honeywell investigates all reports of security vulnerabilities affecting Honeywell products and services.

To report a potential security vulnerability against any Honeywell product, please follow the instructions at:

<https://honeywell.com/pages/vulnerabilityreporting.aspx>

Submit the requested information to Honeywell using one of the following methods:

- Send an email to [security@honeywell.com](mailto:security@honeywell.com).
- or
- Contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC) listed in the “Support and other contacts” section of this document.

---

## Support

For support, contact your local Honeywell Process Solutions Customer Contact Center (CCC). To find your local CCC visit the website, <https://www.honeywellprocess.com/en-US/contact-us/customer-support-contacts/Pages/default.aspx>.

---

## Training classes

Honeywell holds technical training classes on Experion PKS. These classes are taught by experts in the field of process control systems. For more information about these classes, contact your Honeywell representative, or see <http://www.automationcollege.com>.



# Index

## A

### alarms

- archive system alarms 15
  - communications system alarms 19
  - diagnostic system alarms 65
  - duplicate point system alarms 269
  - event archiving system alarms 271
  - history archiving system alarms 275
  - link system alarms 279
  - no condition system alarms 283
  - null system alarms 291
  - orphans system alarms 295
  - replication system alarms 315
  - scripting system alarms 319
  - synchronizing system alarms 453
  - system alarms 15, 19, 65, 269, 271, 275, 279, 283, 291, 295, 315, 319, 453
  - Systems Management 457
- ### archiving
- system alarms 15, 271, 275

## C

- COMMS system alarms 19
- communications
  - system alarms 19

## D

- DIAG system alarms 65
- diagnostics
  - alarms 65
  - system alarms 65
- duplicate point 269

## E

- event archiving
  - system alarms 271
- EVTARC system alarms 271

## H

- history
  - system alarms 275

- HSTARC system alarms 275

## L

- linking
  - system alarms 279

## N

- no condition system alarms 283
- NULL system alarms 291

## O

- ORPHANS system alarms 295

## R

- replication system alarms 315

## S

- scripting
  - system alarms 319
- synchronizing
  - system alarms 453
- system alarms
  - archive alarms 15
  - COMMS (communications) alarms 19
  - DIAG (diagnostic) alarms 65
  - duplicate point alarms 269
  - EVTARC (event archiving) alarms 271
  - HSTARC (history archiving) alarms 275
  - LNK (link) alarms 279
  - no condition alarms 283
  - NULL alarms 291
  - ORPHANS alarms 295
  - replication alarms 315
  - scripting alarms 319
  - SYNC (synchronization) alarms 453
  - Systems Management 457
- Systems Management
  - system alarms 457
- Systems Management system alarms 457

