


## D] Inverter Current Control





We want  $PF = 1$   
 $S = P$

How to ensure that current flowing into the grid is in phase with  $V$




\* Remember Regenerative braking



→ Hysteresis Band Current Controlled PWM

Step 1 Generate reference sinusoid in phase with grid voltage  $V_2$  and of required magnitude (multiply by constant  $< 1$ )



Step 2 Modulate  $S_1$  such that current fits the reference

→ Can we use sinusoidal PWM to obtain unity PF?

- Yes, indirectly.


- Obtain  $V_i = V_m \sin(\omega t + \delta)$  using PWM

$$i = \frac{V_i / s - V_2 / s}{j \times L}$$

$$\Rightarrow L \frac{di}{dt} = V_m \sin(\omega t + \delta) - V_2 \sin(\omega t)$$

★  $\Rightarrow$  Current will be forced to be sinusoidal and in phase


→ We know how to transfer power from DC to AC at UPF.  
We can do reverse (AC to DC at UPF) by reversing current direction.



23/3




## Quiz Review



$$E = V_{dc}^* - V_{dc}(\text{actual})$$

$$= 0 \text{ (steady state)}$$

- To find correct value of  $E$ , finding  $V_1, V_2, X$  and matching power is not practical in real time. Use a controller.
- If there is a power mismatch,  $V_{dc}$  will change.
- When  $E \neq 0$ , we change  $P = \frac{V_1 V_2 \sin \delta}{X}$  as required to make  $E = 0$ .
- Sinusoidal PWM :- IF  $V_{dc} < V_{dc}^*$ , decrease  $P$  by changing  $(\text{increase } |p|)$ .
- Current PWM :-  $P = V_1 I_1 \cos \theta$  :- IF  $V_{dc} < V_{dc}^*$  decrease  $P$  by decreasing  $I$ .  
( $\cos \theta = 1$ )
- IF  $PF \neq 1$ , Power transferred  $\propto I \cos \theta$



In-phase current component  
( $I \cos \theta$ )

Non-zero power

Quadrature current component  
( $I \sin \theta$ )

Zero 'active' power

\* Output voltage of sinusoidal PWM inverter =  $m V_{dc} < V_{dc}$   
 $\uparrow$   
 $M I$   
 'Buck operation'

\* CSI :- ~~buck~~ Boost operation

Close  $S_1, S_4$  together  $\Rightarrow$  current  $\uparrow$ , energy stored  
 $\hookrightarrow$  no short-circuit because of inductor

Open  $S_1, S_4$   $\Rightarrow$  current  $\downarrow$ , energy transferred to output



Brushless DC machine :- Synchronous

Page No.:

## SYNCHRONOUS MACHINES


	Stator I	Rotor
DC	DC	DC
Induction	AC	AC
Synchronous	$\left\{ \begin{array}{l} 3\phi \text{ AC} \\ \text{DC} \end{array} \right\}$	$\left\{ \begin{array}{l} \text{DC} \\ \text{AC} \end{array} \right\}$

- Steady state speed of synchronous machines =  $N_s$  = independent of load.
- High power applications ( $\sim$  MW)

\* Induction machine :- PF is always lagging because of magnetizing

- Stator of SM is like IM, but rotor is DC.
- eg To generate 50 Hz, prime-mover should rotate 2-pole rotor at 3000 rpm.

- Rotors  $\left\{ \begin{array}{l} \rightarrow \text{Cylindrical (2 pole)} \\ \rightarrow \text{Salient pole (4 pole)} \end{array} \right.$



- Air gap is not uniform
- Unsuitable for high speed.
- Air gap is very small along field (direct (D)) axis
- Angle between direct axis and quadrature axis =  $45^\circ$  mechanical =  $90^\circ$  electrical
- Air gap is large along Q-axis
- $\therefore$  Reluctance along Q  $\gg$  Reluctance along D

$$\begin{aligned} R_Q &\gg R_D \\ \star &\rightarrow X_Q \ll X_D \end{aligned}$$

- When rotor is driven at 3000 rpm, DC field (of rotor) is rotated at 3000 rpm.

$$\vec{E} = \vec{A}$$

Voltage induced in stator is AC  $\therefore \vec{E} = 4.44 \phi F N$

$$E \propto \omega I_f$$

--	--	--

- 
- The diagram shows a circuit model of a synchronous motor. An AC voltage source  $\tilde{V}_s$  is connected to a load. The motor's internal circuit consists of a series combination of resistance  $R_s$ , synchronous reactance  $X_{se}$ , and armature reactance  $X_a$ . The induced EMF is  $\tilde{E}$ , and the armature current is  $I_a$ . The synchronous current is  $I_s$ .

- aids in some places  
opposes at others  
(Cross Magnetization)

$X_a$  = Armature Reaction Reactance (fictitious)


$$Z_s = \text{Synchronous Impedance } 2jX_s$$

- 

GBAFO formula for Q



- What we have studied
- If  $I_s$  is leading



GBAFO To which of above cases does

23/3

- $R_s \ll X_s$

→ When machine is connected to the grid,  $V$  and  $f$  cannot change

- Since I/p Power is held constant, active component of current cannot change.
- Reactive current can change.
- PF can change
- Accordingly,  $E_s / \delta$  can change.

GBAFO Locus of current

\* DC Machine :- Projected poles on stator, cylindrical rotor  
Synchronous rotor ?

Both have non-uniform air gaps.

## I SYNCHRONOUS MOTOR

- Three phase supply is given
- For steady torque,  $F_s$  and  $F_r$  should be stationary with respect to each other

$$T \propto F_s F_r \sin \delta$$

$\delta$  should be constant

- Speed of stator field ( $F_s$ ) =  $N_s$
- " " rotor " ( $F_r$ ) =  $N_r$  (Initially zero)

- At smaller frequencies ( $\downarrow N_s$ ), if inertia is small, rotor can catch up speed in spite of unsteady torque. If this happens we can very gradually keep increasing frequency, and rotor will accelerate (if inertia is small)

We don't do this shizz.

- Rotor has two types of windings :- cage winding and field winding
- Because of cage winding, motor starts like an induction motor. However, this torque generated becomes zero at  $N_r \rightarrow N_s$

- As  $N_r \rightarrow N_s$ , connect field winding.

Now  $F_s$  &  $F_r$  are almost constant.

$N_r$  is brought up to  $N_s$  by this field torque

😊\* Torque-producing losses of induction machine ( $sP_{\text{air gap}}$ ) are absent in synchronous machine because  $s = 0$

😊 - But there still are (new) field copper losses

😊 - To remove those, use permanent magnets instead of field winding ----- "Permanent magnet motor"

😊 - In normal synchronous machine, when  $N_r = N_s$ , if load is suddenly increased,  $N_r \downarrow$ . Then cage torque increases too. IE tries to accelerate  $N_r$ .

Hence cage winding provides damping effect to  $N_r$ .

P.T.O



- Since permanent magnet machines do not have cage winding, there is no damping.  $\Rightarrow$  Unstable.
- We can still use permanent magnet machines to drive fan/pump because  $T_L \propto \omega_r^2$  does not change instantaneously.

### Permanent magnet 'Synchronous' Machine

- In general, stator frequency is independent of every disturbance. Keep stator frequency dependent on rotor speed, to overcome instability.
- But we will not be able to maintain a single speed. Use a brushless DC machine instead.





→ Combination of R-L.

-  $\alpha = 0$

-  $\beta < 2\pi$ , because now  $\langle V_o \rangle \neq 0$ .

- Current reaches peak between  $\frac{\pi}{2}$  and  $\pi$   
 $\uparrow$   $\uparrow$   
 when  $L=0$  when  $R=0$

-  $V_m \sin \omega t = iR + L \frac{di}{dt}$

When  $i = i_{\max}$ ,  $V_m = i_{\max} R$

-  $\gamma < 2\pi$

-  $\langle V_o \rangle$  is between  $\frac{V_m}{\pi}$  and 0  
 $\uparrow$   $\uparrow$   
 when  $L=0$  when  $R=0$

• When  $\gamma$  increases,  $\langle V_o \rangle$  decreases.

This is because beyond  $\omega t = \pi$ ,  $V_m < 0$ .