


# **VelocitàCNC**




## **User Guide**


# **Index**

<b>Index</b>	<b>Topic</b>	<b>Page No.</b>
<b>1</b>	<b>Setup</b>	<b>3</b>
<b>2</b>	<b>Facing</b>	<b>4</b>
<b>3</b>	<b>Turning</b>	<b>5</b>
<b>4</b>	<b>Taper Turning</b>	<b>6</b>
<b>6</b>	<b>G-Code File</b>	<b>7</b>
<b>7</b>	<b>Animation</b>	<b>8</b>


## Setup

<b>ENTER STOCK</b>	D: 200	L: 400	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM.	


1. Enter the stock diameter (D) and Press Enter Key.
2. Enter the stock length (L) and Press Enter Key.

<b>CNC MACHINE</b>	D:	L:	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. φ200X400	


## Facing

CNC MACHINE	D:	L: 51	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	


1. Select Facing option.
2. Enter the length (L) to be cut for Facing operation.
3. Press Enter key.

CNC MACHINE	D:	L:	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	


## Turning

CNC MACHINE	D: 100	L: 100	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	


1. Select Turning operation.
2. Select the start point for specified operation.
3. Enter the final diameter (D) you want after Turning.
4. Enter the length (L) to be cut from the selected start point.
5. Press Enter.

CNC MACHINE	D:	L:	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	

## Taper Turning


CNC MACHINE	D:	L: 401	✓
SELECT START POINT	ANGLE: 30	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	

1. Select Taper Turning option.
2. Select the start point at which measurements are to be input.
3. Enter the angle (in degrees) for the taper cut.
4. Enter the horizontal length to be cut for Taper Turning operation.
5. Press Enter.

CNC MACHINE	D:	L:	✓
SELECT START POINT	ANGLE:	OFFSET:	
		FACING	
		TURNING	
		TAPER TURNING	
		STOCK DIM. Φ200X400	

# G-Code File

AFTER FINALIZING ALL THE OPERATIONS, CLICK ON CHECK MARK (✓) TO GENERATE G-CODE/M-CODE




The screenshot shows a software window titled 'GMcode.tap' with a menu bar (File, Edit, Search, View, Encoding, Language, Settings, Macro, Run, Plugins, Window, ?) and a toolbar. The main text area contains 29 lines of G-code, each starting with a line number from 1 to 29. The code includes various G-code commands like G00, G01, M06, M08, X, Y, S, F, and T, with numerical values for coordinates, speeds, and tool numbers.

```
1 N30 G00 M06 X500 Y500 S0 F0 T01
2 N40 G00 M08 X305 Y105 S50 F5 T01
3
4 N50 G00 M08 X298 Y105 S50 F5 T01
5 N60 G01 M08 X298 Y0 S50 F1 T01
6 N70 G01 M08 X318 Y0 S50 F1 T01
7 N80 G00 M08 X318 Y105 S50 F5 T01
8
9 N90 G00 M08 X296 Y105 S50 F5 T01
10 N100 G01 M08 X296 Y0 S50 F1 T01
11 N110 G01 M08 X316 Y0 S50 F1 T01
12 N120 G00 M08 X316 Y105 S50 F5 T01
13
14 N130 G00 M08 X295 Y105 S50 F5 T01
15 N140 G01 M08 X295 Y0 S50 F1 T01
16 N150 G01 M08 X315 Y0 S50 F1 T01
17 N160 G00 M08 X315 Y105 S50 F5 T01
18
19 N170 G00 M06 X500 Y500 S0 F0 T02
20 N180 G00 M08 X300 Y100 S50 F5 T02
21
22 N190 G01 M08 X245 Y100 S50 F1 T02
23 N200 G01 M08 X245 Y100 S50 F1 T02
24 N210 G00 M08 X300 Y100 S50 F5 T02
25 N220 G00 M08 X300 Y98 S50 F5 T02
26
27 N230 G00 M08 X300 Y98 S50 F5 T02
28
29 N240 G01 M08 X245 Y98 S50 F1 T02
```

1. View the G-Code file in the selected directory.
2. Generation of G-Code/M-code from the selected operations is then followed by animation.
3. The animation will show the final order in which the stock will be cut to obtain the desired job.

# Animation



1. Press (ESC) key to close the program once the animation is completed.
2. Press (R) key to repeat the animation.