

Eight Discipline Report (8D Report)

To:	8D report No.:
From: :	RMA claim No.:
CC :	Chicony Power P/N: W065RP02P-SA01
	Customer P/N:
Submit date: 2019/10/04	Product description:
Receive date: 2019/10/04	

Subject : EFT 測試 PWM MOS 損壞 (EFT 引發 SR 誤動作造成 PWM & SR MOS 同時導通)
干擾, 雜訊, 突波, 異常動作 [EFT, short through]

D1.) 問題解決成員: Use Team Approach

主持者 (Team Leader) :

內部成員 (Internal Team Members):


外部成員 (External Team Member):

D2.) 問題說明: Problem Description:

(Note: Use **who, what, when, where, why, how, how many** to specify the Customer's problem.)

65W Power EFT Issue

1. 在客戶端測試 4KV EFT 時, 發生 adapter damage 現象。
2. 開蓋後如下, Q1 & PWM IC 及其周邊有焦黑現象。



D3.) 內部或客戶的暫時解決辦法及實施日期: Implement and Verify Containment Action:

(Note: Internal / external containment action effectiveness and date.)

1. FAE of CPT got this PSU from customer for further analysis.
2. CPT send 1pc PSU to customer for exchange.

D4.)不良原因確認: Define and Verify Root Causes:


(Note: Identify and verify all suspect causes, which needs explain why the problem occurred.)

1. 將二次側 SR circuit 改為 schottky, 測試結果為 PASS
2. 推估是由於一二次側 MOS 同時導通而造成 damage。
3. 實際所勾的波型中發現, 在 EFT 過程中確實 Vgs 會有誤動作的現象, 由於 SR IC 受到 noise 干擾, 使得原本應該 turn off 的 MOS turn on, 而造成一二次側 MOS 同時導通現象。




1. 原本使用 SR IC 為 MPS6907, 將其改為 MPS6908。
2. MP6908 比起 MP6907 新修改了 Min on time 1.6uS→1.1uS, 因此 Vgs 發生誤動作時可減少 Q1 與 SR 同時導通的時間。

Slew rate detection function




MP6907 to MP6908

- Vreg: -70mV → -40mV
- Turn-off propagation delay: 20ns → 15ns
- IQ: 2mA → 110uA. (Don't need LL mode)
- Min. on time: 1.6us → 1.1us
- VDS Turn-on threshold: -200mV → -80mV
- Both turn-on/off delay: Shrinks to 15ns




MP6908 can prevents false turn-on during DCM operations.

- 在發生 EFT noise 的干擾之後，原 MP6907 Vds DCM ring 會造成 Vgs 誤觸發而 turn ON。



- 同樣在發生 EFT noise 的干擾之後，改成 MP6908 的 Vds DCM ring 並不會造成 Vgs 有誤動作現象。



D5.)改善措施:Corrective Action Verification:

(Note: Be make sure the corrective actions is effective in process as well as able to fix the customer complaint problem)

1. PCB 修改 Layout

2. MP6907 改為 MP6908

D6.)改善措施實施日期:Implement Permanent Corrective Actions:

(Note: Be provide the phase-in date or lot# of corrective actions **implementation** in process)

immediately

D7.)預防再發生措施:Prevent Recurrence:

(Note: Modified the management, operating systems, practices, and procedures to prevent recurrence for the problems as well as lessons learned cases.)

EFT 規格較嚴時，需確認一二次側 gate 波形以避免誤動作

D8.)確認並感謝問題解決成員:Check and Congratulate the Team:

(Note: Recognize the collective efforts of the team.)

Thanks to you all ! ! !

Signature	
Team Leader:	
	Name – Title
Signature by Approver:	
	Name-Title