



## Eight Discipline Report (8D Report)

To: 8D report No.: **CPJ0303**

From: **Chicony Power Technology** RMA claim No.: **N/A**

CC: CPT P/N: **A065R161P-HW01-0A**

Customer P/N:

Submit date: **2019/3/7** Product description: **65W adapter**

Receive date: **2019/3/6** Defect D/C or Lot No.: **1809**

Subject : **abnormal output \* 1pc**

D1.) 問題解決成員: Use Team Approach

主持者 (Team Leader) : **CF\_ Liu**

內部成員 (Internal Team Members):

**CQS: Jack Wang**

**FA: Sam Wei**

**QE: Quan Zhang**

**TE: Qing Ye**

**MFG: Caihua Jing**

**ME: Xiong HuangFu**

外部成員 (External Team Member):

D2.) 問題說明: Problem Description:

(Note: Use **who, what, when, where, why, how, how many** to specify the Customer's problem.)

**2019/3/5 Customer feed backed 1pc defect PSU, the defective phenomena is acoustic.**

*Defective PSU Information:*

*Model : TPN-CA10*

*Customer C/T: WGWEN0AP6BC3DR*



**D3.) 內部或客戶的暫時解決辦法及實施日期: Implement and Verify Containment Action:**

(Note: Internal / external containment action effectiveness and date.)

**Chicony took the defective sample from customer to do the further analysis.**

**Date: 2019/3/5**

**D4.) 不良原因確認: Define and Verify Root Causes:**

(Note: Identify and verify all suspect causes, which needs explain why the problem occurred.)

- By tracking the SN in our SFCS, this adapter passed all the test stations in the production line.**

Customer SN

WGWN0AP6BC3DR

Query

Export

Batch Exp

Work Order	N1838S06	Serial Number	FTI38S0601212
Part No	A065R161PHW010A	Customer SN	WGWN0AP6BC3DR
Version	N/A	QC LotNo	QCM0118092739184
SPEC1		Pallet No	PTI38S0600014
OutPut Time	2018/9/27 下午 07:51:57	Carton No	CTI38S0600312
Status	Complete	Box No	N/A

Travel

Repair

Quality Control

KeyParts

Rework



Work Order

Current

Burn In

Version	Route Name	PDLine Name	Stage Name	Process Name	Terminal Name	Assign Process	Current Status	Work Flag
N/A	R-noICC-M1-εM01		FINAL ASSEM	ICT	ICT01		Normal	Normal
N/A	R-noICC-M1-εM01		FINAL ASSEM	ACT	ACT04		Normal	Normal
N/A	R-noICC-M1-εM01		FINAL ASSEM	ASSY	ASSY02		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	BurnIn-Start	BurnIn-Start01		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	HIPOT/GROUND	HIPOT/GROUND		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	M-FINAL-ATE1	M-FINAL-ATE1-		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	M-FINAL-ATE2	M-FINAL-ATE2-		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	M-FINAL-ATE3	M-FINAL-ATE3-		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	PACKING	PACKING01		Normal	Normal
N/A	R-noICC-M1-εM01		PACKING	SNPrint	SNPrint01		Normal	Normal
N/A	R-noICC-M1-εM01		QC	QC	QC01		Normal	Normal

- Take the PSU to do the turn on test, it can power on normally. But when touch to the SR it hasn't the output, after release hand the defective symptom disappeared.**



- Open the case to observe the soldering side and the component side, see the negative pole of the DC cable was false solder that cause it open in the circuit.



- Check the process, and below two stations have the risk which causes such failure: automatic soldering station and repair station.

Observe the defective soldering; the PCB has the traces of flux. This failure is similar as the operator cannot repair well then causes the false solder.



### Risk assessment:

- From the sampling record of the automatic soldering station, the rate of soldering defect is about 0.33%, so the rate of the operator hasn't repaired well is much lower.

IPQC抽檢統計表

日期	拉線	班別	客戶	機種	段別	站別	抽檢數	不良數	不良位
9月25日	M1	白	HW	A065R161P-HW01-0A	組裝	錫面檢查	300	1	FG
9月25日	M1	白	HW	A065R161P-HW01-0A	組裝	內外檢后抽檢		0	
9月26日	M1	白	HW	A065R161P-HW01-0A	組裝	錫面檢查	300	0	
9月26日	M1	白	HW	A065R161P-HW01-0A	組裝	內外檢后抽檢		0	





**Thanks to you all ! ! !**

**Signature**

**Team Leader:**

**CF\_Liu**

Name – Title

**Signature by Approver:**

**Wade\_Lo**

Name-Title