


Eight Discipline Report (8D Report)

To:	8D report No.:
From: :	RMA claim No.:
CC :	Chicony Power P/N: N025A001Q-CT01
	Customer P/N:
Submit date: 2020/12/03	Product description:
Receive date: 2020/12/03	
Subject : 磁鐵影響電源運作 (永久磁鐵占用鐵芯磁路造成變壓器飽和觸發電源保護) 磁鐵, 磁路, 鐵芯, 磁飽和 [磁件]	
D1.) 問題解決成員: Use Team Approach	
主持者 (Team Leader) : 內部成員 (Internal Team Members): 外部成員 (External Team Member):	
D2.) 問題說明: Problem Description: (Note: Use who, what, when, where, why, how, how many to specify the Customer's problem.) 20W Power flicker Issue After assembling the magnet, the power module will cause LED turn off or flicking.	
D3.) 內部或客戶的暫時解決辦法及實施日期: Implement and Verify Containment Action: (Note: Internal / external containment action effectiveness and date.) 1. FAE of CPT got this PSU from customer for further analysis. 2. CPT send 1pc PSU to customer for exchange.	

D4.)不良原因確認: Define and Verify Root Causes:


(Note: Identify and verify all suspect causes, which needs explain why the problem occurred.)

The distance from magnet to Transformer(T1) is 21.0185mm





● **Transformer saturation and magnetic coupling risk.**

- Transformer inductance value suddenly drop and peak current will become non-linear increase.
- Control IC trigger over load protection induce power turn off or auto retry.




- Inductance comparison




- Magnet Distance


- Model 1 : without the magnet




- Model 2 : distance 20mm




- Model 1 : without the magnet




- Model 2 : distance 20mm




- Model 3 : distance 30mm




- Model 4 : distance 40mm



- Model 3 : distance 30mm




- Model 4 : distance 40mm




- N polarity of the magnet towards Transformer.
- The magnet is as far away from the transformer as possible.
- In order to make the magnetic field strength on the transformer <5 Gauss, we add a U-shaped iron to the magnet, and add a magnetic shielding between the magnet and the Power module.

- Change core type from EF20 to EQV19 and reduce saturation impact by Magnet.


- EF20 (Horizontal type)



- EQV19 (Vertical type)




- Measuring Inductance



D5.)改善措施:Corrective Action Verification:

(Note: Be make sure the corrective actions is effective in process as well as able to fix the customer complaint problem)

1. Add U-shaped iron = 3mm
2. Add magnetic shielding = 1.5mm
3. Magnet tilt angle = 20°
4. The distance from magnet to Transformer = 31mm
5. The measured value = 106 Gauss



D6.)改善措施實施日期:Implement Permanent Corrective Actions:

(Note: Be provide the phase-in date or lot# of corrective actions **implementation in process)**

immediately

D7.)預防再發生措施:Prevent Recurrence:

(Note: Modified the management, operating systems, practices, and procedures to prevent recurrence for the problems as well as lessons learned cases.)

1. Transformer(T1) need to be inspected with magnet solution.

2. Make a magnet fixture for IQC inspection, as below.



D8.)確認並感謝問題解決成員:Check and Congratulate the Team:

(Note: Recognize the collective efforts of the team.)

Thanks to you all ! ! !

Signature	
Team Leader:	
	Name – Title
Signature by Approver:	
	Name-Title