

Eight Discipline Report (8D Report)

| | |
|--|---|
| To: | 8D report No.: CPTP0326 |
| From: : Chicony Power Technology | RMA claim No.: N/A |
| CC : N/A | Chicony P/N: A045R07DH |
| | Customer P/N: |
| Submit date: 2014/3/3 | Product description: 45W adapter |
| Receive date: 2014/3/26 | Defect D/C or Lot No.: |
| Subject : There are 0.1% productions which has voltage drop phenomenon during burn in process. | |
| D1.) 問題解決成員:Use Team Approach | |
| 主持者 (Team Leader) : 內部成員 (Internal Team Members): <div style="text-align: center; margin-top: 10px;"> Sales: Angela PM: Emma RD: Brandon/Frankly/Jackson </div> 外部成員 (External Team Member): | |
| D2.)問題說明:Problem Description: | |
| (Note: Use who, what, when, where, why, how, how many to specify the Customer's problem.) | |
| CQ factory feedback information: What : There are 0.1% productions which has voltage drop phenomenon during burn in process. The output voltage is approximately 19 V at cold start, and the voltage will decrease to 18.4V gradually during burn in mode. Who: How many: 16pcs/14530pcs (Defective Rate: 0.11%) Where: CQ factory When: 2014/3/3 | |
| D3.)內部或客戶的暫時解決辦法及實施日期:Implement and Verify Containment Action: | |
| (Note: Internal / external containment action effectiveness and date.) | |
| CQ factory send 5 pcs defective and 5 pcs normal samples to Taipei, and assign RD verify the defective samples. <div style="text-align: right;">Date: 2014.3.7</div> | |

D4.)不良原因確認: Define and Verify Root Causes:

(Note: Identify and verify all suspect causes, which needs explain why the problem occurred.)


Analysis and findings:

- We tested the defective and normal samples in Taipei. Burn in 2 hours, the output voltage of defective samples will decrease 0.47V~0.7V gradually. And the drop voltage of normal samples are 0.11 V~0.25V. Before burn in, the output voltage of defective sample are lower than 19.1V.**

| defective samples | | | | | |
|----------------------------|--------|--------|--------|--------|--------|
| | Vo-no1 | Vo-no2 | Vo-no3 | Vo-no4 | Vo-no5 |
| Before burn in(Full load) | 18.99V | 19.01V | 18.93V | 18.82V | 19.04V |
| Burn in 2 hours(Full load) | 18.35V | 18.42V | 18.23V | 18.35V | 18.43 |
| Different | 0.64V | 0.59V | 0.7 V | 0.47V | 0.61V |

| normal samples | | | | | |
|----------------------------|--------|--------|--------|--------|--------|
| | Vo-no1 | Vo-no2 | Vo-no3 | Vo-no4 | Vo-no5 |
| Before burn in(Full load) | 19.46V | 19.43V | 19.38V | 19.36V | 19.45V |
| Burn in 2 hours(Full load) | 19.35V | 19.28V | 19.17V | 19.17V | 19.2V |
| Different | 0.11V | 0.15V | 0.21V | 0.19V | 0.25V |

- We measured the V_{sense} waveform of defective sample, and find the voltage waveform has oscillating phenomenon. We infer it should be the transformer T1 interfere the control circuit.**



3. We test the transformers parameters of defective and normal samples, the test data shows as follow attachment. All the parameter of defective and normal samples seems similar.




D:\Chicony\
002_brandon\001_HI

4. We modified the control loop parameters of 5pcs defective samples as follow:

- (1) R52 change from 3.6kohm to 560ohm,
- (2) R53 change from 20kohm to 5.6kohm,
- (3) R54 change from 15kohm to 51kohm
- (4) Remove C56(was 1nF).

We re-tested the output voltage of defective samples, the test results and V_{sense} waveform show as follow:

| defective samples(R52=560ohm, R53=5.6kohm, R54=51kohm, remove C56) | | | | | |
|--|--------|--------|--------|--------|--------|
| | Vo-no1 | Vo-no2 | Vo-no3 | Vo-no4 | Vo-no5 |
| Before burn in(Full load) | 19.39V | 19.53V | 19.45V | 19.42V | 19.37V |
| Burn in 2 hours(Full load) | 19.37V | 19.48V | 19.39V | 19.34V | 19.31V |
| Different | 0.02V | 0.05V | 0.06V | 0.08V | 0.06V |



Modified R52/R53/R54/C56 can improve voltage drop issue.

5. We verified the loop gain and dynamic load of modified defective samples, and the test results show as follow:



D:\Chicony\
002_brandon\001_H

6. We requested the CQ factory to modify 10pcs defective and normal samples, respective, and implemented the production process. All the samples can pass the test in production line.

D5.)改善措施:Corrective Action Verification:

(Note: Be make sure the corrective actions is effective in process as well as able to fix the customer complaint problem)

Modified the control loop parameters R52/R53/R54, and remove C56 (was 1nF).

D6.)改善措施實施日期:Implement Permanent Corrective Actions:

(Note: Be provide the phase-in date or lot# of corrective actions **implementation** in process)

Due date: Running change in April, 2014.

D7.)預防再發生措施:Prevent Recurrence:

(Note: Modified the management, operating systems, practices, and procedures to prevent recurrence for the problems as well as lessons learned cases.)

The same as D5

D8.)確認並感謝問題解決成員:Check and Congratulate the Team:

(Note: Recognize the collective efforts of the team.)

Thanks to all members.