



Portland Cement Concrete (PCC) Partial-Depth Spall Repair


Background

Spalling—cracking, breaking, chipping, or fraying of concrete slab edges at joints and cracks—is a common distress in jointed concrete pavements. Spalling reduces pavement serviceability, and if left unrepaired, it can become hazardous to highway users.

a concrete slab can vary from a few millimeters to the full depth of the slab. Once begun, spalls tend to grow or propagate under repeated thermal stresses and traffic loadings.

Most spalls are treated before they extend below the top third of the slab. Repairs of this na-

To examine the merits and deficiencies of current spall repair materials and practices, the Strategic Highway Research Program (SHRP) and the Federal Highway Administration (FHWA) sponsored one of the most extensive partial-depth patching investigations ever undertaken.



Objectives

The primary aim of the partial-depth spall repair study was to determine the most effective and economical materials and procedures for placing quality, long-lasting partial-depth patches in jointed concrete pavements. A secondary objective of the study was to identify any performance-related material tests that would enhance the

Spalling is caused by high-compressive stresses that develop in the concrete when joints or cracks cannot properly close because incompressible materials are present. The depth of spalling in

ture are commonly referred to as “partial depth.” Highway maintenance crews spend a large amount of time and money each year repairing partial-depth spalls, for both temporary and permanent fixes.

material selection process and provide a better guarantee of patch performance.

Key Benefits of This Research

The benefits of this study include service life estimates

for various spall repair materials and procedures, more cost-effective maintenance operations, less exposure of highway workers to traffic, and few maintenance delays for the traveling public.

Experiment Design

Beginning in March 1991, more than 1,600 partial-depth patches were placed in four moderate- to high-volume four-lane highways:

- PA 28 - Kittanning, PA
Wet-freeze region
- I-15 - Ogden, UT
Dry-freeze region
- I-20 - Columbia, SC
Wet-nonfreeze region
- I-17 - Phoenix, AZ
Dry-nonfreeze region

Eleven materials were used with five different repair procedures. For each combination of material and procedure at a location, 20 to 30 patches were placed (see Table 1).

Most of the procedures were performed under normal conditions. However, spalls must sometimes be patched under adverse conditions. To determine whether a cost-effective material could be found for this situation, three materials were tested under adverse conditions using the clean-and-patch procedure. Adverse conditions were defined as an ambient air temperature below 4 degrees

Celsius at the time of patching and a substrate that is surface saturated.

Evaluations

Once the experimental patches were placed, they were monitored for performance through on site visual evaluations. At each site, an immediate inspection was performed to record the development of drying shrinkage cracks and any construction-related failures. Additional evaluations were then conducted at approximately 1, 3, 6, 12, and 18 months following the date of installation. Thereafter, annual evaluations were performed between the fall of 1993 and the spring of 1998. These evaluations mainly entailed a visual examination of the patches to determine if failure had occurred and, if not, to record the type, severity and density of various patch distresses.

For cementitious and polymer patches, the distresses and conditions observed included spalling, cracking, wearing, oxidizing, edge fraying, patch-adjacent deterioration, pavement corner cracking, joint sealant condition, faulting, and patch debonding. For bituminous patches, distresses, and conditions observed included dishing, raveling, and shoving.

Each repair was evaluated for the various distresses (spalling, cracking, faulting, etc.) The areas, lengths, severity, and other characteristics of the

distresses were measured and recorded on a form. This procedure varied somewhat depending on what the distress was. For example, the procedure for evaluating cracking was different from that for evaluating joint sealant condition. After all the field measurements were recorded, evaluators rated each distress on a scale of 1 to 10. The ratings were based on the size (area, length, etc.) and severity (crack width, degree of faulting, dishing, etc.) of the distress.

Finally, after each distress was rated, a total rating for each repair was reached by using a summation technique of deduct values for each distress. Again, a 10-point rating system was used. Adjustments were made when multiple interactive distresses were present.

Key Findings

- Table 1 contains a summary of repair survival ratios after the final site inspection at 7 years. In general, 3 of the 4 sites experienced very good performance of all repair types, with 88 percent survival at the Arizona test site, 90 percent at the South Carolina site, and 91 percent at the Utah site. The 61 percent survival at the Pennsylvania test site appeared to be related to the condition of the overall pavement, which was poorer than conditions at the other three sites.

- The distresses most often

observed during the field inspections of the spall repair test sites consisted of cracking of the patches and elimination of the rigid and two-part epoxy repairs from the underlying PCC material. Deterioration of repair edges, aging, and raveling of material, cracking, and loss of material pieces were the predominant distresses observed for the bituminous repairs. In many instances, the distresses developed during the first year after placement and worsened over time as climate and traffic continued to wear on the repairs.

- Annual cost figures for each site were primarily a factor of the initial material and installation cost.
- In all 28 situations where a repair material was placed using both the saw-and-patch and the chip-and-patch procedures, annual costs for the chip-and-patch repairs were lower than for the saw-and-patch repairs. This was the result of similar performance characteristics observed for all of the repairs placed and the lower installation costs associated with the chip-and-patch procedure.
- Type III PCC performed as well or better than other more expensive rigid repairs at all sites.
- The waterblast-and-patch procedures provided good results when the equipment was

operating properly and by personnel familiar with its use. The same level of good performance could not be expected for a maintenance crew first using the device.

Recommendations

- The needed duration of repair survival should be factored into decisions on which material and methods should be used. For situations where only 2 to 3 years of performance are needed because of impending overlay or rehabilitation plans, different repair types will be dictated than in situations where repairs are expected to last 10 to 12 years.
- Based on the cost-effectiveness of the different operations, the chip-and-patch procedure is recommended over the saw-and-patch procedures for the majority of the materials evaluated. The higher productivity and reduced equipment needs make the chip-and-patch procedure more desirable.
- Partial-depth spall repairs placed on both sides of existing pavement joints should have joints formed in the repair to match the underlying pavement. This is true even for flexible pavement repairs.

References

1. Evans, L.D., et al. 1991. "Strategic Highway Research Program (SHRP) H-106 Experimental Design and Research Plan," SHRP-89-H-106. SHRP, National Research Council,

Washington, D.C.

2. Smith, K.L., et al. 1991. "Innovative Materials and Equipment for Pavement Surface Repairs, Volume 1: Summary of Material Performance and Experimental Plan," Report No. SHRP/UFR-91-504. Strategic Highway Research Program, National Research Council, Washington, D.C.

3. U.S. Department of Commerce. 1983. *Climatic Atlas of the United States*. U.S. Dept. of Commerce, Environmental Science Services Administration, Washington, D.C.

This study was performed by ERES Consultants, Inc. 505 West University Ave., Champaign, IL 61820-3915 under Contract No. DTFH-93-C-00051 for FHWA. This TechBrief is based on Report no. FHWA-RD-99-153 LTPP Pavement Maintenance Materials: SHRP PCC Partial-Depth Spall Repair Experiment, Final Report and is available from the National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.