

F/T sensors through FirmwareUpdater

• Start up : FirmwareUpdater -- admin

ETH → Discover

• Select the desired board

(10.0.1.1 → left arm joints 0 → 3)

10.0.1.3 → right " " " "

10.0.1.6 → left leg joints 0 → 3

10.0.1.7 → " " " " 4 → 5

10.0.1.8 → right leg joints 0 → 3

10.0.1.9 → " " " " 4 → 5

• Click Force ETH maintenance

• Select the board. Discover.

• Select the strain device.

• Calibrate STRAIN to launch the strain calibration GUI

[What to check :

1- Offsets should have a value between 600 and 900

2- Calibration matrix should have small values (below FEXX)
(in hex)

Button : Automatic Offset Adjustment : does not seem to work.

Changes are NOT saved until closing the window (prompt asks for confirm)

~~10.0.1.1 → Ch: 0 Offset: 904 → 821~~ still getting error saturation

Playing with offsets will influence the current values of the channels

⇒ one can adjust the offsets in order to minimize the

(For example above 10 000 is too much)

Close. Accept to keep the changes. Close.

sliding the scroll until achieving a satisfyingly low value is obtained for that channel.

Force ETH Application. Close FirmwareUpdater.

Turn off motors. Turn motors back on.

left leg 0-3 : channels 0, 4

yarp scope --remote /icub/left arm/analog:0