

# Mercury KX1

Revision 3

## Known Issues and Changes



Document Info	
Author(s)	Christoph Glattfelder
Reviewer(s)	
Version	1.01
Date	01.02.2016

Copyright © 2016 Enclustra GmbH, Switzerland. All rights reserved.

Unauthorized duplication of this document, in whole or in part, by any means, is prohibited without the prior written permission of Enclustra GmbH, Switzerland.

Although Enclustra GmbH believes that the information included in this publication is correct as of the date of publication, Enclustra GmbH reserves the right to make changes at any time without notice.

All information in this document is strictly confidential and may only be published by Enclustra GmbH, Switzerland.

All referenced registered marks and trademarks are the property of their respective owners.

## Document History

Version	Date	Author	Comment
1.01	1.02.2016	C. Glattfelder	Added KI1
1.00	12.06.2015	C. Glattfelder	First release

## Table of Contents

<b>1</b>	<b>Introduction .....</b>	<b>4</b>
<b>1.1</b>	<b>Scope .....</b>	<b>4</b>
<b>2</b>	<b>Known Issues.....</b>	<b>5</b>
<b>2.1</b>	<b>Flash programming errors using Impact.....</b>	<b>5</b>
<b>3</b>	<b>Functional Changes .....</b>	<b>6</b>
<b>3.1</b>	<b>No power up when VCC_CFG_B13 is not applied.....</b>	<b>6</b>
<b>3.2</b>	<b>New coils in the power supplies .....</b>	<b>6</b>
<b>3.3</b>	<b>VCC_CFG_B13 .....</b>	<b>6</b>
<b>3.4</b>	<b>Level shifter for I2C .....</b>	<b>6</b>
<b>3.5</b>	<b>New SPI Flash .....</b>	<b>7</b>
<b>3.6</b>	<b>New Security EEPROM .....</b>	<b>7</b>

# 1 Introduction

## 1.1 Scope

This document describes the known issues and the revision changes related to the Mercury KX1 FPGA module.

## 2 Known Issues

In addition to the errata from the FPGA and component manufacturers, Enclustra knows about the following issues with the ME-KX1-R3 modules.

### 2.1 Flash programming errors using Impact

ID	ME-KX1-R3_KI1
Description	The Mercury KX1 does not boot from the SPI flash after programming it with Xilinx Impact. This problem especially occurs when a data file is added after the bitstream.
Workaround	Use Vivado or Enclustra MCT to program the SPI Flash
Status	Xilinx won't update Impact anymore.

## 3 Functional Changes

The following functional changes were made from revision R2 to R3.

### 3.1 No power up when VCC\_CFG\_B13 is not applied

ID	ME-KX1-R3_CH1
Description	Race condition removed by connecting the enable input of the oscillator to VCC_OSC instead of PWR_EN

### 3.2 New coils in the power supplies

ID	ME-KX1-R3_CH2
Description	Smaller coils are now used in the power supplies. The maximum current of the 1.0V supply is reduced from 20A to 16A.

### 3.3 VCC\_CFG\_B13

ID	ME-KX1-R3_CH3
Description	VCC_CFG_B13 now supports 1.8V and 2.5-3.3V.

### 3.4 Level shifter for I2C

ID	ME-KX1-R3_CH4
Description	A level shifter is inserted between the I2C bus and FPGA bank 13.

## 3.5 New SPI Flash

ID	ME-KX1-R3_CH5
Description	The Micron N25Q256A SPI flash is replaced by a Spansion S25FL512S. The new flash is now 512 Mbit and has bigger sectors. This may require adaptations in your programming algorithm.

## 3.6 New Security EEPROM

ID	ME-KX1-R3_CH6
Description	The security EEPROM is replaced by a new type. This requires different I2C accesses to read the module information and MAC address. A software example supporting the new EEPROM is found in the Mercury KX1 Vivado reference design.

## Figures

No table of figures entries found.

## Tables

No table of figures entries found.