


Move to server

stress-strain diagram



32. What does the non-linear portion of a stress-strain diagram represent?

Plastic region -

Permanent deformation.

Strain is not linear with stress.

i.e. $\epsilon = \frac{\sigma}{E}$ linear model

↑
constant of proportionality

$$f(\sigma) = k\sigma + \epsilon_0$$

In plastic region


$$\epsilon = f(\sigma), \quad f(\sigma) \text{ is not linear in } \sigma$$

33. What is the 0.2% offset yield stress?

This is a "convention" (agreement) where yield stress is defined because experimental determination of plastic onset is difficult to do.


∴ A line parallel to elastic region at 0.2% strain is used to identify a "working" value of yield stress

34. What metal exhibits upper and lower yield points?



steel and iron alloys ~~exhibits~~ exhibit upper & lower yield

cause is attributed to interaction of carbon atoms (coordination number 4) and dislocations (defects)



Iron (Fe) has coordination numbers of 3 and 5.

Hence in an alloy random alloy the carbons and Fe are not necessarily aligned. Higher stress can be applied until alignment, then slip

creep and fatigue

creep

- deformation at constant stress and high temperature
- grain boundary sliding, formation of voids (failure)


fatigue

- failure in cyclic loading due to surface defects
- sensitive to surface properties (corrosion, finish)
- endurance limit for steels (unlimited life)

35. What is the cause of creep failure?

Creep is deformation of material under constant stress.

- Negligible until 40%+ of absolute melting point for most materials (glass is a not. is notable exception)




- Internal thermal energy allows dislocations (i.e. C, Fe atoms to rearrange in such a way as to lose ability to resist strain and thus slowly move) [-depends on rate of load.]

- Porching water

→ Grain boundary sliding
formation internal voids

37. Define metal fatigue?

Cyclic loading



generates heat \Rightarrow ~~creep~~
"creep-like" behavior
material changes

(crystal structure rearranges
becomes more brittle)

Stress at surface and
propagates inward

- surface treatments help.

cold roll
shot peen
bead blast
polish
case hardening

ductility



- deformation without fracture (% elongation)
- increases with temperature, lower carbon content

hardness

- resistance to penetration (Brinell, Rockwell tests)
- increases with carbon content, smaller grain size

toughness

- energy absorbed before fracture (Charpy test)
- area under the stress-strain curve




- Steel is an alloy with Fe
- Al is an element, no Fe
many no Fe alloys have
asymptotic behavior so small
as to be useless for
long applications

Corrosion fatigue
- if in corrosive environment
and cyclic stress
(water)

- Ti is an element, no Fe,
but Ti alloys have a touch
of Fe (not much) and Vn to
give them enough cycles
resist.

ductility, hardness, toughness




601 C3 Steel
(cutting tools)
Refers to Hardness
Brinell
and carbon content.

36. Which statement regarding ductile-brittle transition is false?

- sudden loss of ductility below a critical temperature (true)
- loss of toughness at lower temperatures (true)
- carbon steels less susceptible to this transition (sudden, brittle, very susceptible)
— occurs at teneshral temp
- some pure metals (aluminum, copper, nickel) do not exhibit this transition (true)

(Surrogate for stress ductility)
Impact NRG



i.e.
chemistry & microstructure

processing

annealing

- heat and slowly cool (relieves internal stresses)
- increases ductility, lowers yield, softens the material

changes material properties

→ used to work material.

cold working

- stressing past the yield point (reduces grain size)
- increases toughness, hardness, yield strength



quenching

- rapid cooling that promotes hardening
- strong but brittle material (low toughness)

— hardening

— Martensite (crystal structure)

very hard, approaches carbide (newly diamond hardness)
— cutting tools


Case hardening

37. Which statement regarding carbon steel is false?

- a steel can be hardened without carburizing - true
- yield strength can be increased by cold rolling - true
- ductility decreases for steels with more carbon - true
- steels with larger grain size are stronger - false

- Grain boundaries strengthen steel.

For given volume/area smaller grains = more boundaries
 \therefore stronger



boundaries act like a truss, distributes forces

reactions

- eutectic: liquid \rightarrow two solid phases
 $\text{cool} \quad \text{distinct}$
- eutectoid: solid \rightarrow two solid phases
 $S_1 \rightarrow S_2 + S_3$
- peritectic: liquid + solid \rightarrow solid
 second solid
- peritectoid: two solid phases \rightarrow solid
 $S_1 + S_2 \rightarrow S_3$

$W\%$ = weight fraction of an alloy

$A\%$ = molar fraction of an alloy

$$W\% A = \frac{W_A}{W_A + W_B} \times 100\%$$

$$at\% = \frac{\text{mols } A}{\text{mols } A + \text{mols } B} \times 100\%$$

~~$W_A \times MW$~~

$$\text{mols } A = \frac{W - A}{MW_A}$$

Phase Rule

$$P + F = C + (\text{something}) - 2$$

$P = \# \text{ phases}$
 $F = \# \text{ degrees of freedom}$
 $C = \# \text{ components}$

$$2 = \Delta P + \Delta T \quad \text{if } \Delta P = 0 (\text{constant pressure})$$

= # thermodynamic variables adjusted

less need dens solid & liquid

Some alloys are completely miscible
 H₂O & Alcohol
 Cu, Ni


Some only mix at exact compositions, reject extra
 Some blend into alloy & pure

18. What is a peritectoid reaction?

Two solids in solution are in equilibrium with a third solid at a given temperature

solid - solid \rightarrow
 solid - liquid \rightarrow

binary phase diagram



$$\alpha \text{ wt\%} = \frac{x_\beta - x}{x_\beta - x_\alpha} \times 100 ; \beta \text{ wt\%} = \frac{x - x_\alpha}{x_\beta - x_\alpha} \times 100$$

Tool to predict mixture components
 - Equilibrium diagram

2 components are α & β

3 possible solids
 α , $\alpha + \beta$, β
 alloy

x is composition of interest, depends on starting composition.


lever formula tells composition of $\alpha + \beta$ if it exists.

16. Which condition does not lead to stronger metals and alloys?


- presence of second phase precipitates *s'*
- presence of dispersed fibers or particles *stronger*
- presence of martensite phase in steel *stronger*

• annealing of cold worked metal above its recrystallization temperature *+*


→ cold work to crush grains



crystal structures



BCC body-centered cubic






FCC face-centered cubic

Important in calculation values & densities at atomic level


BCC

FCC are only "easy" to create


HCP



Simple cubic



bcc



Fcc

SAMPLE PROBLEMS

* Problem 1

Why is aluminum more rust-resistant than steel?

- (A) The reaction rate with atmospheric oxygen is higher for steel.
- (B) The reaction rate with atmospheric oxygen is higher for aluminum.
- (C) Iron atoms are larger than aluminum atoms, and thus, the interstitial spaces are larger.
- (D) Iron has greater magnetic properties than aluminum.

Solution

Oxygen reacts faster with aluminum. In fact, it reacts so fast that it creates a film of aluminum oxide that acts as a protective coating.

Answer is B.

Problem 2

Which of the following metals do not have a face-centered cubic crystalline structure?

- I. aluminum
- II. gamma-iron
- III. delta-iron
- IV. lead

- (A) III only
- (B) II and III
- (C) III and IV
- (D) I, II, and IV

Solution

Aluminum, lead, and gamma-iron all have face-centered cubic structures. Delta-iron has a body-centered cubic structure.

Answer is A.

Problem 3

Which of the following will affect the hardenability of steel?

- I. composition of austenite
- II. composition of cementite
- III. austenite grain size
- IV. quenching medium
- V. carbon content

- (A) II only
- (B) I and V
- (C) III and V
- (D) I, II, III, and V

Solution

Carbon content and grain size are the primary factors affecting hardenability.


Answer is C.

FE-STYLE EXAM PROBLEMS


1. Which of the following characterize a hot-worked steel part in comparison with a cold-worked part?

- I. higher yield strength
- II. better surface finish
- III. greater hardness
- IV. greater toughness
- V. less ductility

- (A) I and V
- (B) II only
- (C) III and IV
- (D) none of the above *



Problems 2-4 refer to the following phase diagram.



MATERIALS
Metallurgy

2. The region enclosed by points DEF can be described as which of the following?

- (A) a mixture of solid β component and liquid α component
- (B) a mixture of solid and liquid β component
- (C) a peritectic composition
- (D) a mixture of solid β component and the eutectic material

3. Which line(s) is (are) the liquidus?

- (A) CBDFG
(B) CDE
(C) ABC and EFG
(D) CBFE

4. How much solid (as a percentage by weight) exists when the mixture is 30% α and 70% β and the temperature is 800°C?

- (A) 0%
(B) 19%
(C) 30%
(D) 50%

*Use formula
- usually a good guess*

5. Which of the following characteristics describes martensite?

- I. high ductility
II. formed by quenching austenite
III. high hardness

- (A) I only
(B) I and II
(C) II and III
(D) I and III

For the following problems use the NCEES Handbook as your only reference.

6. The activation energy, Q , for aluminum in a copper solvent at 575°C is 1.6×10^8 J/kmol. What is the diffusion coefficient, D , if the constant of proportionality, D_0 , is 7×10^{-6} m²/s?

- (A) 4.04×10^{-47} m²/s
(B) 2.04×10^{-20} m²/s
(C) 9.75×10^{-16} m²/s
(D) 2.31×10^{-5} m²/s

7. An iron alloy contains 2.5% carbon by weight. In what phase is the alloy at 900°C?

- (A) liquid
(B) γ + liquid
(C) δ + carbide
(D) γ austenite and carbide

8. A mixture of ice and water is held at a constant temperature of 0°C. How many degrees of freedom does the mixture have?

- (A) -1
(B) 0
(C) 1
(D) 2

$$P + F = C + 2$$

$$P = 2, C = 1$$

9. A brass alloy is 40% zinc and 60% copper by weight. What is the approximate mole fraction of zinc?


- (A) 5%
(B) 26%
(C) 39%
(D) 50%

10. The crystalline structure of metals can be modified by several processes. Plastic deformation of the crystalline structure resulting in misalignment of atoms, dislocations, and large stresses and strains in small regions are characteristic of which process?


- (A) tempering
(B) cold forming
(C) twinning
(D) isostatic pressing

11. Which of the following figures is a cooling curve of a pure metal?


(A)



(B)



(C)



$$1 + 1 = 2 + 0$$