



Fundamentals of Engineering Spring 2005 Review

Materials Science


Theodore G. Cleveland, Ph.D.

problem distribution

- morning: 6% (7 out of 120 problems)
- afternoon: 5% (3 out of 60 problems)

subject areas

- 30% stress-strain diagram (3)✓
- 20% creep/fatigue (2)✓
- 20% processing/properties (2)✓
- 20% phase diagram (2)✓
- 10% other (1)



32. What does the non-linear portion of a stress-strain diagram represent?

- Plastic region

- Strain is not linear wrt. stress

$$\epsilon = f(\sigma)$$

Elastic

$$f(\sigma) = E\sigma + \epsilon_0$$

Plastic

$$f(\sigma) \neq E\sigma + \epsilon_0$$

some non-linear


33. What is the 0.2% offset yield stress?

- Convention (agreement) when yield stress is defined because its experimentally difficult to determine σ_y .

\therefore A line \parallel to elastic behavior at 0.002 strain is used to id. a "working" value of σ_y

34. What metal exhibits upper and lower yield points?

steel (any iron alloy)



Attributed to carbon atoms & iron atoms

C(4)

Fe (3,5)




creep and fatigue

creep

- deformation at constant stress and high temperature
- grain boundary sliding, formation of voids (failure)



fatigue

- failure in cyclic loading due to surface defects
- sensitive to surface properties (corrosion, finish)
- endurance limit for steels (unlimited life)



40% or higher MP (melting point)

- Creep is significant at high T



Steel is alloy
Al is an element

Ti, Fe, C, Vn

Creep

Fatigue

generates "heat"
→ creep like behavior

crystalline structure rearranges
becomes brittle

Starts at material surface (propagate inward)

Cold rolling - surface polish

shot peen (bead blasting)

polish

case hardening

Corrosion fatigue

→ corrosive environment + cyclic loading

35. What is the cause of creep failure?

- Deformation of material under constant stress.

- Temperature matters
($T > 40\% \text{ MP}$)

internal thermal energy
allows dislocations

C, Fe to rearrange & allow slip


37. Define metal fatigue?

- Failure of material, starts at surface under cyclic loading

ductility, hardness, toughness

ductility

- deformation without fracture (% elongation)
- increases with temperature, lower carbon content




hardness

- resistance to penetration (Brinell, Rockwell tests)
- increases with carbon content, smaller grain size

601 C3
↑
working material


toughness

- energy absorbed before fracture (Charpy test)
- area under the stress-strain curve



36. Which statement regarding ductile-brittle transition is false?

- sudden loss of ductility below a critical temperature (true)
- loss of toughness at lower temperatures (true)
- carbon steels less susceptible to this transition (false)
- some pure metals (aluminum, copper, nickel) do not exhibit this transition (true)



processing

→ chemistry
* microstructure

annealing

- heat and slowly cool (relieves internal stresses)
- increases ductility, lowers yield, softens the material

cold working

- stressing past the yield point (reduces grain size)
- increases toughness, hardness, yield strength


quenching

- rapid cooling that promotes hardening
- strong but brittle material (low toughness)

(martensite) → tools

37. Which statement regarding carbon steel is false?

- a steel can be hardened without carburizing (true)
- yield strength can be increased by cold rolling (true)
- ductility decreases for steels with more carbon (true)
- steels with larger grain size are stronger (false)



reactions

- eutectic: liquid \rightarrow two solid phases
 $\xrightarrow{\text{solid}}$
- eutectoid: solid \rightarrow two solid phases
 $\xrightarrow{\hspace{1cm}}$
- peritectic: liquid + solid \rightarrow solid
 $\xrightarrow{\hspace{1cm}}$
- peritectoid: two solid phases \rightarrow solid
 $\xrightarrow{\hspace{1cm}}$

$W\% = \text{weight fraction of alloy}$

$A\% = \text{molar fraction of a alloy}$

$$W\% - A = \frac{W-A}{W-A+W-B} \times 100\%$$

$$A\% = \frac{\text{mol A}}{\text{mol A} + \text{mol B}} \times 100\%$$

$$\text{mol A} = \frac{W-A}{\underline{MW_A}}$$

phases

given


constituents

possible mixtures

$$P + F = C + 2$$

$\leftarrow \text{\# thermodynamic controls}$
 (P, T)

Some alloys are completely miscible




18. What is a peritectoid reaction?



peritectic



binary phase diagram



Tool to
predict
mixture
composition

- Equilibrium
diagram


2 components

3 possible
solids

$\alpha, \alpha + \beta, \beta$

$$\alpha \text{ wt}\% = \frac{x_\beta - \bar{x}}{x_\beta - x_\alpha} \times 100 ; \beta \text{ wt}\% = \frac{\bar{x} - x_\alpha}{x_\beta - x_\alpha} \times 100$$

iron - iron carbide phase diagram



α ferrite (BCC), δ iron (BCC), γ austenite (FCC)


17. A steel with 0.18 wt% carbon is heated to 1100°C and then slowly cooled to room temperature. What is the phase composition?

16. Which condition does not lead to stronger metals and alloys?


- presence of second phase precipitates *stronger*
- presence of dispersed fibers or particles *stronger*
- presence of martensite phase in steel *stronger*

[• annealing of cold worked metal above its recrystallization temperature *weaker*]

crystal structures



BCC body-centered cubic



FCC face-centered cubic

Volumes / Densities

BCC, FCC, Simple cubic ←

HP
HCP



$$\frac{1 \text{ atom}}{(2r)^3}$$

→ density of cubic structure



$$\frac{4}{4r}$$



be able to recognize