

# 1 Issue 0020539:

## 1.1 Test Report

D-0020539: <EVT FW BB CPLD> DRIVE\_xx\_PWROK register couldn't reflect Drv[x]\_PWR\_EN\_L signal state.

3/26/2015, BB CPLD V01.09:


- 1) Default value is FF 0F 00 00 00 which should be all 00 as design spec defined.
- 2) When DRIV\_x\_PWR\_EN register is 1b and SAS HDD is inserted, the corresponding DRIVE\_x\_PWROK returns 0b which should be 1b to reflect the low active signal is asserted.

5/23/2015, BB CPLD V02.02 duyü

- 1) PCIE SSD' s POWER\_OK can be read correctly from 31h[7:4], 32h, 33h, 34h[3:0]
- 2) SAS SSD' s POWER\_OK is always as '0b'

## 1.2 Root cause

PCIE SSD can output POWER\_OK, but SAS HDD cannot output right POWER\_OK, it is always "0b"



### 1.3 Solution

We can detect DRV\*\_IFDET\_BLUE\_LED and DRV\*\_PRSNT\_AMBER\_LED to check which type HDD inserted, PCIE SSD or SAS HDD.

- a) If PCIE SSD has been inserted, then we use real POWER\_OK signal for power ok register --- 31h[7:4]~34h
- b) If SAS HDD has been inserted, then we use power enable for 31h[7:4]~34h
- c) Always use power enable register value for 30h~31h[3:0]

The real hardware signal as below,

- 1) The slot which can support both PCIE and SAS, test at Slot HDD56:

HDD Type	DRV*_IFDET_BLUE_LED	DRV*_PRSNT_AMBER_LED
PCIE SSD	0.28v	3.25v
SAS HDD	0.28v	0.28v
N/A	3.25v	3.25v

- 2) The slot which only can support SAS, test at HDD6

HDD Type	DRV*_IFDET_BLUE_LED	DRV*_PRSNT_AMBER_LED
SAS HDD	0.3v	0.3v
N/A	3.25v	3.25v

Hudson Comments	
QA Comments	

### 1.4 New BB CPLD version

I will release 02.03 to fix this issue, please QA team help verify, thanks.

## 2 Issue 0020586

### 2.1 Test Report

D-0020586 Priority 3-Normal

Title <EVT FW BB CPLD> Register A0h hasn't control SGPIO outputs enable or disable.

On Fri, Mar 20, 2015 at 3:50 AM EDT, Sharron Yang wrote:  
3/20/2015, V0107:

A0 could control SPGIO, but when system power on, all 72 Drive Activity LEDs are solid on, even no HDD is inserted.

5/23/2015, BB CPLD V02.02 and SSM CPLD V01.06 duyu  
SAS HDD LED can blink and ON, the function is ok.  
PCIE can not blink, because it can not active under OS.

### 2.2 Duyu's comments

CPLD use the same DRV\*\_ACT\_LED signal for PCIE SSD and SAS HDD, so, if SAS HDD's LED can work well, The PCIE SSD should be OK. I also verify latest CPLD on David's test bench, the PCIE LED can be lighted. Please refer to below picture. So, I suggest that we can close this issue on salesforces. Please help verify, thanks.

