

AC transformer :-

An AC transformer is an electrical device that is used to change the voltage in AC electrical circuits.


Construction of Transformer :-

Two basic parts in Transformer Construction.

1. Magnetic core
2. Windings or coils.

1. Magnetic core :-

- Core provides path for magnetic flux (Φ)
- Hence there are two types of losses occur in the core.
 - a) Hysteresis loss
 - b) Eddy Current loss
 } magnetic losses (or) Iron losses.



* Now we need to construct core suchway that these two losses as low as possible.

→ Generally core is made up of high grade Silicon Steel (magnetic material with high permeability) to minimize hysteresis losses.


→ Earlier core is made up of iron.

* For eddy current losses reduction:-

→ Core is made up of thin laminations

2) windings (or) coils :-


- Electric Current passes through windings.
- windings are made up of Copper and are wound on the limbs of magnetic core. Windings are insulated from each other.
- windings are subjected to I^2R losses which are also called as Copper losses.




* Based on the arrangement of core & winding, there are two types of transformer.

i) Core type transformer :-

Here core is surrounded by windings (or) the winding encircles the core.
Draw fig(2)



ii) Shell type Transformer :-




Here the core encircles the windings (or) windings are surrounded by core.

Working principle of Transformer :-

→ Transformer works on the principle of Mutual Induction.

Mutual Induction :-

The principle of mutual Induction states that, when two coils are inductively coupled and if current in one coil changes uniformly then an e.m.f gets induced in the other coil.



→ Whenever there is a supply connected to coil, that coil is called primary winding.

→ Wherever load is connected that coil is called secondary winding.

* Because of AC Supply, current will pass through the primary winding. This current gives rise to magnetic flux through the magnetic core.

→ The magnetic flux changing w.r.t time gets linked in primary winding and e.m.f produced in primary winding. That e.m.f is called self induced e.m.f.


→ Same flux linked in secondary winding and e.m.f produced in secondary coil. This e.m.f is called mutually induced e.m.f.

EMF equation of Transformer :-

$$\phi = \phi_m \sin \omega t.$$

By Faraday's law of electromagnetic induction, e.m.f induced

$$e = N \cdot \frac{d\phi}{dt} \quad \text{--- (1)}$$



By lenz's law, $e = -N \frac{d\phi}{dt} \quad \text{--- (2)}$

lenz's law :- e.m.f induced in a conductor will oppose the current which has produced the flux ϕ

E.m.f induced at the primary side, $e_1 = -N_1 \frac{d\phi}{dt}$

N_1 = no. of turns in primary winding.

$$e_1 = -N_1 \frac{d}{dt} (\phi_m \sin \omega t)$$

$$e_1 = -N_1 \phi_m \cos \omega t \cdot \omega$$

$$e_1 = N_1 \phi_m \omega (-\cos \omega t)$$

$$= N_1 \phi_m \omega \sin(\omega t - 90^\circ)$$

$$e_1 = \phi_m 2\pi f N_1 \sin(\omega t - 90^\circ) \quad \text{--- (3)}$$

$$e_1 = E_{m1} \sin(\omega t + \varphi) \quad \text{--- (4)}$$

Here $E_{m1} = 2\pi f \phi_m N_1$, $\varphi = -90^\circ$.


R.M.S Value of e.m.f, $\frac{E_{m1}}{\sqrt{2}} \Rightarrow \frac{2\pi f \phi_m N_1}{\sqrt{2}}$

$$\boxed{E_1 = 4.44 \phi_m f N_1} \quad \text{--- (5)}$$

Similarly, Secondary side e.m.f, $\boxed{E_2 = 4.44 \phi_m f N_2} \quad \text{--- (6)}$

E_1 & E_2 lag flux ϕ by 90° (or) $\pi/2$

Phasor diagram :-



Transformation Ratio (k) :-

For an ideal transformer, $V_1 = E_1$

$V_2 = E_2$ and $V_1 I_1 = V_2 I_2$

$$\frac{V_1}{V_2} = \frac{I_2}{I_1} \Rightarrow \frac{E_1}{E_2} = \frac{I_2}{I_1} \quad \text{--- (7)}$$

From eq (5) and eq (6),

$$\frac{E_1}{E_2} = \frac{N_1}{N_2} \quad \text{--- (8)}$$

From eq (7) and eq (8),

$$\frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{I_2}{I_1} = k$$

k = Transformation ratio

Losses :- in a transformer :-

There are two losses occur in transformer, 1. Core losses

1. Core losses : Core gets subjected to alternating flux causes core losses.

2. Copper losses

2. Copper losses :- The windings carry currents when transformer is loaded causing copper losses.

Core / Iron / constant losses

i) Hysteresis losses :- Due to AC flux set up in the magnetic core of t/f, it undergoes a cycle of magnetisation and demagnetisation. Due to the process of magnetisation and demagnetisation there is a loss of energy which is called hysteresis losses.

$$P_h = K_h B_m^{1.67} f \cdot V$$

K_h = Hysteresis constant

P_h = Hysteresis loss

B_m = Maximum flux density

f = frequency

V = Volume of core

ii) Eddy Current losses :-

The induced emf in the core tries to set up eddy currents in the core and hence responsible for eddy current losses.

$$P_e = K_e B_m^2 f^2 t^2$$

K_e = Eddy current constant ; t = thickness of the core.

* To avoid hysteresis losses, magnetic core material is made with high grade Silicon Steel.

* To avoid eddy current losses, magnetic core will be made such way that it will consist of very thin laminations

Copper / I^2R / Variable losses :-

Copper losses are due to the power wasted in the form of I^2R loss due to the resistances of the primary and secondary windings.

$$P_{cu} = I_1^2 R_1 + I_2^2 R_2$$

Copper losses depend upon the amount of load current which can be changed depends upon the load connected.

$$\begin{aligned} \text{Total losses} &= \text{Constant losses} + \text{Variable losses} \\ &= (P_h + P_e) + I_1^2 R_1 + I_2^2 R_2 \end{aligned}$$

Efficiency of Transformer :-

Efficiency is denoted by $\eta = \frac{\text{output power}}{\text{input power}} \times 100$

$$\eta = \frac{\text{output power}}{\text{output power} + \text{losses}} \times 100$$

For full load,

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + W_i + W_{cu}}$$

Voltage Regulation :-

The change in terminal voltage from no-load to full load at constant supply voltage w.r.t no-load voltage is known as voltage regulation of the transformer.

$$\% \text{ Voltage regulation} = \frac{E_2 - V_2}{E_2} \times 100$$

$$E_2 = V_2 + I_2 Z$$

E_2 = Secondary voltage at no-load

V_2 = Secondary voltage at full-load

