

Personal Project – Design & Build Log

Emán Rabbani

Date: 1/11/26

Part Name: Prototyping Motor Controller Perfboard mount

Version: 1

Trigger: **Print**

Progress/Changes:

- Decided that rather than adjusting and reprinting the L-bracket several times to get the hole spacing right for the perfboard, it would make more sense to print a temporary mount to the chassis and adjust the hole spacing when the final PCB dimensioning has been confirmed.
- Changed the hole spacing of the perfboard in the CAD because when remeasuring, I found errors in the measurements in the CAD, here is the new diagram for reference:




- Adjusted the holes in the mount to slot in with M5 and added correction for perfboard screw mounting.


Areas to Improve:

- Test the part against the motor controller perfboard

Pictures:



-> Sketch Diagram Photo



-> Assembly Photo

Date: 1/8/26 and 1/10/26

Part Name: 0.25" Mounting Plate



Version: 3

Trigger: (**Print** / Milestone)

Progress/Changes:

- Created a M5 slotted prototyping mounting block for attaching the MOSFEEZ power distribution block. However, this mounting block can be used whenever there are 0.25" screw holes for mounting to the 2020 extrusions.
- Added fillets in the corners to avoid sharp corners.
- Printed with 15% infill out of PETG and PLA.

Pictures:



Date: 1/6/26

Part Name: Shaft Coupler

Version: 13



Trigger: (**Print** / Milestone)

Progress/Changes:

- Adjusted tolerances on the wheel shaft and increased the fit of the coupler on the shaft. Applying clamping force on the wheel shaft resulted in preventing it from sliding out.
- Changed screw holes to M3, tolerance on the screw holes worked well.

Areas to Improve:

- None at the moment.



Date: 1/6/26

Part Name: L Bracket

Version: 26


Trigger: (**Print** / Milestone)

Progress/Changes:

- M2 Mounting holes for the motor controller perfboard.

Areas to Improve:

- On 1/9/26 when the M2 threaded inserts were added to the bottom face of the L bracket via solder, the holes did not line up accurately to the perfboard. Due to it being difficult to measure the exact spacing, this likely resulted in the error.



Date: 1/5/26

Part Name: L Bracket

Version: 24



Trigger: (**Print** / Milestone)



Progress/Changes:

- Countersunk the top plate for the extruded plate on the motor. Counter sunk motor mounting holes and changed them to M3.
- Changed motor bed to account for the 1 mm thick banded section on the motor.
- Realigned screw holes for the saddle mount.
- Added ribs to reinforce bracket structure. Added fillets to round out sharp corners.

Areas to Improve:

- M2 Mounting holes for the motor controller perfboard.





Date: 1/5/26

Part Name: Shaft Coupler

Version: 9


Trigger: (**Print** / Milestone)

Progress/Changes:

- Changed the shape on the motor end to be D-shaped according to the shape of the motor itself.

Areas to Improve:

- Adjust wheel shaft tolerances to make a better fit with the wheel shaft -> adjusting by 0.2 mm
- Change screw holes to M3



Date: 1/4/26

Part Name: Shaft Coupler

Version: 8



Trigger: (**Print** / Milestone)

Progress/Changes:

- Note this part was printed on 1/1/25, this is a review of the part overall done at a later date.
- Overall, the print quality was pretty good and didn't show signs of warping.

Areas to Improve:

- Make screw hole larger than 2.1 mm -> try 2.2 mm for the M2 screw
- Fix the shaft length for the motor shaft and make the coupler more D shaped on the motor end



Date: 1/4/26

Part Name: L Bracket

Version: 12

Trigger: (**Print** / Milestone)

Shaft Coupler V8

Progress/Changes:

- Note this part was printed on 1/1/25, this is a review of the part overall done at a later date.
- Overall, the print quality was pretty good and didn't show signs of warping.

Areas to Improve:

- Wrong screw hole, should be M3
- 0.7239 mm band around the motor for 1.3415" -> add proper adjustment for band
- Counter sink motor screw holes
- Move saddle tabs over to make better contact with the band
 - Add tape around saddle band
 - Cut the saddle band strip
- Consider thickness of the part in relation to the motor shaft (if that is causing problem -> not enough shaft coming out)
- Tolerances:
 - 5.1 mm for M5 is too small -> 5.2 is better
 - 5.45mm is the diameter of the M3 screw head
 - 9mm too short for the shaft hole
 - 15.875 usable shaft

Open Questions:

- Consider reducing the thickness of the top plate on the bracket to have more shaft extending out of the bracket.
- Consider rearranging chassis bar structure to sit connecting rails on top of the motor rails for better clearance with the shaft.

Screenshots:



