

Personal Project – Design & Build Log

Emán Rabbani

Date: 1/6/26

Part Name: L Bracket

Version: 24



Trigger: (**Print** / Milestone)



Progress/Changes:

- Countersunk the top plate for the extruded plate on the motor. Counter sunk motor mounting holes and changed them to M3.
- Changed motor bed to account for the 1 mm thick banded section on the motor.
- Realigned screw holes for the saddle mount.
- Added ribs to reinforce bracket structure. Added fillets to round out sharp corners.

Areas to Improve:

- For now, this is sufficient for a V0 test of the robot's drivetrain.





Date: 1/6/26

Part Name: Shaft Coupler

Version: 9


Trigger: (**Print** / Milestone)

Progress/Changes:

- Changed the shape on the motor end to be D-shaped according to the shape of the motor itself.

Areas to Improve:

- Adjust vex shaft tolerances to make a better fit with the vex shaft -> adjusting by 0.2 mm
- Change screw holes to M3



Date: 1/4/26

Part Name: Shaft Coupler

Version: 8



Trigger: (**Print** / Milestone)

Progress/Changes:

- Note this part was printed on 1/1/25, this is a review of the part overall done at a later date.
- Overall, the print quality was pretty good and didn't show signs of warping.

Areas to Improve:

- Make screw hole larger than 2.1 mm -> try 2.2 mm for the M2 screw
- Fix the shaft length for the motor shaft and make the coupler more D shaped on the motor end



Date: 1/4/26

Part Name: L Bracket

Version: 12

Trigger: (**Print** / Milestone)

Shaft Coupler V8

Progress/Changes:

- Note this part was printed on 1/1/25, this is a review of the part overall done at a later date.
- Overall, the print quality was pretty good and didn't show signs of warping.

Areas to Improve:

- Wrong screw hole, should be M3
- 0.7239 mm band around the motor for 1.3415" -> add proper adjustment for band
- Counter sink motor screw holes
- Move saddle tabs over to make better contact with the band
 - Add tape around saddle band
 - Cut the saddle band strip
- Consider thickness of the part in relation to the motor shaft (if that is causing problem -> not enough shaft coming out)
- Tolerances:
 - 5.1 mm for M5 is too small -> 5.2 is better
 - 5.45mm is the diameter of the M3 screw head
 - 9mm too short for the shaft hole
 - 15.875 usable shaft

Open Questions:

- Consider reducing the thickness of the top plate on the bracket to have more shaft extending out of the bracket.
- Consider rearranging chassis bar structure to sit connecting rails on top of the motor rails for better clearance with the shaft.

Screenshots:



