

Title	990-03957-00 - DOC, M20 WORK INSTRUCTIONS ADAPTER - BUTTER STICK, AMBER	
P/N	710-03085-02_rev01_ASSY, ELEC-MECH, M20 HEADSET, BUTTER STICK, AMBER	
Scope	Assembly instructions for Flex	
Revision	1	
Date	2019-12-20	
Author		
Approver(s):		
Revision History		
01	Initial Release	
02		
03		
04		




Tool / Consumable List	
Description	
Consumables	Tools
	T8 torque driver
	T15 torque driver

Bottom Sub-Assembly




Note: Bottom and top sub-assemblies are
independent and not sequential



Seq #	Cycle Time	Operation Description	Place connector boot around large connector	
01				
			Part Desc:	Part#
			Connector Boot Breakout Board	PN-0171-00 ASM-0282-00
			Tools/Equipment:	Part#
			Critical Process Parameters	
			Critical Quality Attributes	
			Key Points	



Seq #	Cycle Time	Operation Description	Place Breakout Board on bottom housing using 3 alignment pins as guidance. Hold board in place through affixing screws so it does not shift.
02			




Hold in place until screws are fastened

Part Desc:	Part#
Breakout Board Bottom Housing	ASM-0282-00 PN-0163-00
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Key Points	
Alignment pins are flexible so take caution not to apply excessive force when aligning board	




Seq #	Cycle Time	Operation Description	Manually hold down board while securing in place with qty 6 M2.63x6 screws to 35 in-oz. Fasten screws around connector (highlighted in red below) first in a star pattern, then fasten bottom screws (highlighted in blue)
03			



Part Desc:	Part#
Breakout Board Torx M2.63x6mm (x6)	ASM-0282-00 PN-0104-00
Tools/Equipment:	Part#
T8 Torque Driver	
Critical Process Parameters	
35 in-oz tightening torque	
Critical Quality Attributes	
Manually hold board until screws are tightened, do not allow board to shift from position	
Key Points	



Seq #	Cycle Time	Operation Description	Insert o-ring around the groove at the edge of the bottom housing
04			




Part Desc:	Part#
O-ring Bottom Housing	PN-0163-00
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Ensure o-ring is securely within groove	
Key Points	

Top Sub-Assembly

Note: Bottom and top sub-assemblies are
independent and not sequential



Seq #	Cycle Time	Operation Description
01		Using sensor strip assembly built previously (work instructions) insert cables through grommet in order of longest to shortest (Blue-Green-Red-Yellow-Purple). Be careful when pushing on back end of wires to avoid damage, use plastic pliers as necessary to pull connectors through. Wires should enter through narrow side and exit on wider, flanged side



Part Desc:	Part#
Sensor Strip Assembly Grommet	BOM-0284-00 PN-0168-00
Tools/Equipment:	Part#

Critical Process Parameters

--

Critical Quality Attributes


Do not apply push on back end of wires to thread through grommet
--

Key Points

Connectors should exit on wide, flanged side of grommet



Seq #	Cycle Time	Operation Description
02		Insert expandable sleeving through grommet, ensure there is enough length to apply zip tie (~2 inches through grommet)



Part Desc:	Part#
Sensor Strip Assembly Grommet	BOM-0284-00 PN-0168-00
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Key Points	



Seq #	Cycle Time	Operation Description	Pull all 5 cables through hole on top housing. It is recommended to start with the longest cable first and end with the shortest.
06			



Part Desc:	Part#
Sensor Strip Assembly Top Housing	
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Key Points	




Seq #	Cycle Time	Operation Description	Pull expandable sleeving through hole on top housing. Note: if zip ties are not tight enough they will not fit through the hole
07			



Part Desc:	Part#
Sensor Strip Assembly Top Housing	
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Key Points	



Seq #	Cycle Time	Operation Description	Using your fingers, push the grommet flange through the hole on the top housing as shown. Gently pull back on sleeve/cables until the edge is up against the flange
08			





Part Desc:	Part#
Grommet Sensor Strip Assembly Top Housing	
Tools/Equipment:	Part#
Critical Process Parameters	
Critical Quality Attributes	
Key Points	

Final Assembly

15



Seq #	Cycle Time	Operation Description	Align top and bottom housings and close. Fasten qty 4 M3.36x10 screws to bottom housing in a star pattern. Torque to 8.5 in-lbs
30			



Part Desc:	Part#
Bottom Housing Torx M3.36x10 (x4)	PN-0163-00 PN-0216-00
Tools/Equipment:	Part#
T15 Torque Driver	
Critical Process Parameters	
8.5 in-lbs tightening torque	
Critical Quality Attributes	
Screws should fully seat	
Key Points	