

Tecno Wasino JJ-1 Turret Zero Point Setting Procedure - FANUC 18i-TB

Procedure Overview

This procedure will guide you through resetting the zero point on the Tecno Wasino JJ-1's servo-controlled turret using the FANUC 18i-TB controller. Follow each step precisely to avoid errors and ensure correct turret operation.

Steps

1. **Do a full shutdown at control and main PWR and wait 30sec to boot again.**
2. **Select the Turret Side:**
Use the L/R select switch to choose the side you're working on:
L-side for the left turret
R-side for the right turret
3. **Switch to MDI Mode**
4. **Enable Parameter Writing:**
Press the OFFSET/SETTING key, then press [SETTING].
Set PARAMETER WRITE to 1 to enable parameter changes.
5. **Clear the Alarm:**
Press RESET and CAN at the same time to clear it.
6. **Set the Turret Station Number:**
In system goto the pmc/counter area
Set according to LeftHand Or RightHand Side:
LH: C40
RH: C80
Ensure that the preset counter is set to the amount of total stations on the turret (typically 8)
Also ensure that the current tool counter is set to 0
7. **Enter Maintenance Mode for the Selected Turret:**
Goto KeepRelays
Set according to LeftHand Or RightHand Side:
LH: K16.0=1
RH: K16.1=1
8. **Unclamp the Turret Head:**
Press the Reference Point Return button to allow unclamping
Use the +Z jog button to fully unclamp the turret head.
9. **Adjust the Turret Position:**
Use the +X or -X jog button to rotate at least 1 revolution at first
Turn Down The Feed Rate to lowest increment above 0
Continue using +X & -X to align T1 into position
Clamp the Turret Head Using -Z
Verify Clamping:
Check that the turret head is securely clamped.
If the turret does not clamp correctly, unclamp and keep trying until we get T1 properly re-clamped
10. **Power Cycle the CNC @ controller (off for at least 3 sec):**
11. **Select the Turret Side:**
Use the L/R select switch to choose the side you're working on:
L-side for the left turret
R-side for the right turret
12. **Switch to MDI Mode**
13. **Enable Parameter Writing:**
Press the OFFSET/SETTING key, then press [SETTING].
Set PARAMETER WRITE to 1 to enable parameter changes.
14. **Clear the Alarm:**
Press RESET and CAN at the same time to clear it.
15. **Enter Maintenance Mode for the Selected Turret:**
Goto KeepRelays
Set according to LeftHand Or RightHand Side:
LH: K16.0=1
RH: K16.1=1
16. **Final Zero Point Confirmation:**
Press the Reference Point Return button to allow unclamping
Use the +Z jog button to fully unclamp the turret head.
Use the -Z jog buttons to reclamp it now.
Now hold down [-Z | REF | Turret(LH -OR- RH)] for about 2s to set the zero point for station T1.
17. **Final Power Cycle:**
Do a full shutdown at control and main PWR and wait 30sec to boot again.
Hold in [Reset | CAN] while booting up until fully booted
Home All Axis's
Put Machine In RH or LH (whichever you have been working on)
18. **Test Turret Indexing:**
Test manual indexing by pressing the Turret(LH -OR- RH) button.
Now Test automatic indexing, use a T-code command in MDI mode to confirm correct movement.
Example MDI Command= T0808
Test both clockwise and counterclockwise indexing to ensure smooth movement and secure clamping at each position.
Example MDI Command= T0202

When operating correctly, PMC COUNTERs c40/c80 "Current" should change as you index manually.