

1: System to actuator requirements

2: Reluctance actuator

Author: Leon Jabben

Date:


Version: 0.2

2: Reluctance type of actuator

Reluctance actuator



- Large forces (... for small gaps)
 - Used for bearing applications
- Vacuum and/or ultra clean



- References

- Feynman's lecture's on Physics
- PhD thesis – A. Katalenic
- PhD thesis – I. MacKenzie
- PhD thesis – L. Jabben

Control of reluctance actuators for high-precision positioning

Citation for published version (APA):

Katalenic, A. (2013). *Control of reluctance actuators for high-precision positioning*. Technische Universiteit Eindhoven. <https://doi.org/10.6100/IR752336>

Design and control methods for high-accuracy
variable reluctance actuators

by

Ian MacKenzie


Submitted to the Department of Mechanical Engineering
in partial fulfillment of the requirements for the degree of

Doctor of Philosophy in Mechanical Engineering


at the

MASSACHUSETTS INSTITUTE OF TECHNOLOGY

ARCHIVES





Magnetic Levitated Transport system




Challenges :

- Contradicting BW requirements:
 - Big size carrier ($3.1 \times 2.7 \text{ m}^2$): low dynamics (75 Hz)
 - Negative stiffness from AMB
- Use of industrial standard controllers: local control without decoupling
- Mechanical tolerances vs small gap of MagLev
- Timeline: 9 months to realize test track



Magnetic equations for flux density

- Gauss Law: $\nabla \cdot \vec{B} = 0$ or $\oiint_S \vec{B} \cdot d\vec{s} = 0$
 - B: magnetic field (flux density) [T],
- Ampere's Law:
$$\nabla \times \vec{B} = \mu_0(\vec{\rho}_f + \vec{\rho}_m)$$
 - $\mu_0 = 4\pi \cdot 10^{-7} \text{ N/A}^2$: permeability vacuum
 - ρ_f : free current density [A/m²]
 - ρ_m : magnetization current density [A/m²]
- Magnetization current density: $\vec{\rho}_m = \nabla \times \vec{M}$
- Hence: $\nabla \times \vec{B} = \mu_0(\vec{\rho}_f + \nabla \times \vec{M})$



Relation Flux density vs magnetic field

- Ampere's Law becomes

$$\nabla \times \vec{B} = \mu_0(\vec{\rho}_f + \nabla \times \vec{M}) \Leftrightarrow \nabla \times \left(\frac{\vec{B}}{\mu_0} - \vec{M} \right) = \vec{\rho}_f$$

- Can define magnetic field (intensity): $\vec{H} \stackrel{\text{def}}{=} \frac{\vec{B}}{\mu_0} - \vec{M} \Leftrightarrow \vec{B} = \mu_0(\vec{H} + \vec{M})$

- Magnetization is in same direction H : $\vec{M} = \chi(x, y, z, H)\vec{H}$ [A/m]

- If the material is

$$\left. \begin{array}{l} \bullet \text{ linear: } \frac{\partial \chi}{\partial H} = 0 \text{ (ferromagnetic: nope!) and} \\ \bullet \text{ homogeneous: } \frac{\partial \chi}{\partial (x, y, z)} = 0 \text{ (kind of)} \end{array} \right\} \vec{B} = \mu_0(1 + \chi)\vec{H} = \mu_0\mu_r\vec{H}$$

- Integrating both sides of $\nabla \times \vec{H} = \vec{\rho}_f$ over area and using Green's theorem:

$$\iint_A \nabla \times \vec{H} \cdot d\vec{a} = \oint_{\partial A} \vec{H} \cdot d\vec{l} = \iint_A \vec{\rho}_f \cdot d\vec{a}$$

- Current is confined to wire: $\iint_A \vec{\rho}_f \cdot d\vec{a} = n_c i$ (n_c : number of turns)

- Total flux through a surface: $\Phi = \iint_A \vec{B} \cdot d\vec{a}$


- Break up circuit in “tubes” of same material, no flux leaving sides of tubes:

$$n_c i = \oint_{\partial A} \vec{H} \cdot d\vec{l} = \sum_k H_k l_k = \sum_k \frac{B_k l_k}{\mu_0 \mu_k} = \Phi \sum_k \frac{l_k}{A_k \mu_0 \mu_k} = \Phi \mathcal{R}_m$$

- \mathcal{R}_m is the magnetic resistance [A/T/m²]

Magnetic energy

- We have developed a magnetic analogue to simple electric circuit
 - But no flow of power carrying particles \Rightarrow no dissipation!
 - Magnetic flux less confined by circuit than current



- Inductance of the coil:

$$\lambda = n_c \Phi = Li = \frac{n_c^2}{\mathcal{R}_m} i \Rightarrow L = \frac{n_c^2}{\mathcal{R}_m}$$

- Magnetic energy: $E_m = \frac{1}{2} Li^2$

- Force on moveable part:

$$F = \frac{\partial E_m}{\partial x} = \frac{1}{2} i^2 \frac{\partial L}{\partial x} = -\frac{1}{2} \frac{i^2 n_c^2}{\mathcal{R}_m^2} \frac{\partial \mathcal{R}_m}{\partial x}$$

$$u_{MMF} = n_c i = \Phi \mathcal{R}_m$$

MMF: MagnetoMotive Force

Magnetic circuit Modelling

- Total Magnetic resistance:



$$\mathcal{R}_m(x) = \frac{1}{A_{pole}\mu_0} \left(\frac{l_{iron}}{\mu_{iron}} + \frac{2(d_{gap}-x)}{\mu_{air}} \right),$$

- Hence, attraction force on rotor:

$$F = -\frac{1}{2} \frac{i^2 n_c^2}{\mathcal{R}_m^2} \frac{\partial \mathcal{R}_m}{\partial x} = \frac{n_c^2 i^2}{\mu_{air} \mu_0 A_{pole} \mathcal{R}_m^2}$$

- Can simplify: $\mu_{air} \approx 1$, $\mu_{iron} \approx 4000 \Rightarrow \frac{l_{iron}}{\mu_{iron}} \ll \frac{2d_{gap}}{\mu_{air}} \Rightarrow$

$$F \approx \frac{1}{4} \mu_0 n_c^2 A_{pole} \frac{i^2}{x_{gap}^2} = k_{ra} \frac{i^2}{x_{gap}^2} \text{ (using: } x_{gap} = d_{gap} - x \text{)}$$



Linearizing with gravity

- With zero current we have zero force... but also


$$\left. \frac{\partial F}{\partial i} \right|_{i=0} = 0$$

- Need to preload actuator (gravity, other RA, permanent magnet)
- With i_0 the current needed to generate F_{grav} :

$$F = k_{ra} \frac{(i_0 + i)^2}{(d_{gap} - x)^2}$$

- Linearize around $i=0$ & $x=0$

$$F = \frac{\partial F}{\partial i} i + \frac{\partial F}{\partial x} x = 2k_{ra} \frac{i_0}{d_{gap}^2} i + 2k_{ra} \frac{i_0^2}{d_{gap}^3} x$$



Linearizing with two opposite RAs



- Two opposite RAs (often used)

$$F = k_{ra} \frac{(i_0 + i)^2}{(d_{gap} - x)^2} - k_{ra} \frac{(i_0 - i)^2}{(d_{gap} + x)^2}$$

- Linearize around $i=0$ & $x=0$

$$F = \frac{\partial F}{\partial i} i + \frac{\partial F}{\partial x} x = 4k_{ra} \frac{i_0}{d_{gap}^2} i + 4k_{ra} \frac{i_0^2}{d_{gap}^3} x$$

- For completeness: a permanent magnet can also be used for preloading
 - Less thermal dissipation!



Magnetic “pressure”

- Recall: $F = \frac{n_c^2 i^2}{\mu_{air} \mu_0 A_{pole} \mathcal{R}_m^2}$
- With $n_c i = \Phi \mathcal{R}_m$ and $\Phi = B A_{pole}$ the force becomes:

$$F = \frac{A_{pole} B^2}{\mu_0} \Leftrightarrow \frac{F}{A_{pole}} = \frac{B^2}{\mu_0}$$

- Note that
 - the total iron surface is twice the surface of the pole
 - the total surface of the actuator is bigger because of the coil: take another factor 2
- With flux density of 0.5-1.0 T, the “pressure” becomes:


$$\frac{F}{A_{act}} = \frac{B^2}{4\mu_0} = \frac{B^2}{4 \cdot 4\pi \cdot 10^{-7}} \approx 5 - 20 \text{ N/cm}^2 \text{ (0.5-2 bar)}$$

Position coupling: stiffness

- Recall:

$$F = 2k_{ra} \frac{i_0}{d_{gap}^2} i + 2k_{ra} \frac{i_0^2}{d_{gap}^3} x$$

- Positional coupling... Not good in metro-force frame machine concepts
- Even worse, the coupling is actually a negative stiffness!
 - Open loop is unstable!
- Rewrite above as: $F = k_i i - k_x x$, with $k_x = -2k_{ra} \frac{i_0^2}{d_{gap}^3}$
- With bias force: $F_0 = k_{ra} \frac{i_0^2}{d_{gap}^2}$, hence $k_x = -2 \frac{F_0}{d_{gap}}$



With displacement x , a mechanical spring exerts a force:
 $f = -kx \Rightarrow$ stable!

Respect the unstable...

- Gunter Stein, “Respect the Unstable” :
 - Unstable plants are fundamentally more difficult to control
 - Controllers for unstable plants are operationally critical
 - Closed loops with unstable plants are only locally stable
- Bode integral:
 - With $S(j\omega)$: sensitivity function of closed loop system
 - Stable plants: $\int_0^\infty \ln|S(j\omega)|d\omega = 0$
 - Unstable: $\int_0^\infty \ln|S(j\omega)|d\omega = \pi \sum_{p \in P} \operatorname{Re}(p)$




Go find it on YouTube


Controller synthesis (from G. Stijn)

- Conservation law... What is conserved?
 - $\ln|S(j\omega)|$... aka “dirt”

Classic design






Modern design




Example

- Here: $k_x = -2 \frac{F_0}{d_{gap}} = -2 \frac{mg}{d_{gap}}$, with $g=9.81 \text{ m/s}^2$
- Ignoring minus sine: $\omega_{neg}^2 = \frac{k_x}{m} = 2 \frac{g}{d_{gap}}$.
- Air gap of 1mm $\Rightarrow f_{neg} = 22 \text{ Hz} \Rightarrow$ Take $f_{bw} = 50 \text{ Hz}$
 - Standard PID controller




Sensitivity of example

common representation



“Dirt” on linear scales






Stable: $\int_0^{\Omega_{lim}} \ln|S(j\omega)| d\omega = \delta = 14$

Unstable: $\int_0^{\Omega_{lim}} \ln|S(j\omega)| d\omega = \delta + \pi \sum_{p \in P} \text{Re}(p) = 445 \approx 14 + \pi(2\pi 22)$



Practical phenomena (1)

- Fringing of flux
 - Effective pole area becomes bigger
- Leakage flux
 - Less flux through gap \Rightarrow less force
- Eddy currents
 - $\frac{\partial \vec{B}}{\partial t} = -\nabla \times \vec{E}$
 - Use laminations



Practical phenomena (2): Hysteresis

- Recall $\vec{B} = \mu_0(1 + \chi)\vec{H} = \mu_0\mu_r\vec{H}$, valid for linear material: $\frac{\partial \chi}{\partial H} = 0$
- Guess what?



M1 = Silicon Steel, low hysteresis losses (small enclosed area)
M2 = Permanent Magnet, high hysteresis losses (larger enclosed area)
Br of M2 > Br of M1

- Relative permeability goes to one (becoming “air”) when saturating
- Energy loss when cycling through hysteresis loop
- Some phase loss in frequency domain


Benefits of flux control


- Benefits of flux control

- Negative stiffness is much reduced: $F = \frac{A_{pole} B^2}{\mu_0}$
 - Due to flux fringing some remains
- Effects of hysteresis is much reduced through the feedback loop
- Phase loss of eddy currents is much reduced

- The price to pay

- Additional sensor
- Which is usually in the air gap (decreasing efficiency)
- No off-the-shelf amplifiers available





www.mi-partners.nl

Habraken 1199
5507 TB Veldhoven
The Netherlands

T +31(0)40-2914920
E info@mi-partners.nl