

	<b>MAJOR TURNAROUND 2025</b> <b>PRESSURE VESSEL INSPECTION REPORT</b>	Report no.: <b>PLANT1/VI/HX-301/TA2025</b> Report date: 19 Nov 2025 Plant/Unit/Area: Plant 1
--	--	--

Equipment tag no: HX-301

Equipment description: Shell and Tube Heat Exchanger

DOSH registration no.: MK PMT 1001

**FINDINGS, NDTs & RECOMMENDATIONS**

**FINDINGS**

Initial/Pre-Inspection - Not applicable

**Post/Final Inspection**

**Internal**

- 1 1.1 Severe corrosion with significant metal loss exceeding 3mm depth
- 1.2 General corrosion observed with pitting depth up to 2mm across affected area
- 1.3 External corrosion detected on shell surface, localized area approximately 50mm x 50mm with minimal metal loss

**NON-DESTRUCTIVE TESTINGS**

UTTM: No significant wall loss detected compared to nominal thickness upon testing. Please refer UTTM report for complete documentation.

**RECOMMENDATIONS**

- 1: 1.1 Plan repair for next major turnaround
- 1.2 Schedule repair during next planned shutdown within 30 days
- 1.3 Engineering assessment required to determine repair methodology

Inspected by:

Reviewed by:

Approved by (Client):

Recommendation/Comment by DOSH Officer (if applicable):

Name:

Signature:

Date:

Action taken by Plant 1 on recommendation by DOSH (if applicable):

	<b>MAJOR TURNAROUND 2025</b> <b>PRESSURE VESSEL INSPECTION REPORT</b>	Report no.: <b>PLANT1/VI/HX-301/TA2025</b>  Report date: 19 Nov 2025 Plant/Unit/Area: Plant 1
--	--	--

Equipment tag no: HX-301  
Equipment description: Shell and Tube Heat Exchanger


DOSH registration no.: MK PMT 1001

PHOTOS REPORT

Photo 1



- Finding:
- 1.1 1.1 Severe corrosion with significant metal loss exceeding 3mm depth
  - 1.2 General corrosion observed with pitting depth up to 2mm across affected area
  - 1.3 External corrosion detected on shell surface, localized area approximately 50mm x 50mm with minimal metal loss
- Recommendation:
- 1.1 1.1 Plan repair for next major turnaround
  - 1.2 Schedule repair during next planned shutdown within 30 days
  - 1.3 Engineering assessment required to determine repair methodology



- Finding:
- 1.2 1.1 Severe corrosion with significant metal loss exceeding 3mm depth
  - 1.2 General corrosion observed with pitting depth up to 2mm across affected area
  - 1.3 External corrosion detected on shell surface, localized area approximately 50mm x 50mm with minimal metal loss
- Recommendation:
- 1.2 1.1 Plan repair for next major turnaround
  - 1.2 Schedule repair during next planned shutdown within 30 days
  - 1.3 Engineering assessment required to determine repair methodology



- Finding:
- 1.3 1.1 Severe corrosion with significant metal loss exceeding 3mm depth
  - 1.2 General corrosion observed with pitting depth up to 2mm across affected area
  - 1.3 External corrosion detected on shell surface, localized area approximately 50mm x 50mm with minimal metal loss
- Recommendation:
- 1.3 1.1 Plan repair for next major turnaround
  - 1.2 Schedule repair during next planned shutdown within 30 days
  - 1.3 Engineering assessment required to determine repair methodology