




## Receiving Pattern ( $\phi$ ), $\vartheta = 0^\circ$

f=600 MHz,TEM





f=1800 MHz,R22




Uncertainty of Axial Isotropy Assessment:  $\pm 0.5\%$  (k=2)

# Dynamic Range $f(\text{SAR}_{\text{head}})$ (TEM cell , $f_{\text{eval}} = 1900 \text{ MHz}$ )





Uncertainty of Linearity Assessment:  $\pm 0.6\%$  ( $k=2$ )

## Conversion Factor Assessment



## Deviation from Isotropy in Liquid

Error ( $\phi, \theta$ ),  $f = 900 \text{ MHz}$



## DASY/EASY - Parameters of Probe: EX3DV4 - SN:3911

### Other Probe Parameters

Sensor Arrangement	Triangular
Connector Angle (°)	81.9
Mechanical Surface Detection Mode	enabled
Optical Surface Detection Mode	disabled
Probe Overall Length	337 mm
Probe Body Diameter	10 mm
Tip Length	9 mm
Tip Diameter	2.5 mm
Probe Tip to Sensor X Calibration Point	1 mm
Probe Tip to Sensor Y Calibration Point	1 mm
Probe Tip to Sensor Z Calibration Point	1 mm
Recommended Measurement Distance from Surface	1.4 mm

**CUSTOMER  
COPY****PROBE REPAIR REPORT – SPEAG Production Center**

<b>PRODUCT:</b>		<b>EX3DV4</b>	
<b>SERIAL Nr.:</b>		<b>3911</b>	<b>IN DATE: 14-Sep-2015</b>
<b>CUSTOMER:</b>		<b>Sporton CN (Auden)</b>	
<b>PROBE REPAIR</b>			
<b>MATERIAL</b>	<b>WORK DESCRIPTION</b>		<b>WORKING TIME (h)</b>
Proximity Sensor (PEEK)	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Core replacement:	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Dipole sensor:	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Substrate:	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Components (diodes)	fixed <input type="radio"/>	exchanged <input type="radio"/>	Y-channel <input checked="" type="radio"/>
Components (capacitors)	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Bonding R-lines - substrate	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Probe tip:	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Probe connector:	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Probe tube	fixed <input type="radio"/>	exchanged <input type="radio"/>	..... <input type="radio"/>
Modification DS installed:	fixed <input type="radio"/>	installed <input type="radio"/>	..... <input type="radio"/>
Analysis:			..... <input type="radio"/>
Final Assembly:			..... <input type="radio"/>
<b>Total hours</b>			<b>2.50 hours</b>
<b>COMMENTS:</b>			
The probe was returned for repair. Receiving inspection found low response on Y channel. The probe was opened for further inspection. The Y channel diode was found to be defective. In order to re establish full probe functionality the Y channel diode was replaced. The probe will get newly calibrated after this repair.			
<b>CONDUCTED BY:</b>		<b>APPROVED BY:</b>	
DATE: <u>17-Sep-2015</u>		DATE: <u>17-Sep-2015</u>	
<b>REPAIR COST:</b>			
MATERIAL COST:		USD	Euro
REPAIR:		<input type="radio"/>	<input type="radio"/>
		<input type="radio"/>	<input type="radio"/>
<b>TOTAL COST:</b>		<b>QUOTATION #:</b>	
<b>S+M</b>		<b>-</b>	
<b>APPROVED BY:</b>			
DATE: <u>17-Sep-2015</u>			