




WICN 技术月刊  
(专用文档，请勿转发)

(专用文档，请勿转发)

2017年08月刊



# Outline

- WCN SW Case share

- 【BT】 [BT tethering] PAN 连接成功不能上网
- 【GPS】 TTFF 雙邊遮檔，單邊遮檔優化

# WCN SW Case share

【BT】 [BT tethering] PAN 连接成功不能上网					
风险高低	平台	SW版本	WCN IC	软硬件	涉及领域
中	6737	N	6625	SW	BT ,Net
现象描述	➤ 大量开关BT tethering后，PAN连接成功，但不能上网				
复现路径	<ul style="list-style-type: none"><li>➤ B手机PAU 成功连接到A 手机NAP后，B手机可以正常上网</li><li>➤ 不停去关闭A手机的bluetooth tethering 一段时间后</li><li>➤ B手机再次 连接成功时,发现B手机不能正常上网</li></ul>				
解决方案	<ul style="list-style-type: none"><li>➤ 修正方法：IpManager registerObserver而無unregisterObserver</li><li>➤ 當IpManager.shutdown時, 註銷observer</li><li>➤ <a href="#">申请Patch：ALPS03317414</a></li></ul>				



# 问题分析

PANU 端的connectivity service 一直没有连接上，也没有去Register NetworkAgent

正常的时候：

```
06-29 09:16:31.264466 3167 3247 D IpManager.bt-pan: IPv4 configuration succeeded
06-29 09:16:31.265509 3167 3247 D IpManager.bt-pan: CMD_CONFIGURE_LINKADDRESS bt-pan/27 0 0 192.168.44.186/24
06-29 09:16:31.266374 3167 3247 D IpManager.bt-pan: newLp{InterfaceName: bt-pan LinkAddresses: [fe80::749b:46ff:fe03:35c7/64,192.168.44.186/24,] Routes: [fe80::/64 -> ::
06-29 09:16:31.284251 3167 3247 D IpManager.bt-pan: setLinkProperties newLp = {InterfaceName: bt-pan LinkAddresses: [fe80::749b:46ff:fe03:35c7/64,192.168.44.186/24,] Ro
Domains: null MTU: 0}
06-29 09:16:31.284558 3167 3247 D IpManager: compareProvisioning: GAINED_PROVISIONING
06-29 09:16:31.296450 3167 3247 D IpManager.bt-pan: handleLinkPropertiesUpdate delta = GAINED_PROVISIONING
06-29 09:16:31.296673 3167 3247 D IpManager.bt-pan: onProvisioningSuccess()

06-29 09:16:31.304220 3167 3246 D Bluetooth Tethering: NetworkAgent: Registering NetworkAgent
06-29 09:16:31.313263 803 1206 D ConnectivityService: registerNetworkAgent NetworkAgentInfo{ nI{type: Bluetooth Tethering[], state: CONNECTED/CONNECTED
06-29 09:16:31.314356 803 1082 D ConnectivityService: Got NetworkAgent Messenger
06-29 09:16:31.314828 803 1082 D ConnectivityService: NetworkAgentInfo [Bluetooth Tethering () - 101] EVENT_NETWORK_INFO_CHANGED, going from null to CONNECTED
```

异常的log:

```
06-29 09:25:17.229989 3167 4530 D IpManager.bt-pan: IPv4 configuration succeeded
06-29 09:25:17.231222 3167 4530 D IpManager.bt-pan: CMD_CONFIGURE_LINKADDRESS bt-pan/239 0 0 192.168.44.186/24
```

//这个 newLP 没有包含到这个 IP address, 使 Ipmanager 一直在 STILL\_NOT\_PROVISIONED 状态，没有进入到正常的 GAINED\_PROVISIONING 状态，所以没有注册到 NetworkAgent，怀疑后面一直在做 addressRemoved 动作引起的。

```
06-29 09:25:17.259330 3167 4530 D IpManager.bt-pan: newLp{InterfaceName: bt-pan LinkAddresses: [fe80::749b:46ff:fe03:35c7/64,] Routes: [192.168.44.0/24 -> 0.0.0.0 bt-pan,0.0.0.0/24]
06-29 09:25:17.259799 3167 4530 D IpManager.bt-pan: setLinkProperties newLp = {InterfaceName: bt-pan LinkAddresses: [fe80::749b:46ff:fe03:35c7/64,] Routes: [192.168.44.0/24]
06-29 09:25:17.260116 3167 4530 D IpManager: compareProvisioning: STILL_NOT_PROVISIONED
06-29 09:25:17.260317 3167 4530 D IpManager.bt-pan: handleLinkPropertiesUpdate delta = STILL_NOT_PROVISIONED
06-29 09:25:17.260777 3167 4530 D IpManager.bt-pan: onLinkPropertiesChange()

06-29 09:25:49.323048 3167 4529 E BluetoothTetheringNetworkFactory: IP provisioning error.
```





# 问题分析

## 问题原因:

每次 BluetoothTetheringNetworkFactory new IpManager()時, IpManager 會註冊一個 observer

```
try {  
    mNwService.registerObserver(mNetlinkTracker);  
} catch (RemoteException e) {  
    Log.e(mTag, "Couldn't register NetlinkTracker: " + e.toString());  
}
```

如果在 bt tethering 結束後, IpManager 沒有 unregisterObserver(), 就會造成 NetworkManagementService 處理 event 上產生 timing issue

//一開始 framework 收到 netd 的 Address removed event 被延後處理, 因為 NetworkManagementService 正在通知每個 observer

```
06-29 09:18:28.550287 803 1008 D NetdConnector: RCV <- {614 Address removed fe80::749b:46ff:fe03:35c7/64 bt-pan 196 253 1}  
06-29 09:18:28.565593 803 846 D NetworkManagement: onEvent:600 Iface linkstate bt-pan down:5  
06-29 09:18:28.725649 803 846 D NetworkManagement: onEvent:600 Iface linkstate bt-pan down:5  
06-29 09:18:28.774687 803 846 D NetworkManagement: onEvent:600 Iface linkstate bt-pan up:5  
06-29 09:18:28.826811 803 846 D NetworkManagement: onEvent:616 Route updated fe80::/64 dev bt-pan:6  
06-29 09:18:28.879172 803 846 D NetworkManagement: onEvent:614 Address updated fe80::749b:46ff:fe03:35c7/64 bt-pan 196 253 1:8
```

//開始處理這個 event 時, 已經慢了 550ms

```
06-29 09:18:29.253048 803 846 E NetdConnector: NDC event {614 Address removed fe80::749b:46ff:fe03:35c7/64 bt-pan 196 253 1} processed too late: 550ms
```

//跟著 bt on/off observer 越來越多次, 使得 NetworkManagementService 需要通知的 Observer 越來越多

```
06-29 09:25:14.272511 803 1008 D NetdConnector: RCV <- {614 Address updated fe80::749b:46ff:fe03:35c7/64 bt-pan 128 253 1}
```

//最後已經被延遲了 3 分鐘才處理 Address updated

```
06-29 09:28:10.127209 803 846 E NetdConnector: NDC event {614 Address updated fe80::749b:46ff:fe03:35c7/64 bt-pan 128 253 1} processed too late: 181050ms
```

//正常在 DHCP 成功後, IpManager 設定完 bt-pan IP address, 都會收到 callback, 但因為 observer 太多, 已經無法及時處理 event 使得 IpManager 無法及時拿到 ipv4 address 的 onEvent callback

```
06-29 09:25:17.219801 803 1467 D NetdConnector: SND -> {1092 interface setcfg bt-pan 192.168.44.186 24}  
06-29 09:25:17.226211 803 1008 D NetdConnector: RCV <- {200 1092 Interface configuration set}  
06-29 09:25:17.229989 3167 4530 D IpManager.bt-pan: IPv4 configuration succeeded
```

//這邊收到 netd 通知, 但是 IpManager 一直沒收到 callback

```
06-29 09:25:17.231692 803 1008 D NetdConnector: RCV <- {614 Address updated 192.168.44.186/24 bt-pan 128 0 1}  
06-29 09:25:17.259330 3167 4530 D IpManager.bt-pan: newLp[{InterfaceName: bt-pan LinkAddresses: [fe80::749b:46ff:fe03:35c7/64,] Routes: [192.168.44.0/24
```



# 修改方法

修改方法：蓝牙PAN 是在android N 版本才开始用的Ipmanager 的方式，

```
IpManager.java x BluetoothTetheringNetworkFactory.java x EthernetNetworkFactor

// Shut down this IpManager instance altogether.
public void shutdown() {
    stop();

    try{
        mNwService.unregisterObserver(mNetlinkTracker);
    }catch (RemoteException e){
        e.printStackTrace();
    }
    quit();
}
```



## 【GPS】TTFF 雙邊遮檔，單邊遮檔優化

风险高低	平台	SW版本	WCN IC	软硬件	涉及领域
高	MT6750	alps-mp-n0.mp7-V1.24	MT6750		GPS
现象描述	➤ GPS静态性能测试，热启动TTFF成功率以及定位精度均不达标，冷启动定位精度不达标				
复现路径	➤ 華為測試地點執行窗邊CTTFF/HTTFF的測試				
分析过程	➤ 觀察：1. AGPS輔助資訊LLH不夠精確。2. 窗邊測試遭遇到多徑效應影響。複現概率50%。 ➤ 原因：在雙邊遮檔/單面遮擋場景，窗邊測試遭遇到多徑效應影響。				
解决方案	➤ 微調改善窗邊測試 CTTFF/HTTFF 的GNSS 定位演算法。 ➤ <a href="#">打上patch : ALPS03374603</a> ➤ 影響Branch：alps-mp-m0.mp9, alps-mp-m1.mp3, alps-mp-n0.mp1, alps-mp-n0.mp2, alps-mp-n0.mp7, alps-mp-n1.mp7, alps-mp-n1.mp9				



**MEDIATEK**

*everyday genius*