



3F — Framework for FEMM


Contents

1	Geometry	2
1.1	Slots	2
1.2	Stators	3
1.3	SPM Magnets	6
1.4	SPM Rotors	7
2	Winding	9
2.1	Space vector	10
2.2	Sinusoidal dq control	11
2.3	Trapezoidal control	11


Chapter 1

Geometry


1.1 Slots




1.2 Stators




1 pole



2 poles






1.3 SPM Magnets



parallel + rect




parallel + trapz




radial (+ trapz)


1.4 SPM Rotors




1 pole



2 poles



p poles



$2p$ poles

Chapter 2

Winding

We will characterise a winding through

Name	Math symbol	Code symbol
N. of phases	m	m
N. of coils	N_{coils}	coils
N. of turns per coil	N_{turns}	turns
N. of layers	N_{layers}	layers
N. of parallel paths	n_{pp}	ppath
N. of conductors in slot	n_c	nc

Typically, given a lamination stack with Q slots

$$N_{\text{coils}} = \frac{Q}{2} N_{\text{layers}}$$

so if the number of layers is one, the number of coils is half the number of slots, given the fact that a coil side occupies a full slot.

$$n_c = N_{\text{layers}} N_{\text{turns}}$$

This equation means that in each slot there are n_c conductors of any phase due to the turns in each coil side in each layer. We bring this number to the equivalent series-connected machine, through the number of parallel paths:

$$n_{\text{cs}} = \frac{n_c}{n_{\text{pp}}}$$

This number, n_{cs} , is related to the complete set of slots, while the previous n_c was related only to a part of them, due to the parallel connection of the winding. Thanks to this fact, we can compute the whole number of conductors for each phase, through

$$N_c = \frac{Q n_{\text{cs}}}{m}$$

Therefore the full number of turns for each phase, which will appear in the flux linkage, is $N_c/2$. This number is valid for both the real machine and the equivalent series-connected one.

Another equivalence that we will use is the wye-equivalence. For both the wye and the delta connection of the windings, we will refer to the wye equivalent winding. Each winding sustains either the line(-to-line) voltage in the wye (delta) connection. Therefore

$$U_w = \frac{U_N}{\sqrt{3}} \quad [\text{V}] \quad \text{delta connection}$$

$$U_w = U_N \quad [\text{V}] \quad \text{wye connection}$$

In this way we can obtain the winding current directly from the power

$$I_w = \frac{P}{3U_w \cos \varphi} \quad [\text{A}]$$

and use it as the design current for the winding itself. In fact, if each turn is made by some wires with a full section S_c , we will refer to the equivalent turn section

$$S_{c,\text{eq}} = n_{\text{pp}} S_c \quad [\text{mm}^2]$$

which sees the complete winding current, giving the current density

$$J = \frac{I_w}{S_{c,\text{eq}}} \quad [\text{A/mm}^2]$$

It is important to highlight that this current density is the conductor's one, while the slot current density is given by

$$J_{\text{slot}} = k_{\text{fill}} J \quad [\text{A/mm}^2]$$

where the fill factor, k_{fill} , represents the ratio between the actual conductor area in the slot and the slot section. Depending on the starting point, one can find the rms current in the slot through

$$I_{\text{slot}} = J_{\text{slot}} S_{\text{slot}} = n_{\text{cs}} I_w \quad [\text{A}]$$

2.1 Space vector

Given an m -phase winding symmetrically distributed, we can associate its currents to a single complex-valued variable, the *space vector*, which represents the equivalent primitive two-phase winding, with axes α and β . Thus

$$\mathbf{i}_{\alpha\beta} = \frac{2}{m} \left[i_a + i_b e^{j\frac{2\pi}{m}} + i_c e^{j\frac{4\pi}{m}} + \dots + i_m e^{j\frac{(m-1)2\pi}{m}} \right] = \mathbf{i}^s$$

If we want to get the space vector in the synchronous reference frame, it is simply

$$\mathbf{i}^r = \mathbf{i}^s e^{-j\vartheta_m^e}$$

Therefore we can directly relate the dq -current to the m phase currents:

$$\vec{i}_s \xrightarrow{T_{ab \dots m}^{dq}} \mathbf{i}^r$$

2.2 Sinusoidal dq control

2.3 Trapezoidal control