



3F — Framework for FEMM


# Contents

<b>1</b>	<b>Geometry</b>	<b>2</b>
1.1	Slots . . . . .	2
1.2	Stators . . . . .	3
1.3	SPM Magnets . . . . .	6
1.4	SPM Rotors . . . . .	7
<b>2</b>	<b>Winding</b>	<b>9</b>
2.1	Space vector . . . . .	10
2.2	Slot matrix . . . . .	11
2.3	Sinusoidal dq control . . . . .	11
2.4	Trapezoidal control . . . . .	12


# Chapter 1

## Geometry


### 1.1 Slots




## 1.2 Stators




1 pole



2 poles



$p$  poles




### 1.3 SPM Magnets



parallel + rect




parallel + trapz




radial (+ trapz)

## 1.4 SPM Rotors




1 pole




2 poles





$p$  poles



$2p$  poles

## Chapter 2

# Winding

We will characterise a winding through

Name	Math symbol	Code symbol
N. of phases	$m$	<b>m</b>
N. of coils	$N_{\text{coils}}$	<b>coils</b>
N. of turns per coil	$N_{\text{turns}}$	<b>turns</b>
N. of layers	$N_{\text{layers}}$	<b>layers</b>
N. of parallel paths	$n_{\text{pp}}$	<b>ppath</b>
N. of conductors in slot	$n_c$	<b>nc</b>

Typically, given a lamination stack with  $Q$  slots

$$N_{\text{coils}} = \frac{Q}{2} N_{\text{layers}}$$

so if the number of layers is one, the number of coils is half the number of slots, given the fact that a coil side occupies a full slot.

$$n_c = N_{\text{layers}} N_{\text{turns}}$$

This equation means that in each slot there are  $n_c$  conductors of any phase due to the turns in each coil side in each layer. We bring this number to the equivalent series-connected machine, through the number of parallel paths:

$$n_{\text{cs}} = \frac{n_c}{n_{\text{pp}}}$$

This number,  $n_{\text{cs}}$ , is related to the complete set of slots, while the previous  $n_c$  was related only to a part of them, due to the parallel connection of the winding. Thanks to this fact, we can compute the whole number of conductors for each phase, through

$$N_c = \frac{Q n_{\text{cs}}}{m}$$

Therefore the full number of turns for each phase, which will appear in the flux linkage, is  $N_c/2$ . This number is valid for both the real machine and the equivalent series-connected one.

Another equivalence that we will use is the wye-equivalence. For both the wye and the delta connection of the windings, we will refer to the wye equivalent winding. Each winding sustains either the line(-to-line) voltage in the wye (delta) connection. Therefore

$$U_w = \frac{U_N}{\sqrt{3}} \quad [\text{V}] \quad \text{delta connection}$$

$$U_w = U_N \quad [\text{V}] \quad \text{wye connection}$$

In this way we can obtain the winding current directly from the power

$$I_w = \frac{P}{3U_w \cos \varphi} \quad [\text{A}]$$

and use it as the design current for the winding itself. In fact, if each turn is made by some wires with a full section  $S_c$ , we will refer to the equivalent turn section

$$S_{c,\text{eq}} = n_{\text{pp}} S_c \quad [\text{mm}^2]$$

which sees the complete winding current, giving the current density

$$J = \frac{I_w}{S_{c,\text{eq}}} \quad [\text{A/mm}^2]$$

It is important to highlight that this current density is the conductor's one, while the slot current density is given by

$$J_{\text{slot}} = k_{\text{fill}} J \quad [\text{A/mm}^2]$$

where the fill factor,  $k_{\text{fill}}$ , represents the ratio between the actual conductor area in the slot and the slot section. Depending on the starting point, one can find the rms current in the slot through

$$I_{\text{slot}} = J_{\text{slot}} S_{\text{slot}} = n_{\text{cs}} I_w \quad [\text{A}]$$

## 2.1 Space vector

Given an  $m$ -phase winding symmetrically distributed, we can associate its currents to a single complex-valued variable, the *space vector*, which represents the equivalent primitive two-phase winding, with axes  $\alpha$  and  $\beta$ . Thus

$$\mathbf{i}_{\alpha\beta} = \frac{2}{m} \left[ i_a + i_b e^{j\frac{2\pi}{m}} + i_c e^{j\frac{4\pi}{m}} + \dots + i_m e^{j\frac{(m-1)2\pi}{m}} \right] = \mathbf{i}^s$$

If we want to get the space vector in the synchronous reference frame, it is simply

$$\mathbf{i}^r = \mathbf{i}^s e^{-j\vartheta_m^e}$$

Therefore we can directly relate the  $dq$ -current to the  $m$  phase currents:<sup>1</sup>

$$\bar{i}_s \xrightarrow{T_{ab\cdots m}^{dq}} \mathbf{i}^r$$

## 2.2 Slot matrix

The slot matrix is a useful tool for the correct and rapid assignment of currents in the slots. In fact it directly relates phase and slot currents, through

$$\bar{i}_s \xrightarrow{K} \bar{i}_{\text{slot}}$$

This relationships is missing just the number of series conductor per slot. So

$$\bar{i}_{\text{slot}} = n_{\text{cs}} K \bar{i}_s$$

## 2.3 Sinusoidal dq control

For synchronous machines, this is the typical control implemented. A reference current, which comes from the speed loop, is imposed. Usually the control is executed in the  $dq$ -reference frame, therefore we start from

$$\mathbf{i}^r = i_d + j i_q = |\mathbf{i}| e^{j\alpha_i^e}$$

Then we transform it in the  $\alpha\beta$ -reference frame and finally we get the phase currents:<sup>2</sup>

$$\bar{i}_s = U_s^{ab\cdots m} \mathbf{i}^s = U_s^{ab\cdots m} U_r^s \mathbf{i}^r = U_r^{ab\cdots m} \mathbf{i}^r$$

From here, the slot currents are simply

$$\bar{i}_{\text{slot}} = n_{\text{cs}} K \bar{i}_s = n_{\text{cs}} K U_r^{ab\cdots m} \mathbf{i}^r$$

---

<sup>1</sup>The adopted convention is the following

$$\text{Transformation}_{\text{from}}^{\text{to}} \quad U_{\text{antitransformation}_{\text{from}}^{\text{to}}}$$

<sup>2</sup>In the code the transformations made available are `dq2ab` and `U`, which is the one from  $\alpha\beta$  to  $abc\cdots m$ .

## 2.4 Trapezoidal control

This control is typical of BLDC drives. In the trapezoidal control the currents would ideally assume just three values:

$$\{+I_{\text{DC}}, 0, -I_{\text{DC}}\}$$

while the current absorbed from the DC-bus is constant. Only two phases are active simultaneously, while the third one is kept off. Taking half the DC-bus voltage as the reference, the voltages assume just three values too:

$$\{+V_{\text{DC}}/2, 0, -V_{\text{DC}}/2\}$$

The complete number of possible states is the double  $(+/-)$  of all the grouping of the phases  $(m)$  by two:

$$\# \text{ of states} = 2 \binom{m}{2} = m(m-1)$$

Consider a three-phase machine for instance. The supply states can be

state 6	+	-	0
state 1	+	0	-
state 2	0	+	-
state 3	-	+	0
state 4	-	0	+
state 5	0	-	+

