

1.  $F_h = 400 \text{ N}$   $l = 1.5 \text{ m}$



$$\sigma = \frac{M r}{I}$$

$$I = \frac{\pi r^4}{4}$$

$$m = \rho V = \rho \pi r^2 l$$

$$I = \frac{m}{\rho l} \frac{r^2}{4}$$

$$\sigma = \frac{4 M l \rho}{r m} \Rightarrow \boxed{\frac{\sigma}{\rho}} = \frac{4 M l}{m r}$$

Not going to choose ceramics or glass due to cost and brittle. Carbon Fiber is next best material

$$\sigma = \frac{4 M l \rho}{\rho \pi r^2 l} = \frac{4 M}{\pi r}$$

$$1 \times 10^9 = \frac{4 \cdot 400}{\pi r}$$

$$d = 2r = \boxed{3.2 \times 10^{-6} \text{ m}}$$

$$m = 1600 \cdot \pi (1.6 \times 10^{-6})^2 \cdot 1.5$$

$$\boxed{m = 1.9 \times 10^{-8} \text{ kg}}$$


AL:

$$\sigma = 4.6 \times 10^8 = \frac{4 \cdot 400}{\pi \cdot r}$$

$$d = 2r = 2.21 \times 10^{-6}$$

$$m = 3000 \cdot \pi \cdot (1.107 \times 10^{-6})^2 \cdot 1.5$$

$$m = 1.73 \times 10^{-8} \text{ kg}$$



2.

$$l = 2\text{ m}$$

$$m = 5\text{ kg}$$

$$\delta = 20\text{ mm} = 0.02\text{ m}$$

$$\delta = \frac{F l^3}{3 E I}$$

$$I = \frac{\pi r^4}{4}$$

$$m = \rho H r^2 l$$

$$\pi r^2 = \frac{m}{\rho l}$$

$$\delta = \frac{4 F l^3}{3 E \pi r^2 r^2}$$

$$\delta = \frac{4 F \rho l^4}{3 E m r^2}$$

$$\frac{E}{\rho} = \frac{4 F l^4}{3 \delta m r^2}$$

The best material is Carbon fiber Unimply

$$E = 100\text{ GPa} \quad \rho = 1600\text{ kg/m}^3$$

$$\delta = \frac{4 F \rho l^4}{3 E \pi r^2 l r^2} = \frac{4 F l^3}{3 E \pi r^4}$$

$$0.02 = \frac{4 (5 \cdot 9.8) (2)^3}{3 (1 \times 10^{11}) \pi r^4}$$

$$r = 0.017\text{ m}$$

$$d = 0.034\text{ m}$$

$$m = 1600 \pi (0.017)^2 2 = 2.9\text{ kg}$$

$$\text{AL} \quad E = 80\text{ GPa} \quad \rho = 2000\text{ kg/m}^3$$


$$0.02 = \frac{4 (5 \cdot 9.8) 2^3}{3 \cdot 8 \times 10^{10} \pi r^4}$$

$$m = 2000 \pi (0.018)^2 2$$

$$m = 4.07\text{ kg}$$

$$r = 0.018\text{ m}$$

$$d = 0.036\text{ m}$$



Problem 3:

- Vacuum Assisted Transfer Molding would be a good method for a large boat. This method allows you to wet all of the fibers very quickly to prevent uneven curing which is important for large structures.
- Filament winding is the best method for pressure vessels. This method allows fibers to be laid easily in the hoop direction which has the highest stress.
- The autoclave cure process results in the highest quality parts with high fiber content. This process pulls a vacuum on the part, and applies large amounts of pressure and heat to cure the part.