



# RhinoCam

Digital Design Methods I













## Setup Document:

- 1 verify Units:  
go to Options > Units: make sure the document-units are set to millimeters  
When you create a new document:  
select Small Objects - Millimeters


## Locate geometry:

- 2 draw a box representing your material to check that everything fits inside
- 3 make sure, that all your geometry is positioned in positive X, positive Y and **negative Z**  
Origin(0,0,0) at the top-upper-left corner of the box
- 4 Setup Post-Options: select ShopBot-LVML as Current PostProcessor and .nc as Posted File Extension. You find the right PostProcessor under the following path on the server:  
**\\01\_DesignStudio\01\_INPUT\02 Workshops\04 CNC**
- 5 left-click on Stock > Box Stock
- 6 define the top-lower-left corner = (0,0,0)





- 8 go to the Cutting Tools Browser > if it's not yet visible, select the menu RhinoCAM > Cutting Tools Browser
- 9 you can define your own tools or
- 10 Load Tool library
- 11 select shopbot-toollib.csv > OK > this should load 6 tools (3,6,12mm, ball- and flatnose) to your library
- 12 select the tool you want to use (we will start with the 12 mm Flatnose).




Different results with different tools and same stepsize:

left: 6mm ballnose tool

right: 12mm ballnose tool

The result is smoother with the bigger tool!




for flat surfaces, select flat-nose tools  
for slopes, select ball-nose tools  
for smooth surfaces, select larger tools  
for narrow valleys, select thinner tools  
for fast milling, select big diameters  
for fine details, select small diameters

A houses stand too close to each other

B large tool (12mm) doesn't fit inbetween > a lot of rest material


C ballnose tool leaves rounded edges

D result with a flatnose tool



Machining Operations are different strategies to generate toolpaths - threedimensional lines in space as paths for the milling bit.



- 14 switch to the Create tab
- 15 click 3 Axis Adv > Horizontal Roughing > the roughcut quickly gets rid of a lot of material, step by step.
- 16 in the dialog-box that pops up, go to the Cut Parameters tab
  - a set the Stock (e.g. 3 mm for foam)
  - b under Cut Pattern, select Linear
  - c under Cut Direction, select Mixed
  - d under Stepover Control set % Tool Diameter to 90 for foam, less for harder materials...
  - e in the Cut Levels tab under Stepdown Control put % Tool Diameter to 100%-200% for foam, 50% for wood
- 17 click Generate to calculate the toolpath > you should now have a subfolder of Setupv 1 called Horizontal Roughing, which contains all the different components / parameters that defines the operation > double-click on one of them to change the settings > a red star on one of them means Regeneration necessary (right-click > Regenerate)
- 18 switch to the Simulate tab and hit play
- 19 configure visibility using these buttons:



- A Part visibility
- B Stock visibility
- C Material Texture visibility
- D Toolpath visibility
- E Toggle Machine GSYS
- F Tool visibility
- G Holder visibility
- H Machine Tool Visibility





# Machining Operations




- 20 switch back to the Create tab
- 21 if necessary, select a different tool from the list
- 22 click 3 Axis Adv> Parallel Finishing >in this operation, the tool will follow the surface
- 23 in the dialog-box, that pops up, go to the Cut Parameters tab
  - a set the Stock to 0 (normally) and Cut Direction to Mixed
  - b define the Angle of Cuts and the % Tool Diameter > depending on the desired pattern (min 25, max 90).
  - c in the Feeds and Speeds tab, set the Speed to 16'000 RPM and the Cut (cf) to 250 mm/min.
  - d don't forget to set your tools in the tool tab
- 27 click Generate again and Simulate the operation > you can create as many machining operations as you like until you are satisfied with the result.

The most helpful Milling Operation Are „Horizontal Roughing“, „Parallel Finishing“, „Curve Machining“ and „Engraving“. But you can also experiment with „Pocketing“ or „Between 2 Curves Machining“ and other operations.

#	Selected Machining Region(s)
1	Region 1
2	Region 2
3	Region 3

 Select Curves as Regions
   
 Select Flat Area Feature




Closed curves can be selected as so called Regions - either before the Machining Method is chosen or under the Features/Regions tab by clicking Select Curves as Regions.

These curves then act as boundary to limit the toolpath to the specific area.

Curves can also be nested (islands).

Engrave a road



- 1 select a (open or closed) 2D curve
- 2 for sharp edges, select a flatnose mill from the list
- 3 click 3 Axis Adv > Curve Machining
- 4 in the Cut Parameters tab, define a negative stock
- 5 click Generate
- 6 RhinoCAM automatically projects the curve onto all visible geometry and runs the tool along the rail




boarder of a river...

- 1 select two 2D curves (both open or both closed)
- 2 click 3 Axis Adv > Between 2 Curves Machining
- 3 click Generate
- 6 RhinoCAM creates not parallel toolpath-lines but lines that „blend“ curves into one another. Stepsize is smaller where the curves are closer and bigger where they are more distant > the resulting pattern integrates well in the landscape if for example the two borders of a river are selected...







To mill the inner area (red), select the white bounding curve



To mill the outer area (red), select the white AND yellow bounding curve

- 27 post the individual jobs to separate files.
- right-click on the machining operation you want to post and click [Post]
- 28 specify the folder location and the filename (e.g.: NAME\_12Ball\_6Flat.nc)
- 29 click [Post] to write G-Code file
- 32 put your G-Code on a USB stick and bring it down to the RapLab



CNC Workshop on our Shopbot PRS Alpha

The first Model should show a zoom in of your desing in the scale 1:1000

The piece of foam has the following measurements: 1000 x 250 x 100 mm

We will only be using the 6mm Ballnose, 6mm Flatnose and 3mm Flatnose for details

Milling will happen in the following timeslots (please have your g-code ready to mill):

November 7th

13:00h Group 1

15:00h Group 2

17:00h Group 3

19:00h Group 4

November 8th

09:00h Group 5

11:00h Group 6

13:00h Group 7

15:00h Group 8

The final Model should cover a great part of the site showing your most important interventions in the scale 1:5000. The piece of foam has the same measurements as above: 1000 x 250 x 100 mm

We will only be using the 6mm Ballnose and 6mm Flatnose and the 3mm Flatnose and 3mm Ballnose for details.

December 12th

13:00h Group 1

15:00h Group 2

17:00h Group 3

19:00h Group 4

December 13th

09:00h Group 5

11:00h Group 6

13:00h Group 7

15:00h Group 8

Institute for Landscape Architecture  
Prof. Christophe Girot  
ETH Zurich

Instructor:  
Benedikt Kowalewski  
DesignLab  
[kowalewski@arch.ethz.ch](mailto:kowalewski@arch.ethz.ch)  
<http://girot.arch.ethz.ch>

©2020